

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8a6"
    },
    "firstName": "Sachin Powar",
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141aff",
    "email": "bo9938@pnb.co.in",
    "mobileNo": "9503894959",
    "workMobileNo": "9503894959",
    "lastName": "Powar"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6400000",
    "discussWithPerson": "Sachin Powar",
    "expectedFees": 3200,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1812",
  "type": "BANK",
  "name": "Punjab National Bank",
  "displayName": "Punjab National Bank",
  "initial": "PNB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8a6",
  "branchCode": "000016",
  "type": "BRANCH",
  "name": "Goregaon (West) Branch",
  "email": "veenagupta5@rediffmail.com",
  "mobileNo": "28726224 ",
  "alternateMobileNo": "28726225",
  "address": "Topiwala Centre, 174, Jawahar Nagar, Goregaon (West), Mumbai - 400
062, State - Maharashtra, Country - India.\r\n",
  "ledgerName": "PUNJAB NATIONAL BANK - GOREGAON W",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f7fcadf3dd69653a58d9d7",
  "zoneName": "Mumbai Zone (Maharashtra)"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60af6ae22ffdf65bcd65861d",
  "role": "PICKUPPERSON",
  "firstName": "Sunil",
  "email": "misalsunil87@gmail.com",
  "lastName": "Misal",
  "mobileNo": "8422982721",
  "shortName": "SM",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62691c48afd7d55eddecfda3",
  "role": "ADMIN",
  "firstName": "Bhavika",
  "email": "bhavikachavan0102@gmail.com",
  "lastName": "chavan",
  "mobileNo": "8390804382",
  "designation": "Site Engineer",
  "shortName": "BH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f9147bf3dd69653a591e8c",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Vinita",
  "email": "vinita.surve@vastukala.org",
  "lastName": "Surve",
  "mobileNo": "9820652818",
  "designation": "",
  "shortName": "V",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
```

```
    "value": "[N]C.C.I.T/I -14/52/2008-09",
    "label": "Wealth Tax"
  }
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
  {
    "title": {
      "value": "Wealth_Tax",
      "label": "Wealth Tax"
    },
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.1916478576731",
  "longitude": "72.85316333217474"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.85316333217474,
    19.1916478576731
  ]
}
},
```

```
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "15/02/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "1",
    "label": false
  }
}
```

```
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
```

```
"key": "buildingName",
"value": "Malad Gautam Nagar CHSL",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Datta Mandir Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
}
```

```
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "101",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
```



```
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400097",
  "label": false
},
"suburb": {
```

```
    "status": true,
    "name": "Suburb",
    "key": "suburb",
    "value": "Malad East",
    "label": false
  }
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
```

```
"routeLng": "",
"stationName": "",
"routeDistance": ""
},
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
},
```

```
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
```

```
    "label": "Work Completed (%)",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
```

```
"title": "Extra collapsible gates / grill works etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
```



```
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67b0485dc594f0b7b654ea1d",
"ownerName": "Mr. Sudhir Balubhai Trivedi And Mr. Dharmil Sudhir Trivedi",
"ownerPhoneNo": "9322899168",
"appAddress": "C/101 1 St floor Malad Guvtam Nagar Co-op HSG Soc Ltd Malad East
Mumbai 400097",
"remark": "other No Dharmali Trivedi - 9267289209",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67b0485dc594f0b7b654ea1d/
document_1739606084655_1739606082614_Pnb_Topiwala_Sudhir_B_Trivedi.pdf",
    "fileName":
"document_1739606084655_1739606082614_Pnb_Topiwala_Sudhir_B_Trivedi.pdf",
    "id": "624101",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Sat Feb 15 2025 07:55:09 GMT+0000 (Coordinated Universal Time)"
  }
],
"caseNumber": "014349",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
```

```
{
  "id": "950701",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Sat Feb 15 2025 07:55:09 GMT+0000 (Coordinated Universal Time)"
},
"owners": [
  {
    "name": "Mr. Sudhir Balubhai Trivedi And Mr. Dharmil Sudhir Trivedi",
    "phone": "9322899168",
    "ownershipShare": "",
    "email": "",
    "id": "112702"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b0712adc5b7cb7d2fa566d",
    "name": "externalImg_1739616515960_1739616497544_image_0.jpeg",
    "path": "cases/67b0485dc594f0b7b654ea1d/externalImg_1739616515960_1739616497544_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b0712adc5b7cb7d2fa566e",
    "name": "externalImg_1739616516744_1739616497544_image_1.jpeg",
    "path": "cases/67b0485dc594f0b7b654ea1d/externalImg_1739616516744_1739616497544_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
```

```
    "_id": "67b0712adc5b7cb7d2fa566f",
    "name": "externallmg_1739616517894_1739616497544_image_2.jpeg",
    "path": "cases/67b0485dc594f0b7b654ea1d/
externallmg_1739616517894_1739616497544_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b0712adc5b7cb7d2fa5670",
    "name": "externallmg_1739616520588_1739616497544_image_3.jpeg",
    "path": "cases/67b0485dc594f0b7b654ea1d/
externallmg_1739616520588_1739616497544_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b0712adc5b7cb7d2fa5671",
    "name": "externallmg_1739616523771_1739616497544_image_4.jpeg",
    "path": "cases/67b0485dc594f0b7b654ea1d/
externallmg_1739616523771_1739616497544_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b0712adc5b7cb7d2fa5672",
    "name": "externallmg_1739616526619_1739616497544_image_5.jpeg",
    "path": "cases/67b0485dc594f0b7b654ea1d/
externallmg_1739616526619_1739616497544_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b0712adc5b7cb7d2fa5673",
    "name": "externallmg_1739616529994_1739616497544_image_6.jpeg",
    "path": "cases/67b0485dc594f0b7b654ea1d/
externallmg_1739616529994_1739616497544_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b0712adc5b7cb7d2fa5674",
```

```
    "name": "externallmg_1739616533220_1739616497544_image_7.jpeg",
    "path": "cases/67b0485dc594f0b7b654ea1d/
externallmg_1739616533220_1739616497544_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b0712adc5b7cb7d2fa5675",
    "name": "externallmg_1739616536381_1739616497544_image_8.jpeg",
    "path": "cases/67b0485dc594f0b7b654ea1d/
externallmg_1739616536381_1739616497544_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b0712adc5b7cb7d2fa5676",
    "name": "externallmg_1739616539012_1739616497544_image_9.jpeg",
    "path": "cases/67b0485dc594f0b7b654ea1d/
externallmg_1739616539012_1739616497544_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b0712adc5b7cb7d2fa5677",
    "name": "externallmg_1739616539989_1739616497544_image_10.jpeg",
    "path": "cases/67b0485dc594f0b7b654ea1d/
externallmg_1739616539989_1739616497544_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b0712adc5b7cb7d2fa5678",
    "name": "externallmg_1739616541000_1739616497544_image_11.jpeg",
    "path": "cases/67b0485dc594f0b7b654ea1d/
externallmg_1739616541000_1739616497544_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b0712adc5b7cb7d2fa5679",
    "name": "externallmg_1739616541805_1739616497544_image_12.jpeg",
```

```
    "path": "cases/67b0485dc594f0b7b654ea1d/
externallmg_1739616541805_1739616497544_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b0712adc5b7cb7d2fa567a",
    "name": "externallmg_1739616541953_1739616497544_image_13.jpeg",
    "path": "cases/67b0485dc594f0b7b654ea1d/
externallmg_1739616541953_1739616497544_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b0712adc5b7cb7d2fa567b",
    "name": "externallmg_1739616543784_1739616497544_image_14.jpeg",
    "path": "cases/67b0485dc594f0b7b654ea1d/
externallmg_1739616543784_1739616497544_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b0712adc5b7cb7d2fa567c",
    "name": "externallmg_1739616546051_1739616497544_image_15.jpeg",
    "path": "cases/67b0485dc594f0b7b654ea1d/
externallmg_1739616546051_1739616497544_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b0712adc5b7cb7d2fa567d",
    "name": "externallmg_1739616547538_1739616497544_image_16.jpeg",
    "path": "cases/67b0485dc594f0b7b654ea1d/
externallmg_1739616547538_1739616497544_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b0712adc5b7cb7d2fa567e",
    "name": "externallmg_1739616548797_1739616497544_image_17.jpeg",
    "path": "cases/67b0485dc594f0b7b654ea1d/
externallmg_1739616548797_1739616497544_image_17.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67b0712adc5b7cb7d2fa567f",
  "name": "externallmg_1739616549955_1739616497544_image_18.jpeg",
  "path": "cases/67b0485dc594f0b7b654ea1d/
externallmg_1739616549955_1739616497544_image_18.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67b0712adc5b7cb7d2fa5680",
  "name": "externallmg_1739616551421_1739616497544_image_19.jpeg",
  "path": "cases/67b0485dc594f0b7b654ea1d/
externallmg_1739616551421_1739616497544_image_19.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b0712ddc5b7cb7d2fa569e",
  "name": "externallmg_1739616542575_1739616529294_image_0.jpeg",
  "path": "cases/67b0485dc594f0b7b654ea1d/
externallmg_1739616542575_1739616529294_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b0712ddc5b7cb7d2fa569f",
  "name": "externallmg_1739616544274_1739616529294_image_1.jpeg",
  "path": "cases/67b0485dc594f0b7b654ea1d/
externallmg_1739616544274_1739616529294_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b0712ddc5b7cb7d2fa56a0",
  "name": "externallmg_1739616546239_1739616529294_image_2.jpeg",
  "path": "cases/67b0485dc594f0b7b654ea1d/
externallmg_1739616546239_1739616529294_image_2.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67b0712ddc5b7cb7d2fa56a1",
      "name": "externallmg_1739616547247_1739616529294_image_3.jpeg",
      "path": "cases/67b0485dc594f0b7b654ea1d/
externallmg_1739616547247_1739616529294_image_3.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67b0712ddc5b7cb7d2fa56a2",
      "name": "externallmg_1739616548664_1739616529294_image_4.jpeg",
      "path": "cases/67b0485dc594f0b7b654ea1d/
externallmg_1739616548664_1739616529294_image_4.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67b0712ddc5b7cb7d2fa56a3",
      "name": "externallmg_1739616551017_1739616529294_image_5.jpeg",
      "path": "cases/67b0485dc594f0b7b654ea1d/
externallmg_1739616551017_1739616529294_image_5.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67b0712ddc5b7cb7d2fa56a4",
      "name": "externallmg_1739616551943_1739616529294_image_6.jpeg",
      "path": "cases/67b0485dc594f0b7b654ea1d/
externallmg_1739616551943_1739616529294_image_6.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67b0712ddc5b7cb7d2fa56a5",
      "name": "externallmg_1739616552980_1739616529294_image_7.jpeg",
      "path": "cases/67b0485dc594f0b7b654ea1d/
externallmg_1739616552980_1739616529294_image_7.jpeg",
      "orientation": "portrait"
    },
  ],
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b0712ddc5b7cb7d2fa56a6",
  "name": "externalImg_1739616554138_1739616529294_image_8.jpeg",
  "path": "cases/67b0485dc594f0b7b654ea1d/
externalImg_1739616554138_1739616529294_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b0712ddc5b7cb7d2fa56a7",
  "name": "externalImg_1739616555384_1739616529294_image_9.jpeg",
  "path": "cases/67b0485dc594f0b7b654ea1d/
externalImg_1739616555384_1739616529294_image_9.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60f9147bf3dd69653a591e8c",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Vinita",
      "lastName": "Surve",
      "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "67b0684ae1b0fbb7b7ec5199",
    "note": "pending value confirmation \n",
    "taskId": "67b05813e1b0fbb7b7ec3550",
    "createdAt": "2025-02-15T10:11:22.751Z"
  },
  {
    "createdBy": {
      "_id": "60f9147bf3dd69653a591e8c",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Vinita",
```



```

    "lastName": "Surve",
    "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "67b06d5adc5b7cb7d2fa5118",
  "note": "Pending visit\n",
  "taskId": "67b05813e1b0fbb7b7ec3550",
  "createdAt": "2025-02-15T10:32:58.789Z"
}
],
"createdAt": "2025-02-15T07:55:09.740Z",
"updatedAt": "2025-02-15T10:49:17.095Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "62691c48afd7d55eddecfda3",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 101, 1st Floor, Wing - C, Malad Gautam Nagar
CHSL, Datta Mandir Road, Malad East, Mumbai, 400097",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Mr. Sudhir Balubhai Trivedi And Mr. Dharmil Sudhir Trivedi",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"reald": "",
"siteVisitContactNo": "9322899168"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			