

```
{
  "typeOfReport": {
    "value": "Row_House",
    "label": "Row House"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Banking_Purpose",
    "label": "Banking Purpose"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "67b079b3c594f0b7b6552a61"
    },
    "firstName": "Ugale ",
    "type": "CREDITOFFICER",
    "_id": "67b079f1c594f0b7b6552a69",
    "email": "bo3762@pnb.co.in",
    "lastName": "Sir",
    "mobileNo": "2532580753",
    "workMobileNo": "2752221395"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "3000"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Madhusa Elite, Vrundavan Nagar, Jatra - Nandur Naka Link
Road, Adgaon, Nashik - 422003",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1812",
  "type": "BANK",
  "name": "Punjab National Bank",
  "displayName": "Punjab National Bank",
  "initial": "PNB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "67b079b3c594f0b7b6552a61",
  "name": "Sharanpur Road Branch",
  "branchCode": "376200",
  "mobileNo": "1800 180 2222",
  "alternateMobileNo": "02752221395",
  "email": "bo3762@pnb.co.in",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Suyojit heights, Sharanpur Rd, opp. Nashik Muncipal Colony, Racca
Colony, Pandit Colony, Nashik, Maharashtra 422005"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "64b79847ad54e843ebada54d",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "647ed1960ab64c23c9fcf71d",
```

```
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63f9f4adce84bf289ba9956e",
"role": "FRONTDESK + ENGINEER",
"firstName": "Swapnnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"designation": "",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1719821841098_image.jpg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
"designation": "",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
```

```
"designation": "",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "64cde526dc9f3034f3fefa49",
"role": "FRONTDESK",
"firstName": "Rashmi",
"email": "rashmijadhav14feb@gmail.com",
"lastName": "Jadhav",
"mobileNo": "7738144625",
"designation": "Back Office Coordination",
"shortName": "RJ",
"workWithDocumentMaker": "60eeaeddf3dd69653a581316",
"profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "[N]C.C.I.T/I -14/52/2008-09",
"label": "Wealth Tax"
}
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
{
"title": {
"value": "Wealth_Tax",
"label": "Wealth Tax"
}
},
"_id": "6084131a13f01f158c6ea1f4",
"number": "[N]C.C.I.T/I -14/52/2008-09"
```

```
    }
  ],
  "shortName": "SBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6084131a13f01f158c6ea1f3\
\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.958861",
  "longitude": "73.770639"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
```

```
"status": true,
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Nashik",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
```

```
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "Plot No. 63 to 68/ 1 to 7",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Saikamal Row Houses ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
```

```
"name": "Landmark",
"key": "landmark",
"value": "Near Karmaa Residency, Krushnai Nagar, Sonawane Marg",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "No. 899/1+ 899/ 2/ 1 +899/ 3",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
}
```



```
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "Row House No. 05",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
```

```
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code – 422 009",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
}
},
"apfDetails": {
```

```
"buildings": [],
"compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
"label": "RCC Plinth",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
}
```

```
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
```

```
"max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
```

```
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67b07cefc594f0b7b6552de5",
"ownerName": "Shri. Deepak Rajendra Patil & Sau. Mohini Deepak Patil",
"ownerPhoneNo": "9175868309",
"fullAddress": "Residential Row House No. Row House No. 05, Basement Floor,
Saikamal Row Houses , Near Karmaa Residency, Krushnai Nagar, Sonawane Marg,
Plot No. Plot No. 63 to 68/ 1 to 7, New/Current Survey No. No. 899/1+ 899/ 2/ 1 +899/
3, Village - Nashik, Taluka - Nashik, District - Nashik, Nashik, PIN Code – 422 009",
```

```
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1739619507569_Adoobe_Scan_Nov_06_2024_3.pdf",
    "path": "cases/67b07cefc594f0b7b6552de5/
document_1739619507569_Adoobe_Scan_Nov_06_2024_3.pdf",
    "id": "476383",
    "uploadedBy": "647ed1960ab64c23c9fcf71d",
    "createdAt": "Sat Feb 15 2025 11:39:27 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1739619527232_Adoobe_Scan_Nov_13_2024_3.pdf",
    "path": "cases/67b07cefc594f0b7b6552de5/
document_1739619527232_Adoobe_Scan_Nov_13_2024_3.pdf",
    "id": "627650",
    "uploadedBy": "647ed1960ab64c23c9fcf71d",
    "createdAt": "Sat Feb 15 2025 11:39:27 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1739619542020_Adoobe_Scan_Nov_13_2024_4_1.pdf",
    "path": "cases/67b07cefc594f0b7b6552de5/
document_1739619542020_Adoobe_Scan_Nov_13_2024_4_1.pdf",
    "id": "849016",
    "uploadedBy": "647ed1960ab64c23c9fcf71d",
    "createdAt": "Sat Feb 15 2025 11:39:27 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
```

```
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1739619550231_Adobe_Scan_Nov_13_2024_4.pdf",
  "path": "cases/67b07cefc594f0b7b6552de5/
document_1739619550231_Adobe_Scan_Nov_13_2024_4.pdf",
  "id": "337794",
  "uploadedBy": "647ed1960ab64c23c9fcf71d",
  "createdAt": "Sat Feb 15 2025 11:39:27 GMT+0000 (Coordinated Universal Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "014359",
"createdBy": "647ed1960ab64c23c9fcf71d",
"caseHistory": [
  {
    "id": "848907",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Feb 15 2025 11:39:27 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Shri. Deepak Rajendra Patil & Sau. Mohini Deepak Patil",
    "phone": "9175868309",
    "ownershipShare": "",
    "email": "",
    "id": "250068"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b07d3cc594f0b7b6552f2a",
    "name":
"externallmg_1739619639408_WhatsApp_Image_20241112_at_12541_PM_1.jpeg",
    "path": "cases/67b07cefc594f0b7b6552de5/
externallmg_1739619639408_WhatsApp_Image_20241112_at_12541_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b07d3cc594f0b7b6552f2b",
    "name":
"externallmg_1739619639681_WhatsApp_Image_20241112_at_12541_PM.jpeg",
    "path": "cases/67b07cefc594f0b7b6552de5/
externallmg_1739619639681_WhatsApp_Image_20241112_at_12541_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b07d3cc594f0b7b6552f2c",
    "name":
"externallmg_1739619639978_WhatsApp_Image_20241112_at_12542_PM_1.jpeg",
    "path": "cases/67b07cefc594f0b7b6552de5/
externallmg_1739619639978_WhatsApp_Image_20241112_at_12542_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b07d3cc594f0b7b6552f2d",
    "name":
"externallmg_1739619640170_WhatsApp_Image_20241112_at_12542_PM_2.jpeg",
    "path": "cases/67b07cefc594f0b7b6552de5/
externallmg_1739619640170_WhatsApp_Image_20241112_at_12542_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b07d3cc594f0b7b6552f2e",
    "name":
"externallmg_1739619640357_WhatsApp_Image_20241112_at_12542_PM.jpeg",
    "path": "cases/67b07cefc594f0b7b6552de5/
externallmg_1739619640357_WhatsApp_Image_20241112_at_12542_PM.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b07d3cc594f0b7b6552f2f",
    "name":
"externallmg_1739619640590_WhatsApp_Image_20241112_at_12543_PM_1.jpeg",
    "path": "cases/67b07cefc594f0b7b6552de5/
externallmg_1739619640590_WhatsApp_Image_20241112_at_12543_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b07d3cc594f0b7b6552f30",
    "name":
"externallmg_1739619640782_WhatsApp_Image_20241112_at_12543_PM.jpeg",
    "path": "cases/67b07cefc594f0b7b6552de5/
externallmg_1739619640782_WhatsApp_Image_20241112_at_12543_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b07d3cc594f0b7b6552f31",
    "name":
"externallmg_1739619641012_WhatsApp_Image_20241112_at_12544_PM_1.jpeg",
    "path": "cases/67b07cefc594f0b7b6552de5/
externallmg_1739619641012_WhatsApp_Image_20241112_at_12544_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b07d3cc594f0b7b6552f32",
    "name":
"externallmg_1739619641305_WhatsApp_Image_20241112_at_12544_PM.jpeg",
    "path": "cases/67b07cefc594f0b7b6552de5/
externallmg_1739619641305_WhatsApp_Image_20241112_at_12544_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b07d3cc594f0b7b6552f33",
```

```
"name":  
"externallmg_1739619641603_WhatsApp_Image_20241112_at_12545_PM_1.jpeg",  
  "path": "cases/67b07cefc594f0b7b6552de5/  
externallmg_1739619641603_WhatsApp_Image_20241112_at_12545_PM_1.jpeg",  
  "orientation": "landscape"  
},  
{  
  "type": "EXTERNAL_IMAGES",  
  "status": false,  
  "_id": "67b07d3cc594f0b7b6552f34",  
  "name":  
"externallmg_1739619642085_WhatsApp_Image_20241112_at_12545_PM.jpeg",  
  "path": "cases/67b07cefc594f0b7b6552de5/  
externallmg_1739619642085_WhatsApp_Image_20241112_at_12545_PM.jpeg",  
  "orientation": "landscape"  
},  
{  
  "type": "EXTERNAL_IMAGES",  
  "status": false,  
  "_id": "67b07d3cc594f0b7b6552f35",  
  "name":  
"externallmg_1739619642436_WhatsApp_Image_20241112_at_12546_PM_1.jpeg",  
  "path": "cases/67b07cefc594f0b7b6552de5/  
externallmg_1739619642436_WhatsApp_Image_20241112_at_12546_PM_1.jpeg",  
  "orientation": "landscape"  
},  
{  
  "type": "EXTERNAL_IMAGES",  
  "status": false,  
  "_id": "67b07d3cc594f0b7b6552f36",  
  "name":  
"externallmg_1739619642690_WhatsApp_Image_20241112_at_12546_PM.jpeg",  
  "path": "cases/67b07cefc594f0b7b6552de5/  
externallmg_1739619642690_WhatsApp_Image_20241112_at_12546_PM.jpeg",  
  "orientation": "landscape"  
},  
{  
  "type": "EXTERNAL_IMAGES",  
  "status": false,  
  "_id": "67b07d3cc594f0b7b6552f37",  
  "name":  
"externallmg_1739619642894_WhatsApp_Image_20241112_at_12547_PM_1.jpeg",  
  "path": "cases/67b07cefc594f0b7b6552de5/  
externallmg_1739619642894_WhatsApp_Image_20241112_at_12547_PM_1.jpeg",  
  "orientation": "landscape"  
},
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b07d3cc594f0b7b6552f38",
  "name":
"externallmg_1739619643264_WhatsApp_Image_20241112_at_12547_PM.jpeg",
  "path": "cases/67b07cefc594f0b7b6552de5/
externallmg_1739619643264_WhatsApp_Image_20241112_at_12547_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b07d3cc594f0b7b6552f39",
  "name":
"externallmg_1739619643518_WhatsApp_Image_20241112_at_12548_PM_1.jpeg",
  "path": "cases/67b07cefc594f0b7b6552de5/
externallmg_1739619643518_WhatsApp_Image_20241112_at_12548_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b07d3cc594f0b7b6552f3a",
  "name":
"externallmg_1739619643827_WhatsApp_Image_20241112_at_12548_PM.jpeg",
  "path": "cases/67b07cefc594f0b7b6552de5/
externallmg_1739619643827_WhatsApp_Image_20241112_at_12548_PM.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-02-15T11:39:27.884Z",
"updatedAt": "2025-02-15T11:40:44.395Z",
"__v": 0,
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "647ed1960ab64c23c9fcf71d",
"contactPersonName": "Shri. Deepak Rajendra Patil & Sau. Mohini Deepak Patil",
"email": "",
"isExternal": "false",
"isUrgent": "false",
```

"ownershipShare": "",  
"proposePurchaserName": "",  
"purchaseValueAsPerDocument": "",  
"relationWithOwner": "self",  
"rerald": "",  
"siteVisitContactNo": "9175868309"

}

**Name**

**Length**

**Width**

**Total**

---

Composition :

---

Other

Composition :

---