

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "677908cfa5477d50e7dcfbaf"
    },
    "firstName": "Abhishek",
    "type": "CREDITOFFICER",
    "_id": "677908f182ea0d50e10160c8",
    "email": "cb7065@canarabank.com",
    "lastName": "Arora",
    "mobileNo": "",
    "workMobileNo": "7718873563"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Abhishek",
    "expectedFees": 2500,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "676544371f06b62faf373ec8",
  "type": "BANK",
  "name": "Canara Bank",
  "displayName": "Canara Bank",
  "initial": "CNB"
},
"branch": {
  "_id": "677908cfa5477d50e7dcfbaf",
  "name": "Retail Asset Hub, Vasai",
  "branchCode": "7065",
  "mobileNo": "0000000000",
  "alternateMobileNo": "",
  "email": "cb7065@canarabank.com",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "God's Gift Bunglow, Mary Villa Stuo, Stela, Manickpur, Vasai-401202"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "6765457131b0132fc5831fcc",
  "zoneName": "MUMBAI"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "659ccce98f39506e83489828",
    "role": "DELIVERYPERSON",
    "firstName": "Amit",
    "email": "amitsalvi2909@gmail.com",
```

```
"lastName": "Salvi",
"mobileNo": "7499830659",
"shortName": "Amit",
"workWithDocumentMaker": "",
"profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62720a36afd7d55eddedc4a7",
  "role": "SITEENGINEER",
  "firstName": "Anwar",
  "email": "anwar21786@gmail.com",
  "lastName": "Shaikh",
  "mobileNo": "8552884500",
  "designation": "",
  "shortName": "AS",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62720a36afd7d55eddedc4a7/
profilePhoto_1668059819446_anwar_2.jpeg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        }
      }
    ],
    "_id": "60af80072ffdf65bcd658651",
```

```
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.444882425400305",
  "longitude": "72.80261184437036"
},
"geo": {
  "type": "Point",
```

```
"coordinates": [
  72.80261184437036,
  19.444882425400305
],
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "18/02/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Bolinj",
    "label": true
  },
  "floorNo": {
```

```
"status": true,
"name": "Floor No",
"key": "floorNo",
"value": "15",
"label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "11",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Virar",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
```

```
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Mhada Bolinj",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "D",
  "label": true
},
"projectName": {
  "status": false,
```

```
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1502",
  "label": false
}
```



```
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
```

```
"key": "postalCode",
"value": "",
"label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Virar West",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
}
```

```
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
```



```
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67b443b9c594f0b7b6563eec",
"ownerName": "MR GURAV ASHOK SHANKAR / MRS GURAV AKSHATA ASHOK",
"ownerPhoneNo": "9970235467",
"appAddress": "FLAT NO 1502 BLDG NO 11 D 15 SCHEME NO 274 MHADA
BOLINJ VIRAR ",
"remark": "Urgent visit tommorrow soft copy required",
"documents": [
  {
    "documentType": {
      "label": "MHADA Allotment Letter",
      "value": "60ae1267aa6d152c1801b37e"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67b443b9c594f0b7b6563eec/
document_1739866977521_1739866975144_ashok_shankar_gurav0462_1.pdf",
    "fileName":
"document_1739866977521_1739866975144_ashok_shankar_gurav0462_1.pdf",
    "id": "569839",
    "uploadedBy": "659ccce98f39506e83489828",
    "createdAt": "Tue Feb 18 2025 08:24:25 GMT+0000 (Coordinated Universal Time)"
```

```
    },
    {
      "documentType": {
        "label": "Other",
        "value": "60ae124eaa6d152c1801b30b"
      },
      "isHardCopy": false,
      "displayStatus": false,
      "path": "cases/67b443b9c594f0b7b6563eec/
document_1739867052987_1739867050655_Lot_3_Recipte_1.pdf",
      "fileName": "document_1739867052987_1739867050655_Lot_3_Recipte_1.pdf",
      "id": "312827",
      "uploadedBy": "659ccce98f39506e83489828",
      "createdAt": "Tue Feb 18 2025 08:24:25 GMT+0000 (Coordinated Universal Time)"
    }
  ],
  "caseNumber": "014398",
  "createdBy": "659ccce98f39506e83489828",
  "caseHistory": [
    {
      "id": "284271",
      "title": "Create Lead",
      "description": "Create Lead",
      "datetime": "Tue Feb 18 2025 08:24:25 GMT+0000 (Coordinated Universal Time)"
    }
  ],
  "owners": [
    {
      "name": "MR GURAV ASHOK SHANKAR / MRS GURAV AKSHATA ASHOK",
      "phone": "9970235467",
      "ownershipShare": "",
      "email": "",
      "id": "597175"
    }
  ],
  "proposePurchasers": [],
  "siteInspection": [],
  "composition": [],
  "otherComposition": [],
  "externalReport": [],
  "documentPerArea": [],
  "images": [],
  "indicatorArr": [],
  "externalImages": [
    {
      "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67b472b0e1b0fbb7b7ee2b24",
  "name": "externalImg_1739879087804_WhatsApp_Image_20250218_at_162450_740d919c.jpg",
  "path": "cases/67b443b9c594f0b7b6563eec/externalImg_1739879087804_WhatsApp_Image_20250218_at_162450_740d919c.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b472b0e1b0fbb7b7ee2b25",
  "name": "externalImg_1739879087850_IMG20250218WA0104.jpg",
  "path": "cases/67b443b9c594f0b7b6563eec/externalImg_1739879087850_IMG20250218WA0104.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b472b0e1b0fbb7b7ee2b26",
  "name": "externalImg_1739879087854_IMG20250218WA0103.jpg",
  "path": "cases/67b443b9c594f0b7b6563eec/externalImg_1739879087854_IMG20250218WA0103.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b472b0e1b0fbb7b7ee2b27",
  "name": "externalImg_1739879087892_IMG20250218WA0101.jpg",
  "path": "cases/67b443b9c594f0b7b6563eec/externalImg_1739879087892_IMG20250218WA0101.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b472bbdc5b7cb7d2fbc070",
  "name": "externalImg_1739879098824_IMG20250218WA0102.jpg",
  "path": "cases/67b443b9c594f0b7b6563eec/externalImg_1739879098824_IMG20250218WA0102.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67b472bbdc5b7cb7d2fbc071",
  "name": "externalimg_1739879098827_IMG20250218WA0099.jpg",
  "path": "cases/67b443b9c594f0b7b6563eec/
externalimg_1739879098827_IMG20250218WA0099.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b472bbdc5b7cb7d2fbc072",
  "name": "externalimg_1739879098832_IMG20250218WA0100.jpg",
  "path": "cases/67b443b9c594f0b7b6563eec/
externalimg_1739879098832_IMG20250218WA0100.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b472bbdc5b7cb7d2fbc073",
  "name": "externalimg_1739879098854_IMG20250218WA0098.jpg",
  "path": "cases/67b443b9c594f0b7b6563eec/
externalimg_1739879098854_IMG20250218WA0098.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b472bbdc5b7cb7d2fbc074",
  "name": "externalimg_1739879098859_IMG20250218WA0097.jpg",
  "path": "cases/67b443b9c594f0b7b6563eec/
externalimg_1739879098859_IMG20250218WA0097.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b472bbdc5b7cb7d2fbc075",
  "name": "externalimg_1739879098891_IMG20250218WA0095.jpg",
  "path": "cases/67b443b9c594f0b7b6563eec/
externalimg_1739879098891_IMG20250218WA0095.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "67b472bbdc5b7cb7d2fbc076",
    "name": "externalimg_1739879098902_IMG20250218WA0096.jpg",
    "path": "cases/67b443b9c594f0b7b6563eec/
externalimg_1739879098902_IMG20250218WA0096.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b472bbdc5b7cb7d2fbc077",
    "name": "externalimg_1739879098926_IMG20250218WA0093.jpg",
    "path": "cases/67b443b9c594f0b7b6563eec/
externalimg_1739879098926_IMG20250218WA0093.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b472bbdc5b7cb7d2fbc078",
    "name": "externalimg_1739879098935_IMG20250218WA0094.jpg",
    "path": "cases/67b443b9c594f0b7b6563eec/
externalimg_1739879098935_IMG20250218WA0094.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b472bbdc5b7cb7d2fbc079",
    "name": "externalimg_1739879098952_IMG20250218WA0090.jpg",
    "path": "cases/67b443b9c594f0b7b6563eec/
externalimg_1739879098952_IMG20250218WA0090.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b472bbdc5b7cb7d2fbc07a",
    "name": "externalimg_1739879098954_IMG20250218WA0091.jpg",
    "path": "cases/67b443b9c594f0b7b6563eec/
externalimg_1739879098954_IMG20250218WA0091.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b472bbdc5b7cb7d2fbc07b",
```

```
    "name": "externalImg_1739879098973_IMG20250218WA0092.jpg",
    "path": "cases/67b443b9c594f0b7b6563eec/
externalImg_1739879098973_IMG20250218WA0092.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b472bbdc5b7cb7d2fbc07c",
    "name": "externalImg_1739879098976_IMG20250218WA0089.jpg",
    "path": "cases/67b443b9c594f0b7b6563eec/
externalImg_1739879098976_IMG20250218WA0089.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b472bbdc5b7cb7d2fbc07d",
    "name": "externalImg_1739879099006_IMG20250218WA0087.jpg",
    "path": "cases/67b443b9c594f0b7b6563eec/
externalImg_1739879099006_IMG20250218WA0087.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b472bbdc5b7cb7d2fbc07e",
    "name": "externalImg_1739879099020_IMG20250218WA0088.jpg",
    "path": "cases/67b443b9c594f0b7b6563eec/
externalImg_1739879099020_IMG20250218WA0088.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b472bbdc5b7cb7d2fbc07f",
    "name": "externalImg_1739879099024_IMG20250218WA0086.jpg",
    "path": "cases/67b443b9c594f0b7b6563eec/
externalImg_1739879099024_IMG20250218WA0086.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b472bbdc5b7cb7d2fbc080",
    "name": "externalImg_1739879099055_IMG20250218WA0085.jpg",
```

```
    "path": "cases/67b443b9c594f0b7b6563eec/
externalImg_1739879099055_IMG20250218WA0085.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b472bbdc5b7cb7d2fbc081",
    "name": "externalImg_1739879099071_IMG20250218WA0084.jpg",
    "path": "cases/67b443b9c594f0b7b6563eec/
externalImg_1739879099071_IMG20250218WA0084.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b472bbdc5b7cb7d2fbc082",
    "name": "externalImg_1739879099073_IMG20250218WA0083.jpg",
    "path": "cases/67b443b9c594f0b7b6563eec/
externalImg_1739879099073_IMG20250218WA0083.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-02-18T08:24:25.730Z",
"updatedAt": "2025-02-18T11:44:59.396Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 1502, 15th Floor, Building No 11, Wing - D, Mhada
Bolinj, Village - Bolinj, Virar West, Virar",
"updatedBy": "6006d4ce5080a310ac1fdfc2",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "MR GURAV ASHOK SHANKAR / MRS GURAV AKSHATA
ASHOK",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": ""
```

```
"proposePurchaserName": "",  
"purchaseValueAsPerDocument": "",  
"relationWithOwner": "self",  
"rerald": "",  
"siteVisitContactNo": "9970235467"
```

}

Name

Length

Width

Total

Composition :

Other

Composition :
