

```
{
  "typeOfReport": {
    "value": "Row_House",
    "label": "Row House"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "67c2f33d80561479e1f4b24f"
    },
    "firstName": "Amit Kumar",
    "type": "CREDITOFFICER",
    "_id": "67c2f38380561479e1f4b310",
    "email": "aksrivastava1@unionbankofindia.bank",
    "lastName": "Srivastava",
    "mobileNo": "",
    "workMobileNo": "8400608488"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6450f43cba18c8062aad0215",
  "name": "Indore",
  "shortName": "Indore",
  "email": "indore@vastukala.org",
  "address": "106, 1st Floor, Gold Star Tower, 576, M G Road, Opp T1 Mall,
Indore-452001, Madhya Pradesh India",
  "city": "Indore"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "67c2f33d80561479e1f4b24f",
  "name": "UMFB Pithampur",
  "branchCode": "0590410",
  "mobileNo": "0000000000",
  "alternateMobileNo": "",
  "email": "0590410@unionbankofindia.bank",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "House No 33, Ward No 14, Preeti Nagar Colony, Pithampur, T
Pithampur, Dist Dhar M P"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "6437ee3a8989760c1fb68468",
  "zoneName": "Indore Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
```

```
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "6006d4ce5080a310ac1fdcf2",
"role": "ADMIN",
"firstName": "Jagdish ",
"email": "jagdish.bhatt@vastukala.org",
"lastName": "Bhatt",
"mobileNo": "8425864014",
"designation": "",
"shortName": "JB",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\\
\\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
"firstName": "Binumon",
"email": "binu@vastukala.org",
"lastName": "Moozhickal",
"mobileNo": "9930252906",
"designation": "Back Office Team Leader",
"shortName": "BS",
"workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
"profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbc0c819dbff58c0f.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60f91b6f344e052188ffd1fc",
"role": "MAKER",
"firstName": "Jayaraja",
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
"mobileNo": "9867664219",
```

```
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
}
```

```
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "22.763209911699004",
  "longitude": "75.91196566836405"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
}
```

```
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Pipliyakumar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
    "value": "",
    "label": true
  },
  "city": {
    "status": true,
```

```
"name": "City",
"key": "city",
"value": "Indore",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "5",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "MR-IV Colony",
  "label": false
}
```

```
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Mahalaxmi Nagar",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
```



```
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
}
```

```
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "452010",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    }
  }
}
```

```
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
}
```

```
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": []
}
```

```
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
```



```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
```

```
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67c5a0ac1b4369146f2ebda6",
"ownerName": "Smt. Gyandevi W/o. Shri Mahendra Sharma & Shri Deepak S/o. Shri
Mahendra Sharma",
"ownerPhoneNo": "9893522569",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9893522569",
"contactPersonName": "Smt. Gyandevi W/o. Shri Mahendra Sharma & Shri Deepak S/
o. Shri Mahendra Sharma",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Smt. Gyandevi W/o. Shri Mahendra Sharma & Shri Deepak S/o. Shri
Mahendra Sharma",
    "phone": "9893522569",
    "ownershipShare": "",
    "email": "",
    "id": "714872"
  }
],
"caseReferredBy": "5ffe92d27737ca4d986b6453",
"relationWithOwner": "self",
"fullAddress": "Residential Row House No. Ground Floor, Plot No. 5, MR-IV Colony,
Mahalaxmi Nagar, Village - Pipliyakumar, Indore, 452010, State - Madhya Pradesh,
India",
"remark": "",
"documents": [],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": "",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"reald": "",
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "014654",
"createdBy": "6006d4ce5080a310ac1fdfc2",
"caseHistory": [
  {
    "id": "585653",
    "title": "Create Case",
    "description": "Create Case",
```

```
    "datetime": "Mon Mar 03 2025 12:29:32 GMT+0000 (Coordinated Universal Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c699e9a8da631a7e9026a3",
    "name":
"externallmg_1741068776405_WhatsApp_Image_20250224_at_113431_AM_1.jpeg",
    "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068776405_WhatsApp_Image_20250224_at_113431_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c699e9a8da631a7e9026a4",
    "name":
"externallmg_1741068776436_WhatsApp_Image_20250224_at_113431_AM_2.jpeg",
    "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068776436_WhatsApp_Image_20250224_at_113431_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c699e9a8da631a7e9026a5",
    "name":
"externallmg_1741068776474_WhatsApp_Image_20250224_at_113431_AM.jpeg",
    "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068776474_WhatsApp_Image_20250224_at_113431_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c699e9a8da631a7e9026a6",
```

```
"name":
"externallmg_1741068776488_WhatsApp_Image_20250224_at_113432_AM_1.jpeg",
  "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068776488_WhatsApp_Image_20250224_at_113432_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c699e9a8da631a7e9026a7",
  "name":
"externallmg_1741068776581_WhatsApp_Image_20250224_at_113432_AM.jpeg",
  "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068776581_WhatsApp_Image_20250224_at_113432_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c699e9a8da631a7e9026a8",
  "name":
"externallmg_1741068776623_WhatsApp_Image_20250224_at_113433_AM_1.jpeg",
  "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068776623_WhatsApp_Image_20250224_at_113433_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c699e9a8da631a7e9026a9",
  "name":
"externallmg_1741068776669_WhatsApp_Image_20250224_at_113433_AM.jpeg",
  "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068776669_WhatsApp_Image_20250224_at_113433_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c699e9a8da631a7e9026aa",
  "name":
"externallmg_1741068776674_WhatsApp_Image_20250224_at_113434_AM_1.jpeg",
  "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068776674_WhatsApp_Image_20250224_at_113434_AM_1.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c699e9a8da631a7e9026ab",
  "name":
"externallmg_1741068776733_WhatsApp_Image_20250224_at_113434_AM.jpeg",
  "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068776733_WhatsApp_Image_20250224_at_113434_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c699e9a8da631a7e9026ac",
  "name":
"externallmg_1741068776738_WhatsApp_Image_20250224_at_113435_AM_1.jpeg",
  "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068776738_WhatsApp_Image_20250224_at_113435_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c699e9a8da631a7e9026ad",
  "name":
"externallmg_1741068776808_WhatsApp_Image_20250224_at_113435_AM_2.jpeg",
  "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068776808_WhatsApp_Image_20250224_at_113435_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c699e9a8da631a7e9026ae",
  "name":
"externallmg_1741068776842_WhatsApp_Image_20250224_at_113435_AM.jpeg",
  "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068776842_WhatsApp_Image_20250224_at_113435_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c699e9a8da631a7e9026af",
  "name":
"externallmg_1741068776889_WhatsApp_Image_20250224_at_113436_AM.jpeg",
```

```
    "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068776889_WhatsApp_Image_20250224_at_113436_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c699e9a8da631a7e9026b0",
    "name":
"externallmg_1741068776919_WhatsApp_Image_20250224_at_115055_AM.jpeg",
    "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068776919_WhatsApp_Image_20250224_at_115055_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c699e9a8da631a7e9026b1",
    "name":
"externallmg_1741068776961_WhatsApp_Image_20250224_at_115056_AM_1.jpeg",
    "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068776961_WhatsApp_Image_20250224_at_115056_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c699e9a8da631a7e9026b2",
    "name":
"externallmg_1741068777024_WhatsApp_Image_20250224_at_115056_AM.jpeg",
    "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068777024_WhatsApp_Image_20250224_at_115056_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c699fad6dff1a7f78f029",
    "name":
"externallmg_1741068794018_WhatsApp_Image_20250224_at_113534_AM.jpeg",
    "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068794018_WhatsApp_Image_20250224_at_113534_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "67c699fad6dfd1a7f78f02a",
    "name":
"externallmg_1741068794025_WhatsApp_Image_20250224_at_113535_AM_1.jpeg",
    "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068794025_WhatsApp_Image_20250224_at_113535_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c699fad6dfd1a7f78f02b",
    "name":
"externallmg_1741068794031_WhatsApp_Image_20250224_at_113535_AM_2.jpeg",
    "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068794031_WhatsApp_Image_20250224_at_113535_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c699fad6dfd1a7f78f02c",
    "name":
"externallmg_1741068794077_WhatsApp_Image_20250224_at_113535_AM.jpeg",
    "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068794077_WhatsApp_Image_20250224_at_113535_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c699fad6dfd1a7f78f02d",
    "name":
"externallmg_1741068794081_WhatsApp_Image_20250224_at_113536_AM_1.jpeg",
    "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068794081_WhatsApp_Image_20250224_at_113536_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c699fad6dfd1a7f78f02e",
    "name":
"externallmg_1741068794133_WhatsApp_Image_20250224_at_113536_AM.jpeg",
    "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068794133_WhatsApp_Image_20250224_at_113536_AM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c699fad6dff1a7f78f02f",
    "name":
"externallmg_1741068794167_WhatsApp_Image_20250224_at_113537_AM_1.jpeg",
    "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068794167_WhatsApp_Image_20250224_at_113537_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c699fad6dff1a7f78f030",
    "name":
"externallmg_1741068794201_WhatsApp_Image_20250224_at_113537_AM.jpeg",
    "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068794201_WhatsApp_Image_20250224_at_113537_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c699fad6dff1a7f78f031",
    "name":
"externallmg_1741068794278_WhatsApp_Image_20250224_at_113538_AM.jpeg",
    "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068794278_WhatsApp_Image_20250224_at_113538_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c69a09f0a44c1ac758215c",
    "name":
"externallmg_1741068808826_WhatsApp_Image_20250224_at_114003_AM.jpeg",
    "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068808826_WhatsApp_Image_20250224_at_114003_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c69a09f0a44c1ac758215d",
```



```
"name":
"externallmg_1741068808853_WhatsApp_Image_20250224_at_114004_AM_1.jpeg",
  "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068808853_WhatsApp_Image_20250224_at_114004_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c69a09f0a44c1ac758215e",
  "name":
"externallmg_1741068808859_WhatsApp_Image_20250224_at_114004_AM.jpeg",
  "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068808859_WhatsApp_Image_20250224_at_114004_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c69a09f0a44c1ac758215f",
  "name":
"externallmg_1741068808918_WhatsApp_Image_20250224_at_114005_AM_1.jpeg",
  "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068808918_WhatsApp_Image_20250224_at_114005_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c69a09f0a44c1ac7582160",
  "name":
"externallmg_1741068808923_WhatsApp_Image_20250224_at_114005_AM.jpeg",
  "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068808923_WhatsApp_Image_20250224_at_114005_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c69a09f0a44c1ac7582161",
  "name":
"externallmg_1741068808976_WhatsApp_Image_20250224_at_114007_AM_1.jpeg",
  "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068808976_WhatsApp_Image_20250224_at_114007_AM_1.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c69a09f0a44c1ac7582162",
  "name":
"externallmg_1741068809003_WhatsApp_Image_20250224_at_114007_AM.jpeg",
  "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068809003_WhatsApp_Image_20250224_at_114007_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c69a09f0a44c1ac7582163",
  "name":
"externallmg_1741068809028_WhatsApp_Image_20250224_at_114008_AM.jpeg",
  "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068809028_WhatsApp_Image_20250224_at_114008_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c69a09f0a44c1ac7582164",
  "name":
"externallmg_1741068809041_WhatsApp_Image_20250224_at_114009_AM.jpeg",
  "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068809041_WhatsApp_Image_20250224_at_114009_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c69a1bf0a44c1ac75821aa",
  "name":
"externallmg_1741068826654_WhatsApp_Image_20250224_at_114748_AM_1.jpeg",
  "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068826654_WhatsApp_Image_20250224_at_114748_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c69a1bf0a44c1ac75821ab",
  "name":
"externallmg_1741068826659_WhatsApp_Image_20250224_at_114748_AM.jpeg",
```

```
    "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068826659_WhatsApp_Image_20250224_at_114748_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c69a1bf0a44c1ac75821ac",
    "name":
"externallmg_1741068826668_WhatsApp_Image_20250224_at_114749_AM_1.jpeg",
    "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068826668_WhatsApp_Image_20250224_at_114749_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c69a1bf0a44c1ac75821ad",
    "name":
"externallmg_1741068826714_WhatsApp_Image_20250224_at_114749_AM.jpeg",
    "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068826714_WhatsApp_Image_20250224_at_114749_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c69a1bf0a44c1ac75821ae",
    "name":
"externallmg_1741068826748_WhatsApp_Image_20250224_at_114750_AM_1.jpeg",
    "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068826748_WhatsApp_Image_20250224_at_114750_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c69a1bf0a44c1ac75821af",
    "name":
"externallmg_1741068826753_WhatsApp_Image_20250224_at_114750_AM.jpeg",
    "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068826753_WhatsApp_Image_20250224_at_114750_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67c69a1bf0a44c1ac75821b0",
  "name":
"externallmg_1741068826789_WhatsApp_Image_20250224_at_114751_AM_1.jpeg",
  "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068826789_WhatsApp_Image_20250224_at_114751_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c69a1bf0a44c1ac75821b1",
  "name":
"externallmg_1741068826794_WhatsApp_Image_20250224_at_114751_AM.jpeg",
  "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068826794_WhatsApp_Image_20250224_at_114751_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c69a1bf0a44c1ac75821b2",
  "name":
"externallmg_1741068826846_WhatsApp_Image_20250224_at_114752_AM_1.jpeg",
  "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068826846_WhatsApp_Image_20250224_at_114752_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c69a1bf0a44c1ac75821b3",
  "name":
"externallmg_1741068826874_WhatsApp_Image_20250224_at_114752_AM_2.jpeg",
  "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068826874_WhatsApp_Image_20250224_at_114752_AM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c69a1bf0a44c1ac75821b4",
  "name":
"externallmg_1741068826906_WhatsApp_Image_20250224_at_114752_AM.jpeg",
  "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068826906_WhatsApp_Image_20250224_at_114752_AM.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c69a1bf0a44c1ac75821b5",
    "name":
"externallmg_1741068826939_WhatsApp_Image_20250224_at_114753_AM.jpeg",
    "path": "cases/67c5a0ac1b4369146f2ebda6/
externallmg_1741068826939_WhatsApp_Image_20250224_at_114753_AM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [
  {
    "originalname": "Gyandevi Sharma.doc",
    "filename": "1741068719056_Gyandevi_Sharma.doc",
    "path": "cases/67c5a0ac1b4369146f2ebda6/
externalDocuments/1741068719056_Gyandevi_Sharma.doc",
    "size": "4875264",
    "documentType": {
      "value": "649998c6cab24d3d1a2cc577",
      "label": "Draft Word Report"
    },
    "createdAt": "Tue Mar 04 2025 06:11:59 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  }
],
"processingDocuments": [
  {
    "originalname": "Ledger Report.pdf",
    "filename": "1741068738905_Ledger_Report.pdf",
    "path": "cases/67c5a0ac1b4369146f2ebda6/
processingDocuments/1741068738905_Ledger_Report.pdf",
    "size": "44227",
    "createdAt": "Tue Mar 04 2025 06:12:20 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "MONIKA AGARWAL.pdf",
    "filename": "1741068738906_MONIKA_AGARWAL.pdf",
    "path": "cases/67c5a0ac1b4369146f2ebda6/
processingDocuments/1741068738906_MONIKA_AGARWAL.pdf",
    "size": "3438345",
    "createdAt": "Tue Mar 04 2025 06:12:20 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  }
]
```

```
  },
  {
    "originalname": "Old report.pdf",
    "filename": "1741068739001_Old_report.pdf",
    "path": "cases/67c5a0ac1b4369146f2ebda6/
processingDocuments/1741068739001_Old_report.pdf",
    "size": "9295146",
    "createdAt": "Tue Mar 04 2025 06:12:20 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Property Tax Receipt.jpeg",
    "filename": "1741068739476_Property_Tax_Receipt.jpeg",
    "path": "cases/67c5a0ac1b4369146f2ebda6/
processingDocuments/1741068739476_Property_Tax_Receipt.jpeg",
    "size": "67631",
    "createdAt": "Tue Mar 04 2025 06:12:20 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Sale Deed - 2010.pdf",
    "filename": "1741068739480_Sale_Deed__2010.pdf",
    "path": "cases/67c5a0ac1b4369146f2ebda6/
processingDocuments/1741068739480_Sale_Deed__2010.pdf",
    "size": "4874329",
    "createdAt": "Tue Mar 04 2025 06:12:20 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Site Details.jpeg",
    "filename": "1741068740372_Site_Details.jpeg",
    "path": "cases/67c5a0ac1b4369146f2ebda6/
processingDocuments/1741068740372_Site_Details.jpeg",
    "size": "79555",
    "createdAt": "Tue Mar 04 2025 06:12:20 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Sketch.pdf",
    "filename": "1741068740790_Sketch.pdf",
    "path": "cases/67c5a0ac1b4369146f2ebda6/
processingDocuments/1741068740790_Sketch.pdf",
    "size": "329964",
    "createdAt": "Tue Mar 04 2025 06:12:20 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
}
```

```
{
  "originalname": "Tax Receipt (1).jpeg",
  "filename": "1741068740796_Tax_Receipt_1.jpeg",
  "path": "cases/67c5a0ac1b4369146f2ebda6/
processingDocuments/1741068740796_Tax_Receipt_1.jpeg",
  "size": "91480",
  "createdAt": "Tue Mar 04 2025 06:12:20 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Tax Receipt (2).jpeg",
  "filename": "1741068740830_Tax_Receipt_2.jpeg",
  "path": "cases/67c5a0ac1b4369146f2ebda6/
processingDocuments/1741068740830_Tax_Receipt_2.jpeg",
  "size": "90928",
  "createdAt": "Tue Mar 04 2025 06:12:20 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Approved Plan.pdf",
  "filename": "1741068753457_Approved_Plan.pdf",
  "path": "cases/67c5a0ac1b4369146f2ebda6/
processingDocuments/1741068753457_Approved_Plan.pdf",
  "size": "243225",
  "createdAt": "Tue Mar 04 2025 06:12:34 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Land & Buiding - Value Calculation - Mahalaxmi Nagar - PLOT No.
5.xlsx",
  "filename": "1741068753466_Land__Buiding__Value_Calculation__Mahalaxmi_Nag
ar__PLOT_No_5.xlsx",
  "path": "cases/67c5a0ac1b4369146f2ebda6/processingDocuments/1741068753466
_Land__Buiding__Value_Calculation__Mahalaxmi_Nagar__PLOT_No_5.xlsx",
  "size": "4452893",
  "createdAt": "Tue Mar 04 2025 06:12:34 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-03-03T12:29:32.106Z",
"updatedAt": "2025-03-04T06:13:47.165Z",
"__v": 0,
"addressForMap": ""
```

"updatedBy": "60f91b6f344e052188ffd1fc"

}

Name	Length	Width	Total
-------------	---------------	--------------	--------------

Composition :

Other

Composition :
