

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": "",
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "6418456a96b58848585f8cb2",
    "name": "Thane",
    "email": "thane@vastukala.com",
    "phone": "1234567890",
    "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
    "city": "Thane",
    "shortName": "VCIPL/Thane"
  },
  "client": {
```

```
"_id": "66161d2b834794131c1cce9b",
"type": "PRIVATE_CLIENT",
"name": "UTI Asset Management Company Limited",
"displayName": "UTI Asset Management Company Limited",
"initial": "U"
},
"branch": "",
"assetsClass": {
  "value": "Land & Building / Immovable Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": "",
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "656aa949cebbe1714411d21b",
    "role": "FRONTDESK",
    "firstName": "Priyanka",
    "email": "thane@vastukala.org",
    "lastName": "Pawar",
    "mobileNo": "8928414480",
    "shortName": "PCP",
    "workWithDocumentMaker": "627222afafd7d55eddeddd82",
    "profilePhoto": "users/656aa949cebbe1714411d21b/
profilePhoto_1731643469657_WhatsApp_Image_20241115_at_93358_AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "62720b21afd7d55eddedc545",
    "role": "MAKER+CHECKER",
    "firstName": "Avinash",
    "email": "avinash.pandey@vastukala.org",
    "lastName": "Pandey",
    "mobileNo": "9021605621",
    "designation": "",
    "shortName": "AV",
    "workWithDocumentMaker": ""
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
```

```
"firstName": "Binumon",
"email": "binu@vastukala.org",
"lastName": "Moozhickal",
"mobileNo": "9930252906",
"designation": "Back Office Team Leader",
"shortName": "BS",
"workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
"profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvanta",
  "mobileNo": "9821518537",
  "designation": "",
  "shortName": "PS",
  "workWithDocumentMaker": "60f915d3f3dd69653a592199",
  "profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"valuers": [],
},
"clientType": {
  "value": "PRIVATE_CLIENT",
  "label": "Private Clients"
},
"location": {
  "latitude": "28.54826746505961",
```

```
"longitude": "77.21815920805302"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false,
  "area": "1717.00",
  "rate": "21503.00",
  "yearOfConstruction": "1988",
  "compositionOfBuilding": "Ground + 2 Upper Floors"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Khel",
```

```
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "Block S-I",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
```

```
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Asian Games Village Comp",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Block S-I, Hawa Singh Block",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
}
```

```
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
```

```
"key": "selectNo",
"value": "S-I/474",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
}
```



```
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 110 049",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
}
```

```
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
```

```
"title": "Electricity deposits / electrical fittings, etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": false,
```

```
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": true,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67cecb9d8037ced5d24394b9",
"ownerName": "UTI Asset Management Company Limited",
"ownerPhoneNo": "9810229821",
"fullAddress": "Residential Flat No. S-I/474, Ground Floor, Building No Block S-I, Asian
Games Village Comp, Block S-I, Hawa Singh Block, Village - Khel, PIN Code - 110 049,
State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Previous Valuation Report",
      "value": "60ae1248aa6d152c1801b2ee"
    },
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
},
"attachInReport": false,
```



```
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1741605781474_UTI_Asset_Management_Company_Limited_Flat_No_474__10042024.pdf",
    "path": "cases/67cecb9d8037ced5d24394b9/document_1741605781474_UTI_Asset_Management_Company_Limited_Flat_No_474__10042024.pdf",
    "id": "585295",
    "uploadedBy": "656aa949cebbe1714411d21b",
    "createdAt": "Mon Mar 10 2025 11:23:09 GMT+0000 (Coordinated Universal Time)"
  }
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "014813",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "137258",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Mar 10 2025 11:23:09 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "UTI Asset Management Company Limited",
    "phone": "9810229821",
    "ownershipShare": "",
    "email": "",
    "id": "631841"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
  }
]
```

```
    "_id": "67d91cf501f1c07601e48f80",
    "name":
"externallmg_1742281973357_WhatsApp_Image_20250317_at_41727_PM.jpeg",
    "path": "cases/67cecb9d8037ced5d24394b9/
externallmg_1742281973357_WhatsApp_Image_20250317_at_41727_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d91cf501f1c07601e48f81",
    "name":
"externallmg_1742281973388_WhatsApp_Image_20250317_at_41728_PM_1.jpeg",
    "path": "cases/67cecb9d8037ced5d24394b9/
externallmg_1742281973388_WhatsApp_Image_20250317_at_41728_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d91cf501f1c07601e48f82",
    "name":
"externallmg_1742281973478_WhatsApp_Image_20250317_at_41728_PM.jpeg",
    "path": "cases/67cecb9d8037ced5d24394b9/
externallmg_1742281973478_WhatsApp_Image_20250317_at_41728_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d91cf501f1c07601e48f83",
    "name":
"externallmg_1742281973521_WhatsApp_Image_20250317_at_41729_PM_1.jpeg",
    "path": "cases/67cecb9d8037ced5d24394b9/
externallmg_1742281973521_WhatsApp_Image_20250317_at_41729_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d91cf501f1c07601e48f84",
    "name":
"externallmg_1742281973594_WhatsApp_Image_20250317_at_41729_PM_2.jpeg",
    "path": "cases/67cecb9d8037ced5d24394b9/
externallmg_1742281973594_WhatsApp_Image_20250317_at_41729_PM_2.jpeg",
    "orientation": "portrait"
  }
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d91cf501f1c07601e48f85",
  "name":
"externallmg_1742281973659_WhatsApp_Image_20250317_at_41729_PM.jpeg",
  "path": "cases/67cecb9d8037ced5d24394b9/
externallmg_1742281973659_WhatsApp_Image_20250317_at_41729_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d91cf501f1c07601e48f86",
  "name":
"externallmg_1742281973710_WhatsApp_Image_20250317_at_41730_PM_1.jpeg",
  "path": "cases/67cecb9d8037ced5d24394b9/
externallmg_1742281973710_WhatsApp_Image_20250317_at_41730_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d91cf501f1c07601e48f87",
  "name":
"externallmg_1742281973732_WhatsApp_Image_20250317_at_41730_PM.jpeg",
  "path": "cases/67cecb9d8037ced5d24394b9/
externallmg_1742281973732_WhatsApp_Image_20250317_at_41730_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d91cf501f1c07601e48f88",
  "name":
"externallmg_1742281973776_WhatsApp_Image_20250317_at_41731_PM.jpeg",
  "path": "cases/67cecb9d8037ced5d24394b9/
externallmg_1742281973776_WhatsApp_Image_20250317_at_41731_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67d91d05700ebc688493ed5c",
  "name":
"externallmg_1742281989548_WhatsApp_Image_20250317_at_41732_PM_1.jpeg",
```

```
    "path": "cases/67cecb9d8037ced5d24394b9/
externallmg_1742281989548_WhatsApp_Image_20250317_at_41732_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d91d05700ebc688493ed5d",
    "name":
"externallmg_1742281989586_WhatsApp_Image_20250317_at_41732_PM.jpeg",
    "path": "cases/67cecb9d8037ced5d24394b9/
externallmg_1742281989586_WhatsApp_Image_20250317_at_41732_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d91d05700ebc688493ed5e",
    "name":
"externallmg_1742281989646_WhatsApp_Image_20250317_at_41733_PM_1.jpeg",
    "path": "cases/67cecb9d8037ced5d24394b9/
externallmg_1742281989646_WhatsApp_Image_20250317_at_41733_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d91d05700ebc688493ed5f",
    "name":
"externallmg_1742281989682_WhatsApp_Image_20250317_at_41733_PM.jpeg",
    "path": "cases/67cecb9d8037ced5d24394b9/
externallmg_1742281989682_WhatsApp_Image_20250317_at_41733_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d91d05700ebc688493ed60",
    "name":
"externallmg_1742281989706_WhatsApp_Image_20250317_at_41734_PM_1.jpeg",
    "path": "cases/67cecb9d8037ced5d24394b9/
externallmg_1742281989706_WhatsApp_Image_20250317_at_41734_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "67d91d05700ebc688493ed61",
    "name":
"externallmg_1742281989739_WhatsApp_Image_20250317_at_41734_PM.jpeg",
    "path": "cases/67cecb9d8037ced5d24394b9/
externallmg_1742281989739_WhatsApp_Image_20250317_at_41734_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d91d05700ebc688493ed62",
    "name":
"externallmg_1742281989786_WhatsApp_Image_20250317_at_41735_PM_1.jpeg",
    "path": "cases/67cecb9d8037ced5d24394b9/
externallmg_1742281989786_WhatsApp_Image_20250317_at_41735_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d91d05700ebc688493ed63",
    "name":
"externallmg_1742281989817_WhatsApp_Image_20250317_at_41735_PM.jpeg",
    "path": "cases/67cecb9d8037ced5d24394b9/
externallmg_1742281989817_WhatsApp_Image_20250317_at_41735_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d91d05700ebc688493ed64",
    "name":
"externallmg_1742281989843_WhatsApp_Image_20250317_at_41736_PM_1.jpeg",
    "path": "cases/67cecb9d8037ced5d24394b9/
externallmg_1742281989843_WhatsApp_Image_20250317_at_41736_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d91d13df28417602baa2c7",
    "name":
"externallmg_1742282003170_WhatsApp_Image_20250317_at_41736_PM.jpeg",
    "path": "cases/67cecb9d8037ced5d24394b9/
externallmg_1742282003170_WhatsApp_Image_20250317_at_41736_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d91d13df28417602baa2c8",
    "name":
"externallmg_1742282003220_WhatsApp_Image_20250317_at_41737_PM_1.jpeg",
    "path": "cases/67cecb9d8037ced5d24394b9/
externallmg_1742282003220_WhatsApp_Image_20250317_at_41737_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d91d13df28417602baa2c9",
    "name":
"externallmg_1742282003276_WhatsApp_Image_20250317_at_41737_PM.jpeg",
    "path": "cases/67cecb9d8037ced5d24394b9/
externallmg_1742282003276_WhatsApp_Image_20250317_at_41737_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d91d13df28417602baa2ca",
    "name":
"externallmg_1742282003333_WhatsApp_Image_20250317_at_41738_PM_1.jpeg",
    "path": "cases/67cecb9d8037ced5d24394b9/
externallmg_1742282003333_WhatsApp_Image_20250317_at_41738_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d91d13df28417602baa2cb",
    "name":
"externallmg_1742282003379_WhatsApp_Image_20250317_at_41738_PM.jpeg",
    "path": "cases/67cecb9d8037ced5d24394b9/
externallmg_1742282003379_WhatsApp_Image_20250317_at_41738_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67d91d13df28417602baa2cc",
```

```
"name":
"externalImg_1742282003422_WhatsApp_Image_20250317_at_41739_PM.jpeg",
  "path": "cases/67cecb9d8037ced5d24394b9/
externalImg_1742282003422_WhatsApp_Image_20250317_at_41739_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [
{
  "originalName": "1712816989872_Flat_No_474__10042024.doc",
  "filename": "1742279932997_1712816989872_Flat_No_474__10042024.doc",
  "path": "cases/67cecb9d8037ced5d24394b9/
externalDocuments/1742279932997_1712816989872_Flat_No_474__10042024.doc",
  "size": "6180352",
  "documentType": {
    "value": "649998c6cab24d3d1a2cc577",
    "label": "Draft Word Report"
  },
  "createdAt": "Tue Mar 18 2025 06:38:54 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "627222afafd7d55eddeddd82"
}
],
"processingDocuments": [
{
  "originalName": "Residential DDA Flat No. S-I-474.xlsx",
  "filename": "1742023017123_Residential_DDA_Flat_No_SI474.xlsx",
  "path": "cases/67cecb9d8037ced5d24394b9/
processingDocuments/1742023017123_Residential_DDA_Flat_No_SI474.xlsx",
  "size": "2467921",
  "createdAt": "Sat Mar 15 2025 07:16:57 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "64dc7184ccaf1e7b7f637f47"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
  "createdBy": {
    "_id": "627222afafd7d55eddeddd82",
    "role": "FRONTDESK",
    "firstName": "Pratibha",
    "lastName": "Shilvanta",
    "profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
  },
  "workType": "SITE_INSPECTION",
```

```

    "display": true,
    "status": true,
    "_id": "67d91c83df28417602baa146",
    "note": "Photo upload (Task Reopen)",
    "taskId": "67cecba77e0bb1d5cc32ae9f",
    "createdAt": "2025-03-18T07:10:59.995Z"
  }
],
"createdAt": "2025-03-10T11:23:09.419Z",
"updatedAt": "2025-03-18T07:13:23.599Z",
"__v": 0,
"updatedBy": "62720b21afd7d55eddedc545",
"addressForMap": "",
"caseReferredBy": "62720b21afd7d55eddedc545",
"contactPersonName": "UTI Asset Management Company Limited",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"reId": "",
"siteVisitContactNo": "9810229821"
}

```

| Name | Length | Width | Total |
|---------------|--------|-------|-------|
| Composition : | | | |
| Other | | | |
| Composition : | | | |