

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94231032",
    "firstName": "Namrata Salvi",
    "email": "0_DEFAULT_racpc.sion@sbi.co.in",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-8879237774"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Namrata Salvi",
    "expectedFees": 2500,
    "quotedAmount": "2500"
  },
  "organization": {
    "package": {
      "_id": "5fc0d7e47d6c8d39dc34a294",
      "title": "basic",
      "price": 5.1,
      "case": 20,
      "duration": "300"
    }
  }
}
```

```
},
"status": true,
"isdelete": false,
"_id": "5f2bdee67813470eb443deb4",
"name": "Vastukala Consultants India Pvt. Ltd.",
"gstNo": "18AABCT3518Q1ZZ",
"panNo": "ABCDE1234A",
"freeCases": "10",
"email": "vastukalamumbai@vastukala.com",
"phone": "9819670183",
"address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai -
400 093",
"remark": "undefined",
"theme": "DEFAULT",
"profilePhoto": "public\\images\\
\\1606738172464_51041525c82381638d4d202735b1f05d.png",
"shortName": "VCIPL",
"waterMarkImage": [
  {
    "_id": "640f2227282e4e13d7615d9b",
    "path": "public\\Vastukala Letter head H 2019.jpg",
    "pageNo": "2"
  }
],
"city": "Mumbai",
"stampImage": []
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1 6th Floor, Kirol Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
```

```
"ledgerName": "",
"fax": "",
"sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7177d2ffdf65bcd65882a",
    "role": "PICKUPPERSON",
    "firstName": "Saurabh",
    "email": "saurabhvelonde143@gmail.com",
    "lastName": "Velonde",
    "mobileNo": "8691048846",
    "shortName": "SSV",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60b7177d2ffdf65bcd65882a\\
\\profilePhoto_1622701681508_WhatsApp Image 2021-06-02 at 11.09.24 AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "627208c1afd7d55eddedc372",
    "role": "FRONTDESK",
    "firstName": "Aniket",
    "email": "Aniket@vastukala.org",
    "lastName": "Navale",
    "mobileNo": "9892222307",
    "designation": "",
    "shortName": "AN",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/627208c1afd7d55eddedc372/
profilePhoto_1667995077581_WhatsApp_Image_20221109_at_52453_PM.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
```

```
"_id": "627221f4afd7d55eddeddcb4",
"role": "MAKER",
"firstName": "Prajakta",
"email": "prajakta@vastukala.org",
"lastName": "Patil",
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "63f313626f9c2254a9b35ba2",
"role": "MAKER",
"firstName": "Girish",
"email": "agregirish@gmail.com",
"lastName": "Agre",
"mobileNo": "9082114817",
"designation": "Technical Officer",
"shortName": "GA",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f313626f9c2254a9b35ba2/
profilePhoto_1676874632701_WhatsApp_Image_20230220_at_115708_AM.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "627221f4afd7d55eddeddcb4",
"role": "MAKER",
"firstName": "Prajakta",
"email": "prajakta@vastukala.org",
"lastName": "Patil",
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
}
]
```

```
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
```

```
\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
],
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": 0,
  "longitude": 0
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-03-14T18:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-03-14T18:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-03-16T08:51:16.720Z",
      "remark": ""
    }
  ]
},
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2023-03-16T08:51:16.720Z"
  }
]
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Tue Mar 14 2023 10:14:48 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
```

```
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
}
```

```
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Chimi Apartment",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
```



```
"value": "",
"label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Haridas Nagar, Shimoli Road, Borivali West",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
```

```
"status": false,
"name": "CTS No.",
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "203",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
```

```
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "VerifiedTileFlooring"
  },
  "doors": {
    "label": "Teak Wood",
    "value": "TeakWood"
  },
  "windows": {
    "label": "Aluminium Sliding Windows with window grills",
```

```
"value": "Aluminium_Sliding_Windows_with_window_grills"
},
"fittings": {
  "label": "Concealed",
  "value": "Concealed"
},
"finishing": {
  "label": "Cement Plastering + POP Finish",
  "value": "Cement_Plastering+_POP_Finish"
}
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Municipal Corporation of Greater Mumbai (MCGM)",
    "value": "MCGM"
  },
  "asPerActualAgreement": {
    "north": "Victory Arch Building",
    "west": "Haridas Nagar Road",
    "south": "R.M.Bhattad Marg",
    "east": "Gangotri CHSL"
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  }
}
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
}
```

```
"propertyOccupiedByList": {
  "label": "Vacant",
  "value": "Vacant"
},
"monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  },
  "pavementLaid": {
    "label": "Yes",
    "value": "Yes"
  },
  "carParking": {
    "label": "Open Parking",
    "value": "Open_Parking"
  },
  "constructionWorkStatus": {
    "label": "Completed",
    "value": "Completed"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "1990",
    "fullDate": "1/1/1990"
  },
  "propertyTypeList": {
    "value": "Residential",
    "label": "Residential"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "label": "R.C.C. Framed",
    "value": "R.C.C."
  },
  "qualityOfConstruction": {
```

```
"label": "Good",
"value": "Good"
},
"walls": {
"label": "Yes",
"value": "1"
},
"appearanceOfTheBuilding": {
"label": "Normal",
"value": "Normal"
},
"maintenanceOfTheBuilding": {
"label": "Normal",
"value": "Normal"
},
"visibleDamageInBuilding": {
"label": "No",
"value": "0"
},
"groundStilt": {
"label": "Ground",
"value": "ground"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "27",
"ageOfBuilding": "33",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "6",
"flatFloorNo": "",
"noOfLifts": "1",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "3"
},
"routeMap": {
"locationMapImg": []
},
"outward": {
"status": false,
"remark": "SYSTEM_GENERATED"
},
"rateVerify": {
"status": false
},
}
```

```
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```



```
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"createCase": "false",
"type": "CASE",
"status": true,
"caseStatus": "READYFORMAKER",
```

```
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"_id": "640f2227282e4e13d7615d9a",
"ownerName": "Smt. Huseina Slatevala",
"ownerPhoneNo": "8600315105",
"appAddress": "Flat no. 203, 2nd floor, Chimi Apartment, Haridas Nagar, Shimoli
Road, Borivali West, ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Deed of Declaration",
      "value": "60ae128aaa6d152c1801b420"
    },
    "isHardCopy": false,
    "path": "cases/640f2227282e4e13d7615d9a/
document_1678713335012_86390.pdf",
    "fileName": "document_1678713335012_86390.pdf",
    "displayStatus": false,
    "id": "217592",
    "uploadedBy": "60b7177d2ffdf65bcd65882a",
    "createdAt": "Mon Mar 13 2023 18:46:22 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Commencement Certificate",
      "value": "60ae1247aa6d152c1801b2ea"
    },
    "isHardCopy": false,
    "path": "cases/640f2227282e4e13d7615d9a/
document_1678713352419_163528.pdf",
    "fileName": "document_1678713352419_163528.pdf",
    "displayStatus": false,
    "id": "995341",
    "uploadedBy": "60b7177d2ffdf65bcd65882a",
    "createdAt": "Mon Mar 13 2023 18:46:22 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Occupation Certificate",
      "value": "60ae1293aa6d152c1801b447"
    },
    "isHardCopy": false,
    "path": "cases/640f2227282e4e13d7615d9a/
document_1678713366142_49052.pdf",
```

```
"fileName": "document_1678713366142_49052.pdf",
"displayStatus": false,
"id": "641609",
"uploadedBy": "60b7177d2ffdf65bcd65882a",
"createdAt": "Mon Mar 13 2023 18:46:22 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "000659",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
{
  "id": "631742",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Mon Mar 13 2023 18:46:23 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
  "name": "Smt. Huseina Slatevala",
  "phone": "8600315105",
  "ownershipShare": "",
  "email": "",
  "id": "905926"
}
],
"siteInspection": [
{
  "areaType": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "providedBy": {
    "label": "Other",
    "value": "Other"
  },
  "_id": "6412ce42f0b13e493ac2feb7",
  "area": "381.58",
  "providedByName": "Yusuf Slatewala",
  "providedByContactNo": "9892186452"
}
],
"composition": [
{
  "measurementType": {
    "label": "Square Feet",
```

```
    "value": "Square_Feet"
  },
  "id": "113556",
  "name": "Living Room",
  "length": "13.83",
  "length1": "13",
  "length2": "10",
  "width": "9.83",
  "width1": "9",
  "width2": "10",
  "totalArea": "136.03",
  "images": [
    {
      "name": "compositionImg_1678954833944_image.jpg",
      "path": "cases/640f2227282e4e13d7615d9a/
compositionImg_1678954833944_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "136.03"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "7.75",
  "length1": "7",
  "length2": "9",
  "width": "5.75",
  "width1": "5",
  "width2": "9",
  "totalArea": "44.56",
  "images": [
    {
      "name": "compositionImg_1678954892742_image.jpg",
      "path": "cases/640f2227282e4e13d7615d9a/
compositionImg_1678954892742_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "44.56"
}
```

```
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Study Room",
  "length": "7.42",
  "length1": "7",
  "length2": "5",
  "width": "4.58",
  "width1": "4",
  "width2": "7",
  "totalArea": "33.99",
  "images": [
    {
      "name": "compositionImg_1678954963361_image.jpg",
      "path": "cases/640f2227282e4e13d7615d9a/
compositionImg_1678954963361_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "33.99"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "10.25",
  "length1": "10",
  "length2": "3",
  "width": "10.00",
  "width1": "10",
  "width2": "0",
  "totalArea": "102.50",
  "images": [
    {
      "name": "compositionImg_1678955296079_image.jpg",
      "path": "cases/640f2227282e4e13d7615d9a/
compositionImg_1678955296079_image.jpg",
      "orientation": "portrait"
    }
  ]
}
```

```
    }
  ],
  "extraAreas": [],
  "finalArea": "102.50"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "5.17",
  "length1": "5",
  "length2": "2",
  "width": "3.67",
  "width1": "3",
  "width2": "8",
  "totalArea": "18.94",
  "images": [
    {
      "name": "compositionImg_1678955520183_image.jpg",
      "path": "cases/640f2227282e4e13d7615d9a/
compositionImg_1678955520183_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "18.94"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "5.33",
  "length1": "5",
  "length2": "4",
  "width": "3.00",
  "width1": "3",
  "width2": "0",
  "totalArea": "16.00",
  "images": [
    {
```

```
    "name": "compositionImg_1678955574190_image.jpg",
    "path": "cases/640f2227282e4e13d7615d9a/
compositionImg_1678955574190_image.jpg",
    "orientation": "portrait"
  }
],
  "extraAreas": [],
  "finalArea": "16.00"
}
],
"otherComposition": [
  {
    "name": {
      "label": "Passage",
      "value": "Passage"
    },
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "0",
    "length1": "5",
    "length2": "5",
    "length": "5.42",
    "width1": "2",
    "width2": "11",
    "width": "2.92",
    "totalArea": "15.80",
    "percentageBeforeTotal": "15.80",
    "images": [],
    "extraAreas": [],
    "percentage": "100",
    "finalArea": "15.8"
  },
  {
    "name": {
      "label": "Passage",
      "value": "Passage"
    },
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "1",
    "length1": "4",
    "length2": "11",
```

```

    "length": "4.92",
    "width1": "2",
    "width2": "10",
    "width": "2.83",
    "totalArea": "13.93",
    "percentageBeforeTotal": "13.93",
    "images": [],
    "extraAreas": [],
    "percentage": "100",
    "finalArea": "13.93"
  }
],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [],
"externalDocuments": [],
"createdAt": "2023-03-13T13:16:23.983Z",
"updatedAt": "2023-03-16T08:54:22.396Z",
"__v": 0,
"fullAddress": "Residential Flat No. 203, 2nd Floor, Chimi Apartment, Haridas Nagar, Shimoli Road, Borivali West, State - Maharashtra, India",
"updatedBy": "627208c1afd7d55eddedc372",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Smt. Huseina Slatevala",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8600315105",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Study Room + 2 Toilet",
"carpetTotal": "352.02000000000004",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "29.73",
"siteVisitDate": "2023-03-16"
}

```

Name	Length	Width	Total
Composition :			
Living Room	13'10"	9'10"	136.03



Kitchen	7'9"	5'9"	44.56
Study Room	7'5"	4'7"	33.99
Bedroom	10'3"	10'0"	102.50
Toilet	5'2"	3'8"	18.94
Toilet	5'4"	3'0"	16.00
Other Composition :			
Passage	5'5"	2'11"	15.80
Passage	4'11"	2'10"	13.93