

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8dc"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b37",
    "email": "komal.vanjari@cosmosbank.in",
    "firstName": "Komal ",
    "mobileNo": "8080342307",
    "workMobileNo": "8080342307",
    "lastName": "vanjari"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "package": {
      "_id": "5fc0d7e47d6c8d39dc34a294",
      "title": "basic",
      "price": 5.1,
      "case": 20,

```

```
"duration": "300"
},
"status": true,
"isdelete": false,
"_id": "5f2bdee67813470eb443deb4",
"name": "Vastukala Consultants India Pvt. Ltd.",
"gstNo": "18AABCT3518Q1ZZ",
"panNo": "ABCDE1234A",
"freeCases": "10",
"email": "vastukalamumbai@vastukala.com",
"phone": "9819670183",
"address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai -
400 093",
"remark": "undefined",
"theme": "DEFAULT",
"profilePhoto": "public\\images\
\\1606738172464_51041525c82381638d4d202735b1f05d.png",
"shortName": "VCIPL",
"waterMarkImage": [
  {
    "_id": "64104a4d319ffa48baa4a668",
    "path": "public\\Vastukala Letter head H 2019.jpg",
    "pageNo": "2"
  }
],
"city": "Mumbai",
"stampImage": []
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8dc",
  "branchCode": "000005",
  "type": "BRANCH",
  "name": "Naupada",
  "email": "thane@cosmosbank.in",
  "mobileNo": "022-25345923",
  "alternateMobileNo": "",
  "address": "Kusumanjali, Opp. Devdhar Hospital, Naupada, Thane (West) - 400 602,
```

```
State - Maharashtra, Country - India.\r\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62720e52afd7d55eddedc887",
    "role": "SITEENGINEER",
    "firstName": "Harshad",
    "email": "Harshad@vastukala.org",
    "lastName": "Panchal",
    "mobileNo": "9029575553",
    "shortName": "HP",
    "workWithDocumentMaker": ""
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "60f9343b45132d6a6bdd96e8",
    "role": "SITEENGINEER",
    "firstName": "RAJESH",
    "email": "rajeshb.ghadi@gmail.com",
    "lastName": "GHADI",
    "mobileNo": "8652092666",
    "designation": "",
    "shortName": "RHG",
    "workWithDocumentMaker": ""
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60f915d3f3dd69653a592199",
    "role": "CHECKER",
    "firstName": "Shobha",
```

```
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60eebe33f3dd69653a5837ae",
"role": "MAKER",
"firstName": "Shamal",
"email": "shamal@vastukala.org",
"lastName": "Bodke",
"mobileNo": "9821740317",
"designation": "",
"shortName": "SB",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "CHECKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
}
],
"type": "EMPLOYEE",
```

```
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
```

```
    }
  ]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": 0,
  "longitude": 0
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "",
      "remark": ""
    },
    {
      "dateTime": "",
      "remark": ""
    }
  ]
},
"visitedDate": []
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Wadghar",
    "label": true
  }
}
```

```
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "5",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
```

```
"key": "plotNo",
"value": "5",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sai Pride",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "1",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
}
```



```
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
```

```
"value": "507",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
```

```
"status": false,
"name": "Postal Code",
"key": "postalCode",
"value": "",
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "VerifiedTileFlooring"
  },
  "doors": {
    "label": "Teak Wood",
    "value": "TeakWood"
  },
  "windows": {
    "label": "Aluminium Sliding",
    "value": "Alluminum_Sliding_Windows"
  },
  "fittings": {
    "label": "Concealed",
    "value": "Concealed"
  },
  "finishing": {
    "label": "Cement Plastering",
    "value": "Cement_Plastering"
  }
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
```

```
"label": "Urban",
"value": "Urban"
},
"townplanApprovedByList": {
  "label": "As per CIDCO norms",
  "value": "As_per_CIDCO_norms"
},
"asPerActualAgreement": {
  "north": "OOEN",
  "west": "BUILDIND ",
  "south": "UNDER CONSTRUCTION ",
  "east": "ROAD"
},
"asPerDocumentAgreement": {
  "north": "",
  "west": "",
  "south": "",
  "east": ""
}
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Vacant",
    "value": "Vacant"
  },
  "monthlyRent": "6000"
},
"siteMeasurement": {
  "dateOfConstruction": {
    "date": "",
    "month": "",
    "year": "",
    "fullDate": ""
  },
  "propertyTypeList": {
    "value": "Residential",
    "label": "Residential"
  },
}
```

```
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"groundStilt": {
  "label": "Part Ground + Part Stilt",
  "value": "Part_Ground_and_Part_Stilt"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "0",
"estimatedAge": "0",
"ageOfBuilding": "60",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "06",
"flatFloorNo": "",
"noOfLifts": "01",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "07"
},
"routeMap": {
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  }
}
```

```
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
```

```
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"createCase": "true",
"type": "CASE",
"status": true,
"caseStatus": "READYFORMAKER",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"_id": "64104a4d319ffa48baa4a663",
"ownerName": "Vidhya Santosh Jagdale",
"ownerPhoneNo": "7666434996",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "7666434996",
"contactPersonName": "Vidhya Santosh Jagdale",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Vidhya Santosh Jagdale",
    "phone": "7666434996",
```



```
"ownershipShare": "",
"email": "",
"id": "100290"
}
],
"caseReferredBy": "62720e52afd7d55eddedc887",
"relationWithOwner": "self",
"fullAddress": "Residential Flat No. 507, 5th Floor, Sai Pride, Plot No. 5, Sector 1,
Village - Wadghar, State - Maharashtra, India",
"remark": "",
"documents": [
{
"documentType": {
"value": "60ae1246aa6d152c1801b2e4",
"label": "Index- II"
},
"inputs": {
"documentDate": "05/11/2019",
"from": {
"value": "seller",
"label": "seller"
},
"seller": "Guru Sai Devlopers",
"to": {
"value": "purchaser",
"label": "purchaser"
},
"purchaser": "Vidhya Santosh Jagdale",
"number": {
"value": "Document_No",
"label": "Document No"
},
"Document_No": "16278"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1678789113128_Adobe_Scan_13Mar2023_1.pdf",
"path": "cases/64104a4d319ffa48baa4a663/
document_1678789113128_Adobe_Scan_13Mar2023_1.pdf",
"id": "681025",
"uploadedBy": "6006d4ce5080a310ac1fdfc2",
"createdAt": "Tue Mar 14 2023 15:49:55 GMT+0530 (India Standard Time)"
},
{
"documentType": {
"value": "60af48bf2ffdf65bcd6585fa",
```

```
"label": "Agreement for sale"
},
"inputs": {
  "from": {
    "value": "Developers",
    "label": "Developers"
  },
  "Developers": "Guru Sai Devlopers (seller)\t",
  "to": {
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "Vidhya Santosh Jagdale (purchaser)\t",
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "4107"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1678789189485_Adobe_Scan_13Mar2023_3.pdf",
"path": "cases/64104a4d319ffa48baa4a663/
document_1678789189485_Adobe_Scan_13Mar2023_3.pdf",
"id": "222539",
"uploadedBy": "6006d4ce5080a310ac1fdfc2",
"createdAt": "Tue Mar 14 2023 15:49:55 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "20/04/2022",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "CIDCO/BP-16061/TPO(NM & K)/2018/9205"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1678794932358_51PUSHPAKOC.pdf",
  "path": "cases/64104a4d319ffa48baa4a663/
document_1678794932358_51PUSHPAKOC.pdf",
```

```
"id": "130640",
"uploadedBy": "6006d4ce5080a310ac1fdcf2",
"createdAt": "Tue Mar 14 2023 17:25:35 GMT+0530 (India Standard Time)"
}
],
"isUrgent": "false",
"isExternal": "false",
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "000679",
"createdBy": "6006d4ce5080a310ac1fdcf2",
"caseHistory": [
  {
    "id": "577065",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Tue Mar 14 2023 15:49:57 GMT+0530 (India Standard Time)"
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "939274",
    "name": "Kitchen",
    "length": "5.75",
    "length1": "5",
    "length2": "9",
    "width": "9.00",
    "width1": "9",
    "width2": "0",
    "totalArea": "51.75",
    "images": [],
    "extraAreas": [],
    "finalArea": "51.75"
  },
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "1",
    "name": "Living Room",
    "length": "8.83",
```

```
"length1": "8",
"length2": "10",
"width": "11.33",
"width1": "11",
"width2": "4",
"totalArea": "100.11",
"images": [],
"extraAreas": [],
"finalArea": "100.11"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Toilet",
  "length": "3.08",
  "length1": "3",
  "length2": "1",
  "width": "7.75",
  "width1": "7",
  "width2": "9",
  "totalArea": "23.90",
  "images": [],
  "extraAreas": [],
  "finalArea": "23.90"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Flowered Area",
  "length": "2.00",
  "length1": "2",
  "length2": "00",
  "width": "6.00",
  "width1": "6",
  "width2": "00",
  "totalArea": "12.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.00"
},
}
```

```

{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Flowered Area",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "8.42",
  "width1": "8",
  "width2": "5",
  "totalArea": "42.08",
  "images": [],
  "extraAreas": [],
  "finalArea": "42.08"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [],
"externalDocuments": [],
"createdAt": "2023-03-14T10:19:57.505Z",
"updatedAt": "2023-03-20T02:34:55.974Z",
"__v": 0,
"addressForMap": "",
"updatedBy": "60f9343b45132d6a6bdd96e8",
"briefDescOfProperty": "Living Room + Kitchen + Toilet + 2 Flowered Area",
"carpetTotal": "229.84000000000003",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0"
}

```

Name	Length	Width	Total
Composition :			
Kitchen	5'9"	9'0"	51.75
Living Room	8'10"	11'4"	100.11
Toilet	3'1"	7'9"	23.90

Flowered Area	2'00"	6'00"	12.00
Flowered Area	5'00"	8'5"	42.08
Other Composition :			