

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b951"
    },
    "type": "CREDITOFFICER",
    "_id": "635f732fe363ef22db2f1c80",
    "firstName": "KIRAN ",
    "lastName": "AWALE",
    "mobileNo": "",
    "email": "me1@me.com",
    "workMobileNo": "9309969663"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "package": {
      "_id": "5fc0d7e47d6c8d39dc34a294",
      "title": "basic",
      "price": 5.1,
      "case": 20,

```

```
"duration": "300"
},
"status": true,
"isdelete": false,
"_id": "5f2bdee67813470eb443deb4",
"name": "Vastukala Consultants India Pvt. Ltd.",
"gstNo": "18AABCT3518Q1ZZ",
"panNo": "ABCDE1234A",
"freeCases": "10",
"email": "vastukalamumbai@vastukala.com",
"phone": "9819670183",
"address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai -
400 093",
"remark": "undefined",
"theme": "DEFAULT",
"profilePhoto": "public\\images\
\\1606738172464_51041525c82381638d4d202735b1f05d.png",
"shortName": "VCIPL",
"waterMarkImage": [
  {
    "_id": "6410b884319ffa48baa55fae",
    "path": "public\\Vastukala Letter head H 2019.jpg",
    "pageNo": "2"
  }
],
"city": "Mumbai",
"stampImage": []
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b951",
  "branchCode": "000167",
  "type": "BRANCH",
  "name": "RACPC Belapur Branch",
  "email": "sbi.14677@sbi.co.in",
  "mobileNo": "022-27524090",
  "alternateMobileNo": "",
  "address": "Estate Department Corporate Centre, 4th Floor, CIDCO Tower No. 4,
```

Railway Station Building, C.B.D. Belapur, Navi Mumbai - 400 614, State - Maharashtra, Country - India.",

"ledgerName": "STATE BANK OF INDIA - CBD Estate Department",

"fax": "022 2757 7002",

"sendStructuralCertificate": "0"

},

"assetsClass": {

"value": "Land\_&\_Building\_/\_Immovable\_Property",

"label": "Land & Building / Immovable Property"

},

"propertyType": {

"value": "Residential",

"label": "Residential"

},

"zone": {

"\_id": "60e03dac6576061dae462469",

"zoneName": "Mumbai (Metro) & Maharashtra"

},

"staff": {

"pickupPerson": {

"type": "EMPLOYEE",

"\_id": "60b7189d2ffdf65bcd65882b",

"role": "PICKUPPERSON",

"firstName": "Ravindra",

"email": "ravindrakasare186@gmail.com",

"lastName": "Kasare",

"mobileNo": "9167204055",

"shortName": "RBK",

"workWithDocumentMaker": "",

"profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\

\\profilePhoto\_1622701555488\_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"

},

"siteEngineer": {

"type": "EMPLOYEE",

"\_id": "60f9343b45132d6a6bdd96e8",

"role": "SITEENGINEER",

"firstName": "RAJESH",

"email": "rajeshb.ghadi@gmail.com",

"lastName": "GHADI",

"mobileNo": "8652092666",

"designation": "",

"shortName": "RHG",

"workWithDocumentMaker": ""

},

"rateVerifier": {

"type": "EMPLOYEE",

```
    "_id": "60092304a16fab0f2af9b0c2",
    "role": "MAKER+CHECKER",
    "firstName": "Nitesh",
    "email": "nitesh.khedekar@vastukala.org",
    "lastName": "Khedekar",
    "mobileNo": "8369040652",
    "designation": "",
    "shortName": "NK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60092304a16fab0f2af9b0c2\\
\\profilePhoto_1622372532348_Nitesh Khedekar Photo (2).jpg"
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "627221f4afd7d55eddeddcb4",
    "role": "MAKER",
    "firstName": "Prajakta",
    "email": "prajakta@vastukala.org",
    "lastName": "Patil",
    "mobileNo": "9769797568",
    "designation": "",
    "shortName": "P",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "60092304a16fab0f2af9b0c2",
    "role": "MAKER+CHECKER",
    "firstName": "Nitesh",
    "email": "nitesh.khedekar@vastukala.org",
    "lastName": "Khedekar",
    "mobileNo": "8369040652",
    "designation": "",
    "shortName": "NK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60092304a16fab0f2af9b0c2\\
\\profilePhoto_1622372532348_Nitesh Khedekar Photo (2).jpg"
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ]
    }
  ]
}
```

```
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
```

```
\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
],
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": 0,
  "longitude": 0
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "",
      "remark": ""
    },
    {
      "dateTime": "",
      "remark": ""
    }
  ]
},
"visitedDate": [],
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
```

```
"key": "village",
"value": "Sanpada",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "4",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
}
```

```
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "103",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sairaj Complex Co-Operative Housing Society Ltd.",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "1",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
```



```
"value": "A",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
```

```
"status": true,
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "404",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
```

```
"label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Ceramic Tile Flooring",
    "value": "CeramicTileFlooring"
  },
  "doors": {
    "label": "Teak Wood",
    "value": "TeakWood"
  },
  "windows": {
    "label": "Alluminum sliding windows with M. S. Grills",
    "value": "Alluminum_sliding_windows_with_M._S._Grills"
  },
  "fittings": {
    "label": "\\tFittings\\t:\\tOpen plumbing with C.P. fittings. Casing Capping wiring",
    "value": "\\tFittings\\t:\\tOpen_plumbing_with_C.P._fittings._Casing_Capping_wiring"
  },
  "finishing": {
    "label": "Cement Plastering",
    "value": "Cement_Plastering"
  }
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
```

```
"value": "MiddleClass"
},
"populationGroupList": {
  "label": "Urban",
  "value": "Urban"
},
"townplanApprovedByList": {
  "label": "Navi Mumbai Municipal Corporation",
  "value": "NMMC"
},
"asPerActualAgreement": {
  "north": "DHANSHREE ",
  "west": "Road",
  "south": "ROAD",
  "east": "Om Ganesh"
},
"asPerDocumentAgreement": {
  "north": "",
  "west": "",
  "south": "",
  "east": ""
}
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Tenant Occupied",
    "value": "Tenant_Occupied"
  },
  "monthlyRent": "MR INGLE"
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  }
}
```

```
},
"pavementLaid": {
  "label": "No",
  "value": "No"
},
"carParking": {
  "label": "open",
  "value": "open"
},
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2008",
  "fullDate": "1/1/2008"
},
"propertyTypeList": {
  "value": "Residential",
  "label": "Residential"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed",
  "value": "R.C.C."
},
"typeOfFoundation": {
  "label": "R.C.C. Foundation",
  "value": "rcc"
},
"qualityOfConstruction": {
  "label": "Good",
  "value": "Good"
},
"materialUsedList": {
  "label": "Good",
  "value": "Good"
},
"buildingSpecification": {
  "label": "Standard",
  "value": "Standard"
}
```

```
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"maintenanceOfTheBuilding": {
  "label": "External building renovation work is in progress",
  "value": "External_building_renovation_work_is_in_progress"
},
"maintenanceIssues": {
  "label": "No",
  "value": "0"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"systemOfAirConditioning": {
  "label": "No",
  "value": "0"
},
"provisionOfFirefighting": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Part Ground + Part Stilt",
  "value": "Part_Ground_and_Part_Stilt"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "45",
"ageOfBuilding": "15",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "0",
"flatFloorNo": "",
"noOfLifts": "",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "04"
},
```

```
"routeMap": {
  "locationMapImg": []
},
"outward": {
  "status": true,
  "remark": "SYSTEM_GENERATED",
  "date": "Thu Mar 16 2023 15:49:29 GMT+0530 (India Standard Time)",
  "number": "046047",
  "dayCount": "8",
  "monthCount": "241",
  "generatedBy": "627221f4afd7d55eddeddcb4"
},
"rateVerify": {
  "status": false
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
```

```
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```



```
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"createCase": "true",
"type": "CASE",
"status": true,
"caseStatus": "READYFORMAKER",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"_id": "6410b884319ffa48baa55fa9",
"ownerName": "RAMAKANT PRASHANT INGLE",
"ownerPhoneNo": "8379960914",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "8379960914",
"contactPersonName": "RAMAKANT PRASHANT INGLE",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "RAMAKANT PRASHANT INGLE",
    "phone": "8379960914",
    "ownershipShare": "",
    "email": "",
    "id": "359764"
  }
],
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"relationWithOwner": "self",
"fullAddress": "Residential Flat No. 404, 4th Floor, Wing - A, Sairaj Complex Co-Operative Housing Society Ltd., Plot No. 103, Sector 1, Village - Sanpada, Navi Mumbai, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f8",
      "label": "Draft Agreement"
    }
  }
]
```

```
},
"inputs": {
  "documentDate": "07/03/2023",
  "from": {
    "value": "seller",
    "label": "seller"
  },
  "seller": "RAMJI NANJI RATHOD",
  "to": {
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "RAMAKANT PRASHANT INGLE"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1678817406023_agreement_for_sale_Ingle.pdf",
"path": "cases/6410b884319ffa48baa55fa9/
document_1678817406023_agreement_for_sale_Ingle.pdf",
"id": "990065",
"uploadedBy": "6006d4ce5080a310ac1fdfc2",
"createdAt": "Tue Mar 14 2023 23:40:10 GMT+0530 (India Standard Time)"
}
],
"isUrgent": "false",
"isExternal": "false",
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "000691",
"createdBy": "6006d4ce5080a310ac1fdfc2",
"caseHistory": [
  {
    "id": "850760",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Tue Mar 14 2023 23:40:12 GMT+0530 (India Standard Time)"
  }
],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    }
  }
]
```

```
    },
    "_id": "6412889f715c6310059ccfa0",
    "area": "00",
    "providedByName": "RAMAKANT INGLE",
    "providedByContactNo": "8379960914"
  }
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "560902",
    "name": "Bedroom",
    "length": "4.00",
    "length1": "4",
    "length2": "0",
    "width": "4.67",
    "width1": "4",
    "width2": "8",
    "totalArea": "18.67",
    "images": [],
    "extraAreas": [],
    "finalArea": "18.67"
  },
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "1",
    "name": "WC",
    "length": "3.00",
    "length1": "3",
    "length2": "0",
    "width": "4.00",
    "width1": "4",
    "width2": "0",
    "totalArea": "12.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "12.00"
  },
  {
    "measurementType": {
```

```
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Living Room",
  "length": "13.00",
  "length1": "13",
  "length2": "0",
  "width": "9.00",
  "width1": "9",
  "width2": "0",
  "totalArea": "117.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "117.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Kitchen",
  "length": "9.83",
  "length1": "9",
  "length2": "10",
  "width": "6.17",
  "width1": "6",
  "width2": "2",
  "totalArea": "60.64",
  "images": [],
  "extraAreas": [],
  "finalArea": "60.64"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "9.75",
  "length1": "9",
  "length2": "9",
  "width": "10.00",
  "width1": "10",
```

```

    "width2": "0",
    "totalArea": "97.50",
    "images": [],
    "extraAreas": [],
    "finalArea": "97.50"
  },
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "5",
    "name": "Dining",
    "length": "3.00",
    "length1": "3",
    "length2": "00",
    "width": "6.42",
    "width1": "6",
    "width2": "5",
    "totalArea": "19.25",
    "images": [],
    "extraAreas": [],
    "finalArea": "19.25"
  }
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [],
"externalDocuments": [],
"createdAt": "2023-03-14T18:10:12.503Z",
"updatedAt": "2023-03-16T16:49:43.862Z",
"__v": 0,
"updatedBy": "60f9343b45132d6a6bdd96e8",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + WC + Dining",
"carpetTotal": "325.06",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0",
"addressForMap": ""
}

```

Name	Length	Width	Total
Composition :			

Bedroom	4'0"	4'8"	18.67
WC	3'0"	4'0"	12.00
Living Room	13'0"	9'0"	117.00
Kitchen	9'10"	6'2"	60.64
Bedroom	9'9"	10'0"	97.50
Dining	3'00"	6'5"	19.25
Other Composition :			