

```
{
  "typeOfReport": {
    "value": "Land",
    "label": "Land"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Banking_Purpose",
    "label": "Banking Purpose"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6412e43fe6a52007fba976e9"
    },
    "type": "CREDITOFFICER",
    "_id": "6412e43fe6a52007fba976eb",
    "firstName": "Saurabh ",
    "lastName": "Jain",
    "mobileNo": "",
    "workMobileNo": "9619093344",
    "email": "saurabh@stcionline.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "40000 + GST"
  },
  "organization": {
    "package": {
      "_id": "5fc0d7e47d6c8d39dc34a294",
      "title": "basic",
      "price": 5.1,
      "case": 20,
    }
  }
}
```

```
"duration": "300"
},
"status": true,
"isdelete": false,
"_id": "5f2bdee67813470eb443deb4",
"name": "Vastukala Consultants India Pvt. Ltd.",
"gstNo": "18AABCT3518Q1ZZ",
"panNo": "ABCDE1234A",
"freeCases": "10",
"email": "vastukalamumbai@vastukala.com",
"phone": "9819670183",
"address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai -
400 093",
"remark": "undefined",
"theme": "DEFAULT",
"profilePhoto": "public\\images\
\\1606738172464_51041525c82381638d4d202735b1f05d.png",
"shortName": "VCIPL",
"waterMarkImage": [
  {
    "_id": "6412e8d7e6a52007fba99a1c",
    "path": "public\\Vastukala Letter head H 2019.jpg",
    "pageNo": "2"
  }
],
"city": "Mumbai",
"stampImage": []
},
"client": {
  "_id": "6412e13ee6a52007fba949e6",
  "type": "BANK",
  "name": "STCI Finance limited",
  "displayName": "",
  "initial": "STCI"
},
"branch": {
  "_id": "6412e43fe6a52007fba976e9",
  "name": "Lower Parel",
  "branchCode": "",
  "mobileNo": "9619093344",
  "alternateMobileNo": "",
  "email": "monitoring@stcionline.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "A/B 1-802, A Wing, 8th Floor, Marathon Innova, Marathon Nextgen
```

Compound, Off. Ganpatrao Kadam Marg, Lower Parel (West), Mumbai – 400 013, State – Maharashtra, Country – India"

```
  },
  "assetsClass": {
    "value": "Land_&_Building_/_Immovable_Property",
    "label": "Land & Building / Immovable Property"
  },
  "propertyType": {
    "value": "Non_Agriculture",
    "label": "Non Agriculture"
  },
  "zone": {
    "_id": "6412e2fae6a52007fba96749",
    "zoneName": "Pan India"
  },
  "staff": {
    "pickupPerson": {
      "type": "EMPLOYEE",
      "_id": "62727444afd7d55eddee092c",
      "role": "PICKUPPERSON",
      "firstName": "Shantilal",
      "email": "shantilal@vastukala.org",
      "lastName": "Patel",
      "mobileNo": "9969039853",
      "shortName": "SHP",
      "workWithDocumentMaker": "",
      "profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
    },
    "siteEngineer": {
      "type": "EMPLOYEE",
      "_id": "60f91822f3dd69653a5922e3",
      "role": "SITEENGINEER",
      "firstName": "PRAYUSH",
      "email": "Prayush@vastukala.org",
      "lastName": "PAREKH",
      "mobileNo": "9767983840",
      "designation": "",
      "shortName": "PPP",
      "workWithDocumentMaker": "",
      "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
    },
    "rateVerifier": {
      "type": "EMPLOYEE",
      "_id": "60f91822f3dd69653a5922e3",
```

```
"role": "SITEENGINEER",
"firstName": "PRAYUSH",
"email": "Prayush@vastukala.org",
"lastName": "PAREKH",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60f91822f3dd69653a5922e3",
"role": "SITEENGINEER",
"firstName": "PRAYUSH",
"email": "Prayush@vastukala.org",
"lastName": "PAREKH",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60f91822f3dd69653a5922e3",
"role": "SITEENGINEER",
"firstName": "PRAYUSH",
"email": "Prayush@vastukala.org",
"lastName": "PAREKH",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "IBBI"
}
],
}
```

```
{
  "value": "AM161706-3",
  "label": "Chartered Engineer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
]
],
```

```
    "shortName": "MBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": 0,
  "longitude": 0
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-03-16T11:00:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Thu Mar 16 2023 15:31:03 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  }
}
```

```
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Chamtoli & Dahivali",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
```

```
"key": "taluka",
"value": "Ambernath",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
}
```



```
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "78, 9 & 29",
  "label": true
},
"hissaNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "2, 4, 2 & 11A",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
```

```
"value": "",
"label": false
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
```

```
"status": false,
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "421503",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Badlapur",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "Proposed R.C.C. Slab",
    "value": "Proposed_R.C.C._Slab"
  },
  "flooring": {
    "label": "Partly Vitrified tiles / Kota stone / Ceramic tiles flooring",
    "value": "Partly_Vitrified_tiles_/_Kota_stone/_/Ceramic_tiles_flooring"
  },
  "doors": {
    "label": "Proposed Teak wood",
    "value": "Proposed_Teak_wood"
  },
  "windows": {
    "label": "Not Provided",
    "value": "NotProvided"
  },
  "fittings": {
    "label": "Not Provided",
    "value": "NotProvided"
  },
  "finishing": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  }
}
```

```
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Rural",
    "value": "Rural"
  },
  "townplanApprovedByList": {
    "label": "Other",
    "value": "Other"
  },
  "asPerActualAgreement": {
    "north": "open plot ",
    "south": "open plot",
    "east": "road",
    "west": "open plot"
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  }
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Owner Occupied",
    "value": "Owner_Occupied"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  }
}
```

```
},
"waterTank": {
  "label": "Grampanchayat",
  "value": "Grampanchayat"
},
"pavementLaid": {
  "label": "Building Under Construction",
  "value": "Building_Under_Construction"
},
"carParking": {
  "label": "Building Under Construction",
  "value": "Building_Under_Construction"
},
"constructionWorkStatus": {
  "label": "Under Construction",
  "value": "InProgress"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2025",
  "fullDate": "1/1/2025"
},
"propertyTypeList": {
  "value": "Non_Agriculture",
  "label": "Non Agriculture"
},
"planningArea": {
  "value": "Non_Agriculture",
  "label": "Non Agriculture"
},
"typeOfStructure": {
  "label": "Other Pukka Structure",
  "value": "Other_Pukka_Structure"
},
"qualityOfConstruction": {
  "label": "Building Under Construction",
  "value": "UnderConstruction"
},
"walls": {
  "label": "Building Under Construction",
  "value": "Building_Under_Construction"
},
"appearanceOfTheBuilding": {
  "label": "Building Under Construction",
  "value": "UnderConstruction"
}
```

```
},
"maintenanceOfTheBuilding": {
  "label": "Building Under Construction",
  "value": "UnderConstruction"
},
"visibleDamageInBuilding": {
  "label": "Building Under Construction",
  "value": "Building_Under_Construction"
},
"groundStilt": {
  "label": "Ground",
  "value": "ground"
},
"isSiteVisitAllowed": false,
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "0",
"flatFloorNo": "",
"noOfLifts": "0",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "0",
"totalLifeBuilding": "",
"ageOfBuilding": "",
"estimatedAge": ""
},
"routeMap": {
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"underConstruction": {
  "rccFootingFoundation": {
```

```
"label": "RCC Footing/Foundation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
"label": "RCC Plinth",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
```



```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"createCase": "false",
"type": "CASE",
"status": true,
"caseStatus": "READYFORMAKER",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"_id": "6412e8d7e6a52007fba99a1b",
"ownerName": "Umesh Sawant",
"ownerPhoneNo": "9167399723",
"fullAddress": " Land No. Basement Floor, New/Current Survey No. 78, 9 & 29, Hissa
No. 2, 4, 2 & 11A, Village - Chamtoli & Dahivali, Badlapur, Taluka - Ambernath, District -
Thane, 421503, State - Maharashtra, India",
"remark": "",
```

```

"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "04/11/2018",
      "from": {
        "value": "seller",
        "label": "seller"
      },
      "seller": "Dnyaneshwar Kambri",
      "to": {
        "value": "buyer",
        "label": "buyer"
      },
      "buyer": "M/s. Poddar Housing and Developement Ltd.",
      "number": {
        "value": "Registration_No",
        "label": "Registration No"
      },
      "Registration_No": "4564/2018"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName":
"document_1678960838877_Conveyance_Deed_Chamtoli_Survey_No_781782_C.pdf",
    "path": "cases/6412e8d7e6a52007fba99a1b/
document_1678960838877_Conveyance_Deed_Chamtoli_Survey_No_781782_C.pdf",
    "id": "548830",
    "uploadedBy": "60f91822f3dd69653a5922e3",
    "createdAt": "Thu Mar 16 2023 15:30:53 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "000728",
"createdBy": "60f91822f3dd69653a5922e3",
"caseHistory": [
  {
    "id": "828851",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Mar 16 2023 15:30:55 GMT+0530 (India Standard Time)"
  }
],
"owners": [

```

```
{
  "name": "Umesh Sawant",
  "phone": "9167399723",
  "ownershipShare": "",
  "email": "",
  "id": "337586"
},
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "status": false,
    "_id": "6412ed76e6a52007fba9debe",
    "path": "cases/6412e8d7e6a52007fba99a1b/
externallmg_1678962008944_image.jpeg"
  },
  {
    "status": false,
    "_id": "6412ed76e6a52007fba9deb",
    "path": "cases/6412e8d7e6a52007fba99a1b/
externallmg_1678962018032_image.jpeg"
  },
  {
    "status": false,
    "_id": "6412ed76e6a52007fba9dec0",
    "path": "cases/6412e8d7e6a52007fba99a1b/
externallmg_1678962022482_image.jpeg"
  },
  {
    "status": false,
    "_id": "6412ed76e6a52007fba9dec1",
    "path": "cases/6412e8d7e6a52007fba99a1b/
externallmg_1678962026605_image.jpeg"
  },
  {
    "status": false,
    "_id": "6412ed76e6a52007fba9dec2",
    "path": "cases/6412e8d7e6a52007fba99a1b/
externallmg_1678962028774_image.jpeg"
  }
]
```

```
],
"externalDocuments": [],
"createdAt": "2023-03-16T10:00:55.754Z",
"updatedAt": "2023-03-16T10:20:38.103Z",
"__v": 0,
"addressForMap": "",
"caseReferredBy": "5ffe92d27737ca4d986b6453",
"contactPersonName": "Umesh Sawant",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9167399723",
"updatedBy": "60f91822f3dd69653a5922e3"
}
```

Name	Length	Width	Total
Composition :			
Other			
Composition :			