

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b80a"
    },
    "type": "CREDITOFFICER",
    "_id": "6417f02396b58848585ed0c0",
    "firstName": "Anmol Tiwari",
    "lastName": "Tiwari",
    "mobileNo": "",
    "workMobileNo": "7977031040",
    "email": ""
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "15000000",
    "discussWithPerson": "Anmol Tiwari",
    "expectedFees": 7500,
    "quotedAmount": "2500"
  },
  "organization": {
    "package": {
      "_id": "5fc0d7e47d6c8d39dc34a294",
      "title": "basic",
      "price": 5.1,
      "case": 20,

```

```
"duration": "300"
},
"status": true,
"isdelete": false,
"_id": "5f2bdee67813470eb443deb4",
"name": "Vastukala Consultants India Pvt. Ltd.",
"gstNo": "18AABCT3518Q1ZZ",
"panNo": "ABCDE1234A",
"freeCases": "10",
"email": "vastukalamumbai@vastukala.com",
"phone": "9819670183",
"address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai -
400 093",
"remark": "undefined",
"theme": "DEFAULT",
"profilePhoto": "public\\images\
\\1606738172464_51041525c82381638d4d202735b1f05d.png",
"shortName": "VCIPL",
"waterMarkImage": [
  {
    "_id": "6418188a96b58848585f1508",
    "path": "public\\Vastukala Letter head H 2019.jpg",
    "pageNo": "2"
  }
],
"city": "Mumbai",
"stampImage": []
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b80a",
  "branchCode": "000088",
  "type": "BRANCH",
  "name": "RACPC - Chinchpokli (East)",
  "email": "sbi.17889@sbi.co.in",
  "mobileNo": "022-23707514",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, Mumbai South Voltas
```

House, 'A', 1st Floor, Dr. Ambedkar Road, Chinchpokli (East), Mumbai - 400 033, State - Maharashtra, Country - India.\r\n",

"ledgerName": "STATE BANK OF INDIA - CHINCHPOKALI",

"fax": "022-23707512 / 13",

"sendStructuralCertificate": "0"

},

"assetsClass": {

"value": "Land\_&\_Building\_/\_Immovable\_Property",

"label": "Land & Building / Immovable Property"

},

"propertyType": {

"value": "Residential",

"label": "Residential"

},

"zone": {

"\_id": "60e03dac6576061dae462469",

"zoneName": "Mumbai (Metro) & Maharashtra"

},

"staff": {

"pickupPerson": {

"type": "EMPLOYEE",

"\_id": "60af3d172ffdf65bcd6585cd",

"role": "PICKUPPERSON",

"firstName": "Sachin",

"email": "sachin.joshi@vastukala.org",

"lastName": "Joshi",

"mobileNo": "9167204063",

"shortName": "SJ",

"workWithDocumentMaker": "",

"profilePhoto": "users\\60af3d172ffdf65bcd6585cd\\

profilePhoto\_1622372567671\_Sachin Joshi Photo 3 (2).jpg"

},

"siteEngineer": {

"type": "EMPLOYEE",

"\_id": "627208c1afd7d55eddedc372",

"role": "FRONTDESK",

"firstName": "Aniket",

"email": "Aniket@vastukala.org",

"lastName": "Navale",

"mobileNo": "9892222307",

"designation": "",

"shortName": "AN",

"workWithDocumentMaker": "",

"profilePhoto": "users/627208c1afd7d55eddedc372/

profilePhoto\_1667995077581\_WhatsApp\_Image\_20221109\_at\_52453\_PM.jpeg"

},

```
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "CHECKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
  "lastName": "Bodke",
  "mobileNo": "9821740317",
  "designation": "",
  "shortName": "SB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "CHECKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
```

```
    "value": "IBBI/RV/07/2018/10366",
    "label": "Registered Valuer"
  }
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
```

```
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": 0,
  "longitude": 0
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-03-20T08:30:00.000Z",
      "remark": "Haresh Mathur Is Proposed Buyer "
    },
    {
      "dateTime": "2023-03-20T12:28:58.505Z",
      "remark": ""
    },
    {
      "dateTime": "2023-03-20T12:28:59.023Z",
      "remark": ""
    },
    {
      "dateTime": "2023-03-20T12:28:59.517Z",
      "remark": ""
    },
    {
      "dateTime": "2023-03-20T12:28:59.663Z",
      "remark": ""
    },
    {
      "dateTime": "2023-03-20T12:29:00.327Z",
      "remark": ""
    },
    {
      "dateTime": "2023-03-20T12:29:00.701Z",
      "remark": ""
    }
  ]
}
```

```
},
{
  "dateTime": "2023-03-20T12:29:00.888Z",
  "remark": ""
},
{
  "dateTime": "2023-03-20T12:29:01.488Z",
  "remark": ""
},
{
  "dateTime": "2023-03-20T12:29:01.823Z",
  "remark": ""
}
],
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2023-03-20T12:28:58.505Z"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2023-03-20T12:28:59.023Z"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2023-03-20T12:28:59.517Z"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2023-03-20T12:28:59.663Z"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2023-03-20T12:29:00.327Z"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2023-03-20T12:29:00.701Z"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2023-03-20T12:29:00.888Z"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2023-03-20T12:29:01.488Z"
  }
]
```

```
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-03-20T12:29:01.823Z"
    }
  ]
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Mon Mar 20 2023 15:05:37 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Malad",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "19",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "7",
```



```
"label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Neelyog Virat",
  "label": false
},
"selectArea": {
  "status": false,
```

```
"name": "Sector",
"key": "selectArea",
"value": "",
"label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Khotkuwa",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
}
```

```
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1904",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
```

```
"key": "khataNo",
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
}
```

```
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "VerifiedTileFlooring"
  },
  "doors": {
    "label": "Teak Wood",
    "value": "TeakWood"
  },
  "windows": {
    "label": "Alluminum sliding windows with tinted glass ",
    "value": "Alluminum_sliding_windows_with_tinted_glass_"
  },
  "fittings": {
    "label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring",
    "value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring"
  },
  "finishing": {
    "label": "Cement Plastering + POP Finish",
    "value": "Cement_Plastering_+_POP_Finish"
  }
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Municipal Corporation of Greater Mumbai (MCGM)",
    "value": "MCGM"
  },
  "asPerActualAgreement": {
    "north": "B Wing",
    "west": "SRA Building",
    "south": "Shah Housecon Building No. 10",
    "east": "Western Express Highway"
  }
},
```

```
"asPerDocumentAgreement": {
  "north": "",
  "west": "",
  "south": "",
  "east": ""
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Vacant",
    "value": "Vacant"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MuncipalWaterSupply"
  },
  "pavementLaid": {
    "label": "Yes",
    "value": "Yes"
  },
  "carParking": {
    "label": "Basement + Podium car parking",
    "value": "Basement+_Podium_car_parking"
  },
  "constructionWorkStatus": {
    "label": "Under Construction",
    "value": "InProgress"
  },
  "dateOfConstruction": {
    "date": "",
    "month": "1",
```

```
"year": "2023",
"fullDate": "1/1/2023"
},
"propertyTypeList": {
  "value": "Residential",
  "label": "Residential"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"qualityOfConstruction": {
  "label": "Good",
  "value": "Good"
},
"walls": {
  "label": "No",
  "value": "0"
},
"appearanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"maintenanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Ground",
  "value": "ground"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "",
"estimatedAge": "",
"ageOfBuilding": "",
"noOfBasement": "2",
"noOfPodium": "1",
"noOfAmenityFloors": "0",
```

```
"noOfFloors": "22",
"flatFloorNo": "",
"noOfLifts": "3",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "7"
},
"routeMap": {
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "27",
    "percentage": "40",
    "isHideFloor": false,
    "status": true
  },
}
```



```
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "27",
  "percentage": "7.00",
  "isHideFloor": false,
  "status": true
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "27",
  "percentage": "7.00",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "27",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "27",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "27",
  "percentage": "2.50",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "27",
  "percentage": "2.50",
  "isHideFloor": false,
  "status": true
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "27",
  "percentage": "10.00",
```

```
"isHideFloor": false,
"status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "27",
  "percentage": "1.50",
  "isHideFloor": false,
  "status": true
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "27",
  "percentage": "1.50",
  "isHideFloor": false,
  "status": true
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "27",
  "percentage": "5.00",
  "isHideFloor": false,
  "status": true
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "2",
  "percentage": "1.33",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "1",
  "isHideFloor": true,
  "status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "1",
  "isHideFloor": true,
  "status": true
},
"workCompleted": {
```

```
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "97.33",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"createCase": "false",
"type": "CASE",
"status": true,
"caseStatus": "READYFORMAKER",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"_id": "6418188a96b58848585f1507",
"ownerName": "Yati Rushi Mehta",
"ownerPhoneNo": "9821983811",
"appAddress": "flat no 1904 A-wing Building no 7 Neelyog Virat Malad",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Re-Sale",
      "value": "60ae1294aa6d152c1801b44b"
    },
    "isHardCopy": false,
    "path": "cases/6418188a96b58848585f1507/
document_1679301598998_43205.pdf",
    "fileName": "document_1679301598998_43205.pdf",
    "displayStatus": false,
    "id": "904177",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Mon Mar 20 2023 14:13:18 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/6418188a96b58848585f1507/
document_1679301630362_43205.pdf",
```

```
"fileName": "document_1679301630362_43205.pdf",
"displayStatus": false,
"id": "984060",
"uploadedBy": "60af3d172ffdf65bcd6585cd",
"createdAt": "Mon Mar 20 2023 14:13:18 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "000811",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "630043",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Mar 20 2023 13:55:46 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Yati Rushi Mehta",
    "phone": "9821983811",
    "ownershipShare": "",
    "email": "",
    "id": "361020"
  }
],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Other",
      "value": "Other"
    },
    "_id": "6418500896b58848585fb5fd",
    "area": "642.61",
    "providedByName": "Mrs. Minakshi (Sales Office)",
    "providedByContactNo": "9892475542"
  }
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
```

```
    "value": "Square_Feet"
  },
  "id": "175468",
  "name": "Living Room",
  "length": "16.50",
  "length1": "16",
  "length2": "6",
  "width": "10.92",
  "width1": "10",
  "width2": "11",
  "totalArea": "180.12",
  "images": [
    {
      "name": "compositionImg_1679314427839_image.jpg",
      "path": "cases/6418188a96b58848585f1507/
compositionImg_1679314427839_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "180.12"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "10.58",
  "length1": "10",
  "length2": "7",
  "width": "7.92",
  "width1": "7",
  "width2": "11",
  "totalArea": "83.78",
  "images": [
    {
      "name": "compositionImg_1679314479592_image.jpg",
      "path": "cases/6418188a96b58848585f1507/
compositionImg_1679314479592_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "83.78"
}
```

```
    },
    {
      "measurementType": {
        "label": "Square Feet",
        "value": "Square_Feet"
      },
      "id": "2",
      "name": "Bedroom",
      "length": "11.67",
      "length1": "11",
      "length2": "8",
      "width": "10.00",
      "width1": "10",
      "width2": "0",
      "totalArea": "116.67",
      "images": [
        {
          "name": "compositionImg_1679314530401_image.jpg",
          "path": "cases/6418188a96b58848585f1507/
compositionImg_1679314530401_image.jpg",
          "orientation": "portrait"
        },
        {
          "name": "compositionImg_1679314531087_image.jpg",
          "path": "cases/6418188a96b58848585f1507/
compositionImg_1679314531087_image.jpg",
          "orientation": "portrait"
        }
      ],
      "extraAreas": [],
      "finalArea": "116.67"
    },
    {
      "measurementType": {
        "label": "Square Feet",
        "value": "Square_Feet"
      },
      "id": "3",
      "name": "Bedroom",
      "length": "11.67",
      "length1": "11",
      "length2": "8",
      "width": "10.67",
      "width1": "10",
      "width2": "8",
      "totalArea": "124.44",
```

```
"images": [
  {
    "name": "compositionImg_1679314586667_image.jpg",
    "path": "cases/6418188a96b58848585f1507/
compositionImg_1679314586667_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "124.44"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "7.00",
  "length1": "7",
  "length2": "0",
  "width": "4.42",
  "width1": "4",
  "width2": "5",
  "totalArea": "30.92",
  "images": [
    {
      "name": "compositionImg_1679314661240_image.jpg",
      "path": "cases/6418188a96b58848585f1507/
compositionImg_1679314661240_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "30.92"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "6.92",
  "length1": "6",
  "length2": "11",
```

```
"width": "4.33",
"width1": "4",
"width2": "4",
"totalArea": "29.97",
"images": [
  {
    "name": "compositionImg_1679314703390_image.jpg",
    "path": "cases/6418188a96b58848585f1507/
compositionImg_1679314703390_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "29.97"
}
],
"otherComposition": [
  {
    "name": {
      "label": "Passage",
      "value": "Passage"
    },
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "0",
    "length1": "8",
    "length2": "0",
    "length": "8.00",
    "width1": "3",
    "width2": "5",
    "width": "3.42",
    "totalArea": "27.33",
    "percentageBeforeTotal": "27.33",
    "images": [
      {
        "name": "compositionImg_1679314745639_image.jpg",
        "path": "cases/6418188a96b58848585f1507/
compositionImg_1679314745639_image.jpg",
        "orientation": "portrait"
      }
    ],
    "extraAreas": [],
    "percentage": "100",
    "finalArea": "27.33"
  }
]
```



```
},
{
  "name": {
    "label": "Passage",
    "value": "Passage"
  },
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "length1": "4",
  "length2": "5",
  "length": "4.42",
  "width1": "2",
  "width2": "9",
  "width": "2.75",
  "totalArea": "12.15",
  "percentageBeforeTotal": "12.15",
  "images": [
    {
      "name": "compositionImg_1679314795472_image.jpg",
      "path": "cases/6418188a96b58848585f1507/
compositionImg_1679314795472_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "12.15"
}
],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [],
"externalDocuments": [],
"createdAt": "2023-03-20T08:25:46.560Z",
"updatedAt": "2023-03-20T12:31:58.615Z",
"__v": 0,
"updatedBy": "627208c1afd7d55eddedc372",
"fullAddress": " Flat No. 1904, 19th Floor, Building No 7, Wing - A, Neelyog Virat,
Khotkuwa, Village - Malad, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
```

"contactPersonName": "Yati Rushi Mehta",  
 "email": "",  
 "isExternal": "false",  
 "isUrgent": "false",  
 "ownershipShare": "",  
 "purchaseValueAsPerDocument": "",  
 "relationWithOwner": "self",  
 "siteVisitContactNo": "9821983811",  
 "briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Toilet",  
 "carpetTotal": "565.9",  
 "finalMeasurementType": "Sq. Ft.",  
 "otherCarpetTotal": "39.48",  
 "siteVisitDate": "2023-03-20"

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	16'6"	10'11"	180.12
Kitchen	10'7"	7'11"	83.78
Bedroom	11'8"	10'0"	116.67
Bedroom	11'8"	10'8"	124.44
Toilet	7'0"	4'5"	30.92
Toilet	6'11"	4'4"	29.97
Other Composition :			
Passage	8'0"	3'5"	27.33
Passage	4'5"	2'9"	12.15