

```
{
  "typeOfReport": {
    "label": "Residential",
    "value": "Residential"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f9"
    },
    "type": "CREDITOFFICER",
    "_id": "640ace424dda382753e5057d",
    "firstName": "Rajeev kumar Ranjan",
    "lastName": "Ranjan",
    "mobileNo": "",
    "workMobileNo": "9967159553",
    "email": "Rajeevracpc.borivali@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2,800,000",
    "discussWithPerson": "Rajeev kumar Ranjan",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "package": {
      "_id": "5fc0d7e47d6c8d39dc34a294",
      "title": "basic",
      "price": 5.1,
      "case": 20,

```

```
"duration": "300"
},
"status": true,
"isdelete": false,
"_id": "5f2bdee67813470eb443deb4",
"name": "Vastukala Consultants India Pvt. Ltd.",
"gstNo": "18AABCT3518Q1ZZ",
"panNo": "ABCDE1234A",
"freeCases": "10",
"email": "vastukalamumbai@vastukala.com",
"phone": "9819670183",
"address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai -
400 093",
"remark": "",
"theme": "DEFAULT",
"profilePhoto": "public\\images\
\\1606738172464_51041525c82381638d4d202735b1f05d.png",
"shortName": "VCIPL",
"waterMarkImage": [
  {
    "_id": "64198a5c96b5884858604dca",
    "path": "public\\Vastukala Letter head H 2019.jpg",
    "pageNo": "2"
  }
],
"city": "Mumbai",
"stampImage": []
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f9",
  "branchCode": "000066",
  "type": "BRANCH",
  "name": "RACPC Borivali (West) Branch",
  "email": "racpc.borivali@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "MTNL Building, Devidas Road, Borivali (West), Mumbai, State -
```

```
Maharashtra, Country - India. ",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
    "role": "PICKUPPERSON",
    "firstName": "Sunil",
    "email": "misalsunil87@gmail.com",
    "lastName": "Misal",
    "mobileNo": "8422982721",
    "shortName": "SM",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "62724d51afd7d55eddedeb9f",
    "role": "ADMIN",
    "firstName": "Sailee",
    "email": "sailee1997vastukala@gmail.com",
    "lastName": "Shinde",
    "mobileNo": "9607532270",
    "designation": "",
    "shortName": "SS",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62724d51afd7d55eddedeb9f/
profilePhoto_1653907947239_sailee1.png"
  },
  "rateVerifier": {
```

```
"type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER+CHECKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
  "mobileNo": "9529385821",
  "designation": "",
  "shortName": "PR",
  "workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
  "profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER+CHECKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
```

```
    "label": "Registered Valuer"
  }
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": ""
```

```
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": 0,
  "longitude": 0
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-03-21T11:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-03-21T11:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-03-24T04:38:54.235Z",
      "remark": ""
    }
  ]
},
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2023-03-24T04:38:54.235Z"
  }
]
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Tue Mar 21 2023 18:13:40 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
```

```
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Poisar",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
}
```

```
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Arjun Niwas ( SRA) CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "BHatt Lane",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
```



```
"key": "street2",
"value": "",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
}
```

```
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "202",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
```

```
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kandivali West\t",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Marble Flooring",
    "value": "MarbleFlooring"
  },
  "doors": {
    "label": "Teak Wood",
    "value": "TeakWood"
  },
  "windows": {
```

```
    "label": "Aluminium Sliding",
    "value": "Alluminum_Sliding_Windows"
  },
  "fittings": {
    "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring",
    "value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring"
  },
  "finishing": {
    "label": "Cement Plastering",
    "value": "Cement_Plastering"
  }
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Municipal Corporation of Greater Mumbai (MCGM)",
    "value": "MCGM"
  },
  "asPerActualAgreement": {
    "north": "Bhatt lane",
    "south": "Poisar bus depot",
    "east": "Lotus Prestige",
    "west": "Residential building"
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  }
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
```

```
"value": "Residential_Purpose"
},
"propertyOccupiedByList": {
  "label": "Owner Occupied",
  "value": "Owner_Occupied"
},
"monthlyRent": ""
},
"siteMeasurement": {
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  },
  "carParking": {
    "label": "open",
    "value": "open"
  },
  "constructionWorkStatus": {
    "label": "Completed",
    "value": "Completed"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "1999",
    "fullDate": "1/1/1999"
  },
  "propertyTypeList": {
    "value": "Residential",
    "label": "Residential"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "label": "R.C.C. Framed Structure",
    "value": "R.C.C._Framed_Structure"
  },
  "qualityOfConstruction": {
    "label": "Normal",
    "value": "Normal"
  },
  "walls": {
    "label": "Yes",
    "value": "1"
  }
}
```

```
},
"appearanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"maintenanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"visibleDamageInBuilding": {
  "label": "Information Not Available",
  "value": "Information_Not_Available"
},
"groundStilt": {
  "label": "Ground",
  "value": "ground"
},
"isSiteVisitAllowed": true,
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"flatFloorNo": "",
"noOfLiftsInEachWings": "0",
"totalLifeBuilding": "60",
"ageOfBuilding": "24",
"estimatedAge": "36",
"noOfFloors": "7",
"noOfDwellingUnitsInBuilding": "3",
"noOfLifts": "1"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
```

```
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
```



```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"createCase": "false",
"type": "CASE",
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
```

```
"_id": "64198a5c96b5884858604dc9",
"ownerName": "Falguni Santosh Shirke",
"ownerPhoneNo": "8424877199",
"appAddress": "Flat no.201 3 nd floor C-wing,Arjun Niwas SRA CHSL Poisar,Bhatt
Lane Kandivali West",
"remark": "9860413533 ",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/64198a5c96b5884858604dc9/document_1679395280372_pdf.pdf",
    "fileName": "document_1679395280372_pdf.pdf",
    "displayStatus": false,
    "id": "533372",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Tue Mar 21 2023 16:13:38 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "000837",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "806619",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Mar 21 2023 16:13:40 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Falguni Santosh Shirke",
    "phone": "8424877199",
    "ownershipShare": "",
    "email": "",
    "id": "632237"
  }
],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
  },
]
```

```
"providedBy": {
  "label": "Owner",
  "value": "Owner"
},
"_id": "641d287929e5586db05ead73",
"area": "238",
"providedByName": "Falguni Santosh Shirke",
"providedByContactNo": "8424877199"
}
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "318958",
    "name": "Living Room",
    "length": "9.42",
    "length1": "9",
    "length2": "5",
    "width": "12.42",
    "width1": "12",
    "width2": "5",
    "totalArea": "116.92",
    "images": [
      {
        "path": "cases/64198a5c96b5884858604dc9/
compositionImg_1679632755899_image.jpeg",
        "orientation": "portrait"
      }
    ]
  },
  {
    "extraAreas": [],
    "finalArea": "116.92"
  },
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "1",
    "name": "Kitchen",
    "length": "6.33",
    "length1": "6",
    "length2": "4",
    "width": "10.75",
```

```
"width1": "10",
"width2": "9",
"totalArea": "68.08",
"images": [
  {
    "path": "cases/64198a5c96b5884858604dc9/
compositionImg_1679632820176_image.jpeg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "68.08"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Toilets",
  "length": "5.67",
  "length1": "5",
  "length2": "8",
  "width": "4.00",
  "width1": "4",
  "width2": "0",
  "totalArea": "22.67",
  "images": [
    {
      "path": "cases/64198a5c96b5884858604dc9/
compositionImg_1679632862662_image.jpeg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "22.67"
}
],
"otherComposition": [
  {
    "name": {
      "label": "Passage",
      "value": "Passage"
    },
    "measurementType": {
      "label": "Square Feet",
```

```
    "value": "Square_Feet"
  },
  "id": "0",
  "length1": "3",
  "length2": "4",
  "length": "3.33",
  "width1": "8",
  "width2": "6",
  "width": "8.50",
  "totalArea": "28.33",
  "percentageBeforeTotal": "28.33",
  "images": [
    {
      "path": "cases/64198a5c96b5884858604dc9/
compositionImg_1679632676168_image.jpeg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "28.33"
},
{
  "name": {
    "label": "Passage",
    "value": "Passage"
  },
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "length1": "4",
  "length2": "10",
  "length": "4.83",
  "width1": "2",
  "width2": "4",
  "width": "2.33",
  "totalArea": "11.28",
  "percentageBeforeTotal": "11.28",
  "images": [
    {
      "path": "cases/64198a5c96b5884858604dc9/
compositionImg_1679632719453_image.jpeg",
      "orientation": "portrait"
    }
  ]
}
```

```
    ],
    "extraAreas": [],
    "percentage": "100",
    "finalArea": "11.28"
  }
],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "status": false,
    "_id": "641d285029e5586db05ead5f",
    "name": "externalImg_1679632456778_image.jpeg",
    "path": "cases/64198a5c96b5884858604dc9/
externalImg_1679632456778_image.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-03-21T10:43:40.986Z",
"updatedAt": "2023-03-24T04:54:20.634Z",
"__v": 0,
"fullAddress": "Residential Flat No. 202, 2nd Floor, Arjun Niwas ( SRA) CHSL, BHatt
Lane, Village - Poisar, Kandivali West\t, Mumbai, State - Maharashtra, India",
"updatedBy": "62724d51afd7d55eddedeb9f",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Falguni Santosh Shirke",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8424877199",
"briefDescOfProperty": "Living Room + Kitchen + Toilets",
"carpetTotal": "207.67000000000002",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "39.61",
"siteVisitDate": "2023-03-24"
}
```

Name	Length	Width	Total
Composition :			
Living Room	9'5"	12'5"	116.92
Kitchen	6'4"	10'9"	68.08
Toilets	5'8"	4'0"	22.67
Other Composition :			
Passage	3'4"	8'6"	28.33
Passage	4'10"	2'4"	11.28