

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b80a"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230ec0",
    "firstName": "Anuj Mehrotra",
    "email": "0_DEFAULT_a_mehrotra@sbi.co.in",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-9987527007"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "package": {
      "_id": "5fc0d7e47d6c8d39dc34a294",
      "title": "basic",
      "price": 5.1,
      "case": 20,
      "duration": "300"
    }
  }
}
```

```
},
"status": true,
"isdelete": false,
"_id": "5f2bdee67813470eb443deb4",
"name": "Vastukala Consultants India Pvt. Ltd.",
"gstNo": "18AABCT3518Q1ZZ",
"panNo": "ABCDE1234A",
"freeCases": "10",
"email": "vastukalamumbai@vastukala.com",
"phone": "9819670183",
"address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai -
400 093",
"remark": "",
"theme": "DEFAULT",
"profilePhoto": "public\\images\\
\\1606738172464_51041525c82381638d4d202735b1f05d.png",
"shortName": "VCIPL",
"waterMarkImage": [
  {
    "_id": "641991a196b5884858605b02",
    "path": "public\\Vastukala Letter head H 2019.jpg",
    "pageNo": "2"
  }
],
"city": "Mumbai",
"stampImage": []
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b80a",
  "branchCode": "000088",
  "type": "BRANCH",
  "name": "RACPC - Chinchpokli (East)",
  "email": "sbi.17889@sbi.co.in",
  "mobileNo": "022-23707514",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, Mumbai South Voltas
House, 'A', 1st Floor, Dr. Ambedkar Road, Chinchpokli (East), Mumbai - 400 033, State
```

```
- Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - CHINCHPOKALI",
  "fax": "022-23707512 / 13",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60f91822f3dd69653a5922e3",
    "role": "SITEENGINEER",
    "firstName": "PRAYUSH",
    "email": "Prayush@vastukala.org",
    "lastName": "PAREKH",
    "mobileNo": "9767983840",
    "shortName": "PPP",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "627208c1afd7d55eddedc372",
    "role": "FRONTDESK",
    "firstName": "Aniket",
    "email": "Aniket@vastukala.org",
    "lastName": "Navale",
    "mobileNo": "9892222307",
    "designation": "",
    "shortName": "AN",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/627208c1afd7d55eddedc372/
profilePhoto_1667995077581_WhatsApp_Image_20221109_at_52453_PM.jpeg"
  },
  "rateVerifier": {
```

```
"type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER+CHECKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER+CHECKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "0123456789",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
```

```
    "label": "Registered Valuer"
  }
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": ""
```

```
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": 0,
  "longitude": 0
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "",
      "remark": ""
    },
    {
      "dateTime": "2023-03-22T18:47:49.642Z",
      "remark": ""
    },
    {
      "dateTime": "2023-03-22T18:47:50.201Z",
      "remark": ""
    },
    {
      "dateTime": "2023-03-22T18:47:50.706Z",
      "remark": ""
    },
    {
      "dateTime": "2023-03-22T18:47:51.150Z",
      "remark": ""
    },
    {
      "dateTime": "2023-03-22T18:47:52.006Z",
      "remark": ""
    },
    {
      "dateTime": "2023-03-22T18:47:52.445Z",
      "remark": ""
    }
  ]
},
```

```
{
  "dateTime": "2023-03-22T18:47:52.814Z",
  "remark": ""
},
{
  "dateTime": "2023-03-22T18:47:52.943Z",
  "remark": ""
},
{
  "dateTime": "2023-03-22T18:47:53.518Z",
  "remark": ""
},
{
  "dateTime": "2023-03-22T18:47:53.595Z",
  "remark": ""
},
{
  "dateTime": "2023-03-22T18:47:53.964Z",
  "remark": ""
},
{
  "dateTime": "2023-03-22T18:47:54.144Z",
  "remark": ""
},
{
  "dateTime": "2023-03-22T18:47:54.518Z",
  "remark": ""
},
{
  "dateTime": "2023-03-22T18:47:55.429Z",
  "remark": ""
},
{
  "dateTime": "2023-03-22T18:47:55.623Z",
  "remark": ""
},
{
  "dateTime": "2023-03-22T18:47:55.000Z",
  "remark": ""
},
{
  "dateTime": "2023-03-22T18:47:56.262Z",
  "remark": ""
},
{
  "dateTime": "2023-03-22T18:47:56.620Z",
```

```
"remark": ""
},
{
  "dateTime": "2023-03-22T18:47:56.893Z",
  "remark": ""
},
{
  "dateTime": "2023-03-22T18:47:57.080Z",
  "remark": ""
},
{
  "dateTime": "2023-03-22T18:47:57.411Z",
  "remark": ""
},
{
  "dateTime": "2023-03-22T18:47:57.741Z",
  "remark": ""
},
{
  "dateTime": "2023-03-22T18:47:57.965Z",
  "remark": ""
},
{
  "dateTime": "2023-03-22T18:47:58.397Z",
  "remark": ""
},
{
  "dateTime": "2023-03-22T18:47:58.612Z",
  "remark": ""
}
],
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2023-03-22T18:47:49.642Z"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2023-03-22T18:47:50.201Z"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2023-03-22T18:47:50.706Z"
  },
  {
    "status": "COMPLETED",
```



```
"dateTime": "2023-03-22T18:47:51.150Z"  
},  
{  
  "status": "COMPLETED",  
  "dateTime": "2023-03-22T18:47:52.006Z"  
},  
{  
  "status": "COMPLETED",  
  "dateTime": "2023-03-22T18:47:52.445Z"  
},  
{  
  "status": "COMPLETED",  
  "dateTime": "2023-03-22T18:47:52.814Z"  
},  
{  
  "status": "COMPLETED",  
  "dateTime": "2023-03-22T18:47:52.943Z"  
},  
{  
  "status": "COMPLETED",  
  "dateTime": "2023-03-22T18:47:53.518Z"  
},  
{  
  "status": "COMPLETED",  
  "dateTime": "2023-03-22T18:47:53.595Z"  
},  
{  
  "status": "COMPLETED",  
  "dateTime": "2023-03-22T18:47:53.964Z"  
},  
{  
  "status": "COMPLETED",  
  "dateTime": "2023-03-22T18:47:54.144Z"  
},  
{  
  "status": "COMPLETED",  
  "dateTime": "2023-03-22T18:47:54.518Z"  
},  
{  
  "status": "COMPLETED",  
  "dateTime": "2023-03-22T18:47:55.429Z"  
},  
{  
  "status": "COMPLETED",  
  "dateTime": "2023-03-22T18:47:55.623Z"  
},
```

```
{
  "status": "COMPLETED",
  "dateTime": "2023-03-22T18:47:55.000Z"
},
{
  "status": "COMPLETED",
  "dateTime": "2023-03-22T18:47:56.262Z"
},
{
  "status": "COMPLETED",
  "dateTime": "2023-03-22T18:47:56.620Z"
},
{
  "status": "COMPLETED",
  "dateTime": "2023-03-22T18:47:56.893Z"
},
{
  "status": "COMPLETED",
  "dateTime": "2023-03-22T18:47:57.080Z"
},
{
  "status": "COMPLETED",
  "dateTime": "2023-03-22T18:47:57.411Z"
},
{
  "status": "COMPLETED",
  "dateTime": "2023-03-22T18:47:57.741Z"
},
{
  "status": "COMPLETED",
  "dateTime": "2023-03-22T18:47:57.965Z"
},
{
  "status": "COMPLETED",
  "dateTime": "2023-03-22T18:47:58.397Z"
},
{
  "status": "COMPLETED",
  "dateTime": "2023-03-22T18:47:58.612Z"
}
]
},
"address": {
  "state": {
    "status": true,
    "name": "State",
```

```
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Boriwali",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "3",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
}
```

```
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Manu SMruti\t",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Mandir Road Extension, Babhai, Borival\t",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
```

```
"value": "",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
```

```
"status": false,
"name": "CTS No.",
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "302t",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
```

```
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Proposed Vitrified tiles flooring",
    "value": "Proposed_Vitrified_tiles_flooring"
  },
  "doors": {
    "label": "Proposed Teak wood",
    "value": "Proposed_Teak_wood"
  },
  "windows": {
    "label": "Proposed Powder coated aluminium sliding windows",
```

```
"value": "Proposed_Powder_coated_aluminium_sliding_windows"
},
"fittings": {
  "label": "Proposed Concealed plumbing with C.P. fittings. Concealed wiring",
  "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Concealed_wiring"
},
"finishing": {
  "label": "Building Under Construction",
  "value": "Building_Under_Construction"
}
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Municipal Corporation of Greater Mumbai (MCGM)",
    "value": "MCGM"
  },
  "asPerActualAgreement": {
    "north": "Neeta Niwas CHSL",
    "west": "Ashutosh CHSL",
    "south": "Internal Road",
    "east": "Anandrao Pawar School"
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  }
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Medium",
    "value": "Medium"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
}
```



```
"propertyOccupiedByList": {
  "label": "Building Under Construction",
  "value": "Building_Under_Construction"
},
"monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  },
  "pavementLaid": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  },
  "carParking": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  },
  "constructionWorkStatus": {
    "label": "Under Construction",
    "value": "InProgress"
  },
  "dateOfConstruction": {
    "date": "",
    "month": "1",
    "year": "2023",
    "fullDate": "1/1/2023"
  },
  "propertyTypeList": {
    "value": "Residential",
    "label": "Residential"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "label": "R.C.C. Framed Structure",
    "value": "R.C.C._Framed_Structure"
  },
  "qualityOfConstruction": {
```

```
"label": "Good",
"value": "Good"
},
"walls": {
"label": "Building Under Construction",
"value": "Building_Under_Construction"
},
"appearanceOfTheBuilding": {
"label": "Building Under Construction",
"value": "UnderConstruction"
},
"maintenanceOfTheBuilding": {
"label": "Building Under Construction",
"value": "UnderConstruction"
},
"visibleDamageInBuilding": {
"label": "Building Under Construction",
"value": "Building_Under_Construction"
},
"groundStilt": {
"label": "Part Ground + Part Stilt",
"value": "Part_Ground_and_Part_Stilt"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "",
"estimatedAge": "",
"ageOfBuilding": "",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "9",
"flatFloorNo": "",
"noOfLifts": "2",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "2"
},
"routeMap": {
"locationMapImg": []
},
"outward": {
"status": false,
"remark": "SYSTEM_GENERATED"
},
"rateVerify": {
"status": false
},
}
```

```
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "9",
    "percentage": "32.73",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "9",
    "percentage": "7.00",
    "isHideFloor": false,
    "status": true
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "9",
    "percentage": "7.00",
    "isHideFloor": false,
    "status": true
  },
  "internalPlastering": {
    "label": "Internal Plastering",
```

```
"floorsCompleted": "9",
"percentage": "3.50",
"isHideFloor": false,
"status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "4",
  "percentage": "1.27",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
}
```

```
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "61.50",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"createCase": "true",
"type": "CASE",
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
```

```
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"_id": "641991a196b5884858605afd",
"ownerName": "Shweta Goyal\t",
"ownerPhoneNo": "0000000000",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9324126205",
"contactPersonName": "Gangaram bangal\t",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Shweta Goyal\t",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "437163"
  }
],
"caseReferredBy": "60f91822f3dd69653a5922e3",
"relationWithOwner": "self",
"fullAddress": "Residential Flat No. 302\t, 3rd Floor, Manu SMruti\t, Mandir Road
Extension, Babhai, Borival\t, Village - Boriwali, State - Maharashtra, India",
"remark": "",
"documents": [],
"isUrgent": "false",
"isExternal": "false",
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "000839",
"createdBy": "6006d4ce5080a310ac1fdfc2",
"caseHistory": [
  {
    "id": "552756",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Tue Mar 21 2023 16:44:41 GMT+0530 (India Standard Time)"
  }
],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
```

```
    "label": "Other",
    "value": "Other"
  },
  "_id": "641b4d03ee0c792c533ba97f",
  "area": "616.75",
  "providedByName": "site measurement ",
  "providedByContactNo": "0000000000"
}
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "898997",
    "name": "Living Room",
    "length": "12.83",
    "length1": "12",
    "length2": "10",
    "width": "9.92",
    "width1": "9",
    "width2": "11",
    "totalArea": "127.26",
    "images": [
      {
        "name": "compositionImg_r_1679509794009_image.jpg",
        "path": "cases/641991a196b5884858605afd/
compositionImg_r_1679509794009_image.jpg",
        "orientation": "portrait"
      }
    ],
    "extraAreas": [],
    "finalArea": "127.26"
  },
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "1",
    "name": "Kitchen",
    "length": "11.92",
    "length1": "11",
    "length2": "11",
    "width": "8.50",
```

```
"width1": "8",
"width2": "6",
"totalArea": "101.29",
"images": [
  {
    "name": "compositionImg_r_1679509864705_image.jpg",
    "path": "cases/641991a196b5884858605afd/
compositionImg_r_1679509864705_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "101.29"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "12.75",
  "length1": "12",
  "length2": "9",
  "width": "10.33",
  "width1": "10",
  "width2": "4",
  "totalArea": "131.75",
  "images": [
    {
      "name": "compositionImg_r_1679509929662_image.jpg",
      "path": "cases/641991a196b5884858605afd/
compositionImg_r_1679509929662_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "131.75"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Bedroom",
```



```
"length": "12.00",
"length1": "12",
"length2": "0",
"width": "9.83",
"width1": "9",
"width2": "10",
"totalArea": "118.00",
"images": [
  {
    "name": "compositionImg_r_1679509985925_image.jpg",
    "path": "cases/641991a196b5884858605afd/
compositionImg_r_1679509985925_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "118.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "7.25",
  "length1": "7",
  "length2": "3",
  "width": "3.50",
  "width1": "3",
  "width2": "6",
  "totalArea": "25.37",
  "images": [
    {
      "name": "compositionImg_r_1679510130422_image.jpg",
      "path": "cases/641991a196b5884858605afd/
compositionImg_r_1679510130422_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "25.37"
},
{
  "measurementType": {
    "label": "Square Feet",
```

```
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "5.75",
  "length1": "5",
  "length2": "9",
  "width": "2.92",
  "width1": "2",
  "width2": "11",
  "totalArea": "16.77",
  "images": [
    {
      "name": "compositionImg_r_1679510209884_image.jpg",
      "path": "cases/641991a196b5884858605afd/
compositionImg_r_1679510209884_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "16.77"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "8.67",
  "length1": "8",
  "length2": "8",
  "width": "3.58",
  "width1": "3",
  "width2": "7",
  "totalArea": "31.06",
  "images": [
    {
      "name": "compositionImg_r_1679510265240_image.jpg",
      "path": "cases/641991a196b5884858605afd/
compositionImg_r_1679510265240_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "31.06"
```

```
}
],
"otherComposition": [
  {
    "name": {
      "label": "Cupboard",
      "value": "Cupboard"
    },
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "0",
    "length1": "3",
    "length2": "7",
    "length": "3.58",
    "width1": "2",
    "width2": "6",
    "width": "2.50",
    "totalArea": "8.96",
    "percentageBeforeTotal": "8.96",
    "images": [
      {
        "name": "compositionImg_r_1679510320393_image.jpg",
        "path": "cases/641991a196b5884858605afd/
compositionImg_r_1679510320393_image.jpg",
        "orientation": "portrait"
      }
    ],
    "extraAreas": [],
    "percentage": "100",
    "finalArea": "8.96"
  },
  {
    "name": {
      "label": "Passage",
      "value": "Passage"
    },
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "1",
    "length1": "6",
    "length2": "5",
    "length": "6.42",
```

```
"width1": "5",
"width2": "6",
"width": "5.50",
"totalArea": "35.29",
"percentageBeforeTotal": "35.29",
"images": [
  {
    "name": "compositionImg_r_1679510379141_image.jpg",
    "path": "cases/641991a196b5884858605afd/
compositionImg_r_1679510379141_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"percentage": "100",
"finalArea": "35.29"
},
{
  "name": {
    "label": "Passage",
    "value": "Passage"
  },
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "length1": "7",
  "length2": "0",
  "length": "7.00",
  "width1": "3",
  "width2": "7",
  "width": "3.58",
  "totalArea": "25.08",
  "percentageBeforeTotal": "25.08",
  "images": [
    {
      "name": "compositionImg_r_1679510417808_image.jpg",
      "path": "cases/641991a196b5884858605afd/
compositionImg_r_1679510417808_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "25.08"
```

```
}
],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "status": false,
    "_id": "641b4e0eee0c792c533baff1",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510916580_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533baff2",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510919899_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533baff3",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510918684_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533baff4",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510917013_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533baff5",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510924757_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533baff6",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510931216_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533baff7",
```

```
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510944715_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533baff8",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510937328_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533baff9",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510920365_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533baffa",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510927632_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533baffb",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510920856_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533baffc",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510931843_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533baffd",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510937163_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533baffe",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510943380_image.jpg"
  },
  {
```

```
    "status": false,
    "_id": "641b4e0eee0c792c533bafff",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510948367_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb000",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510954416_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb001",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510921186_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb002",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510928471_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb003",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510934116_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb004",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510922001_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb005",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510939871_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb006",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510946606_image.jpg"
  }
```

```
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb007",
  "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510953352_image.jpg"
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb008",
  "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510959774_image.jpg"
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb009",
  "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510922842_image.jpg"
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb00a",
  "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510933082_image.jpg"
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb00b",
  "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510939543_image.jpg"
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb00c",
  "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510925355_image.jpg"
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb00d",
  "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510947418_image.jpg"
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb00e",
```



```
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510954131_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb00f",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510959953_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb010",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510966926_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb011",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510924682_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb012",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510936822_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb013",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510943252_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb014",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510926989_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb015",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510949211_image.jpg"
  },
  {
```

```
    "status": false,
    "_id": "641b4e0eee0c792c533bb016",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510956145_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb017",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510973510_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb018",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510964539_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb019",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510951738_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb01a",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510954736_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb01b",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510965075_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb01c",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510960934_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb01d",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510970038_image.jpg"
```

```
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb01e",
  "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510974593_image.jpg"
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb01f",
  "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510987787_image.jpg"
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb020",
  "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510981582_image.jpg"
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb021",
  "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510961162_image.jpg"
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb022",
  "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510968615_image.jpg"
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb023",
  "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510962421_image.jpg"
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb024",
  "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510973903_image.jpg"
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb025",
```

```
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510979798_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb026",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510987417_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb027",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510998065_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb028",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510993511_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb029",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510967190_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb02a",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510978022_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb02b",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510983422_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb02c",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510970047_image.jpg"
  },
  {
```

```
    "status": false,
    "_id": "641b4e0eee0c792c533bb02d",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510988131_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb02e",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510994334_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb02f",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511000527_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb030",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511008717_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb031",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510924184_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb032",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510943151_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb033",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510927790_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb034",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510954649_image.jpg"
```

```
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb035",
  "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510964379_image.jpg"
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb036",
  "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510976205_image.jpg"
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb037",
  "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510987965_image.jpg"
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb038",
  "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511001479_image.jpg"
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb039",
  "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510973784_image.jpg"
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb03a",
  "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510984289_image.jpg"
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb03b",
  "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510990844_image.jpg"
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb03c",
```

```
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510976206_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb03d",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510996466_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb03e",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511003378_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb03f",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511009390_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb040",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511015548_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb041",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510982928_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb042",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510991720_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb043",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510997188_image.jpg"
  },
  {
```

```
    "status": false,
    "_id": "641b4e0eee0c792c533bb044",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510985218_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb045",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511004311_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb046",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511008358_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb047",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511021561_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb048",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511013883_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb049",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510995587_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb04a",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511003401_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb04b",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511007451_image.jpg"
```



```
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb04c",
  "path": "cases/641991a196b5884858605afd/
externallmg_r_1679510997881_image.jpg"
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb04d",
  "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511012733_image.jpg"
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb04e",
  "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511017983_image.jpg"
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb04f",
  "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511023405_image.jpg"
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb050",
  "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511027123_image.jpg"
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb051",
  "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511003590_image.jpg"
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb052",
  "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511012078_image.jpg"
},
{
  "status": false,
  "_id": "641b4e0eee0c792c533bb053",
```

```
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511015754_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb054",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511005336_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb055",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511021965_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb056",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511027673_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb057",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511031843_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb058",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511034764_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb059",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511015753_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb05a",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511018042_image.jpg"
  },
  {

```

```
    "status": false,
    "_id": "641b4e0eee0c792c533bb05b",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511024317_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb05c",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511026949_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb05d",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511031243_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb05e",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511032559_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb05f",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511035652_image.jpg"
  },
  {
    "status": false,
    "_id": "641b4e0eee0c792c533bb060",
    "path": "cases/641991a196b5884858605afd/
externallmg_r_1679511038271_image.jpg"
  }
],
"externalDocuments": [],
"createdAt": "2023-03-21T11:14:41.986Z",
"updatedAt": "2023-03-22T18:50:54.607Z",
"__v": 0,
"updatedBy": "627208c1afd7d55eddedc372",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 3 Toilet",
"carpetTotal": "551.5",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "69.33",
"siteVisitDate": "2023-03-23"
```

| Name | Length | Width | Total |
|------------------------|---------------|--------------|--------------|
| Composition : | | | |
| Living Room | 12'10" | 9'11" | 127.26 |
| Kitchen | 11'11" | 8'6" | 101.29 |
| Bedroom | 12'9" | 10'4" | 131.75 |
| Bedroom | 12'0" | 9'10" | 118.00 |
| Toilet | 7'3" | 3'6" | 25.37 |
| Toilet | 5'9" | 2'11" | 16.77 |
| Toilet | 8'8" | 3'7" | 31.06 |
| Other Composition : | | | |
| Cupboard | 3'7" | 2'6" | 8.96 |
| Passage | 6'5" | 5'6" | 35.29 |
| Passage | 7'0" | 3'7" | 25.08 |