#### PROFORMA INVOICE

Vastukala Consultants (I) Pvt Ltd Ackruti Star, 1st Floor, 121, Central Road, MIDC, Andheri (E), Mumbai - 400 093 GSTIN/UIN: 27AADCV4303R1ZX State Name: Maharashtra, Code: 27 E-Mail: accounts@vastukala.org

Buyer (Bill to)

STATE BANK OF INDIA- RASMECCC Panvel

RASMECCC Panvel

Sharda Terrace, Shop No 5, Ground Floor, Plot No 65, Sector-11, CBD Belapur GSTIN/UIN : 27AAACS8577K2ZO

State Name

: Maharashtra, Code: 27

Invoice No.	Dated		
PG-130/23-24	17-Apr-23		
Delivery Note	Mode/Terms of Payment		
	<b>AGAINST REPORT</b>		
Reference No. & Date.	Other References		
Buyer's Order No.	Dated		
Dispatch Doc No.	Delivery Note Date		
30652 / 2300132			
Dispatched through	Destination		

Terms of Delivery

SI No.	Particulars	HSN/SAC	GST Rate	Amount
1	STRUCTURAL REPORT FEE (Technical Inspection and Certification Services)  CGST SGST	997224	18 %	2,500.00 225.00 225.00
	Total	1		

Amount Chargeable (in words)

Indian Rupee Two Thousand Nine Hundred Fifty Only

HSN/SAC	Taxable	Central Tax		State Tax		Total
Value		Rate A	Amount	Rate	Amount	Tax Amount
997224	2,500.00	9%	225.00	9%	225.00	450.00
Total	2,500.00		225.00		225.00	450.00

Tax Amount (in words): Indian Rupee Four Hundred Fifty Only

Company's Bank Details

Bank Name : State Bank of India

A/c No. 32632562114

Branch & IFS Code: MIDC Andheri (E) & SBIN0007074

Remarks:

Mrs. Shabana Rafique Mukadam - Residential Flat No. 303, 3rd Floor, "Ramesh Paradise Co-op. Hsg. Soc. Ltd.", Plot No. 111, Sector - 27, Nerul, Navi Mumbai -400 706, Taluka & District - Thane, State -

Maharashtra, Country - India

Company's PAN

: AADCV4303R

NOTE - AS PER MSME RULES INVOICE NEED TO BE CLEARED WITHIN 45 DAYS OR INTEREST CHARGES APPLICABLE AS PER THE RULE. MSME Registration No. - 27222201137

UPI Virtual ID : vastukala@icici

for Vastukala Consultants (I) Pvt Ltd

Authorised Signatory

This is a Computer Generated Invoice



Vastukala Consultants (1) Pvt. Ltd.

An ISO 9001:2015 Certified Company www.vastukala.org



E. & O.E

CIN: U74120MH2010PTC207869 MSME Reg. No.: UDYAM-MH-18-0083617 An ISO 9001:2015 Certified Company





Structural Stability Report Prepared For: SBI / RASMECCC Panvel Branch / Mrs. Shabana Rafique Mukadam (30652/2300132) Page 1 of 3

Vastu/Mumbai/04/2023/30652/2300132 17/19-129-SBA Date: 17.04.2023

# **Structural Stability Report**

Structural Observation Report of Residential Flat No. 303, 3<sup>rd</sup> Floor, "Ramesh Paradise Co-op. Hsg. Soc. Ltd.", Plot No. 111, Sector – 27, Nerul, Navi Mumbai – 400 706, Taluka & District – Thane, State – Maharashtra, Country – India.

Name of Owners: Mrs. Shabana Rafique Mukadam

This is to certify that on visual inspection, it appears that the structure of the at "Ramesh Paradise Co-op. Hsg. Soc. Ltd." is in good condition and the future life can be reasonably takes under good condition and with proper periodic repairs & maintenance is about 44 years.

#### General Information:

A.	7	Introduction
1	Name of Building	"Ramesh Paradise Co-op. Hsg. Soc. Ltd."
2	Property Address	Residential Flat No. 303, 3rd Floor, "Ramesh Paradise
	1	Co-op. Hsg. Soc. Ltd.", Plot No. 111, Sector – 27, Nerul,
	11	Navi Mumbai – 400 706, Taluka & District – Thane, State
		<ul> <li>– Maharashtra, Country – India.</li> </ul>
3	Type of Building	Residential used
4	No. of Floors	(Part) Ground + (Part) Stilt + 4 Upper Floors
5	Whether stilt / podium / open parking	Open / Covered Car Parking
	provided	
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	2007 (As per occupancy certificate)
11	Present age of building	16 years
12	Residual age of the building	44 years Subject to proper, preventive periodic
		maintenance & structural repairs.
13	No. of flats (Per Floor)	4 Flats on 3 <sup>rd</sup> Floor
14	Methodology adopted	As per visual site inspection







B.	External Observation of the Building			
1	Plaster	Good Condition		
2	Chajjas	Good Condition		
3	Plumbing	Good Condition		
4	Cracks on the external walls	Not found		
5	Filling cracks on the external walls	Not found		
6	Cracks on columns & beams	Not found		
7	Vegetation	Not found		
8	Leakages of water in the drainage pipes or water pipes	Not found		
9	Dampness external in the wall due to leakages	Not found		
10	Any other observation about the condition of external side of the building	The external condition of the building is in good condition		
С	Internal Observation of the common areas of the building and captioned premises			
1	Beams (Cracks & Leakages)	Good Condition		
2	Columns (Cracks & Leakages)	Good Condition		
3	Ceiling (Cracks & Leakages)	Good Condition		
4	Leakages inside the property	Not found		
5	Painting inside the property	Good		
6	Maintenance of staircase & cracks	Good		

D	Common Observation			
1	Structural Audit of the Building Under Bye	As per bye Laws No. 77 of Co-Op. Societies bye Laws		
	- Laws No. 77 of the Model Bye Laws	under the Act the society shall conduct a Structural Audit		
	(Co-Operative Societies Act / Rules)	of the building of the society as follows		
2	Remark	No Structural Audit Report is furnished for the perusal		

### Conclusion

The captioned building is having (Part) Ground + (Part) Stilt + 4 Upper Floors which are constructed in year 2007 as per occupancy certificate. Estimated future life under present circumstances is about 44 years subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 26.03.2023 reveals no structural damage or deterioration to the building. The building as well as the property is maintained in good condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs. Our Observations about the structure are given above.

The above assessment is based on visual inspection only.

## For VASTUKALA CONSULTANTS (I) PVT. LTD.

Sharadkumar Chalakwar Chal

B. Chalikwar

4-Vestukala Consultants IR PM. Ltd.

9-CMD. email-conductival a pro. C

Date: 2023.CM.18.09.28.49 = 05.307

Auth, Sign

Sharadkumar B. Chalikwar

Govt. Reg. Valuer Chartered Engineer (India)

C.M.D.

Reg. No. (N) CCIT/1-14/52/2008-09

SBI Empanelment No.: SME/TCC/2021-22/85/13





# **Actual Site Photographs**

















