

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b80a"
    },
    "type": "CREDITOFFICER",
    "_id": "6417f02396b58848585ed0c0",
    "firstName": "Anmol Tiwari",
    "lastName": "Tiwari",
    "mobileNo": "",
    "workMobileNo": "7977031040",
    "email": ""
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "10000000",
    "discussWithPerson": "Anmol Tiwari",
    "expectedFees": 5000,
    "quotedAmount": "2500"
  },
  "organization": {
    "package": {
      "_id": "5fc0d7e47d6c8d39dc34a294",
      "title": "basic",
      "price": 5.1,
      "case": 20,

```

```
"duration": "300"
},
"status": true,
"isdelete": false,
"_id": "5f2bdee67813470eb443deb4",
"name": "Vastukala Consultants India Pvt. Ltd.",
"gstNo": "18AABCT3518Q1ZZ",
"panNo": "ABCDE1234A",
"freeCases": "10",
"email": "vastukalamumbai@vastukala.com",
"phone": "9819670183",
"address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai -
400 093",
"remark": "",
"theme": "DEFAULT",
"profilePhoto": "public\\images\
\\1606738172464_51041525c82381638d4d202735b1f05d.png",
"shortName": "VCIPL",
"waterMarkImage": [
  {
    "_id": "6423b6a26c6a0c53353054ee",
    "path": "public\\Vastukala Letter head H 2019.jpg",
    "pageNo": "2"
  }
],
"city": "Mumbai",
"stampImage": []
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b80a",
  "branchCode": "000088",
  "type": "BRANCH",
  "name": "RACPC - Chinchpokli (East)",
  "email": "sbi.17889@sbi.co.in",
  "mobileNo": "022-23707514",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, Mumbai South Voltas
```

House, 'A', 1st Floor, Dr. Ambedkar Road, Chinchpokli (East), Mumbai - 400 033, State - Maharashtra, Country - India.\r\n",

"ledgerName": "STATE BANK OF INDIA - CHINCHPOKALI",

"fax": "022-23707512 / 13",

"sendStructuralCertificate": "0"

},

"assetsClass": {

"value": "Land_&_Building_/_Immovable_Property",

"label": "Land & Building / Immovable Property"

},

"propertyType": {

"value": "Residential",

"label": "Residential"

},

"zone": {

"_id": "60e03dac6576061dae462469",

"zoneName": "Mumbai (Metro) & Maharashtra"

},

"staff": {

"pickupPerson": {

"type": "EMPLOYEE",

"_id": "60af3d172ffdf65bcd6585cd",

"role": "PICKUPPERSON",

"firstName": "Sachin",

"email": "sachin.joshi@vastukala.org",

"lastName": "Joshi",

"mobileNo": "9167204063",

"shortName": "SJ",

"workWithDocumentMaker": "",

"profilePhoto": "users\\60af3d172ffdf65bcd6585cd\\

profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"

},

"siteEngineer": {

"type": "EMPLOYEE",

"_id": "627208c1afd7d55eddedc372",

"role": "FRONTDESK",

"firstName": "Aniket",

"email": "Aniket@vastukala.org",

"lastName": "Navale",

"mobileNo": "9892222307",

"designation": "",

"shortName": "AN",

"workWithDocumentMaker": "",

"profilePhoto": "users/627208c1afd7d55eddedc372/

profilePhoto_1667995077581_WhatsApp_Image_20221109_at_52453_PM.jpeg"

},

```
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "CHECKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "63f313626f9c2254a9b35ba2",
  "role": "MAKER",
  "firstName": "Girish",
  "email": "agregirish@gmail.com",
  "lastName": "Agre",
  "mobileNo": "9082114817",
  "designation": "Technical Officer",
  "shortName": "GA",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f313626f9c2254a9b35ba2/
profilePhoto_1676874632701_WhatsApp_Image_20230220_at_115708_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "CHECKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
```

```
    "value": "IBBI/RV/07/2018/10366",
    "label": "Registered Valuer"
  }
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
```

```
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "0",
  "longitude": "0"
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-03-29T03:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-03-29T03:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-03T07:26:09.058Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-04-03T07:26:09.058Z"
    }
  ]
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Wed Mar 29 2023 10:00:01 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
```

```
"status": true,
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "14",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "7",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
```

```
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Neelyog Virat",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Khotkuwa",
  "label": false
},
"street2": {
  "status": true,
```



```
"name": "Street 2",
"key": "street2",
"value": "WEH",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
}
```

```
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1403",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
```

```
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Malad West",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "VerifiedTileFlooring"
  },
  "doors": {
    "label": "Teak Wood",
    "value": "TeakWood"
  },
}
```

```
"windows": {
  "label": "Alluminum sliding windows with M. S. Grills",
  "value": "Alluminum_sliding_windows_with_M._S._Grills"
},
"fittings": {
  "label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring",
  "value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring"
},
"finishing": {
  "label": "Cement Plastering + POP Finish",
  "value": "Cement_Plastering_+_POP_Finish"
}
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Municipal Corporation of Greater Mumbai (MCGM)",
    "value": "MCGM"
  },
  "asPerActualAgreement": {
    "north": "B Wing",
    "west": "SRA Building",
    "south": "Building No 10",
    "east": "Western Express Highway"
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  }
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
```

```
"value": "Residential_Purpose"
},
"propertyOccupiedByList": {
  "label": "Owner Occupied",
  "value": "Owner_Occupied"
},
"monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MuncipalWaterSupply"
  },
  "pavementLaid": {
    "label": "Proposed, Yes",
    "value": "Proposed,_Yes"
  },
  "carParking": {
    "label": "Proposed Basement Car Parking",
    "value": "Proposed_Basement_Car_Parking"
  },
  "constructionWorkStatus": {
    "label": "Completed",
    "value": "Completed"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2022",
    "fullDate": "1/1/2022"
  },
  "propertyTypeList": {
    "value": "Residential",
    "label": "Residential"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "label": "R.C.C. Framed Structure",
    "value": "R.C.C._Framed_Structure"
  }
}
```

```
},
"qualityOfConstruction": {
  "label": "Good",
  "value": "Good"
},
"walls": {
  "label": "PROPOSED, Yes",
  "value": "PROPOSED,_Yes"
},
"appearanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"maintenanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Stilt",
  "value": "stilt"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "59",
"ageOfBuilding": "1",
"noOfBasement": "2",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "22",
"flatFloorNo": "",
"noOfLifts": "3",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "7"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "locationMapImg": []
},
"outward": {
  "status": false,
```

```
"remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
```



```
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
```

```
},
"createCase": "false",
"type": "CASE",
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"_id": "6423b6a26c6a0c53353054ed",
"ownerName": "Jaydipkumar Ravariya",
"ownerPhoneNo": "0000000000",
"appAddress": "Flat no 1403 14floor Bldg no7 Neelyog Virat Malad East ",
"remark": "Cont Atul Minakshi +91 89286 68903",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/6423b6a26c6a0c53353054ed/
document_1680062075133_Atul_Agriment_compressed.pdf",
    "fileName": "document_1680062075133_Atul_Agriment_compressed.pdf",
    "displayStatus": false,
    "id": "972189",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Wed Mar 29 2023 09:25:10 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "000971",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "460154",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Mar 29 2023 09:25:14 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Jaydipkumar Ravariya",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "898046"
```

```
}
],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Other",
      "value": "Other"
    },
    "_id": "642a7f9591d7c62df117c802",
    "area": "538.56",
    "providedByName": "Site Measurement ",
    "providedByContactNo": "0000000000"
  }
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "789275",
    "name": "Living Room",
    "length": "17.83",
    "length1": "17",
    "length2": "10",
    "width": "10.42",
    "width1": "10",
    "width2": "5",
    "totalArea": "185.76",
    "images": [
      {
        "path": "cases/6423b6a26c6a0c53353054ed/
compositionImg_r_1680506206469_image.jpg",
        "orientation": "portrait"
      }
    ]
  },
  {
    "extraAreas": [],
    "finalArea": "185.76"
  },
  {
    "measurementType": {
      "label": "Square Feet",
```

```
    "value": "Square_Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "9.83",
  "length1": "9",
  "length2": "10",
  "width": "6.92",
  "width1": "6",
  "width2": "11",
  "totalArea": "68.01",
  "images": [
    {
      "path": "cases/6423b6a26c6a0c53353054ed/
compositionImg_r_1680506279609_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "68.01"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "11.75",
  "length1": "11",
  "length2": "9",
  "width": "10.42",
  "width1": "10",
  "width2": "5",
  "totalArea": "122.40",
  "images": [
    {
      "path": "cases/6423b6a26c6a0c53353054ed/
compositionImg_r_1680506329881_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "122.40"
},
{
```

```
"measurementType": {
  "label": "Square Feet",
  "value": "Square_Feet"
},
"id": "3",
"name": "Bedroom",
"length": "9.33",
"length1": "9",
"length2": "4",
"width": "8.67",
"width1": "8",
"width2": "8",
"totalArea": "80.89",
"images": [
  {
    "path": "cases/6423b6a26c6a0c53353054ed/
compositionImg_r_1680506526971_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "80.89"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "6.83",
  "length1": "6",
  "length2": "10",
  "width": "4.33",
  "width1": "4",
  "width2": "4",
  "totalArea": "29.61",
  "images": [
    {
      "path": "cases/6423b6a26c6a0c53353054ed/
compositionImg_r_1680506610654_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "29.61"
```

```
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "6.33",
  "length1": "6",
  "length2": "4",
  "width": "4.33",
  "width1": "4",
  "width2": "4",
  "totalArea": "27.44",
  "images": [
    {
      "path": "cases/6423b6a26c6a0c53353054ed/
compositionImg_r_1680506713215_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "27.44"
}
],
"otherComposition": [
  {
    "name": {
      "label": "Passage",
      "value": "Passage"
    },
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "0",
    "length1": "4",
    "length2": "5",
    "length": "4.42",
    "width1": "3",
    "width2": "1",
    "width": "3.08",
    "totalArea": "13.62",
    "percentageBeforeTotal": "13.62",
    "images": [
```

```
{
  "path": "cases/6423b6a26c6a0c53353054ed/
compositionImg_r_1680506429579_image.jpg",
  "orientation": "portrait"
}
],
"extraAreas": [],
"percentage": "100",
"finalArea": "13.62"
},
{
  "name": {
    "label": "Passage",
    "value": "Passage"
  },
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "length1": "4",
  "length2": "5",
  "length": "4.42",
  "width1": "3",
  "width2": "6",
  "width": "3.50",
  "totalArea": "15.46",
  "percentageBeforeTotal": "15.46",
  "images": [
    {
      "path": "cases/6423b6a26c6a0c53353054ed/
compositionImg_r_1680506476499_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "15.46"
}
],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "642a801791d7c62df117c84d",
    "name": "externallmg_r_1680506890748_image.jpg",
    "path": "cases/6423b6a26c6a0c53353054ed/
externallmg_r_1680506890748_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "642a801791d7c62df117c84e",
    "name": "externallmg_r_1680506890132_image.jpg",
    "path": "cases/6423b6a26c6a0c53353054ed/
externallmg_r_1680506890132_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "642a801791d7c62df117c84f",
    "name": "externallmg_r_1680506889440_image.jpg",
    "path": "cases/6423b6a26c6a0c53353054ed/
externallmg_r_1680506889440_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "642a801791d7c62df117c850",
    "name": "externallmg_r_1680506889746_image.jpg",
    "path": "cases/6423b6a26c6a0c53353054ed/
externallmg_r_1680506889746_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "642a801791d7c62df117c851",
    "name": "externallmg_r_1680506891651_image.jpg",
    "path": "cases/6423b6a26c6a0c53353054ed/
externallmg_r_1680506891651_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "642a801791d7c62df117c852",
  "name": "externalimg_r_1680506891366_image.jpg",
  "path": "cases/6423b6a26c6a0c53353054ed/
externalimg_r_1680506891366_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "642a801791d7c62df117c853",
  "name": "externalimg_r_1680506891038_image.jpg",
  "path": "cases/6423b6a26c6a0c53353054ed/
externalimg_r_1680506891038_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "642a801791d7c62df117c854",
  "name": "externalimg_r_1680506891881_image.jpg",
  "path": "cases/6423b6a26c6a0c53353054ed/
externalimg_r_1680506891881_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "642a801791d7c62df117c855",
  "name": "externalimg_r_1680506892076_image.jpg",
  "path": "cases/6423b6a26c6a0c53353054ed/
externalimg_r_1680506892076_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "642a801791d7c62df117c856",
  "name": "externalimg_r_1680506894474_image.jpg",
  "path": "cases/6423b6a26c6a0c53353054ed/
externalimg_r_1680506894474_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "642a801791d7c62df117c857",
    "name": "externallmg_r_1680506893412_image.jpg",
    "path": "cases/6423b6a26c6a0c53353054ed/
externallmg_r_1680506893412_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "642a801791d7c62df117c858",
    "name": "externallmg_r_1680506894106_image.jpg",
    "path": "cases/6423b6a26c6a0c53353054ed/
externallmg_r_1680506894106_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "642a801791d7c62df117c859",
    "name": "externallmg_r_1680506893719_image.jpg",
    "path": "cases/6423b6a26c6a0c53353054ed/
externallmg_r_1680506893719_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "642a801791d7c62df117c85a",
    "name": "externallmg_r_1680506895606_image.jpg",
    "path": "cases/6423b6a26c6a0c53353054ed/
externallmg_r_1680506895606_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "642a801791d7c62df117c85b",
    "name": "externallmg_r_1680506895376_image.jpg",
    "path": "cases/6423b6a26c6a0c53353054ed/
externallmg_r_1680506895376_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "642a801791d7c62df117c85c",
```

```
    "name": "externallmg_r_1680506895096_image.jpg",
    "path": "cases/6423b6a26c6a0c53353054ed/
externallmg_r_1680506895096_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "642a801791d7c62df117c85d",
    "name": "externallmg_r_1680506894784_image.jpg",
    "path": "cases/6423b6a26c6a0c53353054ed/
externallmg_r_1680506894784_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "642a801791d7c62df117c85e",
    "name": "externallmg_r_1680506895812_image.jpg",
    "path": "cases/6423b6a26c6a0c53353054ed/
externallmg_r_1680506895812_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "642a801791d7c62df117c85f",
    "name": "externallmg_r_1680506895679_image.jpg",
    "path": "cases/6423b6a26c6a0c53353054ed/
externallmg_r_1680506895679_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "642a801791d7c62df117c860",
    "name": "externallmg_r_1680506898689_image.jpg",
    "path": "cases/6423b6a26c6a0c53353054ed/
externallmg_r_1680506898689_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "642a801791d7c62df117c861",
    "name": "externallmg_r_1680506897419_image.jpg",
```

```
    "path": "cases/6423b6a26c6a0c53353054ed/
externallmg_r_1680506897419_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "642a801791d7c62df117c862",
    "name": "externallmg_r_1680506898132_image.jpg",
    "path": "cases/6423b6a26c6a0c53353054ed/
externallmg_r_1680506898132_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "642a801791d7c62df117c863",
    "name": "externallmg_r_1680506899149_image.jpg",
    "path": "cases/6423b6a26c6a0c53353054ed/
externallmg_r_1680506899149_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "642a801791d7c62df117c864",
    "name": "externallmg_r_1680506899804_image.jpg",
    "path": "cases/6423b6a26c6a0c53353054ed/
externallmg_r_1680506899804_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "642a801791d7c62df117c865",
    "name": "externallmg_r_1680506900630_image.jpg",
    "path": "cases/6423b6a26c6a0c53353054ed/
externallmg_r_1680506900630_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "642a801791d7c62df117c866",
    "name": "externallmg_r_1680506900230_image.jpg",
    "path": "cases/6423b6a26c6a0c53353054ed/
externallmg_r_1680506900230_image.jpg",
```

```

    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "642a801791d7c62df117c867",
    "name": "externalImg_r_1680506900967_image.jpg",
    "path": "cases/6423b6a26c6a0c53353054ed/
externalImg_r_1680506900967_image.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-03-29T03:55:14.398Z",
"updatedAt": "2023-04-03T07:28:31.786Z",
"__v": 0,
"fullAddress": "Residential Flat No. 1403, 14th Floor, Building No 7, Neelyog Virat,
Khotkuwa, WEH, Malad West, Mumbai, State - Maharashtra, India",
"updatedBy": "627208c1afd7d55eddedc372",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Jaydipkumar Ravariya",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "0000000000",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Toilet",
"carpetTotal": "514.11",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "29.08",
"siteVisitDate": "2023-04-03"
}

```

Name	Length	Width	Total
Composition :			
Living Room	17'10"	10'5"	185.76
Kitchen	9'10"	6'11"	68.01
Bedroom	11'9"	10'5"	122.40
Bedroom	9'4"	8'8"	80.89

Toilet	6'10"	4'4"	29.61
Toilet	6'4"	4'4"	27.44
Other Composition :			
Passage	4'5"	3'1"	13.62
Passage	4'5"	3'6"	15.46