

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b80a"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230ec0",
    "firstName": "Anuj Mehrotra",
    "email": "0_DEFAULT_a_mehrotra@sbi.co.in",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-9987527007"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "19500000",
    "discussWithPerson": "Dineshkumar Mishra",
    "expectedFees": 9750,
    "quotedAmount": "5900"
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "vastukalamumbai@vastukala.com",
    "phone": "9819670183",
    "address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai - 400 093",
```

```
  "profilePhoto": "public\\images\\
\\1606738172464_51041525c82381638d4d202735b1f05d.png",
  "shortName": "VCIPL",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b80a",
  "branchCode": "000088",
  "type": "BRANCH",
  "name": "RACPC - Chinchpokli (East)",
  "email": "sbi.17889@sbi.co.in",
  "mobileNo": "022-23707514",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, Mumbai South Voltas
House, 'A', 1st Floor, Dr. Ambedkar Road, Chinchpokli (East), Mumbai - 400 033, State
- Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - CHINCHPOKALI",
  "fax": "022-23707512 / 13",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land & Building / Immovable Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62727444afd7d55eddee092c",
    "role": "PICKUPPERSON",
```

```
"firstName": "Shantilal",
"email": "shantilal@vastukala.org",
"lastName": "Patel",
"mobileNo": "9969039853",
"shortName": "SHP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "627208c1afd7d55eddedc372",
"role": "FRONTDESK",
"firstName": "Aniket",
"email": "Aniket@vastukala.org",
"lastName": "Navale",
"mobileNo": "9892222307",
"designation": "",
"shortName": "AN",
"workWithDocumentMaker": "",
"profilePhoto": "users/627208c1afd7d55eddedc372/
profilePhoto_1667995077581_WhatsApp_Image_20221109_at_52453_PM.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60092304a16fab0f2af9b0c2",
"role": "MAKER+CHECKER",
"firstName": "Nitesh",
"email": "nitesh.khedekar@vastukala.org",
"lastName": "Khedekar",
"mobileNo": "8369040652",
"designation": "",
"shortName": "NK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60092304a16fab0f2af9b0c2\
\profilePhoto_1622372532348_Nitesh Khedekar Photo (2).jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60092304a16fab0f2af9b0c2",
"role": "MAKER+CHECKER",
"firstName": "Nitesh",
"email": "nitesh.khedekar@vastukala.org",
"lastName": "Khedekar",
"mobileNo": "8369040652",
"designation": "",
```

```

    "shortName": "NK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60092304a16fab0f2af9b0c2\
\profilePhoto_1622372532348_Nitesh Khedekar Photo (2).jpg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "627221f4afd7d55eddeddcb4",
    "role": "MAKER",
    "firstName": "Prajakta",
    "email": "prajakta@vastukala.org",
    "lastName": "Patil",
    "mobileNo": "9769797568",
    "designation": "",
    "shortName": "P",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "[N]C.C.I.T/I -14/52/2008-09",
          "label": "Wealth Tax"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "6084131a13f01f158c6ea1f3",
      "PANNo": "AEAPC7114Q",
      "role": "VALUER",
      "firstName": "Sharadkumar",
      "fatherName": "Baburao",
      "email": "cmd@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9422171100",
      "designation": "CMD",
      "registrationNo": [
        {
          "title": {
            "value": "Wealth_Tax",
            "label": "Wealth Tax"
          },
          "_id": "6084131a13f01f158c6ea1f4",
          "number": "[N]C.C.I.T/I -14/52/2008-09"
        }
      ]
    }
  ]
}

```

```
    ],
    "shortName": "SBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
  }
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.198063411500495",
  "longitude": "72.83687786693422"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.83687786693422,
    19.198063411500495
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-04-10T11:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-10T11:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-17T07:07:27.964Z",
      "remark": ""
    }
  ]
},
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2023-04-17T07:07:27.964Z"
  }
]
},
```

```
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Mon Apr 10 2023 17:25:47 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Valnai",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "10",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
    "value": ""
  }
}
```

```
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shreeji Plaza",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
```

```
"name": "Street 1",
"key": "street1",
"value": "Orlem",
"label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Gautam Buddha Marg",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
}
```



```
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1002",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
```

```
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Malad West",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "Proposed R.C.C. Slab",
    "value": "Proposed_R.C.C._Slab"
  },
  "flooring": {
```

```
"label": "Proposed Vitrified tiles flooring",
"value": "Proposed_Vitrified_tiles_flooring"
},
"doors": {
  "label": "Proposed Teak wood door frame with flush doors",
  "value": "Proposed_Teak_wood_door_frame_with_flush_doors"
},
"windows": {
  "label": "Proposed Powder coated aluminium sliding windows",
  "value": "Proposed_Powder_coated_aluminium_sliding_windows"
},
"fixtures": {
  "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring
with Concealed.",
  "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_w
iring_with_Concealed."
},
"finishing": {
  "label": "Proposed Cement Plastering",
  "value": "Proposed_Cement_Plastering"
}
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Municipal Corporation of Greater Mumbai (MCGM)",
    "value": "MCGM"
  },
  "asPerActualAgreement": {
    "north": "Slums",
    "west": "Road / SRA Building ",
    "south": "Shreeji Aspire ",
    "east": "Slums"
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  }
}
```

```
}
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  },
  "pavementLaid": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  },
  "carParking": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  },
  "constructionWorkStatus": {
    "label": "Under Construction",
    "value": "InProgress"
  },
  "dateOfConstruction": {
    "date": "",
    "month": "1",
    "year": "2028",
    "fullDate": "1/1/2028"
  },
  "propertyTypeList": {
    "value": "Residential",
```

```
"label": "Residential"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"qualityOfConstruction": {
  "label": "Building Under Construction",
  "value": "UnderConstruction"
},
"walls": {
  "label": "Building Under Construction",
  "value": "Building_Under_Construction"
},
"appearanceOfTheBuilding": {
  "label": "Building Under Construction",
  "value": "UnderConstruction"
},
"maintenanceOfTheBuilding": {
  "label": "Building Under Construction",
  "value": "UnderConstruction"
},
"visibleDamageInBuilding": {
  "label": "Building Under Construction",
  "value": "Building_Under_Construction"
},
"groundStilt": {
  "label": "Part Ground + Part Stilt",
  "value": "Part_Ground_and_Part_Stilt"
},
"isSiteVisitAllowed": false,
"totalLifeBuilding": "",
"estimatedAge": "",
"ageOfBuilding": "",
"noOfBasement": "0",
"noOfPodium": "4",
"noOfAmenityFloors": "0",
"noOfFloors": "38",
"flatFloorNo": "",
"noOfLifts": "4",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "6"
```

```
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "type": "Point",
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "2",
    "percentage": "1.82",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  }
}
```

```
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "11.82",
  "isHideFloor": true,
  "status": true
}
```



```
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"createCase": "false",
"type": "CASE",
"isSiteMeasurementAllowed": false,
"finalValuationArea": "0",
"empanelmentNo": [],
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"_id": "6433eb8ea99b2228209c633c",
"ownerName": "Melita Mark Martis ",
"ownerPhoneNo": "8451956184",
"appAddress": "shreeji plaza 10 th floor 1002 B wing Orlam Malad West ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1246aa6d152c1801b2e4",
      "label": "Index- II"
    },
    "inputs": {
      "documentDate": "06/02/2023",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "M/s Siddharh Devlopers",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Melita Mark Martis ",
      "number": {
        "value": "Document_No",
```

```
    "label": "Document No"
  },
  "Document_No": "2363"
},
"isHardCopy": false,
"displayStatus": false,
"path": "cases/6433eb8ea99b2228209c633c/document_undefined",
"id": "848165",
"uploadedBy": "6006d4ce5080a310ac1fd2",
"createdAt": "Mon Apr 10 2023 17:25:29 GMT+0530 (India Standard Time)",
"fileName": "document_undefined"
}
],
"caseNumber": "001065",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "850856",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Apr 10 2023 16:27:18 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Melita Mark Martis ",
    "phone": "8451956184",
    "ownershipShare": "",
    "email": "",
    "id": "643005"
  }
],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "643cd1c533d16f6b12382ce7",
    "name": "externalimg_r_1681707454512_image.jpg",
    "path": "cases/6433eb8ea99b2228209c633c/
externalimg_r_1681707454512_image.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "643cd1c533d16f6b12382ce8",
  "name": "externallmg_r_1681707454841_image.jpg",
  "path": "cases/6433eb8ea99b2228209c633c/
externallmg_r_1681707454841_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "643cd1c533d16f6b12382ce9",
  "name": "externallmg_r_1681707455125_image.jpg",
  "path": "cases/6433eb8ea99b2228209c633c/
externallmg_r_1681707455125_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "643cd1c533d16f6b12382cea",
  "name": "externallmg_r_1681707455404_image.jpg",
  "path": "cases/6433eb8ea99b2228209c633c/
externallmg_r_1681707455404_image.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "643cd1c533d16f6b12382ceb",
  "name": "externallmg_r_1681707456798_image.jpg",
  "path": "cases/6433eb8ea99b2228209c633c/
externallmg_r_1681707456798_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "643cd1c533d16f6b12382cec",
  "name": "externallmg_r_1681707455680_image.jpg",
  "path": "cases/6433eb8ea99b2228209c633c/
externallmg_r_1681707455680_image.jpg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "643cd1c533d16f6b12382ced",
      "name": "externalimg_r_1681707455975_image.jpg",
      "path": "cases/6433eb8ea99b2228209c633c/
externalimg_r_1681707455975_image.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "643cd1c533d16f6b12382cee",
      "name": "externalimg_r_1681707456360_image.jpg",
      "path": "cases/6433eb8ea99b2228209c633c/
externalimg_r_1681707456360_image.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "643cd1c533d16f6b12382cef",
      "name": "externalimg_r_1681707457008_image.jpg",
      "path": "cases/6433eb8ea99b2228209c633c/
externalimg_r_1681707457008_image.jpg",
      "orientation": "portrait"
    }
  ],
  "externalDocuments": [],
  "createdAt": "2023-04-10T10:57:18.802Z",
  "updatedAt": "2023-04-17T07:09:52.242Z",
  "__v": 0,
  "fullAddress": "Residential Flat No. 1002, 10th Floor, Wing - B, Shreeji Plaza, Orlem,
Gautam Buddha Marg, Village - Valnai, Malad West, Mumbai, State - Maharashtra,
India",
  "updatedBy": "627208c1afd7d55eddedc372",
  "addressForMap": "",
  "caseReferredBy": "62727444afd7d55eddee092c",
  "contactPersonName": "Melita Mark Martis ",
  "email": "",
  "isExternal": "false",
  "isUrgent": "false",
  "ownershipShare": "",
  "purchaseValueAsPerDocument": "",
  "relationWithOwner": "self",
```

"siteVisitContactNo": "8451956184",
"briefDescOfProperty": "",
"carpetTotal": "0",
"finalMeasurementType": "",
"otherCarpetTotal": "0",
"siteVisitDate": "2023-04-17"

}

Name	Length	Width	Total
-------------	---------------	--------------	--------------

Composition :

Other

Composition :
