

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f9"
    },
    "type": "CREDITOFFICER",
    "_id": "640ace424dda382753e5057d",
    "firstName": "Rajeev kumar Ranjan",
    "lastName": "Ranjan",
    "mobileNo": "",
    "workMobileNo": "9967159553",
    "email": "rajeevrapc.borivali@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "960000",
    "discussWithPerson": "Rajeev kumar Ranjan",
    "expectedFees": 480,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "vastukalamumbai@vastukala.com",
    "phone": "9819670183",
    "address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai -
```

```
400 093",
  "profilePhoto": "public\\images\\
\\1606738172464_51041525c82381638d4d202735b1f05d.png",
  "shortName": "VCIPL",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f9",
  "branchCode": "000066",
  "type": "BRANCH",
  "name": "RACPC Borivali (West) Branch",
  "email": "racpc.borivali@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "MTNL Building, Devidas Road, Borivali (West), Mumbai, State -
Maharashtra, Country - India. ",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
    "role": "PICKUPPERSON",
```

```
"firstName": "Sunil",
"email": "misalsunil87@gmail.com",
"lastName": "Misal",
"mobileNo": "8422982721",
"shortName": "SM",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af6ae22ffdf65bcd65861d\
\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "627208c1afd7d55eddedc372",
"role": "FRONTDESK",
"firstName": "Aniket",
"email": "aniket@vastukala.org",
"lastName": "Navale",
"mobileNo": "9892222307",
"designation": "",
"shortName": "AN",
"workWithDocumentMaker": "",
"profilePhoto": "users/627208c1afd7d55eddedc372/
profilePhoto_1667995077581_WhatsApp_Image_20221109_at_52453_PM.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER+CHECKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "642bad2b91d7c62df117fef2",
"role": "MAKER",
"firstName": "Abhishek",
"email": "abhishekharijan@gmail.com",
"lastName": "Harijan",
"mobileNo": "8369839430",
"designation": ""
```

```
"shortName": "AH",
"workWithDocumentMaker": "60eeaeddf3dd69653a581316"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER+CHECKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyam_Photo.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "6084131a13f01f158c6ea1f3",
    "PANNo": "AEAPC7114Q",
    "role": "VALUER",
    "firstName": "Sharadkumar",
    "fatherName": "Baburao",
    "email": "cmd@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9422171100",
    "designation": "CMD",
    "registrationNo": [
      {
        "title": {
          "value": "Wealth_Tax",
          "label": "Wealth Tax"
        },
        "_id": "6084131a13f01f158c6ea1f4",
        "number": "[N]C.C.I.T/I -14/52/2008-09"
      }
    ],
    "shortName": "SBC",
```

```
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
  }
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.213778",
  "longitude": "72.877437"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.877437,
    19.213778
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-04-12T04:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-12T10:01:27.799Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-12T10:02:15.783Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-12T10:02:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-12T10:02:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-12T10:02:00.000Z",

```

```
"remark": ""
},
{
  "dateTime": "2023-04-12T10:02:00.000Z",
  "remark": ""
},
{
  "dateTime": "2023-04-12T10:02:00.000Z",
  "remark": ""
},
{
  "dateTime": "2023-04-12T10:02:00.000Z",
  "remark": ""
}
],
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2023-04-12T10:01:27.799Z"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2023-04-12T10:02:15.783Z"
  },
  {
    "remark": "MANUAL",
    "status": "COMPLETED",
    "dateTime": "2023-04-11T07:30:00.000Z"
  },
  {
    "remark": "MANUAL",
    "status": "COMPLETED",
    "dateTime": "2023-04-11T18:30:00.000Z"
  },
  {
    "remark": "MANUAL",
    "status": "COMPLETED",
    "dateTime": "2023-04-11T18:30:00.000Z"
  },
  {
    "remark": "MANUAL",
    "status": "COMPLETED",
    "dateTime": "2023-04-12T07:00:00.000Z"
  }
]
},
```

```
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Wed Apr 12 2023 10:40:01 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Thakur",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "1",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "2",
    "label": true
  },
  "district": {
```

```
"status": true,
"name": "District",
"key": "district",
"value": "Mumbai",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Aster Co-op. Hsg. Soc. Ltd., Valley of Flowers",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
```



```
"label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Opp. Balasaheb Thakrey Udyan",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
```

```
"name": "New/Current Survey No.",
"key": "newSurveyNumber",
"value": "",
"label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "809/A/1/11 to 13 & 15 to 18",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "103",
  "label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "R/S",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
}
```

```
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 101",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
```

```
"label": "R. C. C. Slab",
"value": "rcc_Slab"
},
"flooring": {
"label": "Vitrified Tile Flooring",
"value": "VerifiedTileFlooring"
},
"doors": {
"value": "Teak_Wood_Door_frame_with_Solid_flush_door",
"label": "Teak Wood Door frame with Solid flush door"
},
"windows": {
"value": "Proposed_Powder_coated_aluminium_sliding_windows",
"label": "Proposed Powder coated aluminium sliding windows"
},
"fittings": {
"label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring",
"value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring"
},
"finishing": {
"label": "Cement Plastering + POP Finish",
"value": "Cement_Plastering_+_POP_Finish"
}
},
"general": {
"ownership": {
"value": "Sole_Ownership",
"label": "Sole Ownership"
},
"populationClassList": {
"label": "Middle Class",
"value": "MiddleClass"
},
"populationGroupList": {
"label": "Urban",
"value": "Urban"
},
"townplanApprovedByList": {
"label": "Municipal Corporation of Greater Mumbai (MCGM)",
"value": "MCGM"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
```

```

    "north": "BMC School",
    "west": "Gardenia CHSL",
    "south": "B Wing",
    "east": "Thakur Village Road"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "extraDetailOfProperty": ""
},
"compositeRate": {
  "remark": "All the above areas are within +/- 10% of the Agreement for Sale Area.
The above calculations and detail measurements taken by us prove that the Agreement
for Sale are is not exorbitantly inflated. Hence, valuation is based on the Agreement for
Sale area.",
  "depreciationPercentage": "30",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "24690",
  "depreciatedBuildingRate": "1890"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "176080",
  "landRate": "82130",
  "igrImage": "cases/643613a5a99b2228209df094/igr_1681455582352_Image.png",
  "squareMeterGuideLineRate": "176080.00",
  "squareFeetGuideLineRate": "16358.00"
},
"igrFinalRate": {
  "rate": "14613.00",
  "squareFeetGuideLineRate": "14613.00",
  "squareMeterGuideLineRate": "157290.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  }
},

```

```
"propertyOccupiedByList": {
  "value": "Vacant",
  "label": "Vacant"
},
"monthlyRent": "23000",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Located in developed area",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "Details not available",
  "negativeFactorsOfAffectMarketValue": "Details not available"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  },
  "pavementLaid": {
    "label": "Yes",
    "value": "Yes"
  },
  "carParking": {
    "label": "Stilt + Open Car Parking",
    "value": "Stilt+_Open_Car_Parking"
  },
  "constructionWorkStatus": {
    "value": "Completed",
```

```
"label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2003",
  "fullDate": "1/1/2003"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
```

```
"label": "Connected to Municipal Sewerage System"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "20",
"totalLifeBuilding": "60",
"estimatedAge": "40",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "8",
```



```
"flatFloorNo": "1",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "546.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "railway_station",
      "label": "railway station"
    },
    "routeMapImg": "cases/643613a5a99b2228209df094/
routeMap_1681298659255_Image.png",
    "routeLat": "19.213778",
    "routeLng": "72.877437",
    "stationName": "Kandivali",
    "routeDistance": "5.4 Kms"
  },
  "finalLatLng": {
    "coordinates": [
      0,
      0
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "juriaj",
      "name": "juriaj",
      "image": "cases/643613a5a99b2228209df094/
routeMap_1681298533650_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
```

```
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "11233950.00",
"bookValue": "0",
"finalValue": "11233950.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEM_GENERATED",
  "date": "Fri Apr 14 2023 12:32:05 GMT+0530 (India Standard Time)",
  "number": "046357",
  "dayCount": "9",
  "monthCount": "258",
  "generatedBy": "60eeaeddf3dd69653a581316"
},
"rateVerify": {
  "user": {
    "_id": "60eeaeddf3dd69653a581316",
    "firstName": "Shyam",
    "lastName": "Kajvilkar"
  },
  "status": false,
  "dateTime": "Sat Apr 15 2023 10:42:03 GMT+0530 (India Standard Time)"
},
```

```
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "7978698.00",
  "selectedBuildUpValue": "546.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "643681f8e4256a03ecde8910",
      "name": "externalImg_r_1681293791531_image.jpg",
      "path": "cases/643613a5a99b2228209df094/
externalImg_r_1681293791531_image.jpg",
      "orientation": "portrait"
    }
  ]
},
"selfieWithSiteVisitImages": [
```

```
{
  "status": false,
  "_id": "643681f8e4256a03ecde8914",
  "name": "externalImg_r_1681293794592_image.jpg",
  "path": "cases/643613a5a99b2228209df094/
externalImg_r_1681293794592_image.jpg",
  "orientation": "portrait"
}
],
"externalPhotos": [
  {
    "status": false,
    "_id": "643681f8e4256a03ecde8913",
    "name": "externalImg_r_1681293790195_image.jpg",
    "path": "cases/643613a5a99b2228209df094/
externalImg_r_1681293790195_image.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [
  {
    "status": false,
    "_id": "643681f8e4256a03ecde8916",
    "name": "externalImg_r_1681293792462_image.jpg",
    "path": "cases/643613a5a99b2228209df094/
externalImg_r_1681293792462_image.jpg",
    "orientation": "portrait"
  }
],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "64369568e4256a03ecdec1a7",
    "path": "cases/643613a5a99b2228209df094/
compositionImg_r_1681292547015_image.jpg",
    "orientation": "portrait",
    "name": "Living Room"
  },
  {
    "status": false,
    "_id": "64369568e4256a03ecdec1a8",
    "path": "cases/643613a5a99b2228209df094/
compositionImg_r_1681292631115_image.jpg",
    "orientation": "portrait",
    "name": "Dining"
  }
]
```

```
    },
    {
      "status": false,
      "_id": "64369568e4256a03ecdec1a9",
      "path": "cases/643613a5a99b2228209df094/
compositionImg_r_1681292747868_image.jpg",
      "orientation": "portrait",
      "name": "Kitchen"
    },
    {
      "status": false,
      "_id": "64369568e4256a03ecdec1aa",
      "path": "cases/643613a5a99b2228209df094/
compositionImg_r_1681292875042_image.jpg",
      "orientation": "portrait",
      "name": "Balcony Area"
    },
    {
      "status": false,
      "_id": "64369568e4256a03ecdec1ac",
      "path": "cases/643613a5a99b2228209df094/
compositionImg_r_1681293345066_image.jpg",
      "orientation": "portrait",
      "name": "Bedroom"
    },
    {
      "status": false,
      "_id": "643927d68989760c1fb750a0",
      "path": "cases/643613a5a99b2228209df094/
compositionImg_r_1681292993321_image.jpg",
      "orientation": "portrait",
      "name": "Passage"
    }
  ]
},
"taskStatus": {
  "DOCUMENT_VERIFY": false,
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
```

```
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "455.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86A/3"
],
"status": true,
"caseStatus": "DELIVERED",
"_id": "643613a5a99b2228209df094",
"ownerName": "Ms. Savita Raghuvir Singh",
"ownerPhoneNo": "9819752206",
"appAddress": "Flat no. C/103, 1st floor, Bldg no - 2 ,Aster CHS Ltd, Thanku Village ,
Kandivali East - 400101",
"remark": "Staff Case, Urgent Case",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "06/04/2023",
      "from": {
        "value": "vendor",
        "label": "vendor"
      },
      "vendor": "Mr. Renold Soans & Mrs. Anita Renold Soans ",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Ms. Savita Raghuvir Singh",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "4396/9/43"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1681296799130_document_1681272376609_SavitaRSingh
_SBI_Racpc_Borivali_West.pdf",
```



```
  "path": "cases/643613a5a99b2228209df094/document_1681296799130_document_1681272376609_SavitaRSingh_SBI_Racpc_Borivali_West.pdf",
  "id": "790428",
  "uploadedBy": "642bad2b91d7c62df117fef2",
  "createdAt": "Wed Apr 12 2023 16:30:15 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "12/08/2003",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "CHE/A-2062/BP(WS)AR"
},
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1681296945715_document_1681272376609_SavitaRSingh_SBI_Racpc_Borivali_West.pdf",
  "path": "cases/643613a5a99b2228209df094/document_1681296945715_document_1681272376609_SavitaRSingh_SBI_Racpc_Borivali_West.pdf",
  "id": "527977",
  "uploadedBy": "642bad2b91d7c62df117fef2",
  "createdAt": "Wed Apr 12 2023 16:30:15 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ef",
    "label": "Society Share Certificate"
  },
  "inputs": {
    "documentDate": "01/05/2007",
    "nameOfApprovingAuthority": {
      "value": "SOCIETY",
      "label": "SOCIETY"
    }
  },
  "to": {
    "value": "Seller",
```

```
    "label": "Seller"
  },
  "Seller": "Mr. Renold Soans & Mrs. Anita Renold Soans",
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "067"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1681297149719_document_1681272376609_SavitaRSingh_SBI_Racpc_Borivali_West.pdf",
"path": "cases/643613a5a99b2228209df094/document_1681297149719_document_1681272376609_SavitaRSingh_SBI_Racpc_Borivali_West.pdf",
"id": "721383",
"uploadedBy": "642bad2b91d7c62df117fef2",
"createdAt": "Wed Apr 12 2023 16:30:15 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "001089",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "521798",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Apr 12 2023 07:42:53 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Ms. Savita Raghuvir Singh",
    "phone": "9819752206",
    "ownershipShare": "",
    "email": "",
    "id": "888318"
  }
],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    }
  },
  "providedBy": {
```

```
    "label": "Other",
    "value": "Other"
  },
  "_id": "64368139e4256a03ecde85b5",
  "area": "491.97",
  "providedByName": "Site Measurement ",
  "providedByContactNo": "0000000000"
}
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "801417",
    "name": "Living Room",
    "length": "17.25",
    "length1": "17",
    "length2": "3",
    "width": "9.92",
    "width1": "9",
    "width2": "11",
    "totalArea": "171.06",
    "images": [
      {
        "path": "cases/643613a5a99b2228209df094/
compositionImg_r_1681292547015_image.jpg",
        "orientation": "portrait"
      }
    ],
    "extraAreas": [],
    "finalArea": "171.06"
  },
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "1",
    "name": "Dining",
    "length": "7.75",
    "length1": "7",
    "length2": "9",
    "width": "7.58",
    "width1": "7",
```

```
"width2": "7",
"totalArea": "58.77",
"images": [
  {
    "path": "cases/643613a5a99b2228209df094/
compositionImg_r_1681292631115_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "58.77"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "8.92",
  "length1": "8",
  "length2": "11",
  "width": "7.17",
  "width1": "7",
  "width2": "2",
  "totalArea": "63.90",
  "images": [
    {
      "path": "cases/643613a5a99b2228209df094/
compositionImg_r_1681292747868_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "63.90"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Balcony Area",
  "length": "7.33",
  "length1": "7",
  "length2": "4",
```

```
"width": "1.75",
"width1": "1",
"width2": "9",
"totalArea": "12.83",
"images": [
  {
    "path": "cases/643613a5a99b2228209df094/
compositionImg_r_1681292875042_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "12.83"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Passage",
  "length": "4.67",
  "length1": "4",
  "length2": "8",
  "width": "3.42",
  "width1": "3",
  "width2": "5",
  "totalArea": "15.94",
  "images": [
    {
      "path": "cases/643613a5a99b2228209df094/
compositionImg_r_1681292993321_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "15.94"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "W.C",
  "length": "3.92",
```

```
"length1": "3",
"length2": "11",
"width": "3.00",
"width1": "3",
"width2": "0",
"totalArea": "11.75",
"images": [
  {
    "path": "cases/643613a5a99b2228209df094/
compositionImg_r_1681293143740_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "11.75"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "6",
  "name": "Bathroom",
  "length": "5.92",
  "length1": "5",
  "length2": "11",
  "width": "3.67",
  "width1": "3",
  "width2": "8",
  "totalArea": "21.69",
  "images": [
    {
      "path": "cases/643613a5a99b2228209df094/
compositionImg_r_1681293223272_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "21.69"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "7",
```

```
"name": "Bedroom",
"length": "11.92",
"length1": "11",
"length2": "11",
"width": "9.92",
"width1": "9",
"width2": "11",
"totalArea": "118.17",
"images": [
  {
    "path": "cases/643613a5a99b2228209df094/
compositionImg_r_1681293345066_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "118.17"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "8",
  "name": "Balcony Area",
  "length": "6.75",
  "length1": "6",
  "length2": "9",
  "width": "2.83",
  "width1": "2",
  "width2": "10",
  "totalArea": "19.12",
  "images": [],
  "extraAreas": [],
  "finalArea": "19.12"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    }
  },
  "docMeasurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "959812",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "455",
  "squareMeterArea": "42.27",
  "docFinalBuiltUp": "546",
  "docFinalBuiltUpSquareMeter": "50.724000000000004",
  "docBuiltupPercentage": "20",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
  {
    "_id": "6438f8948989760c1fb70453",
    "id": "1",
    "property": "",
    "area": "600",
    "builtUpPercentage": "10",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "floor": "",
    "source": "Housing.Com",
    "expectedPrice": "12500000",
    "expectedRate": "20833.33",
    "builtUpExpectedRate": "12500000",
    "image": "cases/643613a5a99b2228209df094/
indicator_1681455252472_Image.png"
  },
  {
    "_id": "6438f8c88989760c1fb704bc",
    "id": "2",
    "property": "Flat",
    "area": "620",
    "builtUpPercentage": "10",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "floor": "",
    "source": "Housing.Com",
    "expectedPrice": "13000000",
    "expectedRate": "20967.74",
    "builtUpExpectedRate": "13000000",
```



```
    "image": "cases/643613a5a99b2228209df094/
indicator_1681455304232_Image.png"
  },
  {
    "_id": "6438f9248989760c1fb707e0",
    "id": "3",
    "property": "Flat",
    "area": "615",
    "builtUpPercentage": "10",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "floor": "",
    "source": "Nobroker.com",
    "expectedPrice": "12500000",
    "expectedRate": "20325.20",
    "builtUpExpectedRate": "12500000",
    "image": "cases/643613a5a99b2228209df094/
indicator_1681455396691_Image.png"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "643681f8e4256a03ecde8910",
    "name": "externalImg_r_1681293791531_image.jpg",
    "path": "cases/643613a5a99b2228209df094/
externalImg_r_1681293791531_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "643681f8e4256a03ecde8911",
    "name": "externalImg_r_1681293786986_image.jpg",
    "path": "cases/643613a5a99b2228209df094/
externalImg_r_1681293786986_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "643681f8e4256a03ecde8912",
    "name": "externalImg_r_1681293788839_image.jpg",
    "path": "cases/643613a5a99b2228209df094/
externalImg_r_1681293788839_image.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "643681f8e4256a03ecde8913",
  "name": "externalimg_r_1681293790195_image.jpg",
  "path": "cases/643613a5a99b2228209df094/
externalimg_r_1681293790195_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "643681f8e4256a03ecde8914",
  "name": "externalimg_r_1681293794592_image.jpg",
  "path": "cases/643613a5a99b2228209df094/
externalimg_r_1681293794592_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "643681f8e4256a03ecde8915",
  "name": "externalimg_r_1681293793276_image.jpg",
  "path": "cases/643613a5a99b2228209df094/
externalimg_r_1681293793276_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "643681f8e4256a03ecde8916",
  "name": "externalimg_r_1681293792462_image.jpg",
  "path": "cases/643613a5a99b2228209df094/
externalimg_r_1681293792462_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "643681f8e4256a03ecde8917",
  "name": "externalimg_r_1681293799514_image.jpg",
  "path": "cases/643613a5a99b2228209df094/
externalimg_r_1681293799514_image.jpg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "643681f8e4256a03ecde8918",
  "name": "externallmg_r_1681293797724_image.jpg",
  "path": "cases/643613a5a99b2228209df094/
externallmg_r_1681293797724_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "643681f8e4256a03ecde8919",
  "name": "externallmg_r_1681293802529_image.jpg",
  "path": "cases/643613a5a99b2228209df094/
externallmg_r_1681293802529_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "643681f8e4256a03ecde891a",
  "name": "externallmg_r_1681293800916_image.jpg",
  "path": "cases/643613a5a99b2228209df094/
externallmg_r_1681293800916_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "643681f8e4256a03ecde891b",
  "name": "externallmg_r_1681293805241_image.jpg",
  "path": "cases/643613a5a99b2228209df094/
externallmg_r_1681293805241_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "643681f8e4256a03ecde891c",
  "name": "externallmg_r_1681293803603_image.jpg",
  "path": "cases/643613a5a99b2228209df094/
externallmg_r_1681293803603_image.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "643681f8e4256a03ecde891d",
  "name": "externalImg_r_1681293804579_image.jpg",
  "path": "cases/643613a5a99b2228209df094/
externalImg_r_1681293804579_image.jpg",
  "orientation": "portrait"
}
],
"externalDocuments": [
  {
    "originalname": "Valuation_Report_Savita Raghuvir Singh.pdf",
    "filename": "1681543496131_Valuation_Report_Savita_Raghuvir_Singh.pdf",
    "path": "cases/643613a5a99b2228209df094/
externalDocuments/1681543496131_Valuation_Report_Savita_Raghuvir_Singh.pdf",
    "size": "1128858",
    "documentType": {
      "value": "60ae124caa6d152c1801b300",
      "label": "Signed Report"
    },
    "createdAt": "Sat Apr 15 2023 12:54:56 GMT+0530 (India Standard Time)",
    "uploadedBy": "63f31d626f9c2254a9b39144"
  }
],
"createdAt": "2023-04-12T02:12:53.484Z",
"updatedAt": "2023-04-25T06:41:17.038Z",
"__v": 0,
"updatedBy": "642bad2b91d7c62df117fef2",
"fullAddress": "Residential Flat No. 103, 1st Floor, Building No 2, Wing - C, Aster Co-
op. Hsg. Soc. Ltd., Valley of Flowers, Opp. Balasaheb Thakrey Udyan, Village - Thakur,
Municipality Ward No. R/S, Taluka - Borivali, District - Mumbai, Mumbai, PIN - 400 101,
State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Mrs. Laxmi",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Seller's Sister",
"siteVisitContactNo": "9819752206",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Dining + 2 Balcony
Area + Passage + W.C + Bathroom",
"carpetTotal": "493.23",
```

"finalMeasurementType": "Sq. Ft.",
 "otherCarpetTotal": "0",
 "siteVisitDate": "2023-04-12",
 "builtupPercentage": "10",
 "finalBuiltupArea": "542.55",
 "finalCarpetArea": "493.23",
 "finalSalableArea": "596.81",
 "salablePercentage": "10",
 "toBeAdded": "",
 "extendOfSiteRemark": "All the above areas are within +/- 10% of the Agreement for Sale Area. The above calculations and detail measurements taken by us prove that the Agreement for Sale are is not exorbitantly inflated. Hence, valuation is based on the Agreement for Sale area.",
 "siteMeasurementRemark": "",
 "finalAreaType": "Carpet Area",
 "finalAsPerArea": "Agreement for sale",
 "finalBuiltUpPercentage": "20",
 "finalCarpetConvertToBuiltUpPer": "20",
 "finalSaleablePercentage": "0",
 "finalValuationAreaString": "Carpet Area in Sq. Ft. = 455.00",
 "reason": "",
 "buildingServicesRate": "2700",
 "flatRate": "25500",
 "landOtherRate": "22800",
 "otherCompositionBuiltUpTotal": "0.00",
 "otherCompositionCarpetTotal": "0.00",
 "otherCompositionSaleableTotal": "0.00"

Name	Length	Width	Total
Composition :			
Living Room	17'3"	9'11"	171.06
Dining	7'9"	7'7"	58.77
Kitchen	8'11"	7'2"	63.90
Balcony Area	7'4"	1'9"	12.83
Passage	4'8"	3'5"	15.94
W.C	3'11"	3'0"	11.75
Bathroom	5'11"	3'8"	21.69
Bedroom	11'11"	9'11"	118.17

Balcony Area

6'9"

2'10"

19.12

Other

Composition :
