

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "masterTypeOfPurpose": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb63"
    },
    "type": "CREDITOFFICER",
    "_id": "64378b6be4256a03ecdf4219",
    "firstName": "Sandeep",
    "lastName": "Lohakare",
    "mobileNo": "",
    "workMobileNo": "9594965498",
    "email": ""
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "4178500",
    "discussWithPerson": "Sandeep",
    "expectedFees": 2089.25,
    "quotedAmount": "2950"
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
```

```
"name": "Vastukala Consultants India Pvt. Ltd.",
"email": "vastukalamumbai@vastukala.com",
"phone": "9819670183",
"address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai -
400 093",
"profilePhoto": "public\\images\
\1606738172464_51041525c82381638d4d202735b1f05d.png",
"shortName": "VCIPL",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb63",
  "branchCode": "000355",
  "type": "BRANCH",
  "name": "RACPC Kalyan",
  "email": "rasecc.thane@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "Sbi bank racpc kalyan main branch 1st floor Nr LIC office \r\n murbad
road kalyan west. \r\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_ &_ Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "6410199a140f140ffc59b58c",
  "role": "PICKUPPERSON",
  "firstName": "Prakash ",
  "email": "prakashnvetkoli@gmail.com",
  "lastName": "Vetkoli",
  "mobileNo": "9076237689",
  "shortName": "PV",
  "workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc4680ce84bf289ba9c7fc",
  "role": "SITEENGINEER",
  "firstName": "Nikhil ",
  "email": "valtechnical2022@gmail.com",
  "lastName": "Sonawane",
  "mobileNo": "9819470709",
  "designation": "",
  "shortName": "NS",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1681380664371_WhatsApp_Image_20230413_at_33801_PM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER+CHECKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "MAKER",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
```

```
"mobileNo": "9821518537",
"designation": "",
"shortName": "PSH",
"workWithDocumentMaker": "",
"profilePhoto": "users/627222afafd7d55eddedd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER+CHECKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
profilePhoto_1626255068979_Shyam_Photo.jpg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "[N]C.C.I.T/I -14/52/2008-09",
"label": "Wealth Tax"
}
]
},
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
{
"title": {
"value": "Wealth_Tax",
"label": "Wealth Tax"
}
},
"_id": "6084131a13f01f158c6ea1f4",
```

```
        "number": "[N]C.C.I.T/I -14/52/2008-09"
      }
    ],
    "shortName": "SBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
  }
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.229524744412885",
  "longitude": "73.14324824232787"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.14324824232787,
    19.229524744412885
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-04-13T05:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-13T05:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-13T05:00:00.000Z",
      "remark": ""
    }
  ]
},
"visitedDate": [],
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
}
```

```
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Thu Apr 13 2023 11:39:54 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Katemanivali",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "14",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
```

```
"value": "Thane",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Kalyan",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan ",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "71B/4B",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Vasant Vastu",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
```

```
"status": true,
"name": "Street 1",
"key": "street1",
"value": "Poona Link Road",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
```



```
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1406",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
```

```
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "421306",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kalyan (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  }
},
```

```
"flooring": {
  "value": "VerifiedTileFlooring",
  "label": "Vitrified Tile Flooring"
},
"doors": {
  "value": "Teak_Wood_door_frame,_Flush_doors_shutters",
  "label": "Teak Wood door frame, Flush doors shutters"
},
"windows": {
  "value": "PowderCoatedAluminiumSliding",
  "label": "Powder Coated Aluminium Sliding"
},
"fittings": {
  "value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring",
  "label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring"
},
"finishing": {
  "value": "Normal",
  "label": "Normal"
}
},
"general": {
  "ownership": {
    "value": "sole_ownership",
    "label": "sole ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Kalyan_Dombivali_Municipal_Corporation",
    "label": "Kalyan Dombivali Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Nilgiri Housing",
    "west": "Chawls",
    "south": "Shri Sadgurukrupa CHSL",
```

```
"east": "Chawls"
},
"asPerDocumentAgreement": {
  "north": "Nilgiri Housing",
  "west": "Chawls",
  "south": "Shri Sadgurukrupa CHSL",
  "east": "Chawls"
},
"extraDetailOfProperty": ""
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "9,500.00 Expected rental income per month",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "Kalyan Dombivli Municipal Corporation",
  "tenantName": "",
  "maintenanceOfFlat": "Details not available"
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "Details not available",
  "negativeFactorsOfAffectMarketValue": "Details not available"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  }
}
```

```
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": {
  "value": "Stilt+_Open_Car_Parking",
  "label": "Stilt + Open Car Parking"
},
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2022",
  "fullDate": "1/1/2022"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
}
```

```
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
```

```
"value": "stilt",
"label": "Stilt"
},
"yearOfConstructionAsPer": {
"value": "Approx.",
"label": "Approx."
},
"estimatedAge": "59",
"ageOfBuilding": "1",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "21",
"flatFloorNo": "14",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "8"
},
"finalPlinthArea": {
"area": "493.90",
"measurementType": "Sq. Ft.",
"areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
"finalLatLng": {
"type": "Point",
"coordinates": []
},
"locationMapImg": []
},
"outward": {
"status": false,
"remark": "SYSTEM_GENERATED"
},
"rateVerify": {
"status": false
},
"underConstruction": {
"rccFootingFoundation": {
"label": "RCC Footing/Foundation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
}
},
```

```
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
```



```
"isHideFloor": false,
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
```

```
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"createCase": "false",
"type": "CASE",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "449.00",
"empanelmentNo": [],
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"_id": "64378f1ae4256a03ecdf58d3",
"ownerName": "Mrs. Chaitali Nitin Namayate",
"ownerPhoneNo": "7506491119",
"appAddress": "C-101, Sai Dip Apt., Sai Sahara Complex, Near D ed College,
Katemanivali, Kalyan East",
```

```
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "24/11/2022",
      "nameOfApprovingAuthority": {
        "value": "Kalyan_Dombivli_Mahanagarpalika",
        "label": "Kalyan Dombivli Mahanagarpalika"
      },
      "from": {
        "value": "The_Builders",
        "label": "The Builders"
      },
      "The_Builders": "M/s. Sai Sadguru Builders and Developers",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mrs. Chaitali Nitin Namayate",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "15608/2022"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1681803977329_Agreement.pdf",
    "path": "cases/64378f1ae4256a03ecdf58d3/
document_1681803977329_Agreement.pdf"
  }
],
"caseNumber": "001118",
"createdBy": "6410199a140f140ffc59b58c",
"caseHistory": [
  {
    "id": "487220",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Apr 13 2023 10:41:54 GMT+0530 (India Standard Time)"
  }
],
```

```
"owners": [
  {
    "name": "Mrs. Chaitali Nitin Namayate",
    "phone": "7506491119",
    "email": "",
    "ownershipShare": "",
    "id": "275719"
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "9",
    "name": "Bedroom",
    "length": "11.00",
    "length1": "11",
    "length2": "0",
    "width": "9.00",
    "width1": "9",
    "width2": "0",
    "totalArea": "99.00",
    "images": [],
    "finalArea": "99.00",
    "extraAreas": []
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "3",
    "name": "Balcony Area",
    "length": "",
    "length1": "9",
    "length2": "0",
    "width": "",
    "width1": "6",
    "width2": "0",
    "totalArea": "54.00",
    "images": [],
    "finalArea": "54.00",
    "extraAreas": []
  }
]
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Passage",
  "length": "9.00",
  "length1": "9",
  "length2": "0",
  "width": "3.00",
  "width1": "3",
  "width2": "0",
  "totalArea": "27.00",
  "images": [],
  "finalArea": "27.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "WC",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "12.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Bathroom",
  "length": "5.00",
  "length1": "5",
```

```
"length2": "0",
"width": "5.00",
"width1": "5",
"width2": "0",
"totalArea": "25.00",
"images": [],
"finalArea": "25.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Kitchen",
  "length": "8.00",
  "length1": "8",
  "length2": "00",
  "width": "8.00",
  "width1": "8",
  "width2": "00",
  "totalArea": "64.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "64.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Flowered Area",
  "length": "7.00",
  "length1": "7",
  "length2": "00",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "21.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "21.00"
},
{
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "9",
"name": "Living Room",
"length": "",
"length1": "15",
"length2": "0",
"width": "",
"width1": "9",
"width2": "0",
"totalArea": "135.00",
"images": [],
"finalArea": "135.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Flowered Area",
  "length": "",
  "length1": "9",
  "length2": "0",
  "width": "",
  "width1": "3",
  "width2": "0",
  "totalArea": "27.00",
  "images": [],
  "finalArea": "27.00",
  "extraAreas": []
}
],
"otherComposition": [
  {
    "name": {
      "value": "Cupboard",
      "label": "Cupboard"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  },

```

```
"id": "1",
"length1": "4",
"length2": "0",
"length": "4.00",
"width1": "3",
"width2": "0",
"width": "3.00",
"totalArea": "12.00",
"percentageBeforeTotal": "12.00",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "12"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "642359",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "449",
  "squareMeterArea": "41.71",
  "docFinalBuiltUp": "493.9",
  "docFinalBuiltUpSquareMeter": "45.881",
  "docBuiltupPercentage": "10",
  "docSaleablePercentage": "10",
  "docFinalSaleable": "543.29",
  "docFinalSaleableSquareMeter": "50.4691"
}
],
"images": [],
"indicatorArr": [
{
  "_id": "643e601c5dba55204e21ad52",
  "id": "1",
  "property": "Residential",
  "area": "547",
  "builtUpPercentage": "10",
```



```
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Housing.Com",
"expectedPrice": "5207000",
"expectedRate": "9519.20",
"builtUpExpectedRate": "8653.81",
"image": "cases/64378f1ae4256a03ecdf58d3/
indicator_1681809436637_Image.png"
},
{
  "_id": "643e8230f8e52b5dd61e9037",
  "id": "2",
  "property": "Residential",
  "area": "2917.04",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "https://www.proptiger.com/",
  "expectedPrice": "2580000",
  "expectedRate": "884.46",
  "builtUpExpectedRate": "804.05",
  "image": "cases/64378f1ae4256a03ecdf58d3/
indicator_1681818160877_Image.png"
},
{
  "_id": "643e82e6f8e52b5dd61e90ec",
  "id": "3",
  "property": "Residential",
  "area": "397",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "18 Floor",
  "source": "Index_no.2",
  "expectedPrice": "4000000",
  "expectedRate": "10075.57",
  "builtUpExpectedRate": "9159.61",
  "image": "cases/64378f1ae4256a03ecdf58d3/
indicator_1681818342760_Image.png"
},
{
```

```
"_id": "643e83a7f8e52b5dd61e9324",
"id": "4",
"property": "Residential",
"area": "452",
"builtUpPercentage": "10",
"saleablePercentage": "20",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "20 Floor",
"source": "Index_no.2",
"expectedPrice": "4490000",
"expectedRate": "9933.63",
"builtUpExpectedRate": "9030.57",
"image": "cases/64378f1ae4256a03ecdf58d3/
indicator_1681818535247_Image.png"
}
],
"externalImages": [],
"externalDocuments": [],
"createdAt": "2023-04-13T05:11:54.596Z",
"updatedAt": "2023-04-18T11:48:55.338Z",
"__v": 0,
"fullAddress": "Residential Flat No. 1406, 14th Floor, Vasant Vastu, Plot No. 71B/4B,
Poona Link Road, Village - Katemanivali, Kalyan (East), Taluka - Kalyan , District -
Thane, Kalyan, 421306, State - Maharashtra, India",
"updatedBy": "627222afafd7d55eddedd82",
"addressForMap": "",
"caseReferredBy": "6410199a140f140ffc59b58c",
"contactPersonName": "Chaitali Nitin Namyate",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "7506491119",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Balcony Area +
Passage + WC + Bathroom + 2 Flowered Area",
"carpetTotal": "464",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "12.00",
"builtupPercentage": "10",
"extendOfSiteRemark": "",
"finalBuiltupArea": "510.40",
"finalCarpetArea": "464.00",
"finalSalableArea": "561.44",
```

"salablePercentage": "10",
 "siteMeasurementRemark": "",
 "toBeAdded": "",
 "finalAreaType": "Carpet Area",
 "finalAsPerArea": "Agreement for sale",
 "finalBuiltUpPercentage": "10",
 "finalCarpetConvertToBuiltUpPer": "10",
 "finalSaleablePercentage": "10",
 "finalValuationAreaString": "Carpet Area in Sq. Ft. = 449.00"

}

Name	Length	Width	Total
Composition :			
Bedroom	11'0"	9'0"	99.00
Balcony Area	9'0"	6'0"	54.00
Passage	9'0"	3'0"	27.00
WC	4'00"	3'00"	12.00
Bathroom	5'0"	5'0"	25.00
Kitchen	8'00"	8'00"	64.00
Flowered Area	7'00"	3'00"	21.00
Living Room	15'0"	9'0"	135.00
Flowered Area	9'0"	3'0"	27.00
Other Composition :			
Cupboard	4'0"	3'0"	12.00