

```
{
  "typeOfReport": {
    "label": "Residential",
    "value": "Residential"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63b26511191f7b344b008a1d"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b8b",
    "email": "coorddesk.rasmecbhy@sbi.co.in",
    "firstName": "SHASHI RANJAN",
    "mobileNo": "",
    "workMobileNo": "9867369914",
    "lastName": "RANJAN"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "4500000",
    "discussWithPerson": "SHASHI RANJAN",
    "expectedFees": 2250,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "vastukalamumbai@vastukala.com",
    "phone": "9819670183",
    "address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai -
```

```
400 093",
  "profilePhoto": "public\\images\\
\\1606738172464_51041525c82381638d4d202735b1f05d.png",
  "shortName": "VCIPL",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63b26511191f7b344b008a1d",
  "name": "RASMECC BHAYANDAR",
  "branchCode": "",
  "mobileNo": "022-28149108",
  "alternateMobileNo": "",
  "email": "Coorddesk.rasmecbhy@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "150 Feet Road, Venkatesh Orchid, Near Flyover, Bhayander (West),
Thane"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "627219d6afd7d55eddedd283",
    "role": "PICKUPPERSON",
    "firstName": "Mangesh ",
```

```
    "email": "mangeshpalande17@gmail.com",
    "lastName": "Palande",
    "mobileNo": "9833030550",
    "shortName": "MP",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/627219d6afd7d55eddedd283/
profilePhoto_1668055836118_WhatsApp_Image_20221110_at_101725_AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "627208c1afd7d55eddedc372",
    "role": "FRONTDESK",
    "firstName": "Aniket",
    "email": "aniket@vastukala.org",
    "lastName": "Navale",
    "mobileNo": "9892222307",
    "designation": "",
    "shortName": "AN",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/627208c1afd7d55eddedc372/
profilePhoto_1667995077581_WhatsApp_Image_20221109_at_52453_PM.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60092304a16fab0f2af9b0c2",
    "role": "MAKER+CHECKER",
    "firstName": "Nitesh",
    "email": "nitesh.khedekar@vastukala.org",
    "lastName": "Khedekar",
    "mobileNo": "8369040652",
    "designation": "",
    "shortName": "NK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "60092304a16fab0f2af9b0c2",
    "role": "MAKER+CHECKER",
    "firstName": "Nitesh",
    "email": "nitesh.khedekar@vastukala.org",
    "lastName": "Khedekar",
    "mobileNo": "8369040652",
    "designation": "",
    "shortName": "NK",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
  "mobileNo": "9769797568",
  "designation": "",
  "shortName": "P",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "6084131a13f01f158c6ea1f3",
    "PANNo": "AEAPC7114Q",
    "role": "VALUER",
    "firstName": "Sharadkumar",
    "fatherName": "Baburao",
    "email": "cmd@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9422171100",
    "designation": "CMD",
    "registrationNo": [
      {
        "title": {
          "value": "Wealth_Tax",
          "label": "Wealth Tax"
        },
        "_id": "6084131a13f01f158c6ea1f4",
        "number": "[N]C.C.I.T/I -14/52/2008-09"
      }
    ],
  },
],
```

```
    "shortName": "SBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6084131a13f01f158c6ea1f3\
\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.28376303413855",
  "longitude": "72.87496874110225"
},
"geo": {
  "type": "Point",
  "coordinates": []
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-04-14T04:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-14T04:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-14T11:06:23.315Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-14T11:06:41.830Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-04-14T11:06:23.315Z"
    },
    {
      "status": "COMPLETED",
```

```
    "dateTime": "2023-04-14T11:06:41.830Z"
  }
]
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Fri Apr 14 2023 09:59:09 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "3",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
```

```
"status": false,
"name": "District",
"key": "district",
"value": "",
"label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Rashmi Crystal CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
```

```
"label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Sai CComplex",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Near Joggers Park ",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
```



```
"name": "New/Current Survey No.",
"key": "newSurveyNumber",
"value": "",
"label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "301",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
}
```

```
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Mira Road East",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
```

```
"label": "R. C. C. Slab",
"value": "rcc_Slab"
},
"flooring": {
"label": "White Marble Flooring",
"value": "White_Marble_Flooring"
},
"doors": {
"label": "Teak Wood",
"value": "TeakWood"
},
"windows": {
"label": "Alluminum sliding windows with M. S. Grills",
"value": "Alluminum_sliding_windows_with_M._S._Grills"
},
"fittings": {
"label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring",
"value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring"
},
"finishing": {
"label": "Cement Plastering + POP Finish",
"value": "Cement_Plastering_+_POP_Finish"
}
},
"general": {
"populationClassList": {
"label": "Middle Class",
"value": "MiddleClass"
},
"populationGroupList": {
"label": "Urban",
"value": "Urban"
},
"townplanApprovedByList": {
"label": "Municipal Corporation of Greater Mumbai (MCGM)",
"value": "MCGM"
},
"asPerActualAgreement": {
"north": "A Wing",
"west": "Sai Drishti CHSL",
"south": "Sai Sarita CHSL",
"east": "Sanskriti CHSL"
},
"asPerDocumentAgreement": {
"north": "",
"west": "",
```

```
"south": "",
"east": ""
}
},
"outgoingDetail": {
"areaStatusList": {
"label": "Middle Class",
"value": "Middle_Class"
},
"propertyTypeOfUseList": {
"label": "Residential Purpose",
"value": "Residential_Purpose"
},
"propertyOccupiedByList": {
"label": "Owner Occupied",
"value": "Owner_Occupied"
},
"monthlyRent": ""
},
"siteMeasurement": {
"partitions": {
"label": "6\" Thk. Brick Masonery",
"value": "6\"_Thk._Brick_Masonery"
},
"waterTank": {
"label": "Municipal Water Supply",
"value": "MunicipalWaterSupply"
},
"pavementLaid": {
"label": "Yes",
"value": "Yes"
},
"carParking": {
"label": "Open Car Parking",
"value": "Open_Car_Parking"
},
"constructionWorkStatus": {
"label": "Completed",
"value": "Completed"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2004",
"fullDate": "1/1/2004"
},
}
```

```
"propertyTypeList": {
  "value": "Residential",
  "label": "Residential"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"qualityOfConstruction": {
  "label": "Good",
  "value": "Good"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"maintenanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Part Ground + Part Stilt",
  "value": "Part_Ground_and_Part_Stilt"
},
"isSiteVisitAllowed": true,
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"flatFloorNo": "",
"noOfLiftsInEachWings": "0",
"totalLifeBuilding": "60",
"estimatedAge": "41",
"ageOfBuilding": "19",
"noOfFloors": "7",
```

```
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "type": "Point",
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
```

```
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```



```
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"createCase": "false",
"type": "CASE",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"_id": "6438ce0d8989760c1fb6b514",
"ownerName": "Rajesh waghela ",
"ownerPhoneNo": "9833955597",
"appAddress": "b/301 Rashmi crystal chs Sai complex nr joggers park Mira Rd east",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1248aa6d152c1801b2ee",
      "label": "Previous Valuation Report"
    },
    "inputs": {
      "documentDate": "02/02/2021"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName":
"document_1681446347640_Valuation_Report_Rajesh_Wagheladoc.pdf",
    "path": "cases/6438ce0d8989760c1fb6b514/
document_1681446347640_Valuation_Report_Rajesh_Wagheladoc.pdf",
    "id": "166590",
    "uploadedBy": "6006d4ce5080a310ac1fdfc2",
    "createdAt": "Fri Apr 14 2023 09:55:54 GMT+0530 (India Standard Time)"
  }
]
```

```
}
],
"caseNumber": "001137",
"createdBy": "627219d6afd7d55eddedd283",
"caseHistory": [
  {
    "id": "126283",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Apr 14 2023 09:22:45 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Rajesh waghela ",
    "phone": "9833955597",
    "ownershipShare": "",
    "email": "",
    "id": "702643"
  }
],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Other",
      "value": "Other"
    },
    "_id": "6439337113d81f73166c5d49",
    "area": "747.66",
    "providedByName": "Site Measurement ",
    "providedByContactNo": "0000000000"
  }
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "230125",
    "name": "Living Room",
    "length": "15.42",
```

```
"length1": "15",
"length2": "5",
"width": "13.00",
"width1": "13",
"width2": "0",
"totalArea": "200.42",
"images": [
  {
    "path": "cases/6438ce0d8989760c1fb6b514/
compositionImg_r_1681468982718_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "200.42"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "name": "Passage",
  "length": "13.25",
  "length1": "13",
  "length2": "3",
  "width": "8.58",
  "width1": "8",
  "width2": "7",
  "totalArea": "113.73",
  "images": [
    {
      "path": "cases/6438ce0d8989760c1fb6b514/
compositionImg_r_1681469053142_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "113.73"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
```

```
"name": "Balcony Area",
"length": "7.83",
"length1": "7",
"length2": "10",
"width": "3.42",
"width1": "3",
"width2": "5",
"totalArea": "26.76",
"images": [
  {
    "path": "cases/6438ce0d8989760c1fb6b514/
compositionImg_r_1681469108332_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "26.76"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Kitchen",
  "length": "8.83",
  "length1": "8",
  "length2": "10",
  "width": "6.92",
  "width1": "6",
  "width2": "11",
  "totalArea": "61.10",
  "images": [
    {
      "path": "cases/6438ce0d8989760c1fb6b514/
compositionImg_r_1681469189744_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "61.10"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  }
```

```
},
  "id": "4",
  "name": "Passage",
  "length": "8.83",
  "length1": "8",
  "length2": "10",
  "width": "2.83",
  "width1": "2",
  "width2": "10",
  "totalArea": "25.03",
  "images": [
    {
      "path": "cases/6438ce0d8989760c1fb6b514/
compositionImg_r_1681469304445_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "25.03"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "11.08",
  "length1": "11",
  "length2": "1",
  "width": "8.92",
  "width1": "8",
  "width2": "11",
  "totalArea": "98.83",
  "images": [
    {
      "path": "cases/6438ce0d8989760c1fb6b514/
compositionImg_r_1681470124410_image.jpg",
      "orientation": "portrait"
    },
    {
      "path": "cases/6438ce0d8989760c1fb6b514/
compositionImg_r_1681470127281_image.jpg",
      "orientation": "portrait"
    }
  ],
}
```

```
"extraAreas": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "_id": "6439334413d81f73166c5cff",
    "name": "C.B Area",
    "extraAreaType": "Add",
    "length": "3.42",
    "length1": "3",
    "length2": "5",
    "width": "2.00",
    "width1": "2",
    "width2": "0",
    "totalArea": "6.83"
  },
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "_id": "6439334413d81f73166c5d00",
    "name": "Balcony Area",
    "extraAreaType": "Add",
    "length": "5.42",
    "length1": "5",
    "length2": "5",
    "width": "1.42",
    "width1": "1",
    "width2": "5",
    "totalArea": "7.67"
  }
],
"finalArea": "98.847.67"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "12.50",
  "length1": "12",
  "length2": "6",
```

```
"width": "9.08",
"width1": "9",
"width2": "1",
"totalArea": "113.54",
"images": [
  {
    "path": "cases/6438ce0d8989760c1fb6b514/
compositionImg_r_1681470227938_image.jpg",
    "orientation": "portrait"
  },
  {
    "path": "cases/6438ce0d8989760c1fb6b514/
compositionImg_r_1681470229191_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "_id": "6439334413d81f73166c5d01",
    "name": "C.B Area",
    "extraAreaType": "Add",
    "length": "4.08",
    "length1": "4",
    "length2": "1",
    "width": "3.33",
    "width1": "3",
    "width2": "4",
    "totalArea": "13.61"
  },
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "_id": "6439334413d81f73166c5d02",
    "name": "Balcony Area",
    "extraAreaType": "Add",
    "length": "5.42",
    "length1": "5",
    "length2": "5",
    "width": "1.83",
    "width1": "1",
```

```
    "width2": "10",
    "totalArea": "9.93"
  }
],
"finalArea": "113.549.93"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "7",
  "name": "Toilet",
  "length": "8.67",
  "length1": "8",
  "length2": "8",
  "width": "3.83",
  "width1": "3",
  "width2": "10",
  "totalArea": "33.22",
  "images": [
    {
      "path": "cases/6438ce0d8989760c1fb6b514/
compositionImg_r_1681469892403_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "33.22"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "8",
  "name": "Toilet",
  "length": "8.75",
  "length1": "8",
  "length2": "9",
  "width": "4.00",
  "width1": "4",
  "width2": "0",
  "totalArea": "35.00",
  "images": [
    {
```



```
    "path": "cases/6438ce0d8989760c1fb6b514/
compositionImg_r_1681469974767_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "35.00"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c6099",
    "name": "externalImg_r_1681470432841_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externalImg_r_1681470432841_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c609a",
    "name": "externalImg_r_1681470433968_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externalImg_r_1681470433968_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c609b",
    "name": "externalImg_r_1681470428430_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externalImg_r_1681470428430_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c609c",
```

```
    "name": "externallmg_r_1681470435161_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470435161_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c609d",
    "name": "externallmg_r_1681470444317_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470444317_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c609e",
    "name": "externallmg_r_1681470439789_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470439789_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c609f",
    "name": "externallmg_r_1681470454349_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470454349_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c60a0",
    "name": "externallmg_r_1681470448804_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470448804_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c60a1",
    "name": "externallmg_r_1681470438618_image.jpg",
```

```
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470438618_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c60a2",
    "name": "externallmg_r_1681470443398_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470443398_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c60a3",
    "name": "externallmg_r_1681470464304_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470464304_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c60a4",
    "name": "externallmg_r_1681470461074_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470461074_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c60a5",
    "name": "externallmg_r_1681470437686_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470437686_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c60a6",
    "name": "externallmg_r_1681470435591_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470435591_image.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6439342a13d81f73166c60a7",
  "name": "externallmg_r_1681470462485_image.jpg",
  "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470462485_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6439342a13d81f73166c60a8",
  "name": "externallmg_r_1681470445073_image.jpg",
  "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470445073_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6439342a13d81f73166c60a9",
  "name": "externallmg_r_1681470450052_image.jpg",
  "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470450052_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6439342a13d81f73166c60aa",
  "name": "externallmg_r_1681470457314_image.jpg",
  "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470457314_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6439342a13d81f73166c60ab",
  "name": "externallmg_r_1681470440947_image.jpg",
  "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470440947_image.jpg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6439342a13d81f73166c60ac",
  "name": "externallmg_r_1681470437409_image.jpg",
  "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470437409_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6439342a13d81f73166c60ad",
  "name": "externallmg_r_1681470447769_image.jpg",
  "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470447769_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6439342a13d81f73166c60ae",
  "name": "externallmg_r_1681470452493_image.jpg",
  "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470452493_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6439342a13d81f73166c60af",
  "name": "externallmg_r_1681470465289_image.jpg",
  "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470465289_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6439342a13d81f73166c60b0",
  "name": "externallmg_r_1681470460422_image.jpg",
  "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470460422_image.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6439342a13d81f73166c60b1",
  "name": "externallmg_r_1681470438817_image.jpg",
  "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470438817_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6439342a13d81f73166c60b2",
  "name": "externallmg_r_1681470442355_image.jpg",
  "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470442355_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6439342a13d81f73166c60b3",
  "name": "externallmg_r_1681470450574_image.jpg",
  "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470450574_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6439342a13d81f73166c60b4",
  "name": "externallmg_r_1681470464549_image.jpg",
  "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470464549_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6439342a13d81f73166c60b5",
  "name": "externallmg_r_1681470455255_image.jpg",
  "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470455255_image.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c60b6",
    "name": "externallmg_r_1681470460917_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470460917_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c60b7",
    "name": "externallmg_r_1681470458700_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470458700_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c60b8",
    "name": "externallmg_r_1681470454008_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470454008_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c60b9",
    "name": "externallmg_r_1681470447934_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470447934_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c60ba",
    "name": "externallmg_r_1681470462641_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470462641_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6439342a13d81f73166c60bb",
  "name": "externallmg_r_1681470469911_image.jpg",
  "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470469911_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6439342a13d81f73166c60bc",
  "name": "externallmg_r_1681470467591_image.jpg",
  "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470467591_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6439342a13d81f73166c60bd",
  "name": "externallmg_r_1681470455780_image.jpg",
  "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470455780_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6439342a13d81f73166c60be",
  "name": "externallmg_r_1681470446885_image.jpg",
  "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470446885_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6439342a13d81f73166c60bf",
  "name": "externallmg_r_1681470462028_image.jpg",
  "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470462028_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```



```
    "_id": "6439342a13d81f73166c60c0",
    "name": "externallmg_r_1681470438198_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470438198_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c60c1",
    "name": "externallmg_r_1681470473425_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470473425_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c60c2",
    "name": "externallmg_r_1681470468937_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470468937_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c60c3",
    "name": "externallmg_r_1681470482169_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470482169_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c60c4",
    "name": "externallmg_r_1681470476192_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470476192_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c60c5",
```

```
    "name": "externallmg_r_1681470467262_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470467262_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c60c6",
    "name": "externallmg_r_1681470473085_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470473085_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c60c7",
    "name": "externallmg_r_1681470483153_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470483153_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c60c8",
    "name": "externallmg_r_1681470482895_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470482895_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c60c9",
    "name": "externallmg_r_1681470476170_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470476170_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c60ca",
    "name": "externallmg_r_1681470472973_image.jpg",
```

```
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470472973_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c60cb",
    "name": "externallmg_r_1681470466782_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470466782_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c60cc",
    "name": "externallmg_r_1681470482314_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470482314_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c60cd",
    "name": "externallmg_r_1681470485606_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470485606_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c60ce",
    "name": "externallmg_r_1681470484401_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470484401_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6439342a13d81f73166c60cf",
    "name": "externallmg_r_1681470468053_image.jpg",
    "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470468053_image.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6439342a13d81f73166c60d0",
  "name": "externallmg_r_1681470476897_image.jpg",
  "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470476897_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6439342a13d81f73166c60d1",
  "name": "externallmg_r_1681470472861_image.jpg",
  "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470472861_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6439342a13d81f73166c60d2",
  "name": "externallmg_r_1681470482443_image.jpg",
  "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470482443_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6439342a13d81f73166c60d3",
  "name": "externallmg_r_1681470487186_image.jpg",
  "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470487186_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6439342a13d81f73166c60d4",
  "name": "externallmg_r_1681470485273_image.jpg",
  "path": "cases/6438ce0d8989760c1fb6b514/
externallmg_r_1681470485273_image.jpg",
  "orientation": "portrait"
}
```

```

    }
  ],
  "externalDocuments": [],
  "createdAt": "2023-04-14T03:52:45.484Z",
  "updatedAt": "2023-04-14T11:38:51.219Z",
  "__v": 0,
  "fullAddress": "Residential Flat No. 301, 3rd Floor, Wing - B, Rashmi Crystal CHSL, Sai CComplex, Near Joggers Park , Mira Road East, State - Maharashtra, India",
  "updatedAtBy": "62691c48afd7d55eddecfda3",
  "addressForMap": "",
  "caseReferredBy": "",
  "contactPersonName": "Rajesh waghela ",
  "email": "",
  "isExternal": "false",
  "isUrgent": "false",
  "ownershipShare": "",
  "purchaseValueAsPerDocument": "",
  "relationWithOwner": "self",
  "siteVisitContactNo": "9833955597",
  "briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Passage + Balcony Area + 2 Toilet",
  "carpetTotal": "707.63",
  "finalMeasurementType": "Sq. Ft.",
  "otherCarpetTotal": "0",
  "siteVisitDate": "2023-04-14"
}

```

Name	Length	Width	Total
Composition :			
Living Room	15'5"	13'0"	200.42
Passage	13'3"	8'7"	113.73
Balcony Area	7'10"	3'5"	26.76
Kitchen	8'10"	6'11"	61.10
Passage	8'10"	2'10"	25.03
Bedroom	11'1"	8'11"	98.83
Bedroom	12'6"	9'1"	113.54
Toilet	8'8"	3'10"	33.22
Toilet	8'9"	4'0"	35.00

Other
Composition :
