

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8ed"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230d24",
    "firstName": "Jayanta Pawar",
    "email": "cbsprabhadevi@unionbankofindia.com",
    "mobileNo": "022-24220497, 022-24222391",
    "workMobileNo": "9561068315",
    "lastName": "Pawar"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "11988000",
    "discussWithPerson": "Jayanta Pawar",
    "expectedFees": 5994,
    "quotedAmount": "4720"
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "vastukalamumbai@vastukala.com",
    "phone": "9819670183",
    "address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai -
```

```
400 093",
  "profilePhoto": "public\\images\\
\\1606738172464_51041525c82381638d4d202735b1f05d.png",
  "shortName": "VCIPL",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8ed",
  "branchCode": "000003",
  "type": "BRANCH",
  "name": "Prabhadevi Branch",
  "email": "cbsprabhadevi@unionbankofindia.com",
  "mobileNo": "22-24220497",
  "alternateMobileNo": "24222391",
  "address": "263, Madhu Hans, Near Century Bazar, Dr. Annie Besant Road,
Prabhadevi, Mumbai - 400 025, State - Maharashtra, Country - India.\r\n",
  "ledgerName": "",
  "fax": "22-24316188",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "6273650cafd7d55eddee2140",
    "role": "DELIVERYPERSON",
```

```
"firstName": "Yash ",
"email": "yashpednekar150@gmail.com",
"lastName": "Pednekar",
"mobileNo": "8779645643",
"shortName": "YP",
"workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "640c34384dda382753e651f2",
  "role": "SITEENGINEER",
  "firstName": "PRASHANT ",
  "email": "kasarprashant121@gmail.com",
  "lastName": "KASAR",
  "mobileNo": "9892524464",
  "designation": "",
  "shortName": "PK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/640c34384dda382753e651f2/
profilePhoto_1678521400647_WhatsApp_Image_20230311_at_12047_PM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "CHECKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
  "lastName": "Bodke",
  "mobileNo": "9821740317",
  "designation": "",
  "shortName": "SB",
  "workWithDocumentMaker": ""
```

```
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\\
\\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "CHECKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "6084131a13f01f158c6ea1f3",
    "PANNo": "AEAPC7114Q",
    "role": "VALUER",
    "firstName": "Sharadkumar",
    "fatherName": "Baburao",
    "email": "cmd@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9422171100",
    "designation": "CMD",
    "registrationNo": [
      {
        "title": {
          "value": "Wealth_Tax",
          "label": "Wealth Tax"
        },
        "_id": "6084131a13f01f158c6ea1f4",
        "number": "[N]C.C.I.T/I -14/52/2008-09"
      }
    ],
    "shortName": "SBC",
```

```
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.23382900146714",
  "longitude": "73.08603087508838"
},
"geo": {
  "type": "Point",
  "coordinates": []
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-04-14T07:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-14T07:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-14T07:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-14T07:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-15T08:32:12.460Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-04-15T08:32:12.460Z"
    }
  ]
}
```

```
}
]
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Fri Apr 14 2023 12:04:23 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Shivaji Nagar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "7",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
```

```
"name": "District",
"key": "district",
"value": "",
"label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sajjan Darshan",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
}
```

```
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Gariba cha wada",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Krushnai Sajjan Darshan",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
```



```
"key": "newSurveyNumber",
"value": "",
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "703",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
}
```

```
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Dombivali West",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
```

```
"value": "rcc_Slab"
},
"flooring": {
  "label": "Vitrified Tile Flooring",
  "value": "VerifiedTileFlooring"
},
"doors": {
  "label": "Teak Wood Door frame with Solid flush door",
  "value": "Teak_Wood_Door_frame_with_Solid_flush_door"
},
"windows": {
  "label": "Powder Coated Aluminium Sliding",
  "value": "PowderCoatedAluminiumSliding"
},
"fittings": {
  "label": "Concealed",
  "value": "Concealed"
},
"finishing": {
  "label": "Good",
  "value": "Good"
}
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Semi Urban",
    "value": "Semi_Urban"
  },
  "townplanApprovedByList": {
    "label": "Kalyan Dombivali Municipal Corporation",
    "value": "Kalyan_Dombivali_Municipal_Corporation"
  },
  "asPerActualAgreement": {
    "south": "Hari om Pooja Bldg",
    "west": "Chall",
    "north": "Shree Umiya Complex ",
    "east": "Aakar Om Darshan Building & Internal Road"
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": ""
  }
}
```

```
"east": ""
}
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Medium",
    "value": "Medium"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Owner Occupied",
    "value": "Owner_Occupied"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  },
  "pavementLaid": {
    "label": "Yes",
    "value": "Yes"
  },
  "carParking": {
    "label": "Stilt + Open Car Parking",
    "value": "Stilt+_Open_Car_Parking"
  },
  "constructionWorkStatus": {
    "label": "Completed",
    "value": "Completed"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2009",
    "fullDate": "1/1/2009"
  },
  "propertyTypeList": {
```

```
"value": "Residential",
"label": "Residential"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"label": "R.C.C. Framed",
"value": "R.C.C."
},
"qualityOfConstruction": {
"label": "Good",
"value": "Good"
},
"walls": {
"label": "Yes",
"value": "1"
},
"appearanceOfTheBuilding": {
"label": "Good",
"value": "Good"
},
"maintenanceOfTheBuilding": {
"label": "Good",
"value": "Good"
},
"visibleDamageInBuilding": {
"label": "No",
"value": "0"
},
"groundStilt": {
"label": "Part Ground + Part Stilt",
"value": "Part_Ground_and_Part_Stilt"
},
"isSiteVisitAllowed": true,
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "0",
"flatFloorNo": "",
"noOfLiftsInEachWings": "0",
"totalLifeBuilding": "60",
"ageOfBuilding": "14",
"estimatedAge": "46",
"noOfDwellingUnitsInBuilding": "4",
```

```
"noOfLifts": "01"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "type": "Point",
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
```



```
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"createCase": "false",
"type": "CASE",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"_id": "6438d77e8989760c1fb6c39d",
"ownerName": "Arun pardeshi",
"ownerPhoneNo": "9967513140",
"appAddress": "shivaji nagar ,krushnai sajan darshan , B wing flat no 703",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "Arun Narayan Pardeshi",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Arun Narayan Pardeshi"
    },
  },
  "isHardCopy": false,
```

```
    "displayStatus": false,
    "id": "775056",
    "path": "cases/6438d77e8989760c1fb6c39d/
document_1681446681452_Agreement__Arun.pdf",
    "fileName": "document_1681446681452_Agreement__Arun.pdf"
  }
],
"caseNumber": "001140",
"createdBy": "6273650cafd7d55eddee2140",
"caseHistory": [
  {
    "id": "258078",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Apr 14 2023 10:03:02 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Arun pardeshi",
    "phone": "9967513140",
    "ownershipShare": "",
    "email": "",
    "id": "516936"
  }
],
"siteInspection": [
  {
    "areaType": {
      "label": "Built Up",
      "value": "Built Up"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    },
    "_id": "643a5a1e108b68389ed73313",
    "area": "635",
    "providedByName": "Arun pardeshi",
    "providedByContactNo": "9967651314"
  },
  {
    "areaType": {
      "label": "Built Up",
      "value": "Built Up"
    }
  },
]
```

```
"providedBy": {
  "label": "Owner",
  "value": "Owner"
},
"_id": "643a5a1e108b68389ed73314",
"area": "635",
"providedByName": "Arun pardeshi",
"providedByContactNo": "9967513140"
}
],
"composition": [
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "363576",
  "name": "Living Room",
  "length": "15.50",
  "length1": "15",
  "length2": "6",
  "width": "9.50",
  "width1": "9",
  "width2": "6",
  "totalArea": "147.25",
  "images": [
    {
      "path": "cases/6438d77e8989760c1fb6c39d/
compositionImg_1681547307836_image.jpeg",
      "orientation": "landscape"
    }
  ],
  "extraAreas": [],
  "finalArea": "147.25"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "name": "Terrace Area",
  "length": "6.00",
  "length1": "6",
  "length2": "00",
  "width": "9.50",
```

```
"width1": "9",
"width2": "6",
"totalArea": "57.00",
"images": [
  {
    "path": "cases/6438d77e8989760c1fb6c39d/
compositionImg_1681547367978_image.jpeg",
    "orientation": "landscape"
  }
],
"extraAreas": [],
"finalArea": "57.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "8.00",
  "length1": "8",
  "length2": "00",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "24.00",
  "images": [
    {
      "path": "cases/6438d77e8989760c1fb6c39d/
compositionImg_1681547399107_image.jpeg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "24.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "4.17",
  "length1": "4",
```

```
"length2": "2",
"width": "3.50",
"width1": "3",
"width2": "6",
"totalArea": "14.58",
"images": [
  {
    "path": "cases/6438d77e8989760c1fb6c39d/
compositionImg_1681547427967_image.jpeg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "14.58"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Kitchen",
  "length": "9.33",
  "length1": "9",
  "length2": "4",
  "width": "7.17",
  "width1": "7",
  "width2": "2",
  "totalArea": "66.89",
  "images": [
    {
      "path": "cases/6438d77e8989760c1fb6c39d/
compositionImg_1681547456215_image.jpeg",
      "orientation": "landscape"
    }
  ],
  "extraAreas": [],
  "finalArea": "66.89"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "WC",
```

```
"length": "3.00",
"length1": "3",
"length2": "00",
"width": "3.75",
"width1": "3",
"width2": "9",
"totalArea": "11.25",
"images": [
  {
    "path": "cases/6438d77e8989760c1fb6c39d/
compositionImg_1681547483638_image.jpeg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "11.25"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "6",
  "name": "Bathroom",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "5.42",
  "width1": "5",
  "width2": "5",
  "totalArea": "21.67",
  "images": [
    {
      "path": "cases/6438d77e8989760c1fb6c39d/
compositionImg_1681547510267_image.jpeg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "21.67"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
}
```

```
"id": "7",
"name": "Bedroom",
"length": "12.83",
"length1": "12",
"length2": "10",
"width": "9.00",
"width1": "9",
"width2": "00",
"totalArea": "115.50",
"images": [
  {
    "path": "cases/6438d77e8989760c1fb6c39d/
compositionImg_1681547537830_image.jpeg",
    "orientation": "landscape"
  }
],
"extraAreas": [],
"finalArea": "115.50"
},
"otherComposition": [
  {
    "name": {
      "label": "Niche",
      "value": "Niche"
    },
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "0",
    "length1": "1",
    "length2": "5",
    "length": "1.42",
    "width1": "8",
    "width": "8.00",
    "totalArea": "11.33",
    "percentageBeforeTotal": "11.33",
    "percentage": "100",
    "finalArea": "11.33",
    "width2": "0",
    "images": [],
    "extraAreas": []
  },
  {
    "name": {
```

```
    "label": "Cupboard",
    "value": "Cupboard"
  },
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "length1": "2",
  "length2": "00",
  "length": "2.00",
  "width1": "7",
  "width": "7.00",
  "totalArea": "14.00",
  "percentageBeforeTotal": "14.00",
  "percentage": "100",
  "width2": "0",
  "images": [],
  "extraAreas": [],
  "finalArea": "14.00"
}
],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "643d1265902fbd517d597651",
    "name": "externalImg_1681723943552_image.jpeg",
    "path": "cases/6438d77e8989760c1fb6c39d/
externalImg_1681723943552_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "643d1265902fbd517d597652",
    "name": "externalImg_1681723945021_image.jpeg",
    "path": "cases/6438d77e8989760c1fb6c39d/
externalImg_1681723945021_image.jpeg",
    "orientation": "portrait"
  },
  {

```



```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "643d1265902fbd517d597653",
    "name": "externallmg_1681723945721_image.jpeg",
    "path": "cases/6438d77e8989760c1fb6c39d/
externallmg_1681723945721_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "643d1265902fbd517d597654",
    "name": "externallmg_1681723947194_image.jpeg",
    "path": "cases/6438d77e8989760c1fb6c39d/
externallmg_1681723947194_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "643d1265902fbd517d597655",
    "name": "externallmg_1681723949953_image.jpeg",
    "path": "cases/6438d77e8989760c1fb6c39d/
externallmg_1681723949953_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "643d1265902fbd517d597656",
    "name": "externallmg_1681723949966_image.jpeg",
    "path": "cases/6438d77e8989760c1fb6c39d/
externallmg_1681723949966_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "643d1265902fbd517d597657",
    "name": "externallmg_1681723949976_image.jpeg",
    "path": "cases/6438d77e8989760c1fb6c39d/
externallmg_1681723949976_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "643d1265902fbd517d597658",
  "name": "externalimg_1681723950557_image.jpeg",
  "path": "cases/6438d77e8989760c1fb6c39d/
externalimg_1681723950557_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "643d1915902fbd517d597fe1",
  "name": "externalimg_1681725713241_image.jpeg",
  "path": "cases/6438d77e8989760c1fb6c39d/
externalimg_1681725713241_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "643d1915902fbd517d597fe2",
  "name": "externalimg_1681725714793_image.jpeg",
  "path": "cases/6438d77e8989760c1fb6c39d/
externalimg_1681725714793_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "643d193c902fbd517d5980a3",
  "name": "externalimg_1681725750052_image.jpeg",
  "path": "cases/6438d77e8989760c1fb6c39d/
externalimg_1681725750052_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "643d193c902fbd517d5980a4",
  "name": "externalimg_1681725751155_image.jpeg",
  "path": "cases/6438d77e8989760c1fb6c39d/
externalimg_1681725751155_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "643d193c902fbd517d5980a5",
    "name": "externalimg_1681725751722_image.jpeg",
    "path": "cases/6438d77e8989760c1fb6c39d/
externalimg_1681725751722_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "643d193c902fbd517d5980a6",
    "name": "externalimg_1681725752022_image.jpeg",
    "path": "cases/6438d77e8989760c1fb6c39d/
externalimg_1681725752022_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "643d193c902fbd517d5980a7",
    "name": "externalimg_1681725752264_image.jpeg",
    "path": "cases/6438d77e8989760c1fb6c39d/
externalimg_1681725752264_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "643d193c902fbd517d5980a8",
    "name": "externalimg_1681725752822_image.jpeg",
    "path": "cases/6438d77e8989760c1fb6c39d/
externalimg_1681725752822_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "643d193c902fbd517d5980a9",
    "name": "externalimg_1681725753216_image.jpeg",
    "path": "cases/6438d77e8989760c1fb6c39d/
externalimg_1681725753216_image.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"createdAt": "2023-04-14T04:33:02.468Z",
"updatedAt": "2023-04-17T10:02:42.579Z",
```

"\_\_v": 0,  
 "fullAddress": "Residential Flat No. 703, 7th Floor, Wing - B, Sajjan Darshan, Krushnai  
 Sajjan Darshan, Gariba cha wada, Village - Shivaji Nagar, Dombivali West, State -  
 Maharashtra, India",  
 "updatedBy": "640c34384dda382753e651f2",  
 "addressForMap": "",  
 "caseReferredBy": "6273650cafd7d55eddee2140",  
 "contactPersonName": "Arun Narayan Pardeshi",  
 "email": "",  
 "isExternal": "false",  
 "isUrgent": "false",  
 "ownershipShare": "",  
 "purchaseValueAsPerDocument": "",  
 "relationWithOwner": "self",  
 "siteVisitContactNo": "9967513140",  
 "briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Terrace Area + 2  
 Passage + WC + Bathroom",  
 "carpetTotal": "0",  
 "finalMeasurementType": "Sq. Ft.",  
 "otherCarpetTotal": "25.33",  
 "siteVisitDate": "2023-04-15"

Name	Length	Width	Total
Composition :			
Living Room	15'6"	9'6"	147.25
Terrace Area	6'00"	9'6"	57.00
Passage	8'00"	3'00"	24.00
Passage	4'2"	3'6"	14.58
Kitchen	9'4"	7'2"	66.89
WC	3'00"	3'9"	11.25
Bathroom	4'00"	5'5"	21.67
Bedroom	12'10"	9'00"	115.50
Other Composition :			
Niche	1'5"	8'0"	11.33
Cupboard	2'00"	7'0"	14.00