

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94231032",
    "firstName": "Namrata Salvi",
    "email": "0_default_racpc.sion@sbi.co.in",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-8879237774"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Namrata Salvi",
    "expectedFees": 2500,
    "quotedAmount": "2500"
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "this is thane branch address",
    "city": "Mumbai"
  },
}
```

```
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1 6th Floor, Kiro Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7177d2ffdf65bcd65882a",
    "role": "PICKUPPERSON",
    "firstName": "Saurabh",
    "email": "saurabhvelonde143@gmail.com",
    "lastName": "Velonde",
    "mobileNo": "8691048846",
    "shortName": "SSV",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users\\60b7177d2ffdf65bcd65882a\
\profilePhoto_1622701681508_WhatsApp Image 2021-06-02 at 11.09.24 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "RAJESH",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "GHADI",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "0123456789",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
  "lastName": "Bodke",
  "mobileNo": "9821740317",
  "designation": "",
  "shortName": "SB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
  "type": "EMPLOYEE",
```

```

    "_id": "5fc78e26625ecd20ec1f88e9",
    "role": "MAKER+CHECKER",
    "firstName": "Vaishali",
    "email": "v.sarmalkar@vastukala.org",
    "lastName": "Sarmalkar",
    "mobileNo": "0123456789",
    "shortName": "VS",
    "workWithDocumentMaker": "1",
    "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
    "designation": ""
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "[N]C.C.I.T/I -14/52/2008-09",
          "label": "Wealth Tax"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "6084131a13f01f158c6ea1f3",
      "PANNo": "AEAPC7114Q",
      "role": "VALUER",
      "firstName": "Sharadkumar",
      "fatherName": "Baburao",
      "email": "cmd@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9422171100",
      "designation": "CMD",
      "registrationNo": [
        {
          "title": {
            "value": "Wealth_Tax",
            "label": "Wealth Tax"
          },
          "_id": "6084131a13f01f158c6ea1f4",
          "number": "[N]C.C.I.T/I -14/52/2008-09"
        }
      ],
      "shortName": "SBC",
      "workWithDocumentMaker": "",
      "profilePhoto": "users\\6084131a13f01f158c6ea1f3\
\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
    }
  ]

```

```
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.025652698666615",
  "longitude": "73.0875420412463"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.0875420412463,
    19.025652698666615
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-04-19T10:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-19T10:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-20T03:12:40.690Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-04-20T03:12:40.690Z"
    }
  ]
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Tue Apr 18 2023 17:05:08 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
```

```
"status": true,
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Kamothe",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "6",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
```

```
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "79\t",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Samarth Apartment\t",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "22",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
```

```
"name": "Street 2",
"key": "street2",
"value": "",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
}
```



```
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "601\t",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
```

```
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "VerifiedTileFlooring"
  },
  "doors": {
    "label": "Teak Wood",
    "value": "TeakWood"
  },
}
```

```
"windows": {
  "label": "Alluminum sliding windows with M. S. Grills",
  "value": "Alluminum_sliding_windows_with_M._S._Grills"
},
"fittings": {
  "label": "Concealed",
  "value": "Concealed"
},
"finishing": {
  "label": "Cement Plastering + POP Finish",
  "value": "Cement_Plastering+_POP_Finish"
}
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Panvel Municipal Corporation",
    "value": "Panvel_Municipal_Corporation"
  },
  "asPerActualAgreement": {
    "north": "OPEN",
    "south": "road ",
    "east": "SHIVYOJANA",
    "west": "CHIRAU HOSPITAL "
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  }
}
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "10000",
  "depreciatedBuildingRate": "2500"
```

```
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "97000",
  "landRate": "33100",
  "igrImage": "cases/643e7be6f8e52b5dd61e80ef/igr_1682089399401_Image.png",
  "squareMeterGuideLineRate": "101850.00",
  "squareFeetGuideLineRate": "9462.00"
},
"igrFinalRate": {
  "rate": "8951.00",
  "squareFeetGuideLineRate": "8951.00",
  "squareMeterGuideLineRate": "96350.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Owner Occupied",
    "value": "Owner_Occupied"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  },
  "pavementLaid": {
    "label": "No",
    "value": "No"
  },
  "carParking": {
    "label": "open",
    "value": "open"
  }
},
```

```
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2015",
  "fullDate": "1/1/2015"
},
"propertyTypeList": {
  "value": "Residential",
  "label": "Residential"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"qualityOfConstruction": {
  "label": "Good",
  "value": "Good"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"maintenanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Part Ground + Part Stilt",
  "value": "Part_Ground_and_Part_Stilt"
},
```

```
"isSiteVisitAllowed": true,
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"flatFloorNo": "",
"noOfLiftsInEachWings": "0",
"totalLifeBuilding": "60",
"ageOfBuilding": "8",
"estimatedAge": "52",
"noOfFloors": "7",
"noOfLifts": "01",
"noOfDwellingUnitsInBuilding": "05"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": [],
    "type": "Point"
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
```

```
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
```



```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0.00",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"taskStatus": {
  "DOCUMENT_VERIFY": false,
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"status": true,
```

```
"caseStatus": "SITEVISITCOMPLETED",
"_id": "643e7be6f8e52b5dd61e80ef",
"ownerName": "Swapnil Shantaram Mane",
"ownerPhoneNo": "9773543137",
"appAddress": "Flat no. 601, 6th Floor, Shree Samarth apartment, Plot no. 79, Sector -
22, Kamothe Navi Mumbai ",
"remark": "Revaluation ",
"documents": [
  {
    "documentType": {
      "label": "Previous Valuation Report",
      "value": "60ae1248aa6d152c1801b2ee"
    },
    "isHardCopy": false,
    "path": "cases/643e7be6f8e52b5dd61e80ef/document_undefined",
    "displayStatus": false,
    "id": "339475",
    "uploadedBy": "60b7177d2ffdf65bcd65882a",
    "createdAt": "Tue Apr 18 2023 16:45:44 GMT+0530 (India Standard Time)",
    "fileName": "document_undefined"
  }
],
"caseNumber": "001208",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "250170",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Apr 18 2023 16:45:50 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Swapnil Shantaram Mane",
    "phone": "9773543137",
    "ownershipShare": "",
    "email": "",
    "id": "528139"
  }
],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    }
  }
]
```

```
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    },
    "_id": "6440ae1c4a39c56781b8a3b9",
    "area": "00",
    "providedByName": "Swapnil Shantaram Mane",
    "providedByContactNo": "9773543137"
  }
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "492416",
    "name": "Living Room",
    "length": "9.75",
    "length1": "9",
    "length2": "9",
    "width": "17.00",
    "width1": "17",
    "width2": "00",
    "totalArea": "165.75",
    "images": [],
    "extraAreas": [],
    "finalArea": "165.75"
  },
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "1",
    "name": "Dining",
    "length": "6.17",
    "length1": "6",
    "length2": "2",
    "width": "9.42",
    "width1": "9",
    "width2": "5",
    "totalArea": "58.07",
    "images": [],
    "extraAreas": []
  }
]
```

```
"finalArea": "58.07"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "6.83",
  "length1": "6",
  "length2": "10",
  "width": "8.75",
  "width1": "8",
  "width2": "9",
  "totalArea": "59.79",
  "images": [],
  "extraAreas": [],
  "finalArea": "59.79"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "length": "12.00",
  "length1": "12",
  "width": "9.00",
  "width1": "9",
  "totalArea": "108.00",
  "finalArea": "108.00",
  "name": "Bedroom",
  "length2": "0",
  "width2": "0",
  "images": [],
  "extraAreas": []
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "7.00",
```

```
"length1": "7",
"length2": "00",
"width": "4.00",
"width1": "4",
"width2": "00",
"totalArea": "28.00",
"images": [],
"extraAreas": [],
"finalArea": "28.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "7.00",
  "length1": "7",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "28.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "28.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "13.33",
  "length1": "13",
  "length2": "4",
  "width": "10.58",
  "width1": "10",
  "width2": "7",
  "totalArea": "141.11",
  "images": [],
  "extraAreas": [],
  "finalArea": "141.11"
},
}
```

```
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "7",
  "name": "Passage",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "12.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.00"
}
],
"otherComposition": [
  {
    "name": {
      "label": "Flower Bed Area",
      "value": "Flower_Bed_Area"
    },
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "0",
    "length1": "2",
    "length2": "00",
    "length": "2.00",
    "width1": "7",
    "width2": "00",
    "width": "7.00",
    "totalArea": "14.00",
    "percentageBeforeTotal": "14.00",
    "images": [],
    "extraAreas": [],
    "percentage": "100",
    "finalArea": "14"
  }
],
"externalReport": [],
"documentPerArea": [],
```

```
"images": [],
"indicatorArr": [
  {
    "_id": "6442a494629ac20845ea8c5a",
    "id": "1",
    "property": "Flat",
    "area": "780",
    "builtUpPercentage": "10",
    "saleablePercentage": "20",
    "rateType": "sale_Instance",
    "areaType": "Built_Up",
    "floor": "-",
    "source": "https://www.99acres.com/",
    "expectedPrice": "8780000",
    "expectedRate": "11256.41",
    "builtUpExpectedRate": "8780000",
    "image": "cases/643e7be6f8e52b5dd61e80ef/
indicator_1682089108208_Image.png"
  },
  {
    "_id": "6442a4cd629ac20845ea8c67",
    "id": "2",
    "property": "Flat",
    "area": "715",
    "builtUpPercentage": "20",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "5",
    "source": "https://www.99acres.com/",
    "expectedPrice": "9500000",
    "expectedRate": "13286.71",
    "builtUpExpectedRate": "11072.26",
    "image": "cases/643e7be6f8e52b5dd61e80ef/
indicator_1682089165736_Image.png"
  },
  {
    "_id": "6442a52d629ac20845ea8c75",
    "id": "3",
    "property": "Flat",
    "area": "673",
    "builtUpPercentage": "20",
    "saleablePercentage": "20",
    "rateType": "sale_Instance",
    "areaType": "Carpet",
    "floor": "5",
```

```
    "source": "Index_no.2",
    "expectedPrice": "6500000",
    "expectedRate": "9658.25",
    "builtUpExpectedRate": "8048.54",
    "image": "cases/643e7be6f8e52b5dd61e80ef/
indicator_1682089261282_Image.png"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6440ae014a39c56781b8a383",
    "name": "externalImg_1681960446646_image.jpeg",
    "path": "cases/643e7be6f8e52b5dd61e80ef/
externalImg_1681960446646_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6440ae014a39c56781b8a384",
    "name": "externalImg_1681960446697_image.jpeg",
    "path": "cases/643e7be6f8e52b5dd61e80ef/
externalImg_1681960446697_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6440ae014a39c56781b8a385",
    "name": "externalImg_1681960446732_image.jpeg",
    "path": "cases/643e7be6f8e52b5dd61e80ef/
externalImg_1681960446732_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6440ae014a39c56781b8a386",
    "name": "externalImg_1681960446762_image.jpeg",
    "path": "cases/643e7be6f8e52b5dd61e80ef/
externalImg_1681960446762_image.jpeg",
    "orientation": "portrait"
  },
  {

```



```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6440ae014a39c56781b8a387",
    "name": "externalImg_1681960446777_image.jpeg",
    "path": "cases/643e7be6f8e52b5dd61e80ef/
externalImg_1681960446777_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6440ae014a39c56781b8a388",
    "name": "externalImg_1681960447232_image.jpeg",
    "path": "cases/643e7be6f8e52b5dd61e80ef/
externalImg_1681960447232_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6440ae014a39c56781b8a389",
    "name": "externalImg_1681960447512_image.jpeg",
    "path": "cases/643e7be6f8e52b5dd61e80ef/
externalImg_1681960447512_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6440ae014a39c56781b8a38a",
    "name": "externalImg_1681960447852_image.jpeg",
    "path": "cases/643e7be6f8e52b5dd61e80ef/
externalImg_1681960447852_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6440ae014a39c56781b8a38b",
    "name": "externalImg_1681960447892_image.jpeg",
    "path": "cases/643e7be6f8e52b5dd61e80ef/
externalImg_1681960447892_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6440ae014a39c56781b8a38c",
    "name": "externalimg_1681960448292_image.jpeg",
    "path": "cases/643e7be6f8e52b5dd61e80ef/
externalimg_1681960448292_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6440ae014a39c56781b8a38d",
    "name": "externalimg_1681960448297_image.jpeg",
    "path": "cases/643e7be6f8e52b5dd61e80ef/
externalimg_1681960448297_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6440ae014a39c56781b8a38e",
    "name": "externalimg_1681960448337_image.jpeg",
    "path": "cases/643e7be6f8e52b5dd61e80ef/
externalimg_1681960448337_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6440ae014a39c56781b8a38f",
    "name": "externalimg_1681960448362_image.jpeg",
    "path": "cases/643e7be6f8e52b5dd61e80ef/
externalimg_1681960448362_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6440ae014a39c56781b8a390",
    "name": "externalimg_1681960448382_image.jpeg",
    "path": "cases/643e7be6f8e52b5dd61e80ef/
externalimg_1681960448382_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```

    "_id": "6440ae014a39c56781b8a391",
    "name": "externalimg_1681960448392_image.jpeg",
    "path": "cases/643e7be6f8e52b5dd61e80ef/
externalimg_1681960448392_image.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-04-18T11:15:50.165Z",
"updatedAt": "2023-04-21T15:03:59.009Z",
"__v": 0,
"fullAddress": "Residential Flat No. 601\t, 6th Floor, Samarth Apartment\t, Plot No.
79\t, Sector 22, Village - Kamothe, State - Maharashtra, India",
"updatedBy": "5fc78e26625ecd20ec1f88e9",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Swapni IShantaram Mane",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9773543137",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Dining + 2 Toilet +
Passage",
"carpetTotal": "600.72",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "14",
"siteVisitDate": "2023-04-20",
"buildingServicesRate": "2500",
"flatRate": "10000",
"landOtherRate": "7500"
}

```

Name	Length	Width	Total
Composition :			
Living Room	9'9"	17'00"	165.75
Dining	6'2"	9'5"	58.07
Kitchen	6'10"	8'9"	59.79
Bedroom	12'0"	9'0"	108.00

Toilet	7'00"	4'00"	28.00
Toilet	7'00"	4'00"	28.00
Bedroom	13'4"	10'7"	141.11
Passage	3'00"	4'00"	12.00
Other Composition :			
Flower Bed Area	2'00"	7'00"	14.00