

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b942312bd",
    "firstName": "Swarup Shivane",
    "email": "0_default_",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-8668951779"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "10000000",
    "discussWithPerson": "Swarup Shivane",
    "expectedFees": 5000,
    "quotedAmount": "2500"
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "this is thane branch address",
    "city": "Mumbai"
  },
}
```

```
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7177d2ffdf65bcd65882a",
    "role": "PICKUPPERSON",
    "firstName": "Saurabh",
    "email": "saurabhvelonde143@gmail.com",
    "lastName": "Velonde",
    "mobileNo": "8691048846",
    "shortName": "SSV",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users\\60b7177d2ffdf65bcd65882a\
\profilePhoto_1622701681508_WhatsApp Image 2021-06-02 at 11.09.24 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9462345132d6a6bddb9d5",
  "role": "SITEENGINEER",
  "firstName": "Dashrath ",
  "email": "dasrat.jaiswar1234@gmail.com",
  "lastName": "Jaiswar",
  "mobileNo": "9987305468",
  "designation": "",
  "shortName": "DFJ",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "0123456789",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "642bad2b91d7c62df117fef2",
  "role": "MAKER",
  "firstName": "Abhishek",
  "email": "abhishekharijan@gmail.com",
  "lastName": "Harijan",
  "mobileNo": "8369839430",
  "designation": "",
  "shortName": "AH",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
```

```
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "0123456789",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"valuers": [
{
  "valuersRegistrationNumber": [
    {
      "value": "[N]C.C.I.T/I -14/52/2008-09",
      "label": "Wealth Tax"
    }
  ],
  "type": "EMPLOYEE",
  "_id": "6084131a13f01f158c6ea1f3",
  "PANNo": "AEAPC7114Q",
  "role": "VALUER",
  "firstName": "Sharadkumar",
  "fatherName": "Baburao",
  "email": "cmd@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9422171100",
  "designation": "CMD",
  "registrationNo": [
    {
      "title": {
        "value": "Wealth_Tax",
        "label": "Wealth Tax"
      },
      "_id": "6084131a13f01f158c6ea1f4",
      "number": "[N]C.C.I.T/I -14/52/2008-09"
    }
  ],
  "shortName": "SBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6084131a13f01f158c6ea1f3\
\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
```

```
"value": "BANK",
"label": "BANK"
},
"location": {
  "latitude": "19.01082973870381",
  "longitude": "72.83323281811228"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.83323281811228,
    19.01082973870381
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-04-19T04:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-19T04:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-19T04:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-19T04:30:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "remark": "MANUAL",
      "status": "COMPLETED",
      "dateTime": "2023-04-24T06:30:00.000Z"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
```

```
"value": "1BHK",
"label": "1 BHK"
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Wed Apr 19 2023 10:03:27 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Lower Parel",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "4",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
```

```
"name": "District",
"key": "district",
"value": "",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai - 400 012",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "580 of TPS - IV",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Lokmanya Nagar Priyadarshini Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
}
```

```
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "7/162 Lokmanya Nagar",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Kakasaheb Gadgil Marg",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
```



```
"key": "newSurveyNumber",
"value": "",
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "1303",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "403",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
}
```

```
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Dadar West",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
```

```
"label": "R. C. C. Slab"
},
"flooring": {
  "value": "VerifiedTileFlooring",
  "label": "Vitrified Tile Flooring"
},
"doors": {
  "value": "TeakWood",
  "label": "Teak Wood"
},
"windows": {
  "value": "Aluminium_Open_Windows",
  "label": "Aluminium Open Windows"
},
"fittings": {
  "value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring",
  "label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring"
},
"finishing": {
  "value": "Good",
  "label": "Good"
}
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Internal Road",
```

```
"west": "Lodha Grandeur ",
"south": "Mill ",
"east": "Shopping Centre "
},
"asPerDocumentAgreement": {
  "north": "Details not available ",
  "west": "Details not available ",
  "south": "Details not available ",
  "east": "Details not available "
},
"extraDetailOfProperty": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "10.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "33685",
  "depreciatedBuildingRate": "2685"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "241620",
  "landRate": "110080",
  "igrImage": "cases/643e896df8e52b5dd61ea3a5/igr_1682492482106_Image.png",
  "squareMeterGuideLineRate": "193296.00",
  "squareFeetGuideLineRate": "17958.00"
},
"igrFinalRate": {
  "rate": "241620",
  "squareMeterGuideLineRate": "193296.00",
  "squareFeetGuideLineRate": "17958.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  }
},
```

```
"monthlyRent": "40,000",
"assessmentNo": "Details not available ",
"taxPaidHolderName": "Details not available ",
"taxAmount": "Details not available ",
"electricityServiceConnectionNo": "Details not available ",
"meterCardHolderName": "Details not available ",
"undividedAreaOfLandAsPerSaleDeed": "Details not available ",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": {
    "value": "Stilt+_Open_Car_Parking",
    "label": "Stilt + Open Car Parking"
  },
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
```

```
"label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2017",
  "fullDate": "1/1/2017"
},
"planningArea": {
  "value": "Residential_cum_Commercial",
  "label": "Residential cum Commercial"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"structuralSafety": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
```

```
"label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "54",
"ageOfBuilding": "6",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "19",
"flatFloorNo": "4",
"noOfLifts": "3",
"noOfDwellingUnitsInBuilding": "6"
},
```

```
"finalPlinthArea": {
  "area": "570.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/643e896df8e52b5dd61ea3a5/
routeMap_1682505661726_Image.png",
    "routeLat": "19.011007",
    "routeLng": "72.833814",
    "stationName": "Parel",
    "routeDistance": "450 Mt"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "ox8lqs",
      "name": "ox8lqs",
      "image": "cases/643e896df8e52b5dd61ea3a5/
routeMap_1682505574803_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
```



```
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "16000375.00",
"bookValue": "0",
"finalValue": "16000375.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEM_GENERATED",
  "date": "Wed Apr 26 2023 16:18:55 GMT+0530 (India Standard Time)",
  "number": "046505",
  "dayCount": "7",
  "monthCount": "406",
  "generatedBy": "642bad2b91d7c62df117fef2"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "10236060.00",
  "selectedBuildUpValue": "570.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6448ffda4d9dc9386408f09e",
      "name":
"externalImg_1682505689645_WhatsApp_Image_20230425_at_125737_PM.jpeg",
      "path": "cases/643e896df8e52b5dd61ea3a5/
externalImg_1682505689645_WhatsApp_Image_20230425_at_125737_PM.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "6448ffda4d9dc9386408f09a",
      "name":
"externalImg_1682505689581_WhatsApp_Image_20230425_at_125736_PM_1.jpeg",
      "path": "cases/643e896df8e52b5dd61ea3a5/
externalImg_1682505689581_WhatsApp_Image_20230425_at_125736_PM_1.jpeg",
      "orientation": "portrait"
    }
  ]
}
```

```
    },
    {
      "status": false,
      "_id": "6448ffda4d9dc9386408f09b",
      "name":
"externallmg_1682505689595_WhatsApp_Image_20230425_at_125736_PM_2.jpeg",
      "path": "cases/643e896df8e52b5dd61ea3a5/
externallmg_1682505689595_WhatsApp_Image_20230425_at_125736_PM_2.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "6448ffda4d9dc9386408f09d",
      "name":
"externallmg_1682505689634_WhatsApp_Image_20230425_at_125737_PM_1.jpeg",
      "path": "cases/643e896df8e52b5dd61ea3a5/
externallmg_1682505689634_WhatsApp_Image_20230425_at_125737_PM_1.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "6448ffda4d9dc9386408f09e",
      "name":
"externallmg_1682505689645_WhatsApp_Image_20230425_at_125737_PM.jpeg",
      "path": "cases/643e896df8e52b5dd61ea3a5/
externallmg_1682505689645_WhatsApp_Image_20230425_at_125737_PM.jpeg",
      "orientation": "portrait"
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "6448ffda4d9dc9386408f090",
      "name": "Bedroom",
      "path": "cases/643e896df8e52b5dd61ea3a5/
externallmg_1682505689470_WhatsApp_Image_20230425_at_125732_PM_1.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "6448ffda4d9dc9386408f092",
      "name": "Kitchen",
      "path": "cases/643e896df8e52b5dd61ea3a5/
externallmg_1682505689489_WhatsApp_Image_20230425_at_125733_PM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6448ffda4d9dc9386408f093",
    "name": "Living Room",
    "path": "cases/643e896df8e52b5dd61ea3a5/
externallmg_1682505689503_WhatsApp_Image_20230425_at_125733_PM_2.jpeg",
    "orientation": "portrait"
  }
]
},
"taskStatus": {
  "DOCUMENT_VERIFY": false,
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": true,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": "LEAD",
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "475.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86A/3"
],
"status": true,
"caseStatus": "READYFORCHECKER",
"_id": "643e896df8e52b5dd61ea3a5",
"ownerName": "Mrs. Hausabai Sambhaji Mane",
"ownerPhoneNo": "9004403941",
"appAddress": "Flat no. B- 403, 4th Floor, Lokmanya Nagar Priyadarshini CHS.,
Lokmanya Nagar, Kakasaheb Gadgil Marg, Dadar West ",
"remark": "",
"documents": [
  {
    "documentType": {
```

```
"value": "60ae1255aa6d152c1801b329",
"label": "Possession Receipt"
},
"inputs": {
  "documentDate": "30/06/2016",
  "nameOfApprovingAuthority": {
    "value": "SOCIETY",
    "label": "SOCIETY"
  }
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1682502734254_Possession_Receipt.pdf",
"path": "cases/643e896df8e52b5dd61ea3a5/
document_1682502734254_Possession_Receipt.pdf",
"id": "571336",
"uploadedBy": "642bad2b91d7c62df117fef2",
"createdAt": "Wed Apr 26 2023 15:25:14 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "17/11/2011",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "EEBPC/4414/GN/A"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1682502798248_CC.pdf",
"path": "cases/643e896df8e52b5dd61ea3a5/document_1682502798248_CC.pdf",
"id": "910895",
"uploadedBy": "642bad2b91d7c62df117fef2",
"createdAt": "Wed Apr 26 2023 15:25:14 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
```

```
"value": "60ae124baa6d152c1801b2fd",
"label": "Occupancy Certificate"
},
"inputs": {
  "documentDate": "23/02/2016",
  "nameOfApprovingAuthority": {
    "value": "Municipal_Corporation_Of_Greater_Mumbai",
    "label": "Municipal Corporation Of Greater Mumbai"
  },
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "EB/4414/GN/A"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1682502859488_OC.pdf",
"path": "cases/643e896df8e52b5dd61ea3a5/document_1682502859488_OC.pdf",
"id": "866320",
"uploadedBy": "642bad2b91d7c62df117fef2",
"createdAt": "Wed Apr 26 2023 15:25:14 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1264aa6d152c1801b371",
    "label": "Share Certificate "
  },
  "inputs": {
    "documentDate": "14/03/2004",
    "nameOfApprovingAuthority": {
      "value": "SOCIETY",
      "label": "SOCIETY"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "267"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1682502909219_Share_Certificate.pdf",
  "path": "cases/643e896df8e52b5dd61ea3a5/
document_1682502909219_Share_Certificate.pdf",
  "id": "933764",
```



```
"uploadedBy": "642bad2b91d7c62df117fef2",
"createdAt": "Wed Apr 26 2023 15:25:14 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "001212",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "105115",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Apr 18 2023 17:43:33 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Hausabai Sambhaji Mane",
    "phone": "9004403941",
    "email": "",
    "ownershipShare": "",
    "id": "273264"
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "211936",
    "name": "Dining",
    "length": "11.83",
    "length1": "11",
    "length2": "10",
    "width": "8.50",
    "width1": "8",
    "width2": "6",
    "totalArea": "100.58",
    "images": [],
    "extraAreas": [],
    "finalArea": "100.58"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Living Room",
  "length": "8.75",
  "length1": "8",
  "length2": "9",
  "width": "11.50",
  "width1": "11",
  "width2": "6",
  "totalArea": "100.62",
  "images": [],
  "extraAreas": [],
  "finalArea": "100.62"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "6.67",
  "length1": "6",
  "length2": "8",
  "width": "3.33",
  "width1": "3",
  "width2": "4",
  "totalArea": "22.22",
  "images": [],
  "extraAreas": [],
  "finalArea": "22.22"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Kitchen",
  "length": "13.83",
  "length1": "13",
  "length2": "10",
  "width": "5.75",
  "width1": "5",
  "width2": "9",
```

```
"totalArea": "79.54",
"images": [],
"extraAreas": [],
"finalArea": "79.54"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "WC",
  "length": "4.17",
  "length1": "4",
  "length2": "2",
  "width": "3.17",
  "width1": "3",
  "width2": "2",
  "totalArea": "13.19",
  "images": [],
  "extraAreas": [],
  "finalArea": "13.19"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bathroom",
  "length": "",
  "length1": "4",
  "length2": "8",
  "width": "",
  "width1": "5",
  "width2": "9",
  "totalArea": "26.83",
  "images": [],
  "finalArea": "26.83",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
}
```

```
"id": "6",
"name": "Bedroom",
"length": "13.83",
"length1": "13",
"length2": "10",
"width": "9.58",
"width1": "9",
"width2": "7",
"totalArea": "132.57",
"images": [],
"extraAreas": [],
"finalArea": "132.57"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60ae1255aa6d152c1801b329",
    "label": "Possession Receipt"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "684551",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "475",
  "squareMeterArea": "44.13",
  "docFinalBuiltUp": "570",
  "docFinalBuiltUpSquareMeter": "52.956",
  "docBultupPercentage": "20",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "6448cb45d11ef125ab266e44",
  "id": "1",
  "property": "Flat",
  "area": "480",
```

```
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "15500000",
"expectedRate": "32291.67",
"builtUpExpectedRate": "26909.72",
"image": "cases/643e896df8e52b5dd61ea3a5/
indicator_1682492229744_Image.png"
},
{
  "printlnReport": true,
  "_id": "6448cb8bd11ef125ab266e5f",
  "id": "3",
  "property": "Flat",
  "area": "250",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "6",
  "source": "Index_no.2",
  "expectedPrice": "7500000",
  "expectedRate": "30000.00",
  "builtUpExpectedRate": "25000.00",
  "image": "cases/643e896df8e52b5dd61ea3a5/
indicator_1682492299859_Image.png"
},
{
  "printlnReport": true,
  "_id": "6448cc0ad11ef125ab267004",
  "id": "3",
  "property": "Flat",
  "area": "475",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "Nobroker.com",
  "expectedPrice": "16500000",
  "expectedRate": "34736.84",
  "builtUpExpectedRate": "28947.37",
  "image": "cases/643e896df8e52b5dd61ea3a5/
indicator_1682492426365_Image.png"
```

```
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6448ffda4d9dc9386408f08d",
    "name":
"externallmg_1682505689389_WhatsApp_Image_20230425_at_125730_PM_3.jpeg",
    "path": "cases/643e896df8e52b5dd61ea3a5/
externallmg_1682505689389_WhatsApp_Image_20230425_at_125730_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6448ffda4d9dc9386408f08e",
    "name":
"externallmg_1682505689445_WhatsApp_Image_20230425_at_125731_PM_1.jpeg",
    "path": "cases/643e896df8e52b5dd61ea3a5/
externallmg_1682505689445_WhatsApp_Image_20230425_at_125731_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6448ffda4d9dc9386408f08f",
    "name":
"externallmg_1682505689450_WhatsApp_Image_20230425_at_125731_PM.jpeg",
    "path": "cases/643e896df8e52b5dd61ea3a5/
externallmg_1682505689450_WhatsApp_Image_20230425_at_125731_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6448ffda4d9dc9386408f090",
    "name":
"externallmg_1682505689470_WhatsApp_Image_20230425_at_125732_PM_1.jpeg",
    "path": "cases/643e896df8e52b5dd61ea3a5/
externallmg_1682505689470_WhatsApp_Image_20230425_at_125732_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "6448ffda4d9dc9386408f091",
    "name":
"externallmg_1682505689485_WhatsApp_Image_20230425_at_125732_PM.jpeg",
    "path": "cases/643e896df8e52b5dd61ea3a5/
externallmg_1682505689485_WhatsApp_Image_20230425_at_125732_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6448ffda4d9dc9386408f092",
    "name":
"externallmg_1682505689489_WhatsApp_Image_20230425_at_125733_PM_1.jpeg",
    "path": "cases/643e896df8e52b5dd61ea3a5/
externallmg_1682505689489_WhatsApp_Image_20230425_at_125733_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6448ffda4d9dc9386408f093",
    "name":
"externallmg_1682505689503_WhatsApp_Image_20230425_at_125733_PM_2.jpeg",
    "path": "cases/643e896df8e52b5dd61ea3a5/
externallmg_1682505689503_WhatsApp_Image_20230425_at_125733_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6448ffda4d9dc9386408f094",
    "name":
"externallmg_1682505689515_WhatsApp_Image_20230425_at_125733_PM.jpeg",
    "path": "cases/643e896df8e52b5dd61ea3a5/
externallmg_1682505689515_WhatsApp_Image_20230425_at_125733_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6448ffda4d9dc9386408f095",
    "name":
"externallmg_1682505689526_WhatsApp_Image_20230425_at_125734_PM_1.jpeg",
    "path": "cases/643e896df8e52b5dd61ea3a5/
externallmg_1682505689526_WhatsApp_Image_20230425_at_125734_PM_1.jpeg",
    "orientation": "portrait"
  }
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6448ffda4d9dc9386408f096",
      "name":
"externallmg_1682505689542_WhatsApp_Image_20230425_at_125734_PM_2.jpeg",
      "path": "cases/643e896df8e52b5dd61ea3a5/
externallmg_1682505689542_WhatsApp_Image_20230425_at_125734_PM_2.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6448ffda4d9dc9386408f097",
      "name":
"externallmg_1682505689558_WhatsApp_Image_20230425_at_125734_PM.jpeg",
      "path": "cases/643e896df8e52b5dd61ea3a5/
externallmg_1682505689558_WhatsApp_Image_20230425_at_125734_PM.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6448ffda4d9dc9386408f098",
      "name":
"externallmg_1682505689567_WhatsApp_Image_20230425_at_125735_PM_1.jpeg",
      "path": "cases/643e896df8e52b5dd61ea3a5/
externallmg_1682505689567_WhatsApp_Image_20230425_at_125735_PM_1.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6448ffda4d9dc9386408f099",
      "name":
"externallmg_1682505689574_WhatsApp_Image_20230425_at_125735_PM.jpeg",
      "path": "cases/643e896df8e52b5dd61ea3a5/
externallmg_1682505689574_WhatsApp_Image_20230425_at_125735_PM.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6448ffda4d9dc9386408f09a",
      "name":
"externallmg_1682505689581_WhatsApp_Image_20230425_at_125736_PM_1.jpeg",
```



```
    "path": "cases/643e896df8e52b5dd61ea3a5/
externallmg_1682505689581_WhatsApp_Image_20230425_at_125736_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6448ffda4d9dc9386408f09b",
    "name":
"externallmg_1682505689595_WhatsApp_Image_20230425_at_125736_PM_2.jpeg",
    "path": "cases/643e896df8e52b5dd61ea3a5/
externallmg_1682505689595_WhatsApp_Image_20230425_at_125736_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6448ffda4d9dc9386408f09c",
    "name":
"externallmg_1682505689625_WhatsApp_Image_20230425_at_125736_PM.jpeg",
    "path": "cases/643e896df8e52b5dd61ea3a5/
externallmg_1682505689625_WhatsApp_Image_20230425_at_125736_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6448ffda4d9dc9386408f09d",
    "name":
"externallmg_1682505689634_WhatsApp_Image_20230425_at_125737_PM_1.jpeg",
    "path": "cases/643e896df8e52b5dd61ea3a5/
externallmg_1682505689634_WhatsApp_Image_20230425_at_125737_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6448ffda4d9dc9386408f09e",
    "name":
"externallmg_1682505689645_WhatsApp_Image_20230425_at_125737_PM.jpeg",
    "path": "cases/643e896df8e52b5dd61ea3a5/
externallmg_1682505689645_WhatsApp_Image_20230425_at_125737_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
```

```
"createdAt": "2023-04-18T12:13:33.847Z",
"updatedAt": "2023-05-02T10:15:42.911Z",
"__v": 0,
"fullAddress": "Residential Flat No. 403, 4th Floor, Lokmanya Nagar Priyadarshini Co-
op. Hsg. Soc. Ltd., Plot No. 580 of TPS - IV, 7/162 Lokmanya Nagar, Kakasaheb Gadgil
Marg, Village - Lower Parel, Dadar West, Mumbai - 400 012, State - Maharashtra,
India",
"updatedBy": "642bad2b91d7c62df117fef2",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mrs. Hausabai Sambhaji Mane",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9004403941",
"reason": "",
"buildingServicesRate": "3000",
"flatRate": "34000",
"landOtherRate": "31000",
"siteVisitDate": "2023-04-24",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Dining + Passage +
WC + Bathroom",
"carpetTotal": "475.55",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "570.66",
"finalCarpetArea": "475.55",
"finalSalableArea": "570.66",
"salablePercentage": "0",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Possession Receipt",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 475.00",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"
}
```

Name	Length	Width	Total
Composition :			
Dining	11'10"	8'6"	100.58
Living Room	8'9"	11'6"	100.62
Passage	6'8"	3'4"	22.22
Kitchen	13'10"	5'9"	79.54
WC	4'2"	3'2"	13.19
Bathroom	4'8"	5'9"	26.83
Bedroom	13'10"	9'7"	132.57
Other Composition :			