

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9ff"
    },
    "type": "CREDITOFFICER",
    "_id": "635f7d78e363ef22db2f2888",
    "firstName": "Amita ",
    "lastName": "Patel",
    "mobileNo": "",
    "email": "me2@me.com",
    "workMobileNo": "8691048841"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "42000000",
    "discussWithPerson": "Amita ",
    "expectedFees": 21000,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
    "city": "Mumbai"
  }
}
```

```
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9ff",
  "branchCode": "000220",
  "type": "BRANCH",
  "name": "RASMECCC Panvel",
  "email": "cord.21117@sbi.co.in",
  "mobileNo": "02227572748",
  "alternateMobileNo": "",
  "address": "Shop No 5,Ground Floor,Sharda Terrace, Plot No 65,Sector-11,CBD
Belapur, Navi Mumbai, Taluka & District - Thane, State - Maharashtra, Country - India",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7189d2ffdf65bcd65882b",
    "role": "PICKUPPERSON",
    "firstName": "Ravindra",
    "email": "ravindrakasare186@gmail.com",
    "lastName": "Kasare",
    "mobileNo": "9167204055",
    "shortName": "RBK",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users\\60b7189d2ffdf65bcd65882b\
\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "RAJESH",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "GHADI",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "0123456789",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
  "mobileNo": "9529385821",
  "designation": "",
  "shortName": "PR",
  "workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
  "profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
```

```

    "_id": "5fc78e26625ecd20ec1f88e9",
    "role": "MAKER+CHECKER",
    "firstName": "Vaishali",
    "email": "v.sarmalkar@vastukala.org",
    "lastName": "Sarmalkar",
    "mobileNo": "0123456789",
    "shortName": "VS",
    "workWithDocumentMaker": "1",
    "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
    "designation": ""
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "[N]C.C.I.T/I -14/52/2008-09",
          "label": "Wealth Tax"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "6084131a13f01f158c6ea1f3",
      "PANNo": "AEAPC7114Q",
      "role": "VALUER",
      "firstName": "Sharadkumar",
      "fatherName": "Baburao",
      "email": "cmd@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9422171100",
      "designation": "CMD",
      "registrationNo": [
        {
          "title": {
            "value": "Wealth_Tax",
            "label": "Wealth Tax"
          },
          "_id": "6084131a13f01f158c6ea1f4",
          "number": "[N]C.C.I.T/I -14/52/2008-09"
        }
      ],
      "shortName": "SBC",
      "workWithDocumentMaker": "",
      "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
    }
  ]
}

```

```
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.02407581753253",
  "longitude": "73.09440937812573"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.09440937812573,
    19.02407581753253
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-04-26T02:13:10.801Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-26T02:13:59.757Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-26T02:13:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-26T02:13:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-26T02:13:00.000Z",
      "remark": ""
    }
  ]
},
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2023-04-26T02:13:10.801Z"
  },
  {

```

```
    "status": "COMPLETED",
    "dateTime": "2023-04-26T02:13:59.757Z"
  },
  {
    "remark": "MANUAL",
    "status": "COMPLETED",
    "dateTime": "2023-04-25T18:30:00.000Z"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Thu Apr 20 2023 17:46:25 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kamothe",
    "label": true
  },
  "floorNo": {
    "status": true,
```

```
"name": "Floor No",
"key": "floorNo",
"value": "3",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Raigad",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Panvel",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "1 & 22",
  "label": true
}
```

```
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Mayur Park Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "36",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "G",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
```



```
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "301",
  "label": false
},
}
```

```
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
```

```
"value": "PIN - 410 206",
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "VerifiedTileFlooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "label": "Concealed",
    "value": "Concealed"
  },
  "finishing": {
    "label": "Cement Plastering + POP Finish",
    "value": "Cement_Plastering_+_POP_Finish"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  }
},
```

```
"populationGroupList": {
  "label": "Urban",
  "value": "Urban"
},
"townplanApprovedByList": {
  "value": "CIDCO",
  "label": "City Industrial Development Corporation of Maharashtra"
},
"whetherCoveredUnderAnyState": {
  "value": "Yes",
  "label": "Yes"
},
"asPerActualAgreement": {
  "north": "Wing - J",
  "south": "Internal Road",
  "east": "Wing - F",
  "west": "Internal Road"
},
"asPerDocumentAgreement": {
  "north": "Plot No. 21",
  "west": "Proposed 15.00 Mtr. Wide Road",
  "south": "Proposed 22.00 Mtr. Wide Road",
  "east": "Plot No. 1 & 2"
},
"extraDetailOfProperty": "Details not available"
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "24",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "10400",
  "depreciatedBuildingRate": "1900"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "100100",
  "landRate": "35500",
  "igrImage": "cases/64412768f8dc9a26350cd3a8/igr_1682676154630_Image.png",
  "squareMeterGuideLineRate": "85085.00",
  "squareFeetGuideLineRate": "7905.00"
},
"igrFinalRate": {
  "rate": "7168.00",
  "squareFeetGuideLineRate": "7168.00",
  "squareMeterGuideLineRate": "77151.00"
```

```
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Vacant",
    "value": "Vacant"
  },
  "monthlyRent": "10,000",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "CIDCO",
  "tenantName": "",
  "maintenanceOfFlat": "Details not available"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Details not available",
  "negativeFactorsOfAffectMarketValue": "Details not available"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MuncipalWaterSupply"
  }
},
```

```
"pavementLaid": {
  "label": "Yes",
  "value": "Yes"
},
"carParking": {
  "value": "Open_Car_Parking",
  "label": "Open Car Parking"
},
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2007",
  "fullDate": "1/1/2007"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed",
  "value": "R.C.C."
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
}
```

```
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenancelssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "label": "Yes",
  "value": "1"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "label": "Part Ground + Part Stilt",
  "value": "Part_Ground_and_Part_Stilt"
},
"yearOfConstructionAsPer": {
  "value": "As_Per_Occupancy_Certificate",
```

```
"label": "As Per Occupancy Certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "16",
"totalLifeBuilding": "60",
"estimatedAge": "44",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "4",
"flatFloorNo": "3",
"noOfLifts": "0",
"noOfDwellingUnitsInBuilding": "04"
},
"finalPlinthArea": {
  "area": "459.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/64412768f8dc9a26350cd3a8/
routeMap_1682754089901_Image.png",
    "routeLat": "19.024076",
    "routeLng": "73.094409",
    "stationName": "Kharghar",
    "routeDistance": "5.3 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "f1qera",
```



```
    "name": "f1qera",
    "image": "cases/64412768f8dc9a26350cd3a8/
routeMap_1682753882696_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "4773600.00",
  "bookValue": "0",
  "finalValue": "4773600.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEM_GENERATED",
  "date": "Sat Apr 29 2023 14:18:50 GMT+0530 (India Standard Time)",
  "number": "046530",
  "dayCount": "2",
  "monthCount": "431",
  "generatedBy": "62fe044a48a26047e6552796"
```

```
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "3290112.00",
  "selectedBuildUpValue": "459.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "64488879d11ef125ab260503",
      "name": "externalimg_1682475127583_1682475002122_image_11.jpeg",
      "path": "cases/64412768f8dc9a26350cd3a8/
externalimg_1682475127583_1682475002122_image_11.jpeg",
```

```
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [
  {
    "status": false,
    "_id": "64488879d11ef125ab2604f4",
    "name": "externallmg_1682475102404_1682474980902_image_14.jpeg",
    "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475102404_1682474980902_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64488879d11ef125ab260501",
    "name": "externallmg_1682475124921_1682475002122_image_9.jpeg",
    "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475124921_1682475002122_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "64488879d11ef125ab2604f1",
    "name": "externallmg_1682475102393_1682474980902_image_11.jpeg",
    "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475102393_1682474980902_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64488879d11ef125ab2604f7",
    "name": "externallmg_1682475102612_1682474980902_image_17.jpeg",
    "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475102612_1682474980902_image_17.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "64488879d11ef125ab2604ec",
    "name": "externallmg_1682475100432_1682474980902_image_6.jpeg",
    "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475100432_1682474980902_image_6.jpeg",
```

```
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "64488879d11ef125ab2604e6",
    "name": "Living Room",
    "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475100291_1682474980902_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64488879d11ef125ab2604e8",
    "name": "Living Room",
    "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475100351_1682474980902_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64488879d11ef125ab2604ed",
    "name": "Living Room",
    "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475100461_1682474980902_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64488879d11ef125ab260504",
    "name": "Living Room",
    "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475127584_1682475002122_image_12.jpeg",
    "orientation": "portrait"
  }
]
},
"taskStatus": {
  "DOCUMENT_VERIFY": false,
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": true,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
```

```
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": "LEAD",
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "459.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86A/3"
],
"status": true,
"caseStatus": "DELIVERED",
"_id": "64412768f8dc9a26350cd3a8",
"ownerName": "Mr. Ganesh Trimbak Jadhav & Mrs. Vrushali Ganesh Jadhav",
"ownerPhoneNo": "9594090200",
"appAddress": "flat no G 301 3th floor mayur park cHs Ltd plot no 01 and 22 Sector no
36 kamothe ",
"remark": "vijendra number 9594090200",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "18/04/2023",
      "from": {
        "value": "The_Transferor",
        "label": "The Transferor"
      },
      "The_Transferor": "Mr. Sandip Ganpat Lubal & Mrs. Asha Sandip Lubal",
      "to": {
        "value": "The_Transferee",
        "label": "The Transferee"
      },
      "The_Transferee": "Mr. Ganesh Trimbak Jadhav & Mrs. Vrushali Ganesh Jadhav",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      }
    },
    "Document_No": "3527 / 2023"
  }
]
```

```
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "466676",
    "path": "cases/64412768f8dc9a26350cd3a8/
document_1681992794412_sbi_Rasmecc_panvel_Ganesh_T_Jadhav.pdf",
    "fileName":
"document_1681992794412_sbi_Rasmecc_panvel_Ganesh_T_Jadhav.pdf"
  },
  {
    "documentType": {
      "value": "60ae124baa6d152c1801b2fd",
      "label": "Occupancy Certificate"
    },
    "inputs": {
      "documentDate": "04/05/2007",
      "nameOfApprovingAuthority": {
        "value": "City_and_Industrial_Development_Corp_Of_Maharashtra_ltd.",
        "label": "City and Industrial Development Corp Of Maharashtra ltd."
      },
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "CIDCO / BP / ATPO / 733"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/64412768f8dc9a26350cd3a8/
document_1682751972332_document.pdf",
    "fileName": "document_1682751972332_document.pdf",
    "id": "358535",
    "uploadedBy": "62fe044a48a26047e6552796",
    "createdAt": "Sat Apr 29 2023 12:39:05 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    },
    "inputs": {
      "documentDate": "23/10/2003",
      "nameOfApprovingAuthority": {
        "value": "City_and_Industrial_Development_Corp_Of_Maharashtra_ltd.",
        "label": "City and Industrial Development Corp Of Maharashtra ltd."
      },
    },
  },
}
```



```
"number": {
  "value": "Document_No",
  "label": "Document No"
},
"Document_No": "CIDCO / BP / ATPO / 201"
},
"isHardCopy": false,
"displayStatus": false,
"path": "cases/64412768f8dc9a26350cd3a8/
document_1682752091825_document.pdf",
"fileName": "document_1682752091825_document.pdf",
"id": "665332",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Sat Apr 29 2023 12:39:05 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "001255",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "490712",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Apr 20 2023 17:22:08 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Ganesh Trimbak Jadhav & Mrs. Vrushali Ganesh Jadhav",
    "phone": "9594090200",
    "email": "",
    "ownershipShare": "",
    "id": "635919"
  }
],
"siteInspection": [
  {
    "areaType": {
      "label": "Saleable",
      "value": "Saleable"
    },
    "providedBy": {
      "label": "Other",
      "value": "Other"
    }
  },
  {
    "_id": "6447f126d11ef125ab25fa42",
```

```
"area": "00",
"providedByName": "YOGESH KARANDE",
"providedByContactNo": "098207 498"
},
],
"composition": [
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "775508",
  "name": "Bedroom",
  "length": "10.25",
  "length1": "10",
  "length2": "3",
  "width": "12.67",
  "width1": "12",
  "width2": "8",
  "totalArea": "129.83",
  "images": [],
  "extraAreas": [],
  "finalArea": "129.83"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "name": "Passage",
  "length": "2.75",
  "length1": "2",
  "length2": "9",
  "width": "5.17",
  "width1": "5",
  "width2": "2",
  "totalArea": "14.21",
  "images": [],
  "extraAreas": [],
  "finalArea": "14.21"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  }
}
```

```
},
  "id": "2",
  "name": "Kitchen",
  "length": "7.83",
  "length1": "7",
  "length2": "10",
  "width": "6.92",
  "width1": "6",
  "width2": "11",
  "totalArea": "54.18",
  "images": [],
  "extraAreas": [],
  "finalArea": "54.18"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "2.00",
  "length1": "2",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "8.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "8.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "WC",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "12.00",
```

```
"images": [],
"extraAreas": [],
"finalArea": "12.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "Bathroom",
  "length": "3.83",
  "length1": "3",
  "length2": "10",
  "width": "3.83",
  "width1": "3",
  "width2": "10",
  "totalArea": "14.69",
  "images": [],
  "extraAreas": [],
  "finalArea": "14.69"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "6",
  "name": "Living Room",
  "length": "8.92",
  "length1": "8",
  "length2": "11",
  "width": "15.33",
  "width1": "15",
  "width2": "4",
  "totalArea": "136.72",
  "images": [],
  "extraAreas": [],
  "finalArea": "136.72"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
```

```
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "686848",
  "selectAreaTypeDocument": "Built_Up",
  "totalAreaDocument": "459",
  "squareMeterArea": "42.64",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docBUILTUPPercentage": "",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "644b9706ba47a23af30e35c3",
    "id": "1",
    "property": "Flat",
    "area": "450",
    "builtUpPercentage": "20",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "5",
    "source": "https://www.99acres.com/",
    "expectedPrice": "5300000",
    "expectedRate": "11777.78",
    "builtUpExpectedRate": "9814.81",
    "image": "cases/64412768f8dc9a26350cd3a8/
indicator_1682675462332_Image.png"
  },
  {
    "printlnReport": true,
    "_id": "644b9734ba47a23af30e360e",
    "id": "2",
    "property": "Flat",
    "area": "420",
    "builtUpPercentage": "20",
```

```
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "6500000",
"expectedRate": "15476.19",
"builtUpExpectedRate": "12896.83",
"image": "cases/64412768f8dc9a26350cd3a8/
indicator_1682675508011_Image.png"
},
{
  "printlnReport": true,
  "_id": "644b9773ba47a23af30e363a",
  "id": "3",
  "property": "Flat",
  "area": "450",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "3",
  "source": "https://www.99acres.com/",
  "expectedPrice": "5700000",
  "expectedRate": "12666.67",
  "builtUpExpectedRate": "10555.56",
  "image": "cases/64412768f8dc9a26350cd3a8/
indicator_1682675571592_Image.png"
},
{
  "printlnReport": true,
  "_id": "644b97d1ba47a23af30e3760",
  "id": "4",
  "property": "Flat",
  "area": "735",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "6",
  "source": "https://www.99acres.com/",
  "expectedPrice": "7000000",
  "expectedRate": "9523.81",
  "builtUpExpectedRate": "7000000",
  "image": "cases/64412768f8dc9a26350cd3a8/
indicator_1682675665032_Image.png"
```

```
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64488879d11ef125ab2604e6",
    "name": "externallmg_1682475100291_1682474980902_image_0.jpeg",
    "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475100291_1682474980902_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64488879d11ef125ab2604e7",
    "name": "externallmg_1682475100342_1682474980902_image_1.jpeg",
    "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475100342_1682474980902_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64488879d11ef125ab2604e8",
    "name": "externallmg_1682475100351_1682474980902_image_2.jpeg",
    "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475100351_1682474980902_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64488879d11ef125ab2604e9",
    "name": "externallmg_1682475100372_1682474980902_image_3.jpeg",
    "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475100372_1682474980902_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64488879d11ef125ab2604ea",
    "name": "externallmg_1682475100386_1682474980902_image_4.jpeg",
    "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475100386_1682474980902_image_4.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64488879d11ef125ab2604eb",
  "name": "externallmg_1682475100411_1682474980902_image_5.jpeg",
  "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475100411_1682474980902_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64488879d11ef125ab2604ec",
  "name": "externallmg_1682475100432_1682474980902_image_6.jpeg",
  "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475100432_1682474980902_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64488879d11ef125ab2604ed",
  "name": "externallmg_1682475100461_1682474980902_image_7.jpeg",
  "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475100461_1682474980902_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64488879d11ef125ab2604ee",
  "name": "externallmg_1682475100476_1682474980902_image_8.jpeg",
  "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475100476_1682474980902_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64488879d11ef125ab2604ef",
  "name": "externallmg_1682475100486_1682474980902_image_9.jpeg",
  "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475100486_1682474980902_image_9.jpeg",
  "orientation": "landscape"
}
```



```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64488879d11ef125ab2604f0",
      "name": "externallmg_1682475102392_1682474980902_image_10.jpeg",
      "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475102392_1682474980902_image_10.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64488879d11ef125ab2604f1",
      "name": "externallmg_1682475102393_1682474980902_image_11.jpeg",
      "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475102393_1682474980902_image_11.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64488879d11ef125ab2604f2",
      "name": "externallmg_1682475102395_1682474980902_image_12.jpeg",
      "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475102395_1682474980902_image_12.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64488879d11ef125ab2604f3",
      "name": "externallmg_1682475102396_1682474980902_image_13.jpeg",
      "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475102396_1682474980902_image_13.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64488879d11ef125ab2604f4",
      "name": "externallmg_1682475102404_1682474980902_image_14.jpeg",
      "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475102404_1682474980902_image_14.jpeg",
      "orientation": "portrait"
    },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64488879d11ef125ab2604f5",
  "name": "externallmg_1682475102404_1682474980902_image_15.jpeg",
  "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475102404_1682474980902_image_15.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64488879d11ef125ab2604f6",
  "name": "externallmg_1682475102491_1682474980902_image_16.jpeg",
  "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475102491_1682474980902_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64488879d11ef125ab2604f7",
  "name": "externallmg_1682475102612_1682474980902_image_17.jpeg",
  "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475102612_1682474980902_image_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64488879d11ef125ab2604f8",
  "name": "externallmg_1682475124751_1682475002122_image_0.jpeg",
  "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475124751_1682475002122_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64488879d11ef125ab2604f9",
  "name": "externallmg_1682475124781_1682475002122_image_1.jpeg",
  "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475124781_1682475002122_image_1.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64488879d11ef125ab2604fa",
    "name": "externallmg_1682475124792_1682475002122_image_2.jpeg",
    "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475124792_1682475002122_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64488879d11ef125ab2604fb",
    "name": "externallmg_1682475124811_1682475002122_image_3.jpeg",
    "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475124811_1682475002122_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64488879d11ef125ab2604fc",
    "name": "externallmg_1682475124826_1682475002122_image_4.jpeg",
    "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475124826_1682475002122_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64488879d11ef125ab2604fd",
    "name": "externallmg_1682475124846_1682475002122_image_5.jpeg",
    "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475124846_1682475002122_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64488879d11ef125ab2604fe",
    "name": "externallmg_1682475124871_1682475002122_image_6.jpeg",
    "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475124871_1682475002122_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
"status": false,
  "_id": "64488879d11ef125ab2604ff",
  "name": "externallmg_1682475124892_1682475002122_image_7.jpeg",
  "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475124892_1682475002122_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64488879d11ef125ab260500",
  "name": "externallmg_1682475124906_1682475002122_image_8.jpeg",
  "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475124906_1682475002122_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64488879d11ef125ab260501",
  "name": "externallmg_1682475124921_1682475002122_image_9.jpeg",
  "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475124921_1682475002122_image_9.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64488879d11ef125ab260502",
  "name": "externallmg_1682475127582_1682475002122_image_10.jpeg",
  "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475127582_1682475002122_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64488879d11ef125ab260503",
  "name": "externallmg_1682475127583_1682475002122_image_11.jpeg",
  "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475127583_1682475002122_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
```

```
    "_id": "64488879d11ef125ab260504",
    "name": "externallmg_1682475127584_1682475002122_image_12.jpeg",
    "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475127584_1682475002122_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64488879d11ef125ab260505",
    "name": "externallmg_1682475127585_1682475002122_image_13.jpeg",
    "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475127585_1682475002122_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64488879d11ef125ab260506",
    "name": "externallmg_1682475127591_1682475002122_image_14.jpeg",
    "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475127591_1682475002122_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64488879d11ef125ab260507",
    "name": "externallmg_1682475127592_1682475002122_image_15.jpeg",
    "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475127592_1682475002122_image_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64488879d11ef125ab260508",
    "name": "externallmg_1682475127596_1682475002122_image_16.jpeg",
    "path": "cases/64412768f8dc9a26350cd3a8/
externallmg_1682475127596_1682475002122_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64488879d11ef125ab260509",
```

```
    "name": "externalImg_1682475127599_1682475002122_image_17.jpeg",
    "path": "cases/64412768f8dc9a26350cd3a8/
externalImg_1682475127599_1682475002122_image_17.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [
  {
    "originalName": "Valuation_Report_Ganesh Trimbak Jadhav & Mrs. Vrushali
Ganesh Jadhav.pdf",
    "filename": "1682999011043_Valuation_Report_Ganesh_Trimbak_Jadhav__Mrs_Vr
ushali_Ganesh_Jadhav.pdf",
    "path": "cases/64412768f8dc9a26350cd3a8/externalDocuments/1682999011043_V
aluation_Report_Ganesh_Trimbak_Jadhav__Mrs_Vrushali_Ganesh_Jadhav.pdf",
    "size": "1162710",
    "documentType": {
      "value": "60ae124caa6d152c1801b300",
      "label": "Signed Report"
    },
    "createdAt": "Tue May 02 2023 09:13:31 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f9589345132d6a6bddcc3a"
  }
],
"createdAt": "2023-04-20T11:52:08.990Z",
"updatedAt": "2023-05-02T10:21:13.637Z",
"__v": 0,
"fullAddress": "Residential Flat No. 301, 3rd Floor, Wing - G, Mayur Park Co-Op. Hsg.
Soc. Ltd., Plot No. 1 & 22, Sector 36, Village - Kamothe, Taluka - Panvel, District -
Raigad, Navi Mumbai, PIN - 410 206, State - Maharashtra, India",
"updatedBy": "62fe044a48a26047e6552796",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Ganesh Trimrak jadhav ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9594090200",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + 2 Passage + WC +
Bathroom",
"carpetTotal": "369.63",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0",
"siteVisitDate": "2023-04-26",
```

```

"reason": "",
"buildingServicesRate": "2500",
"flatRate": "11000",
"landOtherRate": "8500",
"builtupPercentage": "10",
"extendOfSiteRemark": "",
"finalBuiltupArea": "406.59",
"finalCarpetArea": "369.63",
"finalSalableArea": "447.25",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 459.00",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"

```

| Name | Length | Width | Total |
|------------------------|--------|-------|--------|
| Composition : | | | |
| Bedroom | 10'3" | 12'8" | 129.83 |
| Passage | 2'9" | 5'2" | 14.21 |
| Kitchen | 7'10" | 6'11" | 54.18 |
| Passage | 2'00" | 4'00" | 8.00 |
| WC | 3'00" | 4'00" | 12.00 |
| Bathroom | 3'10" | 3'10" | 14.69 |
| Living Room | 8'11" | 15'4" | 136.72 |
| Other Composition : | | | |