

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64019061ce84bf289bac0837"
    },
    "type": "CREDITOFFICER",
    "_id": "6417edd296b58848585ec249",
    "firstName": "Joyti Madam",
    "lastName": "Madam",
    "mobileNo": "",
    "workMobileNo": "9026565489",
    "email": ""
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Joyti Madam",
    "expectedFees": 2500,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
    "city": "Mumbai"
  }
}
```

```
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1812",
  "type": "BANK",
  "name": "Punjab National Bank",
  "displayName": "Punjab National Bank",
  "initial": "PNB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64019061ce84bf289bac0837",
  "name": "PLP BKC",
  "branchCode": "",
  "mobileNo": "8699542403",
  "alternateMobileNo": "",
  "email": "plp6605@pnb.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "PNB Pragati Tower C 9, G Block, 3rd floor, Bandra Kurla Complex,
Bandra(E), Mumbai - 400051, State - Maharashtra, Country - India"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f7fcadf3dd69653a58d9d7",
  "zoneName": "Mumbai Zone (Maharashtra)"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62723addafd7d55eddeddfe4",
    "role": "DELIVERYPERSON",
    "firstName": "Ramkrishna ",
    "email": "rampatakar1991@gmail.com",
    "lastName": "Patkar",
    "mobileNo": "7045746060",
    "shortName": "RP",
    "workWithDocumentMaker": ""
  }
}
```

```
"profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "RAJESH",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "GHADI",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "CHECKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
  "lastName": "Bodke",
  "mobileNo": "9821740317",
  "designation": "",
  "shortName": "SB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
```

```
"role": "CHECKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "[N]C.C.I.T/I -14/52/2008-09",
"label": "Wealth Tax"
}
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
{
"title": {
"value": "Wealth_Tax",
"label": "Wealth Tax"
},
"_id": "6084131a13f01f158c6ea1f4",
"number": "[N]C.C.I.T/I -14/52/2008-09"
}
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
```

```
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.01986281639451",
  "longitude": "73.09118663289718"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.09118663289718,
    19.01986281639451
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-04-25T03:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-25T03:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-25T03:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-26T02:07:39.494Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-04-26T02:07:39.494Z"
    }
  ]
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Tue Apr 25 2023 09:54:37 GMT+0530 (India Standard Time)"
}
```

```
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kamothe",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "3",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
    "value": "",
    "label": true
  },
  "city": {
    "status": true,
```

```
"name": "City",
"key": "city",
"value": "Navi Mumbai",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "8",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Satlaj Residency",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "35",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
}
```

```
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "E",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
```



```
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "301",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
}
```

```
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "VerifiedTileFlooring"
  },
  "doors": {
```

```

    "label": "Teak Wood",
    "value": "TeakWood"
  },
  "windows": {
    "label": "Alluminum sliding windows with M. S. Grills",
    "value": "Alluminum_sliding_windows_with_M._S._Grills"
  },
  "fittings": {
    "label": "\tFittings\t:\tOpen plumbing with C.P. fittings. Casing Capping wiring",
    "value": "\tFittings\t:\tOpen_plumbing_with_C.P._fittings._Casing_Capping_wiring"
  },
  "finishing": {
    "label": "Cement Plastering + POP Finish",
    "value": "Cement_Plastering_+_POP_Finish"
  }
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Panvel Municipal Corporation",
    "value": "Panvel_Municipal_Corporation"
  },
  "asPerActualAgreement": {
    "north": "BLUE HEAVEN",
    "south": "A WING",
    "east": "Mahalaxmi mall",
    "west": "D WING"
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  }
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  }
}

```

```
},
"propertyTypeOfUseList": {
  "label": "Residential Purpose",
  "value": "Residential_Purpose"
},
"propertyOccupiedByList": {
  "label": "Vacant",
  "value": "Vacant"
},
"monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  },
  "pavementLaid": {
    "label": "Yes",
    "value": "Yes"
  },
  "carParking": {
    "label": "covered",
    "value": "covered"
  },
  "constructionWorkStatus": {
    "label": "Completed",
    "value": "Completed"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2008",
    "fullDate": "1/1/2008"
  },
  "propertyTypeList": {
    "value": "Residential",
    "label": "Residential"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
}
```

```
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"qualityOfConstruction": {
  "label": "Good",
  "value": "Good"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"maintenanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"visibleDamageInBuilding": {
  "label": "Yes",
  "value": "1"
},
"groundStilt": {
  "label": "Ground",
  "value": "ground"
},
"isSiteVisitAllowed": true,
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"flatFloorNo": "",
"noOfLifts": "0",
"noOfLiftsInEachWings": "0",
"totalLifeBuilding": "60",
"ageOfBuilding": "15",
"estimatedAge": "45",
"noOfFloors": "04",
"noOfDwellingUnitsInBuilding": "06"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
```

```
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
```



```
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"taskStatus": {
  "DOCUMENT_VERIFY": false,
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"_id": "64474e13d11ef125ab24b63b",
"ownerName": "Sandip Ramchandra Wagh",
"ownerPhoneNo": "8837872964",
"appAddress": "flat no - E - 301, 3rd floor, bldg name - satlaj residency chs Ltd ,plot no
- 8 & 8B, sect - 35, kamothe ,Panvel ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "19/04/2023",
      "from": {
        "value": "seller",
        "label": "seller"
      }
    }
  },

```

```
    "seller": "SUnil Kashinath Thakur",
    "to": {
      "value": "purchaser",
      "label": "purchaser"
    },
    "purchaser": "Sandeep Ramchandra Wagh"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "576921",
  "path": "cases/64474e13d11ef125ab24b63b/
document_1682395258296_plp__Sandip.pdf",
  "fileName": "document_1682395258296_plp__Sandip.pdf"
}
],
"caseNumber": "001301",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "551000",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Apr 25 2023 09:20:43 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Sandip Ramchandra Wagh",
    "phone": "8837872964",
    "ownershipShare": "",
    "email": "",
    "id": "496189"
  }
],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    }
  },
  "_id": "6447f384d11ef125ab25fb06",
  "area": "0",
```

```
"providedByName": "Sandip Ramchandra Wagh",
"providedByContactNo": "8837872964"
},
{
  "areaType": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "providedBy": {
    "label": "Owner",
    "value": "Owner"
  },
  "_id": "6447f384d11ef125ab25fb07",
  "area": "0",
  "providedByName": "Sandip Ramchandra Wagh",
  "providedByContactNo": "8837872964"
},
{
  "areaType": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "providedBy": {
    "label": "Owner",
    "value": "Owner"
  },
  "_id": "6447f384d11ef125ab25fb08",
  "area": "0",
  "providedByName": "Sandip Ramchandra Wagh",
  "providedByContactNo": "8837872964"
}
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "189028",
    "name": "Bedroom",
    "length": "9.00",
    "length1": "9",
    "length2": "00",
    "width": "11.33",
    "width1": "11",
    "width2": "4",
```

```
"totalArea": "102.00",
"images": [],
"extraAreas": [],
"finalArea": "102.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "8.08",
  "length1": "8",
  "length2": "1",
  "width": "6.92",
  "width1": "6",
  "width2": "11",
  "totalArea": "55.91",
  "images": [],
  "extraAreas": [],
  "finalArea": "55.91"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "2.83",
  "length1": "2",
  "length2": "10",
  "width": "9.00",
  "width1": "9",
  "width2": "00",
  "totalArea": "25.50",
  "images": [],
  "extraAreas": [],
  "finalArea": "25.50"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
}
```

```
"id": "3",
"name": "WC",
"length": "3.00",
"length1": "3",
"length2": "00",
"width": "4.00",
"width1": "4",
"width2": "00",
"totalArea": "12.00",
"images": [],
"extraAreas": [],
"finalArea": "12.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Bathroom",
  "length": "4.83",
  "length1": "4",
  "length2": "10",
  "width": "3.83",
  "width1": "3",
  "width2": "10",
  "totalArea": "18.53",
  "images": [],
  "extraAreas": [],
  "finalArea": "18.53"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "Living Room",
  "length": "8.83",
  "length1": "8",
  "length2": "10",
  "width": "14.17",
  "width1": "14",
  "width2": "2",
  "totalArea": "125.14",
  "images": [],
```

```
"extraAreas": [],
"finalArea": "125.14"
},
],
"otherComposition": [
{
  "name": {
    "label": "Flower Bed Area",
    "value": "Flower_Bed_Area"
  },
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "0",
  "length1": "2",
  "length2": "00",
  "length": "2.00",
  "width1": "9",
  "width2": "00",
  "width": "9.00",
  "totalArea": "18.00",
  "percentageBeforeTotal": "18.00",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "18"
},
{
  "name": {
    "label": "Flowerbed",
    "value": "Flowerbed"
  },
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "length1": "2",
  "length2": "00",
  "length": "2.00",
  "width1": "6",
  "width2": "11",
  "width": "6.92",
  "totalArea": "13.83",
  "percentageBeforeTotal": "13.83",
```

```
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "13.83"
}
],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644887b7d11ef125ab26035f",
  "name": "externalImg_1682474930723_1682474808538_image_0.jpeg",
  "path": "cases/64474e13d11ef125ab24b63b/
externalImg_1682474930723_1682474808538_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644887b7d11ef125ab260360",
  "name": "externalImg_1682474930748_1682474808538_image_1.jpeg",
  "path": "cases/64474e13d11ef125ab24b63b/
externalImg_1682474930748_1682474808538_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644887b7d11ef125ab260361",
  "name": "externalImg_1682474930793_1682474808538_image_2.jpeg",
  "path": "cases/64474e13d11ef125ab24b63b/
externalImg_1682474930793_1682474808538_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644887b7d11ef125ab260362",
  "name": "externalImg_1682474930829_1682474808538_image_3.jpeg",
  "path": "cases/64474e13d11ef125ab24b63b/
externalImg_1682474930829_1682474808538_image_3.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "644887b7d11ef125ab260363",
      "name": "externallmg_1682474930878_1682474808538_image_4.jpeg",
      "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474930878_1682474808538_image_4.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "644887b7d11ef125ab260364",
      "name": "externallmg_1682474930943_1682474808538_image_5.jpeg",
      "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474930943_1682474808538_image_5.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "644887b7d11ef125ab260365",
      "name": "externallmg_1682474931283_1682474808538_image_6.jpeg",
      "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474931283_1682474808538_image_6.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "644887b7d11ef125ab260366",
      "name": "externallmg_1682474931318_1682474808538_image_7.jpeg",
      "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474931318_1682474808538_image_7.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "644887b7d11ef125ab260367",
      "name": "externallmg_1682474931353_1682474808538_image_8.jpeg",
      "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474931353_1682474808538_image_8.jpeg",
      "orientation": "portrait"
    },
  ],
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644887b7d11ef125ab260368",
  "name": "externallmg_1682474931408_1682474808538_image_9.jpeg",
  "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474931408_1682474808538_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644887b7d11ef125ab260369",
  "name": "externallmg_1682474931434_1682474808538_image_10.jpeg",
  "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474931434_1682474808538_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644887b7d11ef125ab26036a",
  "name": "externallmg_1682474931468_1682474808538_image_11.jpeg",
  "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474931468_1682474808538_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644887b7d11ef125ab26036b",
  "name": "externallmg_1682474931718_1682474808538_image_12.jpeg",
  "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474931718_1682474808538_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644887b7d11ef125ab26036c",
  "name": "externallmg_1682474931763_1682474808538_image_13.jpeg",
  "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474931763_1682474808538_image_13.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644887b7d11ef125ab26036d",
    "name": "externallmg_1682474931813_1682474808538_image_14.jpeg",
    "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474931813_1682474808538_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644887b7d11ef125ab26036e",
    "name": "externallmg_1682474932443_1682474808538_image_15.jpeg",
    "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474932443_1682474808538_image_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644887b7d11ef125ab26036f",
    "name": "externallmg_1682474932478_1682474808538_image_16.jpeg",
    "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474932478_1682474808538_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644887b7d11ef125ab260370",
    "name": "externallmg_1682474932513_1682474808538_image_17.jpeg",
    "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474932513_1682474808538_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644887b7d11ef125ab260371",
    "name": "externallmg_1682474932538_1682474808538_image_18.jpeg",
    "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474932538_1682474808538_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
    "status": false,
    "_id": "644887b7d11ef125ab260372",
    "name": "externallmg_1682474925238_1682474786833_image_0.jpeg",
    "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474925238_1682474786833_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "644887b7d11ef125ab260373",
    "name": "externallmg_1682474925264_1682474786833_image_1.jpeg",
    "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474925264_1682474786833_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "644887b7d11ef125ab260374",
    "name": "externallmg_1682474925313_1682474786833_image_2.jpeg",
    "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474925313_1682474786833_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "644887b7d11ef125ab260375",
    "name": "externallmg_1682474925378_1682474786833_image_3.jpeg",
    "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474925378_1682474786833_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "644887b7d11ef125ab260376",
    "name": "externallmg_1682474925443_1682474786833_image_4.jpeg",
    "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474925443_1682474786833_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
```

```
    "_id": "644887b7d11ef125ab260377",
    "name": "externallmg_1682474925533_1682474786833_image_5.jpeg",
    "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474925533_1682474786833_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "644887b7d11ef125ab260378",
    "name": "externallmg_1682474925959_1682474786833_image_6.jpeg",
    "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474925959_1682474786833_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "644887b7d11ef125ab260379",
    "name": "externallmg_1682474926003_1682474786833_image_7.jpeg",
    "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474926003_1682474786833_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "644887b7d11ef125ab26037a",
    "name": "externallmg_1682474926038_1682474786833_image_8.jpeg",
    "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474926038_1682474786833_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "644887b7d11ef125ab26037b",
    "name": "externallmg_1682474926088_1682474786833_image_9.jpeg",
    "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474926088_1682474786833_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "644887b7d11ef125ab26037c",
```

```
    "name": "externallmg_1682474926103_1682474786833_image_10.jpeg",
    "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474926103_1682474786833_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "644887b7d11ef125ab26037d",
    "name": "externallmg_1682474926138_1682474786833_image_11.jpeg",
    "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474926138_1682474786833_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "644887b7d11ef125ab26037e",
    "name": "externallmg_1682474926443_1682474786833_image_12.jpeg",
    "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474926443_1682474786833_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "644887b7d11ef125ab26037f",
    "name": "externallmg_1682474926483_1682474786833_image_13.jpeg",
    "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474926483_1682474786833_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "644887b7d11ef125ab260380",
    "name": "externallmg_1682474926548_1682474786833_image_14.jpeg",
    "path": "cases/64474e13d11ef125ab24b63b/
externallmg_1682474926548_1682474786833_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "644887b7d11ef125ab260381",
    "name": "externallmg_1682474927403_1682474786833_image_15.jpeg",
```

```
    "path": "cases/64474e13d11ef125ab24b63b/
externalImg_1682474927403_1682474786833_image_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "644887b7d11ef125ab260382",
    "name": "externalImg_1682474927469_1682474786833_image_16.jpeg",
    "path": "cases/64474e13d11ef125ab24b63b/
externalImg_1682474927469_1682474786833_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "644887b7d11ef125ab260383",
    "name": "externalImg_1682474927488_1682474786833_image_17.jpeg",
    "path": "cases/64474e13d11ef125ab24b63b/
externalImg_1682474927488_1682474786833_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "644887b7d11ef125ab260384",
    "name": "externalImg_1682474927493_1682474786833_image_18.jpeg",
    "path": "cases/64474e13d11ef125ab24b63b/
externalImg_1682474927493_1682474786833_image_18.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-04-25T03:50:43.466Z",
"updatedAt": "2023-04-26T02:09:55.771Z",
"__v": 0,
"updatedBy": "60f9343b45132d6a6bdd96e8",
"fullAddress": "Residential Flat No. 301, 3rd Floor, Wing - E, Satlaj Residency, Plot
No. 8, Sector 35, Village - Kamothe, Navi Mumbai, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "Sandip Ramchandra Wagh",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": ""
```

"purchaseValueAsPerDocument": "",  
 "relationWithOwner": "self",  
 "siteVisitContactNo": "8837872964",  
 "briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + WC +  
 Bathroom",  
 "carpetTotal": "339.08",  
 "finalMeasurementType": "Sq. Ft.",  
 "otherCarpetTotal": "31.83",  
 "siteVisitDate": "2023-04-26"

Name	Length	Width	Total
Composition :			
Bedroom	9'00"	11'4"	102.00
Kitchen	8'1"	6'11"	55.91
Passage	2'10"	9'00"	25.50
WC	3'00"	4'00"	12.00
Bathroom	4'10"	3'10"	18.53
Living Room	8'10"	14'2"	125.14
Other Composition :			
Flower Bed Area	2'00"	9'00"	18.00
Flowerbed	2'00"	6'11"	13.83