

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b899"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230f71",
    "firstName": "Ajay Kumar Sinha",
    "email": "0_default_sbi04498@sbi.co.in",
    "mobileNo": "0_DEFAULT_022-25372748",
    "workMobileNo": "0_DEFAULT_91-9953680140"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "3000"
  },
  "organization": {
    "_id": "6418456a96b58848585f8cb2",
    "name": "Thane",
    "email": "thane@vastukala.com",
    "phone": "1234567890",
    "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
```

```
"city": "Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b899",
  "branchCode": "000127",
  "type": "BRANCH",
  "name": "RACPC Thane ",
  "email": "rasecc.thane@sbi.co.in",
  "mobileNo": "02220812026",
  "alternateMobileNo": "02220812027",
  "address": "Retail Assets Centralized, Processing Centre,Dosti Pinnacle , Plot no
E7,Near New Passport Office,Gate No-3,Road No 22,Panchpakhadi Village Wagle Indl
Estate,Thane- 400604\r\n",
  "ledgerName": "STATE BANK OF INDIA - THANE RACPC",
  "fax": "2538 2750 ",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62720e52afd7d55eddedc887",
    "role": "SITEENGINEER",
    "firstName": "Harshad",
    "email": "harshad@vastukala.org",
    "lastName": "Panchal",
```

```
"mobileNo": "9029575553",
"shortName": "HP",
"workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc4680ce84bf289ba9c7fc",
  "role": "SITEENGINEER",
  "firstName": "Nikhil ",
  "email": "valtechnical2022@gmail.com",
  "lastName": "Sonawane",
  "mobileNo": "9819470709",
  "designation": "",
  "shortName": "NS",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1681380664371_WhatsApp_Image_20230413_at_33801_PM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "0123456789",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
  "lastName": "Bodke",
  "mobileNo": "9821740317",
  "designation": "",
  "shortName": "SB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
```

```

"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "0123456789",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "6084131a13f01f158c6ea1f3",
    "PANNo": "AEAPC7114Q",
    "role": "VALUER",
    "firstName": "Sharadkumar",
    "fatherName": "Baburao",
    "email": "cmd@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9422171100",
    "designation": "CMD",
    "registrationNo": [
      {
        "title": {
          "value": "Wealth_Tax",
          "label": "Wealth Tax"
        },
        "_id": "6084131a13f01f158c6ea1f4",
        "number": "[N]C.C.I.T/I -14/52/2008-09"
      }
    ],
    "shortName": "SBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
  }
]

```

```
    }
  ]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "18.534465799776008 ",
  "longitude": "73.82864731185639"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.82864731185639,
    18.534465799776008
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-04-25T18:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-25T18:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-25T18:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-25T18:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-25T18:30:00.000Z",
      "remark": ""
    }
  ]
}
```

```
    "dateTime": "2023-04-25T18:30:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-04-25T18:30:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-04-25T18:30:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-04-25T18:30:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-04-25T18:30:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-04-25T18:30:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-04-25T18:30:00.000Z",
    "remark": ""
  }
],
"visitedDate": [
  {
    "remark": "MANUAL",
    "status": "COMPLETED",
    "dateTime": "2023-04-25T18:30:00.000Z"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"verifiedDocument": {
  "value": true,
  "remark": ""
}
```

```
"dateTime": "Tue Apr 25 2023 17:11:16 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Shivaji Nagar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "1",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Thane",
    "label": true
  },
  "city": {
```

```
"status": true,
"name": "City",
"key": "city",
"value": "Dombivali (West)",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Ragaidevi Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
```



```
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Ganesh Nagar",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "8",
  "label": true
},
"hissaNo": {
  "status": true,
```

```
"name": "Hissa No.",
"key": "hissaNo",
"value": "11",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "4",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
}
```

```
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "421 202",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "Mosaic_tiles_flooring",
    "label": "Mosaic tiles flooring"
  }
},
}
```

```

"doors": {
  "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
  "label": "Teak Wood Door frame with Solid flush door"
},
"windows": {
  "value": "Powder_coated_Aluminum_sliding_windows",
  "label": "Powder coated Aluminum sliding windows"
},
"fittings": {
  "value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring",
  "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring"
},
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Kalyan_Dombivali_Municipal_Corporation",
    "label": "Kalyan Dombivali Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Internal Road & Under Construction Building ",
    "west": "Datta Bhavan Building ",
    "south": "Shiv Vishnu Darshan CHSL",
    "east": "Shantivan CHSL & Internal Road "
  },
  "asPerDocumentAgreement": {

```

```
"north": "Details not available",
"west": "Details not available",
"south": "Details not available",
"east": "Details not available"
},
"extraDetailOfProperty": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "43.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "7412.5",
  "depreciatedBuildingRate": "1412.5"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "64200",
  "landRate": "23900",
  "igrImage": "cases/6447bc51d11ef125ab25be37/igr_1682672777020_Image.png",
  "squareMeterGuideLineRate": "60990.00",
  "squareFeetGuideLineRate": "5666.00"
},
"igrFinalRate": {
  "rate": "4667.00",
  "squareFeetGuideLineRate": "4667.00",
  "squareMeterGuideLineRate": "50234.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "8,500",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
```

```
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per KDMC norms",
"tenantName": "",
"maintenanceOfFlat": "Normal "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": {
    "value": "Open_Car_Parking",
    "label": "Open Car Parking"
  },
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
```

```
"year": "1994",
"fullDate": "1/1/1994"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C.",
"label": "R.C.C. Framed"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Normal",
"label": "Normal"
},
"materialUsedList": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"buildingSpecification": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"structuralSafety": {
"value": "Normal",
"label": "Normal"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
}
```

```
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "Building_Completion_Certificate",
  "label": "Building Completion Certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "29",
"totalLifeBuilding": "60",
"estimatedAge": "31",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "3",
"flatFloorNo": "1",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
  "area": "553.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
}
```



```
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6447bc51d11ef125ab25be37/
routeMap_1682674986581_Image.png",
    "routeLat": "19.228329",
    "routeLng": "73.089462",
    "stationName": "Thakurli",
    "routeDistance": "1.1 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "hqy0n",
      "name": "hqy0n",
      "image": "cases/6447bc51d11ef125ab25be37/
routeMap_1682674997366_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
```

```
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "4099389.00",
"bookValue": "0",
"finalValue": "4099389.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEM_GENERATED",
  "date": "Wed Apr 26 2023 13:05:59 GMT+0530 (India Standard Time)",
  "number": "046502",
  "dayCount": "4",
  "monthCount": "403",
  "generatedBy": "62691c48afd7d55eddecfda3"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
},
```

```
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
```

```
    "label": "External Development & Final Finishing",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": false
  },
  "workCompleted": {
    "label": "Work Completed (%)",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "2580851.00",
  "selectedBuildUpValue": "553.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "644b9554ba47a23af30e2b8d",
      "name":
"externallmg_1682675027289_WhatsApp_Image_20230427_at_12110_PM_2.jpeg",
      "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675027289_WhatsApp_Image_20230427_at_12110_PM_2.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "644b9554ba47a23af30e2b96",
      "name":
"externallmg_1682675027426_WhatsApp_Image_20230427_at_12110_PM_11.jpeg",
      "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675027426_WhatsApp_Image_20230427_at_12110_PM_11.jpeg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "644b9554ba47a23af30e2b8c",
```

```
    "name":
"externallmg_1682675027281_WhatsApp_Image_20230427_at_12110_PM_1.jpeg",
    "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675027281_WhatsApp_Image_20230427_at_12110_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "644b9554ba47a23af30e2b8d",
    "name":
"externallmg_1682675027289_WhatsApp_Image_20230427_at_12110_PM_2.jpeg",
    "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675027289_WhatsApp_Image_20230427_at_12110_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "644b9554ba47a23af30e2b8e",
    "name":
"externallmg_1682675027315_WhatsApp_Image_20230427_at_12110_PM_3.jpeg",
    "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675027315_WhatsApp_Image_20230427_at_12110_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "644b9554ba47a23af30e2b90",
    "name":
"externallmg_1682675027357_WhatsApp_Image_20230427_at_12110_PM_5.jpeg",
    "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675027357_WhatsApp_Image_20230427_at_12110_PM_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "644b9554ba47a23af30e2b9a",
    "name":
"externallmg_1682675027456_WhatsApp_Image_20230427_at_12110_PM.jpeg",
    "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675027456_WhatsApp_Image_20230427_at_12110_PM.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
```

```
    "status": false,
    "_id": "644b9554ba47a23af30e2b8f",
    "name":
"externallmg_1682675027324_WhatsApp_Image_20230427_at_12110_PM_4.jpeg",
    "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675027324_WhatsApp_Image_20230427_at_12110_PM_4.jpeg",
    "orientation": "landscape"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "644b9554ba47a23af30e2b91",
    "name": "Living Room",
    "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675027377_WhatsApp_Image_20230427_at_12110_PM_6.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "644b9554ba47a23af30e2b97",
    "name": "Bedroom",
    "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675027431_WhatsApp_Image_20230427_at_12110_PM_12.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "644b9554ba47a23af30e2b92",
    "name": "Passage",
    "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675027394_WhatsApp_Image_20230427_at_12110_PM_7.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "644b9554ba47a23af30e2b94",
    "name": "Kitchen",
    "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675027411_WhatsApp_Image_20230427_at_12110_PM_9.jpeg",
    "orientation": "landscape"
  }
]
},
"taskStatus": {
  "DOCUMENT_VERIFY": false,
```

```
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": true,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": "LEAD",
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "553.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86A/3"
],
"status": true,
"caseStatus": "READYFORCHECKER",
"_id": "6447bc51d11ef125ab25be37",
"ownerName": "Mr. Ramchandra Bhikanrao More",
"ownerPhoneNo": "9819226306",
"fullAddress": "Residential Flat No. 4, 1st Floor, Wing - B, Ragaidevi Co-op. Hsg. Soc.
Ltd., Ganesh Nagar, Village - Shivaji Nagar, Taluka - Kalyan, District - Thane, Dombivali
(West), 421 202, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "18/06/2004",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Mr. Gopalkrishnan Lakshminarayanan",
      "to": {
        "value": "Transferee",
        "label": "Transferee"
      }
    }
  }
]
```



```
    },
    "Transferee": "Mr. Ramchandra Bhikanrao More"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "188349",
  "path": "cases/6447bc51d11ef125ab25be37/document_undefined",
  "fileName": "document_undefined"
},
{
  "documentType": {
    "value": "60ae1267aa6d152c1801b380",
    "label": "Building Completion Certificate"
  },
  "inputs": {
    "documentDate": "04/06/1994",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Mahanagarpalika",
      "label": "Kalyan Dombivli Mahanagarpalika"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "KMP / NRV / CC / DV / 181"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "764975",
  "path": "cases/6447bc51d11ef125ab25be37/document_1682672833053_96537.pdf"
}
],
"caseNumber": "001320",
"createdBy": "6430f74691d7c62df11f3f15",
"caseHistory": [
  {
    "id": "801099",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Apr 25 2023 17:11:05 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Ramchandra Bhikanrao More",
    "phone": "9819226306",
```

```
    "ownershipShare": "",
    "email": "",
    "id": "935580"
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "535293",
    "name": "Bedroom",
    "length": "14.42",
    "length1": "14",
    "length2": "5",
    "width": "11.08",
    "width1": "11",
    "width2": "1",
    "totalArea": "159.78",
    "images": [],
    "extraAreas": [],
    "finalArea": "159.78"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "WC",
    "length": "4.00",
    "length1": "4",
    "length2": "00",
    "width": "3.00",
    "width1": "3",
    "width2": "00",
    "totalArea": "12.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "12.00"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bathroom",
  "length": "6.58",
  "length1": "6",
  "length2": "7",
  "width": "3.67",
  "width1": "3",
  "width2": "8",
  "totalArea": "24.14",
  "images": [],
  "extraAreas": [],
  "finalArea": "24.14"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Kitchen",
  "length": "11.00",
  "length1": "11",
  "length2": "00",
  "width": "8.00",
  "width1": "8",
  "width2": "00",
  "totalArea": "88.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "88.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Passage",
  "length": "7.17",
  "length1": "7",
  "length2": "2",
  "width": "4.25",
  "width1": "4",
  "width2": "3",
```

```
"totalArea": "30.46",
"images": [],
"extraAreas": [],
"finalArea": "30.46"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Living Room",
  "length": "18.33",
  "length1": "18",
  "length2": "4",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "183.33",
  "images": [],
  "extraAreas": [],
  "finalArea": "183.33"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "value": "Cupboard",
      "label": "Cupboard"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length1": "3",
    "length2": "2",
    "length": "3.17",
    "width1": "2",
    "width2": "4",
    "width": "2.33",
    "totalArea": "7.39",
```

```
"percentageBeforeTotal": "7.39",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "7.39"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "119028",
  "selectAreaTypeDocument": "Built_Up",
  "totalAreaDocument": "553",
  "squareMeterArea": "51.37",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docBuiltupPercentage": "",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "644b8aa8ba47a23af30e10cb",
  "id": "1",
  "property": "Flat",
  "area": "550",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Nobroker.com",
  "expectedPrice": "4500000",
  "expectedRate": "8181.82",
```

```
"builtUpExpectedRate": "4500000",
"image": "cases/6447bc51d11ef125ab25be37/
indicator_1682672295917_Image.png"
},
{
  "printlnReport": true,
  "_id": "644b8b15ba47a23af30e1134",
  "id": "2",
  "property": "Flat",
  "area": "510",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "Housing.Com",
  "expectedPrice": "4713000",
  "expectedRate": "9241.18",
  "builtUpExpectedRate": "7700.98",
  "image": "cases/6447bc51d11ef125ab25be37/
indicator_1682672405839_Image.png"
},
{
  "printlnReport": true,
  "_id": "644b8b58ba47a23af30e11fb",
  "id": "3",
  "property": "Flat",
  "area": "385",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "Housing.Com",
  "expectedPrice": "3850000",
  "expectedRate": "10000.00",
  "builtUpExpectedRate": "8333.33",
  "image": "cases/6447bc51d11ef125ab25be37/
indicator_1682672472297_Image.png"
},
{
  "printlnReport": true,
  "_id": "644b8bdeba47a23af30e13f7",
  "id": "4",
  "property": "Flat",
  "area": "450",
```

```
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "4700000",
"expectedRate": "10444.44",
"builtUpExpectedRate": "8703.70",
"image": "cases/6447bc51d11ef125ab25be37/
indicator_1682672606531_Image.png"
}
],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "644b9554ba47a23af30e2b8c",
"name":
"externalImg_1682675027281_WhatsApp_Image_20230427_at_12110_PM_1.jpeg",
"path": "cases/6447bc51d11ef125ab25be37/
externalImg_1682675027281_WhatsApp_Image_20230427_at_12110_PM_1.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "644b9554ba47a23af30e2b8d",
"name":
"externalImg_1682675027289_WhatsApp_Image_20230427_at_12110_PM_2.jpeg",
"path": "cases/6447bc51d11ef125ab25be37/
externalImg_1682675027289_WhatsApp_Image_20230427_at_12110_PM_2.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "644b9554ba47a23af30e2b8e",
"name":
"externalImg_1682675027315_WhatsApp_Image_20230427_at_12110_PM_3.jpeg",
"path": "cases/6447bc51d11ef125ab25be37/
externalImg_1682675027315_WhatsApp_Image_20230427_at_12110_PM_3.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "644b9554ba47a23af30e2b8f",
  "name":
"externallmg_1682675027324_WhatsApp_Image_20230427_at_12110_PM_4.jpeg",
  "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675027324_WhatsApp_Image_20230427_at_12110_PM_4.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644b9554ba47a23af30e2b90",
  "name":
"externallmg_1682675027357_WhatsApp_Image_20230427_at_12110_PM_5.jpeg",
  "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675027357_WhatsApp_Image_20230427_at_12110_PM_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644b9554ba47a23af30e2b91",
  "name":
"externallmg_1682675027377_WhatsApp_Image_20230427_at_12110_PM_6.jpeg",
  "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675027377_WhatsApp_Image_20230427_at_12110_PM_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644b9554ba47a23af30e2b92",
  "name":
"externallmg_1682675027394_WhatsApp_Image_20230427_at_12110_PM_7.jpeg",
  "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675027394_WhatsApp_Image_20230427_at_12110_PM_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644b9554ba47a23af30e2b93",
  "name":
"externallmg_1682675027404_WhatsApp_Image_20230427_at_12110_PM_8.jpeg",
  "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675027404_WhatsApp_Image_20230427_at_12110_PM_8.jpeg",
```



```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644b9554ba47a23af30e2b94",
    "name":
"externallmg_1682675027411_WhatsApp_Image_20230427_at_12110_PM_9.jpeg",
    "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675027411_WhatsApp_Image_20230427_at_12110_PM_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644b9554ba47a23af30e2b95",
    "name":
"externallmg_1682675027419_WhatsApp_Image_20230427_at_12110_PM_10.jpeg",
    "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675027419_WhatsApp_Image_20230427_at_12110_PM_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644b9554ba47a23af30e2b96",
    "name":
"externallmg_1682675027426_WhatsApp_Image_20230427_at_12110_PM_11.jpeg",
    "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675027426_WhatsApp_Image_20230427_at_12110_PM_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644b9554ba47a23af30e2b97",
    "name":
"externallmg_1682675027431_WhatsApp_Image_20230427_at_12110_PM_12.jpeg",
    "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675027431_WhatsApp_Image_20230427_at_12110_PM_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644b9554ba47a23af30e2b98",
```

```
"name":
"externallmg_1682675027444_WhatsApp_Image_20230427_at_12110_PM_13.jpeg",
  "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675027444_WhatsApp_Image_20230427_at_12110_PM_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644b9554ba47a23af30e2b99",
  "name":
"externallmg_1682675027451_WhatsApp_Image_20230427_at_12110_PM_14.jpeg",
  "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675027451_WhatsApp_Image_20230427_at_12110_PM_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644b9554ba47a23af30e2b9a",
  "name":
"externallmg_1682675027456_WhatsApp_Image_20230427_at_12110_PM.jpeg",
  "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675027456_WhatsApp_Image_20230427_at_12110_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644b9582ba47a23af30e2c38",
  "name": "externallmg_1682675074265_0b938677c05741ef8eb4d59ed3261c53.jpg",
  "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675074265_0b938677c05741ef8eb4d59ed3261c53.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644b9582ba47a23af30e2c39",
  "name":
"externallmg_1682675074272_7be66493256c4054978a2b53f6244d8a.jpg",
  "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675074272_7be66493256c4054978a2b53f6244d8a.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644b9582ba47a23af30e2c3a",
    "name":
"externallmg_1682675074285_33f9b8979a2a40148e98a315631e2366.jpg",
    "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675074285_33f9b8979a2a40148e98a315631e2366.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644b9582ba47a23af30e2c3b",
    "name":
"externallmg_1682675074290_1742a4deaeb243a39890b0895c3bf66a.jpg",
    "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675074290_1742a4deaeb243a39890b0895c3bf66a.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644b9582ba47a23af30e2c3c",
    "name": "externallmg_1682675074303_67989222d30743c3beefd1f2b6037931.jpg",
    "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675074303_67989222d30743c3beefd1f2b6037931.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644b9582ba47a23af30e2c3d",
    "name": "externallmg_1682675074312_fb3123c8f62049b9ab07a06f7de25d02.jpg",
    "path": "cases/6447bc51d11ef125ab25be37/
externallmg_1682675074312_fb3123c8f62049b9ab07a06f7de25d02.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-04-25T11:41:05.301Z",
"updatedAt": "2023-04-28T10:26:10.457Z",
"__v": 0,
"addressForMap": "",
"caseReferredBy": "62720e52afd7d55eddedc887",
"contactPersonName": "Mr. Ramchandra More",
"email": "",
```

```

"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9819226306",
"updatedBy": "60eebe33f3dd69653a5837ae",
"buildingServicesRate": "2500",
"flatRate": "8500",
"landOtherRate": "6000",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + WC + Bathroom +
Passage",
"carpetTotal": "497.71",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "7.39",
"builtupPercentage": "20",
"finalBuiltupArea": "606.12",
"finalCarpetArea": "505.10",
"finalSalableArea": "606.12",
"salablePercentage": "0",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 553.00",
"reason": "",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "7.39",
"otherCompositionSaleableTotal": "0.00",
"siteVisitDate": "2023-04-26"
}

```

Name	Length	Width	Total
Composition :			
Bedroom	14'5"	11'1"	159.78
WC	4'00"	3'00"	12.00
Bathroom	6'7"	3'8"	24.14
Kitchen	11'00"	8'00"	88.00

Passage	7'2"	4'3"	30.46
Living Room	18'4"	10'00"	183.33
Other Composition :			
Cupboard	3'2"	2'4"	7.39