

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7fb"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230e8b",
    "firstName": "Gopikrishna N. Goli",
    "email": "0_default_gopikrishna.goli@sbi.co.in",
    "mobileNo": "0_DEFAULT_022-27759224",
    "workMobileNo": "0_DEFAULT_91-7506739724"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "56.24.050.00",
    "discussWithPerson": "Gopikrishna N. Goli",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
    "city": "Mumbai"
  },
}
```

```
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7fb",
  "branchCode": "000068",
  "type": "BRANCH",
  "name": "RBO Sanpada Branch",
  "email": "sbi.05141@sbi.co.in",
  "mobileNo": "022-27759215",
  "alternateMobileNo": "",
  "address": "Regional Business Office (II), E/202, 2nd Floor, Sanpada Rly. Station
Complex, Navi Mumbai - 400 705, State - Maharashtra, Country - India.\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RBO SANPADA",
  "fax": "022-27752206",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_ &_ Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7189d2ffdf65bcd65882b",
    "role": "PICKUPPERSON",
    "firstName": "Ravindra",
    "email": "ravindrakasare186@gmail.com",
    "lastName": "Kasare",
    "mobileNo": "9167204055",
    "shortName": "RBK",
    "workWithDocumentMaker": ""
  }
}
```

```
"profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "RAJESH",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "GHADI",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "CHECKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
  "lastName": "Bodke",
  "mobileNo": "9821740317",
  "designation": "",
  "shortName": "SB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eebe33f3dd69653a5837ae\\
\\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
```

```
"role": "CHECKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
{
  "valuersRegistrationNumber": [
    {
      "value": "IBBI/RV/07/2018/10366",
      "label": "Registered Valuer"
    }
  ],
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
```

```
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "18.966347",
  "longitude": "73.021999"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.021999,
    18.966347
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-04-27T04:30:00.000Z",
      "remark": ""
    }
  ],
}
```

```
    "dateTime": "2023-04-27T04:30:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-04-27T04:30:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-04-27T04:30:00.000Z",
    "remark": ""
  }
],
"visitedDate": [
  {
    "remark": "MANUAL",
    "status": "COMPLETED",
    "dateTime": "2023-04-26T18:30:00.000Z"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Wed Apr 26 2023 11:57:35 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  }
}
```

```
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Ulwe",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Raigad",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
```

```
"key": "taluka",
"value": "Panvel ",
"label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "99",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Grey Stone",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "18 (Part)",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
}
```



```
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
```

```
"value": "",
"label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "201",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
```

```
"status": false,
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "410 206",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Aluminium_Sliding_Windows_with_window_grills",
    "label": "Aluminium Sliding Windows with window grills"
  },
  "fittings": {
    "value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring",
    "label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring"
  },
  "finishing": {
    "value": "Good",
    "label": "Good"
  }
}
```

```
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "CIDCO",
    "label": "City Industrial Development Corporation of Maharashtra"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Neelkanth Majestic",
    "west": "Akshar Stone",
    "south": "Internal Road ",
    "east": "Under Construction Building "
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "extraDetailOfProperty": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "10.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "12716.5",
  "depreciatedBuildingRate": "2416.5"
},
"igrRate": {
  "propertyName": "Ulwe Sector 18",
```

```
"rate": "82500",
"landRate": "20400",
"igrImage": "cases/6448b7dad11ef125ab2641d4/igr_1682680916517_Image.png",
"squareMeterGuideLineRate": "82500.00",
"squareFeetGuideLineRate": "7665.00"
},
"igrFinalRate": {
  "rate": "7261.00",
  "squareFeetGuideLineRate": "7261.00",
  "squareMeterGuideLineRate": "78153.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Tenant_Occupied",
    "label": "Tenant Occupied"
  },
  "monthlyRent": "25,000",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per CIDCO norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
```

```
"label": "R. C. C. Slab"
},
"partitions": {
  "value": "6\"_Thk._Brick_Masonry",
  "label": "6\" Thk. Brick Masonery"
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": {
  "value": "Stilt+_Open_Car_Parking",
  "label": "Stilt + Open Car Parking"
},
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2016",
  "fullDate": "1/1/2016"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
```

```
"label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
}
```

```
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "7",
"totalLifeBuilding": "60",
"estimatedAge": "53",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "1",
"noOfFloors": "13",
"flatFloorNo": "2",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "2"
},
"finalPlinthArea": {
  "area": "1262.40",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6448b7dad11ef125ab2641d4/
routeMap_1682685812807_Image.png",
    "routeLat": "18.966347",
    "routeLng": "73.021999",
    "stationName": "Bamandongri ",
    "routeDistance": "1.7 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ]
  }
}
```



```
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "imf6e9",
    "name": "imf6e9",
    "image": "cases/6448b7dad11ef125ab2641d4/
routeMap_1682685567789_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "13378284.00",
  "bookValue": "0",
```

```
"finalValue": "13378284.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEM_GENERATED",
  "date": "Fri Apr 28 2023 18:20:49 GMT+0530 (India Standard Time)",
  "number": "046527",
  "dayCount": "15",
  "monthCount": "428",
  "generatedBy": "60eebe33f3dd69653a5837ae"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "9166286.00",
  "selectedBuildUpValue": "1262.40",
```

```
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "644bbff0ba47a23af30eba89",
      "name":
"externallmg_1682685935921_WhatsApp_Image_20230427_at_90428_PM.jpeg",
      "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685935921_WhatsApp_Image_20230427_at_90428_PM.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "644bbff0ba47a23af30eba87",
      "name":
"externallmg_1682685935898_WhatsApp_Image_20230427_at_90428_PM_1.jpeg",
      "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685935898_WhatsApp_Image_20230427_at_90428_PM_1.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "644bbfd1ba47a23af30eba2a",
      "name":
"externallmg_1682685905069_WhatsApp_Image_20230427_at_90417_PM_2.jpeg",
      "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685905069_WhatsApp_Image_20230427_at_90417_PM_2.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "644bbff0ba47a23af30eba83",
      "name":
"externallmg_1682685935837_WhatsApp_Image_20230427_at_90426_PM.jpeg",
      "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685935837_WhatsApp_Image_20230427_at_90426_PM.jpeg",
      "orientation": "portrait"
    }
  ],
  {
    "status": false,
```

```
    "_id": "644bbff0ba47a23af30eba84",
    "name":
"externallmg_1682685935845_WhatsApp_Image_20230427_at_90427_PM_1.jpeg",
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685935845_WhatsApp_Image_20230427_at_90427_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "644bbff0ba47a23af30eba89",
    "name":
"externallmg_1682685935921_WhatsApp_Image_20230427_at_90428_PM.jpeg",
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685935921_WhatsApp_Image_20230427_at_90428_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "644bbfd1ba47a23af30eba2d",
    "name":
"externallmg_1682685905115_WhatsApp_Image_20230427_at_90418_PM_2.jpeg",
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685905115_WhatsApp_Image_20230427_at_90418_PM_2.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "644bbff0ba47a23af30eba86",
    "name":
"externallmg_1682685935887_WhatsApp_Image_20230427_at_90427_PM.jpeg",
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685935887_WhatsApp_Image_20230427_at_90427_PM.jpeg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "644bbfd1ba47a23af30eba30",
    "name": "Living Room",
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685905224_WhatsApp_Image_20230427_at_90419_PM_2.jpeg",
    "orientation": "portrait"
  }
]
```

```
    },
    {
      "status": false,
      "_id": "644bbfd1ba47a23af30eba31",
      "name": "Living Room",
      "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685905248_WhatsApp_Image_20230427_at_90419_PM.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "644bbfd1ba47a23af30eba33",
      "name": "Kitchen",
      "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685905272_WhatsApp_Image_20230427_at_90420_PM_2.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "644bbff0ba47a23af30eba79",
      "name": "Bedroom",
      "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685935759_WhatsApp_Image_20230427_at_90423_PM.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "644bbff0ba47a23af30eba7b",
      "name": "Bedroom",
      "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685935771_WhatsApp_Image_20230427_at_90424_PM_2.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "644bbfd1ba47a23af30eba36",
      "name": "Bedroom",
      "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685905302_WhatsApp_Image_20230427_at_90421_PM_2.jpeg",
      "orientation": "portrait"
    }
  ]
},
"taskStatus": {
  "DOCUMENT_VERIFY": false,
  "SITE_INSPECTION": false,
```

```
"RATE_VERIFY": false,
"MAKER": true,
"CHECKER": true,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": "LEAD",
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1052.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"status": true,
"caseStatus": "REPORTGENERATED",
"_id": "6448b7dad11ef125ab2641d4",
"ownerName": "Mr. Sanjay Kumar Nangia & Mrs. Kalra Anita Omprakash Nangia",
"ownerPhoneNo": "9167449325",
"appAddress": "Flat no 201 B'wing gare saton plot no 99 sector no 18 part Ulwe ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "02/05/2011",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Akshar Home Makers",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Mr. Sanjay Kumar Nangia & Mrs. Kalra Anita Omprakash Nangia",
      "number": {
```



```
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "4160"
},
"isHardCopy": false,
"displayStatus": true,
"id": "334141",
"path": "cases/6448b7dad11ef125ab2641d4/
document_1682490421155_DocScanner_10Jan2023_433_pm_2.pdf",
"fileName": "document_1682490421155_DocScanner_10Jan2023_433_pm_2.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "15/02/2016",
    "nameOfApprovingAuthority": {
      "value": "CIDCO",
      "label": "CIDCO"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "CIDCO / BP-8200 / TPO (NM & K) / 2016 / 1639"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "174854",
  "path": "cases/6448b7dad11ef125ab2641d4/
document_1682490444773_DOC20230110WA0017_2.pdf",
  "fileName": "document_1682490444773_DOC20230110WA0017_2.pdf"
}
],
"caseNumber": "001328",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "652327",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Apr 26 2023 11:04:18 GMT+0530 (India Standard Time)"
  }
]
```

```
],
"owners": [
  {
    "name": "Mr. Sanjay Kumar Nangia & Mrs. Kalra Anita Omprakash Nangia",
    "phone": "9167449325",
    "ownershipShare": "",
    "email": "",
    "id": "205646"
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "255163",
    "name": "Bedroom",
    "length": "12.83",
    "length1": "12",
    "length2": "10",
    "width": "10.83",
    "width1": "10",
    "width2": "10",
    "totalArea": "139.03",
    "images": [],
    "extraAreas": [
      {
        "measurementType": {
          "value": "Square_Feet",
          "label": "Square Feet"
        },
        "_id": "644bb813ba47a23af30eaa07",
        "name": "Extra",
        "extraAreaType": "Add",
        "length": "4.67",
        "length1": "4",
        "length2": "8",
        "width": "2.75",
        "width1": "2",
        "width2": "9",
        "totalArea": "12.83"
      }
    ]
  }
],
"finalArea": "151.86"
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Bedroom",
  "length": "12.25",
  "length1": "12",
  "length2": "3",
  "width": "10.75",
  "width1": "10",
  "width2": "9",
  "totalArea": "131.69",
  "images": [],
  "extraAreas": [],
  "finalArea": "131.69"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "8.42",
  "length1": "8",
  "length2": "5",
  "width": "3.25",
  "width1": "3",
  "width2": "3",
  "totalArea": "27.35",
  "images": [],
  "extraAreas": [],
  "finalArea": "27.35"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Living Room",
  "length": "11.00",
  "length1": "11",
```

```
"length2": "0",
"width": "16.83",
"width1": "16",
"width2": "10",
"totalArea": "185.17",
"images": [],
"extraAreas": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "_id": "644bb936ba47a23af30eada5",
    "name": "Extra",
    "extraAreaType": "Add",
    "length": "8.33",
    "length1": "8",
    "length2": "4",
    "width": "2.75",
    "width1": "2",
    "width2": "9",
    "totalArea": "22.92"
  }
],
"finalArea": "208.08999999999997"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Kitchen",
  "length": "7.42",
  "length1": "7",
  "length2": "5",
  "width": "9.58",
  "width1": "9",
  "width2": "7",
  "totalArea": "71.08",
  "images": [],
  "extraAreas": [],
  "finalArea": "71.08"
},
{
  "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Dining Area",
  "length": "5.92",
  "length1": "5",
  "length2": "11",
  "width": "8.92",
  "width1": "8",
  "width2": "11",
  "totalArea": "52.76",
  "images": [],
  "extraAreas": [],
  "finalArea": "52.76"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "3.67",
  "length1": "3",
  "length2": "8",
  "width": "6.75",
  "width1": "6",
  "width2": "9",
  "totalArea": "24.75",
  "images": [],
  "extraAreas": [],
  "finalArea": "24.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Bedroom",
  "length": "10.17",
  "length1": "10",
  "length2": "2",
  "width": "9.67",
  "width1": "9",
```

```
"width2": "8",
"totalArea": "98.28",
"images": [],
"extraAreas": [],
"finalArea": "98.28"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Toilet",
  "length": "6.58",
  "length1": "6",
  "length2": "7",
  "width": "3.83",
  "width1": "3",
  "width2": "10",
  "totalArea": "25.24",
  "images": [],
  "extraAreas": [],
  "finalArea": "25.24"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Toilet",
  "length": "4.17",
  "length1": "4",
  "length2": "2",
  "width": "6.50",
  "width1": "6",
  "width2": "6",
  "totalArea": "27.08",
  "images": [],
  "extraAreas": [],
  "finalArea": "27.08"
}
],
"otherComposition": [
  {
    "toBeAdded": {
```

```
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "value": "Dry_balcony",
    "label": "Dry Balcony"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length1": "2",
  "length2": "00",
  "length": "2.00",
  "width1": "5",
  "width2": "9",
  "width": "5.75",
  "totalArea": "11.50",
  "percentageBeforeTotal": "11.50",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "11.5"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "value": "Flowerbed",
    "label": "Flowerbed"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length1": "9",
  "length2": "10",
  "length": "9.83",
  "width1": "4",
  "width2": "10",
  "width": "4.83",
  "totalArea": "47.53",
```

```
"percentageBeforeTotal": "47.53",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "47.53"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "value": "Flowerbed",
    "label": "Flowerbed"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length1": "10",
  "length2": "9",
  "length": "10.75",
  "width1": "2",
  "width2": "0",
  "width": "2.00",
  "totalArea": "21.50",
  "percentageBeforeTotal": "21.50",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "21.5"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "value": "Flowerbed",
    "label": "Flowerbed"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
}
```



```
"id": "3",
"length1": "12",
"length2": "00",
"length": "12.00",
"width1": "2",
"width2": "00",
"width": "2.00",
"totalArea": "24.00",
"percentageBeforeTotal": "24.00",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "24"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "value": "Terrace",
    "label": "Terrace"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "length1": "12",
  "length2": "11",
  "length": "12.92",
  "width1": "4",
  "width2": "11",
  "width": "4.92",
  "totalArea": "63.51",
  "percentageBeforeTotal": "63.51",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "63.51"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
```

```
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "727485",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "1052",
  "squareMeterArea": "97.73",
  "docFinalBuiltUp": "1262.4",
  "docFinalBuiltUpSquareMeter": "117.27600000000001",
  "docBuiltupPercentage": "20",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "644baaefba47a23af30e6753",
    "id": "1",
    "property": "Akshar Greystone, Ulwe",
    "area": "800",
    "builtUpPercentage": "10",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "13th Floor",
    "source": "https://www.99acres.com/",
    "expectedPrice": "10700000",
    "expectedRate": "13375.00",
    "builtUpExpectedRate": "12159.09",
    "image": "cases/6448b7dad11ef125ab2641d4/
indicator_1682680559347_Image.png"
  },
  {
    "printlnReport": true,
    "_id": "644bab88ba47a23af30e68f0",
    "id": "2",
    "property": "Akshar Greystone, Ulwe",
    "area": "812",
    "builtUpPercentage": "10",
```

```
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "Housing.Com",
"expectedPrice": "11000000",
"expectedRate": "13546.80",
"builtUpExpectedRate": "12315.27",
"image": "cases/6448b7dad11ef125ab2641d4/
indicator_1682680712647_Image.png"
},
{
  "printlnReport": true,
  "_id": "644babf1ba47a23af30e6908",
  "id": "3",
  "property": "Ulwe Sector 18",
  "area": "900",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "12",
  "source": "magic_bricks",
  "expectedPrice": "11000000",
  "expectedRate": "12222.22",
  "builtUpExpectedRate": "11111.11",
  "image": "cases/6448b7dad11ef125ab2641d4/
indicator_1682680817224_Image.png"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644bbfd1ba47a23af30eba28",
    "name":
"externallmg_1682685905025_WhatsApp_Image_20230427_at_90416_PM.jpeg",
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685905025_WhatsApp_Image_20230427_at_90416_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644bbfd1ba47a23af30eba29",
    "name":
"externallmg_1682685905037_WhatsApp_Image_20230427_at_90417_PM_1.jpeg",
```

```
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685905037_WhatsApp_Image_20230427_at_90417_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644bbfd1ba47a23af30eba2a",
    "name":
"externallmg_1682685905069_WhatsApp_Image_20230427_at_90417_PM_2.jpeg",
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685905069_WhatsApp_Image_20230427_at_90417_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644bbfd1ba47a23af30eba2b",
    "name":
"externallmg_1682685905072_WhatsApp_Image_20230427_at_90417_PM.jpeg",
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685905072_WhatsApp_Image_20230427_at_90417_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644bbfd1ba47a23af30eba2c",
    "name":
"externallmg_1682685905085_WhatsApp_Image_20230427_at_90418_PM_1.jpeg",
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685905085_WhatsApp_Image_20230427_at_90418_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644bbfd1ba47a23af30eba2d",
    "name":
"externallmg_1682685905115_WhatsApp_Image_20230427_at_90418_PM_2.jpeg",
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685905115_WhatsApp_Image_20230427_at_90418_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "644bbfd1ba47a23af30eba2e",
    "name":
"externallmg_1682685905184_WhatsApp_Image_20230427_at_90418_PM.jpeg",
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685905184_WhatsApp_Image_20230427_at_90418_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644bbfd1ba47a23af30eba2f",
    "name":
"externallmg_1682685905202_WhatsApp_Image_20230427_at_90419_PM_1.jpeg",
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685905202_WhatsApp_Image_20230427_at_90419_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644bbfd1ba47a23af30eba30",
    "name":
"externallmg_1682685905224_WhatsApp_Image_20230427_at_90419_PM_2.jpeg",
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685905224_WhatsApp_Image_20230427_at_90419_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644bbfd1ba47a23af30eba31",
    "name":
"externallmg_1682685905248_WhatsApp_Image_20230427_at_90419_PM.jpeg",
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685905248_WhatsApp_Image_20230427_at_90419_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644bbfd1ba47a23af30eba32",
    "name":
"externallmg_1682685905262_WhatsApp_Image_20230427_at_90420_PM_1.jpeg",
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685905262_WhatsApp_Image_20230427_at_90420_PM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644bbfd1ba47a23af30eba33",
    "name":
"externallmg_1682685905272_WhatsApp_Image_20230427_at_90420_PM_2.jpeg",
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685905272_WhatsApp_Image_20230427_at_90420_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644bbfd1ba47a23af30eba34",
    "name":
"externallmg_1682685905281_WhatsApp_Image_20230427_at_90420_PM.jpeg",
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685905281_WhatsApp_Image_20230427_at_90420_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644bbfd1ba47a23af30eba35",
    "name":
"externallmg_1682685905288_WhatsApp_Image_20230427_at_90421_PM_1.jpeg",
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685905288_WhatsApp_Image_20230427_at_90421_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644bbfd1ba47a23af30eba36",
    "name":
"externallmg_1682685905302_WhatsApp_Image_20230427_at_90421_PM_2.jpeg",
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685905302_WhatsApp_Image_20230427_at_90421_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644bbfd1ba47a23af30eba37",
```

```
    "name":
"externallmg_1682685905315_WhatsApp_Image_20230427_at_90421_PM.jpeg",
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685905315_WhatsApp_Image_20230427_at_90421_PM.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644bbfd1ba47a23af30eba38",
    "name":
"externallmg_1682685905323_WhatsApp_Image_20230427_at_90422_PM_1.jpeg",
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685905323_WhatsApp_Image_20230427_at_90422_PM_1.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644bbff0ba47a23af30eba79",
    "name":
"externallmg_1682685935759_WhatsApp_Image_20230427_at_90423_PM.jpeg",
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685935759_WhatsApp_Image_20230427_at_90423_PM.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644bbff0ba47a23af30eba7a",
    "name":
"externallmg_1682685935761_WhatsApp_Image_20230427_at_90424_PM_1.jpeg",
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685935761_WhatsApp_Image_20230427_at_90424_PM_1.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644bbff0ba47a23af30eba7b",
    "name":
"externallmg_1682685935771_WhatsApp_Image_20230427_at_90424_PM_2.jpeg",
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685935771_WhatsApp_Image_20230427_at_90424_PM_2.jpeg",
    "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644bbff0ba47a23af30eba7c",
  "name":
"externallmg_1682685935778_WhatsApp_Image_20230427_at_90424_PM.jpeg",
  "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685935778_WhatsApp_Image_20230427_at_90424_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644bbff0ba47a23af30eba7d",
  "name":
"externallmg_1682685935794_WhatsApp_Image_20230427_at_90425_PM_1.jpeg",
  "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685935794_WhatsApp_Image_20230427_at_90425_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644bbff0ba47a23af30eba7e",
  "name":
"externallmg_1682685935819_WhatsApp_Image_20230427_at_90425_PM_2.jpeg",
  "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685935819_WhatsApp_Image_20230427_at_90425_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644bbff0ba47a23af30eba7f",
  "name":
"externallmg_1682685935822_WhatsApp_Image_20230427_at_90425_PM.jpeg",
  "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685935822_WhatsApp_Image_20230427_at_90425_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644bbff0ba47a23af30eba80",
  "name":
"externallmg_1682685935824_WhatsApp_Image_20230427_at_90426_PM_1.jpeg",
```



```
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685935824_WhatsApp_Image_20230427_at_90426_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644bbff0ba47a23af30eba81",
    "name":
"externallmg_1682685935827_WhatsApp_Image_20230427_at_90426_PM_2.jpeg",
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685935827_WhatsApp_Image_20230427_at_90426_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644bbff0ba47a23af30eba82",
    "name":
"externallmg_1682685935829_WhatsApp_Image_20230427_at_90426_PM_3.jpeg",
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685935829_WhatsApp_Image_20230427_at_90426_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644bbff0ba47a23af30eba83",
    "name":
"externallmg_1682685935837_WhatsApp_Image_20230427_at_90426_PM.jpeg",
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685935837_WhatsApp_Image_20230427_at_90426_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644bbff0ba47a23af30eba84",
    "name":
"externallmg_1682685935845_WhatsApp_Image_20230427_at_90427_PM_1.jpeg",
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685935845_WhatsApp_Image_20230427_at_90427_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "644bbff0ba47a23af30eba85",
  "name":
"externallmg_1682685935862_WhatsApp_Image_20230427_at_90427_PM_2.jpeg",
  "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685935862_WhatsApp_Image_20230427_at_90427_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644bbff0ba47a23af30eba86",
  "name":
"externallmg_1682685935887_WhatsApp_Image_20230427_at_90427_PM.jpeg",
  "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685935887_WhatsApp_Image_20230427_at_90427_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644bbff0ba47a23af30eba87",
  "name":
"externallmg_1682685935898_WhatsApp_Image_20230427_at_90428_PM_1.jpeg",
  "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685935898_WhatsApp_Image_20230427_at_90428_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644bbff0ba47a23af30eba88",
  "name":
"externallmg_1682685935909_WhatsApp_Image_20230427_at_90428_PM_2.jpeg",
  "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685935909_WhatsApp_Image_20230427_at_90428_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "644bbff0ba47a23af30eba89",
  "name":
"externallmg_1682685935921_WhatsApp_Image_20230427_at_90428_PM.jpeg",
  "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685935921_WhatsApp_Image_20230427_at_90428_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "644bbff0ba47a23af30eba8a",
    "name":
"externallmg_1682685935956_WhatsApp_Image_20230427_at_90429_PM.jpeg",
    "path": "cases/6448b7dad11ef125ab2641d4/
externallmg_1682685935956_WhatsApp_Image_20230427_at_90429_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-04-26T05:34:18.806Z",
"updatedAt": "2023-04-29T10:36:04.919Z",
"__v": 0,
"fullAddress": "Residential Flat No. 201, 2nd Floor, Wing - B, Grey Stone, Plot No. 99,
Sector 18 (Part), Village - Ulwe, Taluka - Panvel , District - Raigad, Navi Mumbai, 410
206, State - Maharashtra, India",
"updatedBy": "62691c48afd7d55eddecfda3",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Desetiny",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Tenant",
"siteVisitContactNo": "9167449325",
"buildingServicesRate": "2700",
"flatRate": "13000",
"landOtherRate": "10300",
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + Passage + Dining Area
+ 3 Toilet",
"carpetTotal": "818.18",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "168.04",
"builtupPercentage": "20",
"finalBuiltupArea": "1183.46",
"finalCarpetArea": "986.22",
"finalSalableArea": "1301.81",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": ""
```

"siteMeasurementRemark": "",
 "finalAreaType": "Carpet Area",
 "finalAsPerArea": "Agreement for sale",
 "finalBuiltUpPercentage": "20",
 "finalCarpetConvertToBuiltUpPer": "20",
 "finalSaleablePercentage": "0",
 "finalValuationAreaString": "Carpet Area in Sq. Ft. = 1052.00",
 "reason": "",
 "otherCompositionBuiltUpTotal": "0.00",
 "otherCompositionCarpetTotal": "168.04",
 "otherCompositionSaleableTotal": "0.00",
 "siteVisitDate": "2023-04-27"

}

Name	Length	Width	Total
Composition :			
Bedroom	12'10"	10'10"	139.03
Bedroom	12'3"	10'9"	131.69
Passage	8'5"	3'3"	27.35
Living Room	11'0"	16'10"	185.17
Kitchen	7'5"	9'7"	71.08
Dining Area	5'11"	8'11"	52.76
Toilet	3'8"	6'9"	24.75
Bedroom	10'2"	9'8"	98.28
Toilet	6'7"	3'10"	25.24
Toilet	4'2"	6'6"	27.08
Other Composition :			
Dry Balcony	2'00"	5'9"	11.50
Flowerbed	9'10"	4'10"	47.53
Flowerbed	10'9"	2'0"	21.50
Flowerbed	12'00"	2'00"	24.00
Terrace	12'11"	4'11"	63.51