

```
{
  "typeOfReport": {
    "label": "Residential",
    "value": "Residential"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63b26511191f7b344b008a1d"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b8b",
    "email": "coorddesk.rasmecbhy@sbi.co.in",
    "firstName": "SHASHI RANJAN",
    "mobileNo": "",
    "workMobileNo": "9867369914",
    "lastName": "RANJAN"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2900000",
    "discussWithPerson": "SHASHI RANJAN",
    "expectedFees": 1450,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
    "city": "Mumbai"
  }
}
```

```
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63b26511191f7b344b008a1d",
  "name": "RASMECC BHAYANDAR",
  "branchCode": "",
  "mobileNo": "022-28149108",
  "alternateMobileNo": "",
  "email": "Coorddesk.rasmecbhy@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "RASMECCC Bhayandar Branch\nUnit No. 101, 102, 103B, 1st Floor, IT
Landmark Building, 150ft. Road, Near Hotel Shree Nidhi, \nOpp. Maxus Mall,
Bhayander (West), Thane – 401 101, \nState – Maharashtra, Country – India."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "627219d6afd7d55eddedd283",
    "role": "PICKUPPERSON",
    "firstName": "Mangesh ",
    "email": "mangeshpalande17@gmail.com",
    "lastName": "Palande",
    "mobileNo": "9833030550",
    "shortName": "MP",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users/627219d6afd7d55eddedd283/
profilePhoto_1668055836118_WhatsApp_Image_20221110_at_101725_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "6401b61f0e28255fb44e636a",
  "role": "SITEENGINEER",
  "firstName": "Sanket",
  "email": "ksanket7414@yahoo.com",
  "lastName": "Karalkar",
  "mobileNo": "8080582858",
  "designation": "",
  "shortName": "SAK",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "0123456789",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
  "lastName": "Bodke",
  "mobileNo": "9821740317",
  "designation": "",
  "shortName": "SB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
  "type": "EMPLOYEE",
```

```

    "_id": "5fc78e26625ecd20ec1f88e9",
    "role": "MAKER+CHECKER",
    "firstName": "Vaishali",
    "email": "v.sarmalkar@vastukala.org",
    "lastName": "Sarmalkar",
    "mobileNo": "0123456789",
    "shortName": "VS",
    "workWithDocumentMaker": "1",
    "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
    "designation": ""
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "[N]C.C.I.T/I -14/52/2008-09",
          "label": "Wealth Tax"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "6084131a13f01f158c6ea1f3",
      "PANNo": "AEAPC7114Q",
      "role": "VALUER",
      "firstName": "Sharadkumar",
      "fatherName": "Baburao",
      "email": "cmd@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9422171100",
      "designation": "CMD",
      "registrationNo": [
        {
          "title": {
            "value": "Wealth_Tax",
            "label": "Wealth Tax"
          },
          "_id": "6084131a13f01f158c6ea1f4",
          "number": "[N]C.C.I.T/I -14/52/2008-09"
        }
      ],
      "shortName": "SBC",
      "workWithDocumentMaker": "",
      "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
    }
  ]

```

```
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.449692",
  "longitude": "72.816906"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.816906,
    19.449692
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-05-07T18:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-05-07T18:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-05-07T18:30:00.000Z",
      "remark": ""
    }
  ]
},
"visitedDate": [
  {
    "remark": "MANUAL",
    "status": "COMPLETED",
    "dateTime": "2023-05-08T07:00:00.000Z"
  },
  {
    "remark": "MANUAL",
    "status": "COMPLETED",
    "dateTime": "2023-05-07T18:30:00.000Z"
  },
  {
    "remark": "MANUAL",
    "status": "COMPLETED",
    "dateTime": "2023-05-07T18:30:00.000Z"
  }
]
```

```
    "dateTime": "2023-05-07T18:30:00.000Z"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Wed May 03 2023 10:38:27 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Virar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "3",
    "label": false
  },
  "buildingNo": {
```

```
"status": true,
"name": "Building No",
"key": "buildingNo",
"value": "1",
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Palghar",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Virar (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Vasai",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Viva Dronagiri Co-op. Hsg. Soc. Ltd.",
```

```
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Manvelpada Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Viva Girivihar ",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
```



```
"name": "Old Survey No.",
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "236/1, 243/2, 247/3, 4, 248/2B, 3, 249",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "304",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
}
```

```
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "401 305",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
```

```

    "key": "suburb",
    "value": "",
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "CeramicTileFlooring",
    "label": "Ceramic Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {

```

```
"value": "CIDCO",
"label": "City Industrial Development Corporation of Maharashtra"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Chawl ",
"west": "Silver Circle Road",
"south": "Manvelpada Road",
"east": "Chawl / Rani Talav Road"
},
"asPerDocumentAgreement": {
"north": "Details not available",
"west": "Details not available",
"south": "Details not available",
"east": "Details not available"
},
"extraDetailOfProperty": ""
},
"compositeRate": {
"remark": "",
"depreciationPercentage": "34.5",
"depreciationRatioOfBuilding": "",
"salvageValue": "10",
"depreciatedCostOfConstruction": "6337.5",
"depreciatedBuildingRate": "1637.5"
},
"igrRate": {
"propertyName": "Flat",
"rate": "57800",
"landRate": "15100",
"igrImage": "cases/6451dcf0b531512773050852/igr_1683609131814_Image.png",
"squareMeterGuideLineRate": "49130.00",
"squareFeetGuideLineRate": "4564.00"
},
"igrFinalRate": {
"rate": "3837.00",
"squareFeetGuideLineRate": "3837.00",
"squareMeterGuideLineRate": "41303.00"
},
"outgoingDetail": {
"areaStatusList": {
"value": "Medium",
"label": "Medium"
}
```

```
},
"propertyTypeOfUseList": {
  "value": "Residential_Purpose",
  "label": "Residential Purpose"
},
"propertyOccupiedByList": {
  "value": "Owner_Occupied",
  "label": "Owner Occupied"
},
"monthlyRent": "6,500",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per CIDCO norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  }
},
"anyFavouringForExtraPotentialValue": "Located in developing area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": {
```

```
"value": "Open_Car_Parking",
"label": "Open Car Parking"
},
"constructionWorkStatus": {
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2000",
"fullDate": "1/1/2000"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C._Framed_Structure",
"label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
"materialUsedList": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"buildingSpecification": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"structuralSafety": {
"value": "Normal",
"label": "Normal"
},
"protAgainstNatDis": {
```

```
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceIssues": {
"value": "Information_not_available",
"label": "Information not available"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "Information_not_available",
"label": "Information not available"
},
"groundStilt": {
"value": "ground",
"label": "Ground"
},
"yearOfConstructionAsPer": {
"value": "As_Per_Part_Occupancy_Certificate",
"label": "As Per Part Occupancy Certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "23",
"totalLifeBuilding": "60",
```

```
"estimatedAge": "37",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "4",
"flatFloorNo": "3",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "495.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/6451dcf0b531512773050852/
routeMap_1683537232769_Image.png",
    "routeLat": "19.449692",
    "routeLng": "72.816906",
    "stationName": "Virar",
    "routeDistance": "950 Mtr."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "hxx0jt",
      "name": "hxx0jt",
      "image": "cases/6451dcf0b531512773050852/
routeMap_1683537091867_Image.png"
    }
  ]
}
```



```
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "3137310.00",
  "bookValue": "0",
  "finalValue": "3137310.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEM_GENERATED",
  "date": "Tue May 09 2023 10:43:03 GMT+0530 (India Standard Time)",
  "number": "046618",
  "dayCount": "3",
  "monthCount": "78",
  "generatedBy": "5fc78e26625ecd20ec1f88e9"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
```

```
"rccFootingFoundation": {
  "label": "RCC Footing/Foundation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
```

```
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "1899315.00",
"selectedBuildUpValue": "495.00",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "6458bd8f7f94762ec7857108",
"name":
"externallmg_1683537294882_WhatsApp_Image_20230508_at_120016_PM.jpeg",
"path": "cases/6451dcf0b531512773050852/
externallmg_1683537294882_WhatsApp_Image_20230508_at_120016_PM.jpeg",
"orientation": "landscape"
}
],
"selfieWithSiteVisitImages": [
```

```
{
  "status": false,
  "_id": "6458bd8f7f94762ec7857114",
  "name":
"externallmg_1683537295137_WhatsApp_Image_20230508_at_120021_PM.jpeg",
  "path": "cases/6451dcf0b531512773050852/
externallmg_1683537295137_WhatsApp_Image_20230508_at_120021_PM.jpeg",
  "orientation": "landscape"
}
],
"externalPhotos": [
  {
    "status": false,
    "_id": "6458bd8f7f94762ec785710e",
    "name":
"externallmg_1683537295047_WhatsApp_Image_20230508_at_120019_PM.jpeg",
    "path": "cases/6451dcf0b531512773050852/
externallmg_1683537295047_WhatsApp_Image_20230508_at_120019_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6458bd8f7f94762ec785710a",
    "name":
"externallmg_1683537294935_WhatsApp_Image_20230508_at_120018_PM_1.jpeg",
    "path": "cases/6451dcf0b531512773050852/
externallmg_1683537294935_WhatsApp_Image_20230508_at_120018_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6458bd8f7f94762ec7857109",
    "name":
"externallmg_1683537294905_WhatsApp_Image_20230508_at_120017_PM.jpeg",
    "path": "cases/6451dcf0b531512773050852/
externallmg_1683537294905_WhatsApp_Image_20230508_at_120017_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6458bd8f7f94762ec7857110",
    "name":
"externallmg_1683537295084_WhatsApp_Image_20230508_at_120020_PM_2.jpeg",
    "path": "cases/6451dcf0b531512773050852/
externallmg_1683537295084_WhatsApp_Image_20230508_at_120020_PM_2.jpeg",
    "orientation": "portrait"
  }
]
```

```
}
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "6458bd8f7f94762ec7857111",
    "name":
"externallmg_1683537295101_WhatsApp_Image_20230508_at_120020_PM.jpeg",
    "path": "cases/6451dcf0b531512773050852/
externallmg_1683537295101_WhatsApp_Image_20230508_at_120020_PM.jpeg",
    "orientation": "landscape"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "6458bd9d7f94762ec7857194",
    "name": "Living Room",
    "path": "cases/6451dcf0b531512773050852/
externallmg_1683537308429_WhatsApp_Image_20230508_at_120024_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6458bd9d7f94762ec7857197",
    "name": "Living Room",
    "path": "cases/6451dcf0b531512773050852/
externallmg_1683537308459_WhatsApp_Image_20230508_at_120026_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6458bd8f7f94762ec7857113",
    "name": "Bedroom",
    "path": "cases/6451dcf0b531512773050852/
externallmg_1683537295128_WhatsApp_Image_20230508_at_120021_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6458bd9d7f94762ec7857191",
    "name": "Bedroom",
    "path": "cases/6451dcf0b531512773050852/
externallmg_1683537308393_WhatsApp_Image_20230508_at_120022_PM.jpeg",
    "orientation": "portrait"
  }
]
```

```
    },
    {
      "status": false,
      "_id": "6458bd9d7f94762ec7857195",
      "name": "Kitchen",
      "path": "cases/6451dcf0b531512773050852/
externallmg_1683537308439_WhatsApp_Image_20230508_at_120024_PM.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "6458bd9d7f94762ec7857196",
      "name": "Passage",
      "path": "cases/6451dcf0b531512773050852/
externallmg_1683537308452_WhatsApp_Image_20230508_at_120025_PM.jpeg",
      "orientation": "portrait"
    }
  ]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
},
```

```
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```



```
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false,
  "DOCUMENT_VERIFY": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
```

```
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "495.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86A/3"
],
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"_id": "6451dcf0b531512773050852",
"ownerName": "Lila Madhukar Rathod",
"ownerPhoneNo": "9423724530",
"appAddress": "A/304 dronagiri bldg viva dronagiri chs viva giri vihar bldg no 1 virar
east",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "27/04/2023",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Mr. Aniket Anil Deshmukh",
      "to": {
        "value": "Transferee",
        "label": "Transferee"
      },
      "Transferee": "Lila Madhukar Rathod"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "251886",
    "path": "cases/6451dcf0b531512773050852/document_1683090501864_lila.pdf",
    "fileName": "document_1683090501864_lila.pdf"
  },
  {
    "documentType": {
      "value": "60ae1250aa6d152c1801b316",
      "label": "Part Occupancy Certificate"
    },
    "inputs": {
```

```
"documentDate": "18/11/2000",
"nameOfApprovingAuthority": {
  "value": "CIDCO",
  "label": "CIDCO"
},
"number": {
  "value": "No",
  "label": "No"
},
"No": "CIDCO / VVSR / BP-2222 & 2223 / W "
},
"isHardCopy": false,
"displayStatus": false,
"path": "cases/6451dcf0b531512773050852/
document_1683535450068_144225.pdf",
"id": "488501",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Mon May 08 2023 14:14:16 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "001407",
"createdBy": "627219d6afd7d55eddedd283",
"caseHistory": [
  {
    "id": "504686",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed May 03 2023 09:32:56 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Lila Madhukar Rathod",
    "phone": "9423724530",
    "email": "",
    "ownershipShare": "",
    "id": "918328"
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  },

```

```
"id": "766143",
"name": "Living Room",
"length": "9.00",
"length1": "9",
"length2": "00",
"width": "15.00",
"width1": "15",
"width2": "00",
"totalArea": "135.00",
"images": [],
"extraAreas": [],
"finalArea": "135.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "",
  "length1": "8",
  "length2": "2",
  "width": "",
  "width1": "3",
  "width2": "0",
  "totalArea": "24.50",
  "images": [],
  "finalArea": "24.50",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "8.75",
  "length1": "8",
  "length2": "9",
  "width": "7.50",
  "width1": "7",
  "width2": "6",
  "totalArea": "65.62",
  "images": [],
```

```
"extraAreas": [],
"finalArea": "65.62"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bathroom",
  "length": "5.17",
  "length1": "5",
  "length2": "2",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "20.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "20.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "WC",
  "length": "4.25",
  "length1": "4",
  "length2": "3",
  "width": "3.17",
  "width1": "3",
  "width2": "2",
  "totalArea": "13.46",
  "images": [],
  "extraAreas": [],
  "finalArea": "13.46"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
```

```
"length": "12.08",
"length1": "12",
"length2": "1",
"width": "9.25",
"width1": "9",
"width2": "3",
"totalArea": "111.77",
"images": [],
"extraAreas": [],
"finalArea": "111.77"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "172674",
  "selectAreaTypeDocument": "Built_Up",
  "totalAreaDocument": "495",
  "squareMeterArea": "45.99",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docBuiltupPercentage": "",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "6459d3ad7f94762ec7861e7c",
  "id": "1",
  "property": "Flat",
  "area": "495",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
```

```
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "3500000",
"expectedRate": "7070.71",
"builtUpExpectedRate": "3500000",
"image": "cases/6451dcf0b531512773050852/
indicator_1683608493432_Image.png"
},
{
  "printlnReport": true,
  "_id": "6459d41c7f94762ec7861f7b",
  "id": "2",
  "property": "Flat",
  "area": "465",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "",
  "source": "https://www.99acres.com/",
  "expectedPrice": "3500000",
  "expectedRate": "7526.88",
  "builtUpExpectedRate": "3500000",
  "image": "cases/6451dcf0b531512773050852/
indicator_1683608604696_Image.png"
},
{
  "printlnReport": true,
  "_id": "6459d59a7f94762ec786276b",
  "id": "3",
  "property": "Flat",
  "area": "395",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "4",
  "source": "Index_no.2",
  "expectedPrice": "2600000",
  "expectedRate": "6582.28",
  "builtUpExpectedRate": "2600000",
  "image": "cases/6451dcf0b531512773050852/
indicator_1683608986093_Image.png"
}
```

```
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6458bd8f7f94762ec7857104",
    "name":
"externallmg_1683537294817_WhatsApp_Image_20230508_at_120014_PM.jpeg",
    "path": "cases/6451dcf0b531512773050852/
externallmg_1683537294817_WhatsApp_Image_20230508_at_120014_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6458bd8f7f94762ec7857105",
    "name":
"externallmg_1683537294832_WhatsApp_Image_20230508_at_120014_PM.jpeg",
    "path": "cases/6451dcf0b531512773050852/
externallmg_1683537294832_WhatsApp_Image_20230508_at_120014_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6458bd8f7f94762ec7857106",
    "name":
"externallmg_1683537294856_WhatsApp_Image_20230508_at_120015_PM_1.jpeg",
    "path": "cases/6451dcf0b531512773050852/
externallmg_1683537294856_WhatsApp_Image_20230508_at_120015_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6458bd8f7f94762ec7857107",
    "name":
"externallmg_1683537294874_WhatsApp_Image_20230508_at_120015_PM.jpeg",
    "path": "cases/6451dcf0b531512773050852/
externallmg_1683537294874_WhatsApp_Image_20230508_at_120015_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6458bd8f7f94762ec7857108",
```



```
"name":
"externallmg_1683537294882_WhatsApp_Image_20230508_at_120016_PM.jpeg",
  "path": "cases/6451dcf0b531512773050852/
externallmg_1683537294882_WhatsApp_Image_20230508_at_120016_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6458bd8f7f94762ec7857109",
  "name":
"externallmg_1683537294905_WhatsApp_Image_20230508_at_120017_PM.jpeg",
  "path": "cases/6451dcf0b531512773050852/
externallmg_1683537294905_WhatsApp_Image_20230508_at_120017_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6458bd8f7f94762ec785710a",
  "name":
"externallmg_1683537294935_WhatsApp_Image_20230508_at_120018_PM_1.jpeg",
  "path": "cases/6451dcf0b531512773050852/
externallmg_1683537294935_WhatsApp_Image_20230508_at_120018_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6458bd8f7f94762ec785710b",
  "name":
"externallmg_1683537294968_WhatsApp_Image_20230508_at_120018_PM_2.jpeg",
  "path": "cases/6451dcf0b531512773050852/
externallmg_1683537294968_WhatsApp_Image_20230508_at_120018_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6458bd8f7f94762ec785710c",
  "name":
"externallmg_1683537294993_WhatsApp_Image_20230508_at_120018_PM.jpeg",
  "path": "cases/6451dcf0b531512773050852/
externallmg_1683537294993_WhatsApp_Image_20230508_at_120018_PM.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6458bd8f7f94762ec785710d",
  "name":
"externallmg_1683537295030_WhatsApp_Image_20230508_at_120019_PM_1.jpeg",
  "path": "cases/6451dcf0b531512773050852/
externallmg_1683537295030_WhatsApp_Image_20230508_at_120019_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6458bd8f7f94762ec785710e",
  "name":
"externallmg_1683537295047_WhatsApp_Image_20230508_at_120019_PM.jpeg",
  "path": "cases/6451dcf0b531512773050852/
externallmg_1683537295047_WhatsApp_Image_20230508_at_120019_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6458bd8f7f94762ec785710f",
  "name":
"externallmg_1683537295069_WhatsApp_Image_20230508_at_120020_PM_1.jpeg",
  "path": "cases/6451dcf0b531512773050852/
externallmg_1683537295069_WhatsApp_Image_20230508_at_120020_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6458bd8f7f94762ec7857110",
  "name":
"externallmg_1683537295084_WhatsApp_Image_20230508_at_120020_PM_2.jpeg",
  "path": "cases/6451dcf0b531512773050852/
externallmg_1683537295084_WhatsApp_Image_20230508_at_120020_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6458bd8f7f94762ec7857111",
  "name":
"externallmg_1683537295101_WhatsApp_Image_20230508_at_120020_PM.jpeg",
```

```
    "path": "cases/6451dcf0b531512773050852/
externallmg_1683537295101_WhatsApp_Image_20230508_at_120020_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6458bd8f7f94762ec7857112",
    "name":
"externallmg_1683537295116_WhatsApp_Image_20230508_at_120021_PM_1.jpeg",
    "path": "cases/6451dcf0b531512773050852/
externallmg_1683537295116_WhatsApp_Image_20230508_at_120021_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6458bd8f7f94762ec7857113",
    "name":
"externallmg_1683537295128_WhatsApp_Image_20230508_at_120021_PM_2.jpeg",
    "path": "cases/6451dcf0b531512773050852/
externallmg_1683537295128_WhatsApp_Image_20230508_at_120021_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6458bd8f7f94762ec7857114",
    "name":
"externallmg_1683537295137_WhatsApp_Image_20230508_at_120021_PM.jpeg",
    "path": "cases/6451dcf0b531512773050852/
externallmg_1683537295137_WhatsApp_Image_20230508_at_120021_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6458bd9d7f94762ec7857190",
    "name":
"externallmg_1683537308380_WhatsApp_Image_20230508_at_120022_PM_1.jpeg",
    "path": "cases/6451dcf0b531512773050852/
externallmg_1683537308380_WhatsApp_Image_20230508_at_120022_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6458bd9d7f94762ec7857191",
    "name":
"externallmg_1683537308393_WhatsApp_Image_20230508_at_120022_PM.jpeg",
    "path": "cases/6451dcf0b531512773050852/
externallmg_1683537308393_WhatsApp_Image_20230508_at_120022_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6458bd9d7f94762ec7857192",
    "name":
"externallmg_1683537308407_WhatsApp_Image_20230508_at_120023_PM_1.jpeg",
    "path": "cases/6451dcf0b531512773050852/
externallmg_1683537308407_WhatsApp_Image_20230508_at_120023_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6458bd9d7f94762ec7857193",
    "name":
"externallmg_1683537308418_WhatsApp_Image_20230508_at_120023_PM.jpeg",
    "path": "cases/6451dcf0b531512773050852/
externallmg_1683537308418_WhatsApp_Image_20230508_at_120023_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6458bd9d7f94762ec7857194",
    "name":
"externallmg_1683537308429_WhatsApp_Image_20230508_at_120024_PM_1.jpeg",
    "path": "cases/6451dcf0b531512773050852/
externallmg_1683537308429_WhatsApp_Image_20230508_at_120024_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6458bd9d7f94762ec7857195",
    "name":
"externallmg_1683537308439_WhatsApp_Image_20230508_at_120024_PM.jpeg",
    "path": "cases/6451dcf0b531512773050852/
externallmg_1683537308439_WhatsApp_Image_20230508_at_120024_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6458bd9d7f94762ec7857196",
    "name":
"externallmg_1683537308452_WhatsApp_Image_20230508_at_120025_PM.jpeg",
    "path": "cases/6451dcf0b531512773050852/
externallmg_1683537308452_WhatsApp_Image_20230508_at_120025_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6458bd9d7f94762ec7857197",
    "name":
"externallmg_1683537308459_WhatsApp_Image_20230508_at_120026_PM_1.jpeg",
    "path": "cases/6451dcf0b531512773050852/
externallmg_1683537308459_WhatsApp_Image_20230508_at_120026_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6458bd9d7f94762ec7857198",
    "name":
"externallmg_1683537308468_WhatsApp_Image_20230508_at_120026_PM.jpeg",
    "path": "cases/6451dcf0b531512773050852/
externallmg_1683537308468_WhatsApp_Image_20230508_at_120026_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6458bd9d7f94762ec7857199",
    "name":
"externallmg_1683537308498_WhatsApp_Image_20230508_at_120027_PM.jpeg",
    "path": "cases/6451dcf0b531512773050852/
externallmg_1683537308498_WhatsApp_Image_20230508_at_120027_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6458bd9d7f94762ec785719a",
```

```
"name":
"externalImg_1683537308507_WhatsApp_Image_20230508_at_120042_PM.jpeg",
  "path": "cases/6451dcf0b531512773050852/
externalImg_1683537308507_WhatsApp_Image_20230508_at_120042_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"createdAt": "2023-05-03T04:02:56.468Z",
"updatedAt": "2023-05-09T05:57:48.590Z",
"__v": 0,
"fullAddress": "Residential Flat No. 304, 3rd Floor, Building No 1, Wing - A, Viva
Dronagiri Co-op. Hsg. Soc. Ltd., Viva Girivihar , Manvelpada Road, Village - Virar,
Taluka - Vasai, District - Palghar, Virar (East), 401 305, State - Maharashtra, India",
"updatedAtBy": "60eebe33f3dd69653a5837ae",
"addressForMap": "",
"caseReferredBy": "627219d6afd7d55eddedd283",
"contactPersonName": "Ankush Babu Jadhav",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner's Husband",
"siteVisitContactNo": "9423724530",
"reason": "",
"siteVisitDate": "2023-05-08",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + Bathroom +
WC",
"carpetTotal": "371.02",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "408.12",
"finalCarpetArea": "371.02",
"finalSalableArea": "448.93",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 495.00",
```

"buildingServicesRate": "2500",
"flatRate": "7200",
"landOtherRate": "4700",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"

}

Name	Length	Width	Total
Composition :			
Living Room	9'00"	15'00"	135.00
Passage	8'2"	3'0"	24.50
Kitchen	8'9"	7'6"	65.62
Bathroom	5'2"	4'00"	20.67
WC	4'3"	3'2"	13.46
Bedroom	12'1"	9'3"	111.77
Other Composition :			