

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b80a"
    },
    "type": "CREDITOFFICER",
    "_id": "6417f02396b58848585ed0c0",
    "firstName": "Anmol Tiwari",
    "lastName": "Tiwari",
    "mobileNo": "",
    "workMobileNo": "7977031040",
    "email": ""
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "12000000",
    "discussWithPerson": "Anmol Tiwari",
    "expectedFees": 6000,
    "quotedAmount": "2500"
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
    "city": "Mumbai"
  }
}
```

```
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b80a",
  "branchCode": "000088",
  "type": "BRANCH",
  "name": "RACPC - Chinchpokli ",
  "email": "sbi.17889@sbi.co.in",
  "mobileNo": "022-23707514",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, Mumbai South Voltas
House, 'A', 1st Floor, Dr. Ambedkar Road, Chinchpokli (East), Mumbai - 400 033, State
- Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - CHINCHPOKALI",
  "fax": "022-23707512 / 13",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af3d172ffdf65bcd6585cd",
    "role": "PICKUPPERSON",
    "firstName": "Sachin",
    "email": "sachin.joshi@vastukala.org",
    "lastName": "Joshi",
    "mobileNo": "9167204063",
```

```
    "shortName": "SJ",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af3d172ffdf65bcd6585cd\
\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "62550ed0aba01e0af98f2f75",
    "role": "SITEENGINEER",
    "firstName": "Chandan",
    "email": "chandan@vastukala.org",
    "lastName": "Singh",
    "mobileNo": "8454863607",
    "designation": "",
    "shortName": "CH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60092304a16fab0f2af9b0c2",
    "role": "MAKER+CHECKER",
    "firstName": "Nitesh",
    "email": "nitesh.khedekar@vastukala.org",
    "lastName": "Khedekar",
    "mobileNo": "8369040652",
    "designation": "",
    "shortName": "NK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "60092304a16fab0f2af9b0c2",
    "role": "MAKER+CHECKER",
    "firstName": "Nitesh",
    "email": "nitesh.khedekar@vastukala.org",
    "lastName": "Khedekar",
    "mobileNo": "8369040652",
    "designation": "",
    "shortName": "NK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
```

```
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
  "mobileNo": "9769797568",
  "designation": "",
  "shortName": "P",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.053850617793568",
  "longitude": "72.89135947758702"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.89135947758702,
    19.053850617793568
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
```

```
    "dateTime": "2023-05-09T11:00:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-05-09T11:00:00.000Z",
    "remark": ""
  }
],
"visitedDate": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Tue May 09 2023 17:31:02 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Chembur",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "9",
    "label": false
  }
}
```

```
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
```

```
"key": "buildingName",
"value": "Veer Siddhank CHSL",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Shiv SHrushti ",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Near Nehru Nagar",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
}
```



```
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "904",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
```

```
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
```

```
"status": true,
"name": "Suburb",
"key": "suburb",
"value": "Chembur",
"label": false
}
},
"flatSpecifications": {
"roof": {
"label": "Proposed R.C.C. Slab",
"value": "Proposed_R.C.C._Slab"
},
"flooring": {
"label": "Proposed Vitrified tiles flooring",
"value": "Proposed_Vitrified_tiles_flooring"
},
"doors": {
"label": "Proposed Teak wood door frame with flush doors",
"value": "Proposed_Teak_wood_door_frame_with_flush_doors"
},
"windows": {
"label": "Aluminium Sliding Window ",
"value": "Aluminium_Sliding_Window_"
},
"fittings": {
"label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring",
"value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring"
},
"finishing": {
"label": "Building Under Construction",
"value": "Building_Under_Construction"
}
},
"general": {
"populationClassList": {
"label": "Middle Class",
"value": "MiddleClass"
},
"populationGroupList": {
"label": "Urban",
"value": "Urban"
},
"townplanApprovedByList": {
"label": "Municipal Corporation of Greater Mumbai (MCGM)",
"value": "MCGM"
},
},
```

```
"asPerActualAgreement": {
  "south": "jijamata apartment",
  "east": "CST Road",
  "west": "Plot 18",
  "north": "udyamitra shivsrusti"
},
"asPerDocumentAgreement": {
  "north": "",
  "west": "",
  "south": "",
  "east": ""
}
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  },
  "carParking": {
    "label": "Silt+Podium Car Parking",
    "value": "Silt+Podium_Car_Parking"
  },
  "constructionWorkStatus": {
    "label": "Under Construction",
    "value": "InProgress"
  },
  "dateOfConstruction": {
    "date": "",
    "month": "1",
    "year": "2023",
    "fullDate": "1/1/2023"
  }
}
```

```
},
"propertyTypeList": {
  "value": "Residential",
  "label": "Residential"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"qualityOfConstruction": {
  "label": "Building Under Construction",
  "value": "UnderConstruction"
},
"walls": {
  "label": "Building Under Construction",
  "value": "Building_Under_Construction"
},
"appearanceOfTheBuilding": {
  "label": "Building Under Construction",
  "value": "UnderConstruction"
},
"maintenanceOfTheBuilding": {
  "label": "Building Under Construction",
  "value": "UnderConstruction"
},
"visibleDamageInBuilding": {
  "label": "Building Under Construction",
  "value": "Building_Under_Construction"
},
"groundStilt": {
  "label": "Ground",
  "value": "ground"
},
"isSiteVisitAllowed": true,
"flatFloorNo": "",
"noOfLiftsInEachWings": "0",
"totalLifeBuilding": "",
"ageOfBuilding": "",
"estimatedAge": "",
"noOfBasement": "",
"noOfPodium": "3",
"noOfFloors": "14",
```

```
"noOfDwellingUnitsInBuilding": "6",
"noOfLifts": "3",
"noOfAmenityFloors": ""
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "11",
    "percentage": "23.16",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "8",
    "percentage": "7.00",
```

```
"isHideFloor": false,
"status": true
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "9",
  "percentage": "7.00",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "8",
  "percentage": "4.21",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
```

```
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "51.37",
"isHideFloor": true,
```



```
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
```

```
"title": "Potential value, if any",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
isSiteMeasurementAllowed": false,
finalValuationArea": "0",
```

```
"empanelmentNo": [],
"status": true,
"caseStatus": "NEW",
"_id": "645a2d5e7f94762ec786b5f0",
"ownerName": "Subinkumar Parui",
"ownerPhoneNo": "9224381305",
"appAddress": "Flat no 904,9floor,Veer Siddhanak CHS,Shiv shrushti Neharu Nagar
Kurla East",
"remark": "Cont Person Mr Sauvin +91 92243 81305\napprox value Nitesh ",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/645a2d5e7f94762ec786b5f0/
document_1683631414272_Subinkumar_Parui__Shobha_Parui.pdf",
    "fileName": "document_1683631414272_Subinkumar_Parui__Shobha_Parui.pdf",
    "displayStatus": false,
    "id": "885021",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Tue May 09 2023 16:54:06 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "001491",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "112128",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue May 09 2023 16:54:14 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Subinkumar Parui",
    "phone": "9224381305",
    "ownershipShare": "",
    "email": "",
    "id": "615811"
  }
],
"siteInspection": [],
"composition": [],
```

```

"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "645b35447f94762ec7872ecc",
    "name": "externalimg_1683699008526_image.jpeg",
    "path": "cases/645a2d5e7f94762ec786b5f0/
externalimg_1683699008526_image.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-05-09T11:24:14.939Z",
"updatedAt": "2023-05-10T06:10:34.287Z",
"__v": 0,
"fullAddress": "Residential Flat No. 904, 9th Floor, Veer Siddhank CHSL, Shiv
SHrushti , Near Nehru Nagar, Village - Chembur, Chembur, Mumbai, State -
Maharashtra, India",
"updatedBy": "62550ed0aba01e0af98f2f75",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Subinkumar Parui",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9224381305",
"briefDescOfProperty": "",
"carpetTotal": "0",
"finalMeasurementType": "",
"otherCarpetTotal": "0"
}

```

Name	Length	Width	Total
Composition :			

Other  
Composition :

---