

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b80a"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94231288",
    "firstName": "Rupesh Juvekar",
    "email": "0_default_rupesh.juvekar@sbi.co.in_and_rm.lodha@sbi.co.in",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-9769882458"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "7500000",
    "discussWithPerson": "Rupesh Juvekar",
    "expectedFees": 3750,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
    "city": "Mumbai"
  },
}
```

```
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b80a",
  "branchCode": "000088",
  "type": "BRANCH",
  "name": "RACPC - Chinchpokli ",
  "email": "sbi.17889@sbi.co.in",
  "mobileNo": "022-23707514",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, Mumbai South Voltas
House, 'A', 1st Floor, Dr. Ambedkar Road, Chinchpokli (East), Mumbai - 400 033, State
- Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - CHINCHPOKALI",
  "fax": "022-23707512 / 13",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62727444afd7d55eddee092c",
    "role": "PICKUPPERSON",
    "firstName": "Shantilal",
    "email": "shantilal@vastukala.org",
    "lastName": "Patel",
    "mobileNo": "9969039853",
    "shortName": "SHP",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "RAJESH",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "GHADI",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER+CHECKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER+CHECKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"checker": {
  "type": "EMPLOYEE",
```

```
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
  "mobileNo": "9769797568",
  "designation": "",
  "shortName": "P",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      },
      {
        "title": {
```

```
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.07043352031711",
  "longitude": "73.08077336997731"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.08077336997731,
    19.07043352031711
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-05-20"
    }
  ]
}
```

```
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Thu May 18 2023 09:01:46 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Owe Kharghar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "19",
    "label": false
  },
  "buildingNo": {
    "status": false,
```

```
"name": "Building No",
"key": "buildingNo",
"value": "",
"label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "15, 17, 18, 18A, 19 & 20",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Niharika Residency",
  "label": false
}
```

```
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "34B",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
```



```
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1903",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
}
```

```
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
```

```
"value": "",
"label": false
}
},
"flatSpecifications": {
"roof": {
"label": "R. C. C. Slab",
"value": "rcc_Slab"
},
"flooring": {
"label": "Vitrified Tile Flooring",
"value": "VerifiedTileFlooring"
},
"doors": {
"value": "Teak_Wood_Door_frame_with_Solid_flush_door",
"label": "Teak Wood Door frame with Solid flush door"
},
"windows": {
"value": "PowderCoatedAluminiumSliding",
"label": "Powder Coated Aluminium Sliding"
},
"fittings": {
"value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
"label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
"value": "Cement_Plastering",
"label": "Cement Plastering"
}
},
"general": {
"populationClassList": {
"label": "Higher Middle Class",
"value": "HigherMiddleClass"
},
"populationGroupList": {
"label": "Urban",
"value": "Urban"
},
"townplanApprovedByList": {
"label": "As per CIDCO norms",
"value": "As_per_CIDCO_norms"
},
"asPerActualAgreement": {
"north": "ROAS",
```

```
"south": "FUTURE PRIDE",
"east": "OPEN",
"west": "ANMOL RESIDENCY"
},
"asPerDocumentAgreement": {
  "north": "",
  "west": "",
  "south": "",
  "east": ""
}
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "I Class",
    "value": "I_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Tenant Occupied",
    "value": "Tenant_Occupied"
  },
  "monthlyRent": "` 25,000.00 present rental income per month ",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "Details not available",
  "tenantName": "Anil Kumar",
  "maintenanceOfFlat": "Details not available"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
```

```
"label": "R. C. C. Slab"
},
"partitions": {
  "label": "6\" Thk. Brick Masonery",
  "value": "6\"_Thk._Brick_Masonery"
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "label": "Yes",
  "value": "Yes"
},
"carParking": {
  "value": "Silt+Podium_Car_Parking",
  "label": "Silt+Podium Car Parking"
},
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2014",
  "fullDate": "1/1/2014"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
```

```
"label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "label": "Excellent",
  "value": "Excellent"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
}
```

```
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "label": "Stilt",
  "value": "stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "51",
"ageOfBuilding": "9",
"noOfBasement": "0",
"noOfPodium": "01",
"noOfAmenityFloors": "2",
"noOfFloors": "23",
"flatFloorNo": "19",
"noOfLifts": "03",
"noOfDwellingUnitsInBuilding": "06"
},
"finalPlinthArea": {
  "area": "678.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": ""
  }
}
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```



```
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
```

```
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
```

```
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"_id": "6464fbaeee6a9735bf798f79",
"ownerName": "Hansh Kumar ",
"ownerPhoneNo": "8097411857",
"appAddress": "Niharika\n1903 19 th floor Kharghar\nNew Mumbai panvel",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/6464fbaeee6a9735bf798f79/document_1684339624597_Hans.pdf",
    "fileName": "document_1684339624597_Hans.pdf",
    "displayStatus": false,
    "id": "643118",
    "uploadedBy": "62727444afd7d55eddee092c",
    "createdAt": "Wed May 17 2023 21:38:00 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "001613",
```

```
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "421612",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed May 17 2023 21:38:10 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Hansh Kumar ",
    "phone": "8097411857",
    "email": "",
    "ownershipShare": "",
    "id": "936010"
  },
  {
    "name": "Hans Kumar",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "645955"
  },
  {
    "name": "Mrs. Priya",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "113745"
  }
],
"siteInspection": [
  {
    "areaType": {
      "label": "Saleable",
      "value": "Saleable"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    },
    "_id": "6468298846e69b7878e98671",
    "area": "0",
    "providedByName": "Hansh Kumar ",
    "providedByContactNo": "8097411857"
  }
]
```

```
}
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "485210",
    "name": "Bathroom",
    "length": "11.33",
    "length1": "11",
    "length2": "4",
    "width": "10.00",
    "width1": "10",
    "width2": "00",
    "totalArea": "113.33",
    "images": [],
    "extraAreas": [],
    "finalArea": "113.33"
  },
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "1",
    "name": "Living Room",
    "length": "10.00",
    "length1": "10",
    "length2": "00",
    "width": "18.33",
    "width1": "18",
    "width2": "4",
    "totalArea": "183.33",
    "images": [],
    "extraAreas": [],
    "finalArea": "183.33"
  },
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "2",
    "name": "Dining",
```

```
"length": "4.67",
"length1": "4",
"length2": "8",
"width": "8.00",
"width1": "8",
"width2": "00",
"totalArea": "37.33",
"images": [],
"extraAreas": [],
"finalArea": "37.33"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Kitchen",
  "length": "10.92",
  "length1": "10",
  "length2": "11",
  "width": "7.08",
  "width1": "7",
  "width2": "1",
  "totalArea": "77.33",
  "images": [],
  "extraAreas": [],
  "finalArea": "77.33"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Passage",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "2.50",
  "width1": "2",
  "width2": "6",
  "totalArea": "12.50",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.50"
}
```



```
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "Toilets",
  "length": "7.00",
  "length1": "7",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "28.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "28.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "12.00",
  "length1": "12",
  "length2": "00",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "120.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "120.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "7",
  "name": "Toilet",
  "length": "4.00",
  "length1": "4",
```

```
"length2": "00",
"width": "7.00",
"width1": "7",
"width2": "00",
"totalArea": "28.00",
"images": [],
"extraAreas": [],
"finalArea": "28.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "8",
  "name": "Passage",
  "length": "6.00",
  "length1": "6",
  "length2": "00",
  "width": "2.00",
  "width1": "2",
  "width2": "00",
  "totalArea": "12.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.00"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Flower Bed Area",
      "value": "Flower_Bed_Area"
    },
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "0",
    "length1": "2",
    "length2": "00",
    "length": "2.00",
```

```
"width1": "7",
"width2": "00",
"width": "7.00",
"totalArea": "14.00",
"percentageBeforeTotal": "14.00",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "14"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flower Bed Area",
    "value": "Flower_Bed_Area"
  },
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "length1": "2",
  "length2": "00",
  "length": "2.00",
  "width1": "10",
  "width2": "00",
  "width": "10.00",
  "totalArea": "20.00",
  "percentageBeforeTotal": "20.00",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "20"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "368691",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "565",
  "squareMeterArea": "52.49",
  "docFinalBuiltUp": "678",
  "docFinalBuiltUpSquareMeter": "62.988",
  "docBultupPercentage": "20",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "6475a48ab05e530fb6c807ff",
    "id": "1",
    "property": "Juhi Niharika Residency, Sector 34B, Kharghar, Navi Mumbai",
    "area": "700",
    "builtUpPercentage": "20",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "",
    "source": "https://www.99acres.com/",
    "expectedPrice": "11000000",
    "expectedRate": "15714.29",
    "builtUpExpectedRate": "13095.24",
    "image": "cases/6464fbaee6a9735bf798f79/indicator_1685431434141_Image.png"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646827b446e69b7878e985b1",
    "name": "externalImg_1684547502648_1684547406624_image_0.jpeg",
    "path": "cases/6464fbaee6a9735bf798f79/externalImg_1684547502648_1684547406624_image_0.jpeg",
    "orientation": "portrait"
  },
  {
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646827b446e69b7878e985b2",
    "name": "externallmg_1684547503552_1684547406624_image_1.jpeg",
    "path": "cases/6464fbaee6a9735bf798f79/
externallmg_1684547503552_1684547406624_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646827b446e69b7878e985b3",
    "name": "externallmg_1684547503582_1684547406624_image_2.jpeg",
    "path": "cases/6464fbaee6a9735bf798f79/
externallmg_1684547503582_1684547406624_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646827b446e69b7878e985b4",
    "name": "externallmg_1684547506059_1684547406624_image_3.jpeg",
    "path": "cases/6464fbaee6a9735bf798f79/
externallmg_1684547506059_1684547406624_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646827b446e69b7878e985b5",
    "name": "externallmg_1684547506075_1684547406624_image_4.jpeg",
    "path": "cases/6464fbaee6a9735bf798f79/
externallmg_1684547506075_1684547406624_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646827b446e69b7878e985b6",
    "name": "externallmg_1684547506075_1684547406624_image_5.jpeg",
    "path": "cases/6464fbaee6a9735bf798f79/
externallmg_1684547506075_1684547406624_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "646827b446e69b7878e985b7",
  "name": "externallmg_1684547506076_1684547406624_image_6.jpeg",
  "path": "cases/6464fbaee6a9735bf798f79/
externallmg_1684547506076_1684547406624_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "646827b446e69b7878e985b8",
  "name": "externallmg_1684547506082_1684547406624_image_7.jpeg",
  "path": "cases/6464fbaee6a9735bf798f79/
externallmg_1684547506082_1684547406624_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "646827b446e69b7878e985b9",
  "name": "externallmg_1684547506102_1684547406624_image_8.jpeg",
  "path": "cases/6464fbaee6a9735bf798f79/
externallmg_1684547506102_1684547406624_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "646827b446e69b7878e985ba",
  "name": "externallmg_1684547506127_1684547406624_image_9.jpeg",
  "path": "cases/6464fbaee6a9735bf798f79/
externallmg_1684547506127_1684547406624_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "646827b446e69b7878e985bb",
  "name": "externallmg_1684547506177_1684547406624_image_10.jpeg",
  "path": "cases/6464fbaee6a9735bf798f79/
externallmg_1684547506177_1684547406624_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "646827b446e69b7878e985bc",
    "name": "externallmg_1684547506179_1684547406624_image_11.jpeg",
    "path": "cases/6464fbaee6a9735bf798f79/
externallmg_1684547506179_1684547406624_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646827b446e69b7878e985bd",
    "name": "externallmg_1684547506362_1684547406624_image_12.jpeg",
    "path": "cases/6464fbaee6a9735bf798f79/
externallmg_1684547506362_1684547406624_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646827b446e69b7878e985be",
    "name": "externallmg_1684547506386_1684547406624_image_13.jpeg",
    "path": "cases/6464fbaee6a9735bf798f79/
externallmg_1684547506386_1684547406624_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646827b446e69b7878e985bf",
    "name": "externallmg_1684547506437_1684547406624_image_14.jpeg",
    "path": "cases/6464fbaee6a9735bf798f79/
externallmg_1684547506437_1684547406624_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646827b446e69b7878e985c0",
    "name": "externallmg_1684547506941_1684547406624_image_15.jpeg",
    "path": "cases/6464fbaee6a9735bf798f79/
externallmg_1684547506941_1684547406624_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "646827b446e69b7878e985c1",
```

```
    "name": "externallmg_1684547470801_1684547373812_image_0.jpeg",
    "path": "cases/6464fbaee6a9735bf798f79/
externallmg_1684547470801_1684547373812_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "646827b446e69b7878e985c2",
    "name": "externallmg_1684547471932_1684547373813_image_1.jpeg",
    "path": "cases/6464fbaee6a9735bf798f79/
externallmg_1684547471932_1684547373813_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "646827b446e69b7878e985c3",
    "name": "externallmg_1684547471957_1684547373813_image_2.jpeg",
    "path": "cases/6464fbaee6a9735bf798f79/
externallmg_1684547471957_1684547373813_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "646827b446e69b7878e985c4",
    "name": "externallmg_1684547474240_1684547373813_image_3.jpeg",
    "path": "cases/6464fbaee6a9735bf798f79/
externallmg_1684547474240_1684547373813_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "646827b446e69b7878e985c5",
    "name": "externallmg_1684547474772_1684547373813_image_4.jpeg",
    "path": "cases/6464fbaee6a9735bf798f79/
externallmg_1684547474772_1684547373813_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "646827b446e69b7878e985c6",
    "name": "externallmg_1684547474787_1684547373813_image_5.jpeg",
```



```
    "path": "cases/6464fbaeee6a9735bf798f79/  
externallmg_1684547474787_1684547373813_image_5.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "MEASUREMENT_IMAGE",  
    "status": false,  
    "_id": "646827b446e69b7878e985c7",  
    "name": "externallmg_1684547474813_1684547373813_image_6.jpeg",  
    "path": "cases/6464fbaeee6a9735bf798f79/  
externallmg_1684547474813_1684547373813_image_6.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "MEASUREMENT_IMAGE",  
    "status": false,  
    "_id": "646827b446e69b7878e985c8",  
    "name": "externallmg_1684547474852_1684547373813_image_7.jpeg",  
    "path": "cases/6464fbaeee6a9735bf798f79/  
externallmg_1684547474852_1684547373813_image_7.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "MEASUREMENT_IMAGE",  
    "status": false,  
    "_id": "646827b446e69b7878e985c9",  
    "name": "externallmg_1684547474891_1684547373813_image_8.jpeg",  
    "path": "cases/6464fbaeee6a9735bf798f79/  
externallmg_1684547474891_1684547373813_image_8.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "MEASUREMENT_IMAGE",  
    "status": false,  
    "_id": "646827b446e69b7878e985ca",  
    "name": "externallmg_1684547474921_1684547373813_image_9.jpeg",  
    "path": "cases/6464fbaeee6a9735bf798f79/  
externallmg_1684547474921_1684547373813_image_9.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "MEASUREMENT_IMAGE",  
    "status": false,  
    "_id": "646827b446e69b7878e985cb",  
    "name": "externallmg_1684547474982_1684547373813_image_10.jpeg",  
    "path": "cases/6464fbaeee6a9735bf798f79/  
externallmg_1684547474982_1684547373813_image_10.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "646827b446e69b7878e985cc",
  "name": "externallmg_1684547475422_1684547373813_image_11.jpeg",
  "path": "cases/6464fbaee6a9735bf798f79/
externallmg_1684547475422_1684547373813_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "646827b446e69b7878e985cd",
  "name": "externallmg_1684547475567_1684547373813_image_12.jpeg",
  "path": "cases/6464fbaee6a9735bf798f79/
externallmg_1684547475567_1684547373813_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "646827b446e69b7878e985ce",
  "name": "externallmg_1684547475571_1684547373813_image_13.jpeg",
  "path": "cases/6464fbaee6a9735bf798f79/
externallmg_1684547475571_1684547373813_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "646827b446e69b7878e985cf",
  "name": "externallmg_1684547475572_1684547373813_image_14.jpeg",
  "path": "cases/6464fbaee6a9735bf798f79/
externallmg_1684547475572_1684547373813_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "646827b446e69b7878e985d0",
  "name": "externallmg_1684547475648_1684547373813_image_15.jpeg",
  "path": "cases/6464fbaee6a9735bf798f79/
externallmg_1684547475648_1684547373813_image_15.jpeg",
  "orientation": "portrait"
}
```

```

    }
  ],
  "externalDocuments": [],
  "createdAt": "2023-05-17T16:08:10.079Z",
  "updatedAt": "2023-05-30T07:23:54.248Z",
  "__v": 0,
  "fullAddress": "Residential Flat No. 1903, 19th Floor, Niharika Residency, Plot No. 15,
17, 18, 18A, 19 & 20, Sector 34B, Village - Owe Kharghar, Navi Mumbai, State -
Maharashtra, India",
  "updatedBy": "627221f4afd7d55eddeddcb4",
  "addressForMap": "",
  "caseReferredBy": "62727444afd7d55eddee092c",
  "contactPersonName": "Hansh Kumar ",
  "email": "",
  "isExternal": "false",
  "isUrgent": "false",
  "ownershipShare": "",
  "purchaseValueAsPerDocument": "",
  "relationWithOwner": "self",
  "siteVisitContactNo": "8097411857",
  "briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Bathroom + Dining + 2
Passage + Toilets + Toilet",
  "carpetTotal": "611.8199999999999",
  "finalMeasurementType": "Sq. Ft.",
  "otherCarpetTotal": "34",
  "siteVisitDate": "2023-05-20",
  "otherCompositionBuiltUpTotal": "0.00",
  "otherCompositionCarpetTotal": "34.00",
  "otherCompositionSaleableTotal": "0.00",
  "builtupPercentage": "10",
  "finalBuiltupArea": "710.40",
  "finalCarpetArea": "645.82",
  "finalSalableArea": "781.44",
  "salablePercentage": "10",
  "toBeAdded": ""
}

```

Name	Length	Width	Total
Composition :			
Bathroom	11'4"	10'00"	113.33
Living Room	10'00"	18'4"	183.33
Dining	4'8"	8'00"	37.33

Kitchen	10'11"	7'1"	77.33
Passage	5'00"	2'6"	12.50
Toilets	7'00"	4'00"	28.00
Bedroom	12'00"	10'00"	120.00
Toilet	4'00"	7'00"	28.00
Passage	6'00"	2'00"	12.00
Other Composition :			
Flower Bed Area	2'00"	7'00"	14.00
Flower Bed Area	2'00"	10'00"	20.00