

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Fair_Market_Value_Visa",
    "label": "Visa Application"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "fees": {
    "type": "agreed",
    "propertyValue": "100000",
    "discussWithPerson": "Manoj Sir",
    "expectedFees": 50,
    "quotedAmount": "5000"
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
    "city": "Mumbai"
  },
  "client": {
    "_id": "646b0eceb05e530fb6c2d067",
    "type": "PRIVATE_CLIENT",
    "name": "Asif Kasamali Shaikh\t",
    "displayName": "Asif Kasamali Shaikh\t",
    "initial": "A"
  },
  "assetsClass": {
    "value": "Land_&_Building_/_Immovable_Property",
    "label": "Land & Building / Immovable Property"
  },
}
```

```
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "shortName": "MBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "60f9343b45132d6a6bdd96e8",
    "role": "SITEENGINEER",
    "firstName": "RAJESH",
    "email": "rajeshb.ghadi@gmail.com",
    "lastName": "GHADI",
    "mobileNo": "8652092666",
    "designation": "",
    "shortName": "RHG",
    "workWithDocumentMaker": ""
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60eeaeddf3dd69653a581316",
    "role": "MAKER+CHECKER",
    "firstName": "Shyam",
    "email": "shyam@vastukala.org",
    "lastName": "Kajvilkar",
    "mobileNo": "9765074720",
    "designation": "",
    "shortName": "SK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyma_Photo.jpg"
  },
  "maker": {
    "type": "EMPLOYEE",
```

```
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER+CHECKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "0123456789",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        }
      }
    ]
  }
]
```

```
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "PRIVATE_CLIENT",
  "label": "Private Clients"
},
"location": {
  "latitude": "19.161069889206406",
  "longitude": "72.99072061230503"
},
```

```
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-05-24"
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Airoli",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
```

```
"value": "2",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "42-43\t",
  "label": true
},
"buildingName": {
```

```
"status": true,
"name": "Building Name",
"key": "buildingName",
"value": "Bhumiraj Meadows\t",
"label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "19",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "E\t",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
```

```
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "204t",
  "label": false
},
"municipalityWardNo": {
  "status": false,
```



```
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
}
```

```
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "VerifiedTileFlooring"
  },
  "doors": {
    "label": "Teak Wood Door frame with Solid flush door",
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door"
  },
  "windows": {
    "label": "Aluminium Open Windows",
    "value": "Aluminium_Open_Windows"
  },
  "fittings": {
    "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring",
    "value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring"
  },
  "finishing": {
    "label": "Normal",
    "value": "Normal"
  }
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
```

```
"label": "Navi Mumbai Municipal Corporation",
"value": "NMMC"
},
"asPerActualAgreement": {
  "north": "RENBOW",
  "south": "SWASTIC VRUNDAVAN",
  "east": "ROAD",
  "west": "MHALSA"
},
"asPerDocumentAgreement": {
  "north": "",
  "west": "",
  "south": "",
  "east": ""
}
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Tenant Occupied",
    "value": "Tenant_Occupied"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  },
  "pavementLaid": {
    "label": "Yes",
    "value": "Yes"
  },
  "carParking": {
    "label": "Open Car Parking",
```

```
"value": "Open_Car_Parking"
},
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2005",
  "fullDate": "1/1/2005"
},
"propertyTypeList": {
  "value": "Residential",
  "label": "Residential"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"qualityOfConstruction": {
  "label": "Excellent",
  "value": "Excellent"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"maintenanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Stilt",
```

```
"value": "stilt"
},
"isSiteVisitAllowed": true,
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"flatFloorNo": "",
"noOfLiftsInEachWings": "0",
"totalLifeBuilding": "60",
"ageOfBuilding": "18",
"estimatedAge": "42",
"noOfFloors": "07",
"noOfDwellingUnitsInBuilding": "04",
"noOfLifts": "01"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
},
```

```
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
```

```
    "label": "External Development & Final Finishing",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": false
  },
  "workCompleted": {
    "label": "Work Completed (%)",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
},
```



```
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
```

```
"COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": "LEAD",
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"_id": "646b0ed8b05e530fb6c2d070",
"ownerName": "Asif Kasamali Shaikh\t",
"ownerPhoneNo": "0000000000",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "0000000000",
"contactPersonName": "Asif Kasamali Shaikh\t",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Asif Kasamali Shaikh\t",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "116459"
  }
],
"caseReferredBy": "5ffe92d27737ca4d986b6453",
"relationWithOwner": "self",
"fullAddress": "Residential Flat No. 204\t, 2nd Floor, Wing - E\t, Bhumiraj Meadows\t,
Plot No. 42-43\t, Sector 19, Village - Airoli, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "02/06/2015",
      "from": {
        "value": "Developers",
        "label": "Developers"
      }
    },
    "Developers": "Bhumiraj Construction",
```

```
"to": {
  "value": "purchaser",
  "label": "purchaser"
},
"purchaser": "Asif Kasamali Shaikh"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1684737711133_E204BhumirajDeed_of_Assignment_and_Conveyance.pdf",
"path": "cases/646b0ed8b05e530fb6c2d070/document_1684737711133_E204BhumirajDeed_of_Assignment_and_Conveyance.pdf",
"id": "571708",
"uploadedBy": "6006d4ce5080a310ac1fdcf2",
"createdAt": "Mon May 22 2023 12:12:22 GMT+0530 (India Standard Time)"
}
],
"isUrgent": "false",
"isExternal": "false",
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "001668",
"createdBy": "6006d4ce5080a310ac1fdcf2",
"caseHistory": [
  {
    "id": "227117",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Mon May 22 2023 12:12:32 GMT+0530 (India Standard Time)"
  }
],
"siteInspection": [
  {
    "areaType": {
      "label": "Saleable",
      "value": "Saleable"
    },
    "providedBy": {
      "label": "Tenants",
      "value": "Tenants"
    },
    "_id": "646d7f0eb05e530fb6c41c04",
    "area": "0",
    "providedByName": "AFIM SHAIKH",
    "providedByContactNo": "9004952191"
  }
],
```

```
"composition": [  
  {  
    "measurementType": {  
      "label": "Square Feet",  
      "value": "Square_Feet"  
    },  
    "id": "491626",  
    "name": "Living Room",  
    "length": "9.17",  
    "length1": "9",  
    "length2": "2",  
    "width": "17.42",  
    "width1": "17",  
    "width2": "5",  
    "totalArea": "159.65",  
    "images": [],  
    "extraAreas": [],  
    "finalArea": "159.65"  
  },  
  {  
    "measurementType": {  
      "label": "Square Feet",  
      "value": "Square_Feet"  
    },  
    "id": "1",  
    "name": "Passage",  
    "length": "8.25",  
    "length1": "8",  
    "length2": "3",  
    "width": "2.92",  
    "width1": "2",  
    "width2": "11",  
    "totalArea": "24.06",  
    "images": [],  
    "extraAreas": [],  
    "finalArea": "24.06"  
  },  
  {  
    "measurementType": {  
      "label": "Square Feet",  
      "value": "Square_Feet"  
    },  
    "id": "2",  
    "name": "Living Room",  
    "length": "11.17",  
    "length1": "11",
```

```
"length2": "2",
"width": "7.00",
"width1": "7",
"width2": "00",
"totalArea": "78.17",
"images": [],
"extraAreas": [],
"finalArea": "78.17"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "W.C",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "12.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Bathroom",
  "length": "5.00",
  "length1": "5",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "20.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "20.00"
},
{
```

```
"measurementType": {
  "label": "Square Feet",
  "value": "Square_Feet"
},
"id": "5",
"name": "Bedroom",
"length": "8.92",
"length1": "8",
"length2": "11",
"width": "11.58",
"width1": "11",
"width2": "7",
"totalArea": "103.28",
"images": [],
"extraAreas": [],
"finalArea": "103.28"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646d7d5bb05e530fb6c41b3b",
    "name": "externalImg_1684897111723_1684896888879_image_0.jpeg",
    "path": "cases/646b0ed8b05e530fb6c2d070/
externalImg_1684897111723_1684896888879_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646d7d5bb05e530fb6c41b3c",
    "name": "externalImg_1684897112146_1684896888879_image_1.jpeg",
    "path": "cases/646b0ed8b05e530fb6c2d070/
externalImg_1684897112146_1684896888879_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646d7d5bb05e530fb6c41b3d",
```

```
    "name": "externallmg_1684897112321_1684896888879_image_2.jpeg",
    "path": "cases/646b0ed8b05e530fb6c2d070/
externallmg_1684897112321_1684896888879_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646d7d5bb05e530fb6c41b3e",
    "name": "externallmg_1684897112556_1684896888879_image_3.jpeg",
    "path": "cases/646b0ed8b05e530fb6c2d070/
externallmg_1684897112556_1684896888879_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646d7d5bb05e530fb6c41b3f",
    "name": "externallmg_1684897112576_1684896888879_image_4.jpeg",
    "path": "cases/646b0ed8b05e530fb6c2d070/
externallmg_1684897112576_1684896888879_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646d7d5bb05e530fb6c41b40",
    "name": "externallmg_1684897112586_1684896888879_image_5.jpeg",
    "path": "cases/646b0ed8b05e530fb6c2d070/
externallmg_1684897112586_1684896888879_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646d7d5bb05e530fb6c41b41",
    "name": "externallmg_1684897112621_1684896888879_image_6.jpeg",
    "path": "cases/646b0ed8b05e530fb6c2d070/
externallmg_1684897112621_1684896888879_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646d7d5bb05e530fb6c41b42",
    "name": "externallmg_1684897112656_1684896888879_image_7.jpeg",
```



```
    "path": "cases/646b0ed8b05e530fb6c2d070/
externallmg_1684897112656_1684896888879_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646d7d5bb05e530fb6c41b43",
    "name": "externallmg_1684897112691_1684896888879_image_8.jpeg",
    "path": "cases/646b0ed8b05e530fb6c2d070/
externallmg_1684897112691_1684896888879_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646d7d5bb05e530fb6c41b44",
    "name": "externallmg_1684897112721_1684896888879_image_9.jpeg",
    "path": "cases/646b0ed8b05e530fb6c2d070/
externallmg_1684897112721_1684896888879_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646d7d5bb05e530fb6c41b45",
    "name": "externallmg_1684897112751_1684896888879_image_10.jpeg",
    "path": "cases/646b0ed8b05e530fb6c2d070/
externallmg_1684897112751_1684896888879_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646d7d5bb05e530fb6c41b46",
    "name": "externallmg_1684897112761_1684896888879_image_11.jpeg",
    "path": "cases/646b0ed8b05e530fb6c2d070/
externallmg_1684897112761_1684896888879_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "646d7d5bb05e530fb6c41b47",
    "name": "externallmg_1684897112781_1684896888879_image_12.jpeg",
    "path": "cases/646b0ed8b05e530fb6c2d070/
externallmg_1684897112781_1684896888879_image_12.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "646d7d5bb05e530fb6c41b48",
  "name": "externallmg_1684897112806_1684896888879_image_13.jpeg",
  "path": "cases/646b0ed8b05e530fb6c2d070/
externallmg_1684897112806_1684896888879_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "646d7d5bb05e530fb6c41b49",
  "name": "externallmg_1684897112841_1684896888879_image_14.jpeg",
  "path": "cases/646b0ed8b05e530fb6c2d070/
externallmg_1684897112841_1684896888879_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "646d7d5bb05e530fb6c41b4a",
  "name": "externallmg_1684897112851_1684896888879_image_15.jpeg",
  "path": "cases/646b0ed8b05e530fb6c2d070/
externallmg_1684897112851_1684896888879_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "646d7d5bb05e530fb6c41b4b",
  "name": "externallmg_1684897112891_1684896888879_image_16.jpeg",
  "path": "cases/646b0ed8b05e530fb6c2d070/
externallmg_1684897112891_1684896888879_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "646d7d5bb05e530fb6c41b4c",
  "name": "externallmg_1684897112916_1684896888879_image_17.jpeg",
  "path": "cases/646b0ed8b05e530fb6c2d070/
externallmg_1684897112916_1684896888879_image_17.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "646d7d5bb05e530fb6c41b4d",
      "name": "externallmg_1684897084602_1684896865600_image_0.jpeg",
      "path": "cases/646b0ed8b05e530fb6c2d070/externallmg_1684897084602_1684896865600_image_0.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "646d7d5bb05e530fb6c41b4e",
      "name": "externallmg_1684897084657_1684896865600_image_1.jpeg",
      "path": "cases/646b0ed8b05e530fb6c2d070/externallmg_1684897084657_1684896865600_image_1.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "646d7d5bb05e530fb6c41b4f",
      "name": "externallmg_1684897085116_1684896865600_image_2.jpeg",
      "path": "cases/646b0ed8b05e530fb6c2d070/externallmg_1684897085116_1684896865600_image_2.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "646d7d5bb05e530fb6c41b50",
      "name": "externallmg_1684897085331_1684896865600_image_3.jpeg",
      "path": "cases/646b0ed8b05e530fb6c2d070/externallmg_1684897085331_1684896865600_image_3.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "646d7d5bb05e530fb6c41b51",
      "name": "externallmg_1684897085711_1684896865600_image_4.jpeg",
      "path": "cases/646b0ed8b05e530fb6c2d070/externallmg_1684897085711_1684896865600_image_4.jpeg",
      "orientation": "portrait"
    },
  ],
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "646d7d5bb05e530fb6c41b52",
  "name": "externallmg_1684897085721_1684896865600_image_5.jpeg",
  "path": "cases/646b0ed8b05e530fb6c2d070/
externallmg_1684897085721_1684896865600_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "646d7d5bb05e530fb6c41b53",
  "name": "externallmg_1684897085761_1684896865600_image_6.jpeg",
  "path": "cases/646b0ed8b05e530fb6c2d070/
externallmg_1684897085761_1684896865600_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "646d7d5bb05e530fb6c41b54",
  "name": "externallmg_1684897085786_1684896865600_image_7.jpeg",
  "path": "cases/646b0ed8b05e530fb6c2d070/
externallmg_1684897085786_1684896865600_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "646d7d5bb05e530fb6c41b55",
  "name": "externallmg_1684897085831_1684896865600_image_8.jpeg",
  "path": "cases/646b0ed8b05e530fb6c2d070/
externallmg_1684897085831_1684896865600_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "646d7d5bb05e530fb6c41b56",
  "name": "externallmg_1684897085871_1684896865600_image_9.jpeg",
  "path": "cases/646b0ed8b05e530fb6c2d070/
externallmg_1684897085871_1684896865600_image_9.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "646d7d5bb05e530fb6c41b57",
    "name": "externallmg_1684897085926_1684896865600_image_10.jpeg",
    "path": "cases/646b0ed8b05e530fb6c2d070/
externallmg_1684897085926_1684896865600_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "646d7d5bb05e530fb6c41b58",
    "name": "externallmg_1684897085966_1684896865600_image_11.jpeg",
    "path": "cases/646b0ed8b05e530fb6c2d070/
externallmg_1684897085966_1684896865600_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "646d7d5bb05e530fb6c41b59",
    "name": "externallmg_1684897085996_1684896865600_image_12.jpeg",
    "path": "cases/646b0ed8b05e530fb6c2d070/
externallmg_1684897085996_1684896865600_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "646d7d5bb05e530fb6c41b5a",
    "name": "externallmg_1684897086031_1684896865600_image_13.jpeg",
    "path": "cases/646b0ed8b05e530fb6c2d070/
externallmg_1684897086031_1684896865600_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "646d7d5bb05e530fb6c41b5b",
    "name": "externallmg_1684897086041_1684896865600_image_14.jpeg",
    "path": "cases/646b0ed8b05e530fb6c2d070/
externallmg_1684897086041_1684896865600_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
    "status": false,
    "_id": "646d7d5bb05e530fb6c41b5c",
    "name": "externalimg_1684897086121_1684896865600_image_15.jpeg",
    "path": "cases/646b0ed8b05e530fb6c2d070/
externalimg_1684897086121_1684896865600_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "646d7d5bb05e530fb6c41b5d",
    "name": "externalimg_1684897086151_1684896865600_image_16.jpeg",
    "path": "cases/646b0ed8b05e530fb6c2d070/
externalimg_1684897086151_1684896865600_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "646d7d5bb05e530fb6c41b5e",
    "name": "externalimg_1684897086161_1684896865600_image_17.jpeg",
    "path": "cases/646b0ed8b05e530fb6c2d070/
externalimg_1684897086161_1684896865600_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "646d7d5bb05e530fb6c41b5f",
    "name": "externalimg_1684897086171_1684896865600_image_18.jpeg",
    "path": "cases/646b0ed8b05e530fb6c2d070/
externalimg_1684897086171_1684896865600_image_18.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-05-22T06:42:32.455Z",
"updatedAt": "2023-05-24T03:06:36.765Z",
"__v": 0,
"updatedBy": "60f9343b45132d6a6bdd96e8",
"briefDescOfProperty": "1 Bedroom + 2 Living Room + Passage + W.C + Bathroom",
"carpetTotal": "397.15999999999997",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0"
}
```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	9'2"	17'5"	159.65
Passage	8'3"	2'11"	24.06
Living Room	11'2"	7'00"	78.17
W.C	3'00"	4'00"	12.00
Bathroom	5'00"	4'00"	20.00
Bedroom	8'11"	11'7"	103.28
Other Composition :			