

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b80a"
    },
    "type": "CREDITOFFICER",
    "_id": "6417f02396b58848585ed0c0",
    "firstName": "Anmol Tiwari",
    "lastName": "Tiwari",
    "mobileNo": "",
    "workMobileNo": "7977031040",
    "email": ""
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "9000000",
    "discussWithPerson": "Anmol Tiwari",
    "expectedFees": 4500,
    "quotedAmount": "2500"
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
    "city": "Mumbai"
  }
}
```

```
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b80a",
  "branchCode": "000088",
  "type": "BRANCH",
  "name": "RACPC - Chinchpokli ",
  "email": "sbi.17889@sbi.co.in",
  "mobileNo": "022-23707514",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, Mumbai South Voltas
House, 'A', 1st Floor, Dr. Ambedkar Road, Chinchpokli (East), Mumbai - 400 033, State
- Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - CHINCHPOKALI",
  "fax": "022-23707512 / 13",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af3d172ffdf65bcd6585cd",
    "role": "PICKUPPERSON",
    "firstName": "Sachin",
    "email": "sachin.joshi@vastukala.org",
    "lastName": "Joshi",
    "mobileNo": "9167204063",
```

```
    "shortName": "SJ",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af3d172ffdf65bcd6585cd\
\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "60f9343b45132d6a6bdd96e8",
    "role": "SITEENGINEER",
    "firstName": "RAJESH",
    "email": "rajeshb.ghadi@gmail.com",
    "lastName": "GHADI",
    "mobileNo": "8652092666",
    "designation": "",
    "shortName": "RHG",
    "workWithDocumentMaker": ""
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60092304a16fab0f2af9b0c2",
    "role": "MAKER+CHECKER",
    "firstName": "Nitesh",
    "email": "nitesh.khedekar@vastukala.org",
    "lastName": "Khedekar",
    "mobileNo": "8369040652",
    "designation": "",
    "shortName": "NK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "60092304a16fab0f2af9b0c2",
    "role": "MAKER+CHECKER",
    "firstName": "Nitesh",
    "email": "nitesh.khedekar@vastukala.org",
    "lastName": "Khedekar",
    "mobileNo": "8369040652",
    "designation": "",
    "shortName": "NK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
  },
  "checker": {
```

```
"type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
  "mobileNo": "9769797568",
  "designation": "",
  "shortName": "P",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    }
  }
]
```

```
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.02554492630476",
  "longitude": "73.08912403743501"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.08912403743501,
    19.02554492630476
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-05-31"
    }
  ]
}
```

```
    }
  ],
  "schedule": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Mon May 29 2023 12:09:35 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kamothe",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "4",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": ""
  }
}
```

```
"label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "56",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shree Shankar Heights",
  "label": false
},
"selectArea": {
  "status": true,
```

```
"name": "Sector",
"key": "selectArea",
"value": "36",
"label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
}
```



```
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "402",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
```

```
"key": "khataNo",
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
}
```

```
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "VerifiedTileFlooring"
  },
  "doors": {
    "label": "Teak Wood Door frame with Solid flush door",
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door"
  },
  "windows": {
    "label": "Aluminium Sliding Window ",
    "value": "Aluminium_Sliding_Window_"
  },
  "fittings": {
    "label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring",
    "value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring"
  },
  "finishing": {
    "label": "Cement Plastering with POP Finished",
    "value": "Cement_Plastering_with_POP_Finished"
  }
},
"general": {
  "populationClassList": {
    "label": "Upper Class",
    "value": "UpperClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Panvel Municipal Corporation",
    "value": "Panvel_Municipal_Corporation"
  },
  "asPerActualAgreement": {
    "north": "Open",
    "south": "Open",
    "east": "Roaf",
    "west": "Crick"
  }
},
```

```
"asPerDocumentAgreement": {
  "north": "",
  "west": "",
  "south": "",
  "east": ""
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "I Class",
    "value": "I_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Seller Occupied",
    "value": "Seller_Occupied"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MuncipalWaterSupply"
  },
  "pavementLaid": {
    "label": "Yes",
    "value": "Yes"
  },
  "carParking": {
    "label": "Open Parking",
    "value": "Open_Parking"
  },
  "constructionWorkStatus": {
    "label": "Completed",
    "value": "Completed"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
```

```
"year": "2013",
"fullDate": "1/1/2013"
},
"propertyTypeList": {
  "value": "Residential",
  "label": "Residential"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"qualityOfConstruction": {
  "label": "Good",
  "value": "Good"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"maintenanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Stilt",
  "value": "stilt"
},
"isSiteVisitAllowed": true,
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"flatFloorNo": "",
"noOfLiftsInEachWings": "0",
"noOfFloors": "013",
```

```
"noOfDwellingUnitsInBuilding": "07",
"noOfLifts": "02",
"totalLifeBuilding": "60",
"ageOfBuilding": "10",
"estimatedAge": "50"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
```



```
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
```

```
"title": "Showcases",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
```

```
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"_id": "64743e9eb05e530fb6c7a85b",
"ownerName": "Vijay Murlidhar Jadhav",
"ownerPhoneNo": "9797074211",
"appAddress": "Flat no 402.4floor,Shree Shankar Heights CHS,Plot no 56 Sector
36,Kamothe ",
"remark": "Vijay jadhav 9797074211\nApprox value Nitesh ",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/64743e9eb05e530fb6c7a85b/
document_1685339769862_DocScanner_24May2023_554_pm.pdf",
    "fileName": "document_1685339769862_DocScanner_24May2023_554_pm.pdf",
    "displayStatus": false,
    "id": "426078",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Mon May 29 2023 11:26:35 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "001759",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "104975",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon May 29 2023 11:26:46 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Vijay Murlidhar Jadhav",
    "phone": "9797074211",
    "ownershipShare": "",
    "email": "",
    "id": "893575"
  }
],
```

```
"siteInspection": [
  {
    "areaType": {
      "label": "Saleable",
      "value": "Saleable"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    },
    "_id": "6476ad4cb05e530fb6c8d9d1",
    "area": "0",
    "providedByName": "Vijay Murlidhar Jadhav",
    "providedByContactNo": "9797074211"
  }
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "691654",
    "name": "Bedroom",
    "length": "12.00",
    "length1": "12",
    "length2": "00",
    "width": "10.33",
    "width1": "10",
    "width2": "4",
    "totalArea": "124.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "124.00"
  },
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "1",
    "name": "Living Room",
    "length": "9.83",
    "length1": "9",
    "length2": "10",
    "width": "17.33",
```

```
"width1": "17",
"width2": "4",
"totalArea": "170.44",
"images": [],
"extraAreas": [],
"finalArea": "170.44"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "3.83",
  "length1": "3",
  "length2": "10",
  "width": "14.00",
  "width1": "14",
  "width2": "00",
  "totalArea": "53.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "53.67"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "4.83",
  "length1": "4",
  "length2": "10",
  "width": "5.42",
  "width1": "5",
  "width2": "5",
  "totalArea": "26.18",
  "images": [],
  "extraAreas": [],
  "finalArea": "26.18"
},
{
  "measurementType": {
    "label": "Square Feet",
```

```
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Kitchen",
  "length": "9.75",
  "length1": "9",
  "length2": "9",
  "width": "9.92",
  "width1": "9",
  "width2": "11",
  "totalArea": "96.69",
  "images": [],
  "extraAreas": [],
  "finalArea": "96.69"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "6.83",
  "length1": "6",
  "length2": "10",
  "width": "3.83",
  "width1": "3",
  "width2": "10",
  "totalArea": "26.19",
  "images": [],
  "extraAreas": [],
  "finalArea": "26.19"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "12.00",
  "length1": "12",
  "length2": "00",
  "width": "10.42",
  "width1": "10",
  "width2": "5",
```

```
"totalArea": "125.00",
"images": [],
"extraAreas": [],
"finalArea": "125.00"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "7",
  "name": "Toilet",
  "length": "6.83",
  "length1": "6",
  "length2": "10",
  "width": "3.83",
  "width1": "3",
  "width2": "10",
  "totalArea": "26.19",
  "images": [],
  "extraAreas": [],
  "finalArea": "26.19"
}
],
"otherComposition": [
  {
    "name": {
      "label": "Flower Bed Area",
      "value": "Flower_Bed_Area"
    },
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "0",
    "length1": "10",
    "length2": "00",
    "length": "10.00",
    "width1": "2",
    "width2": "00",
    "width": "2.00",
    "totalArea": "20.00",
    "percentageBeforeTotal": "20.00",
    "images": [],
    "extraAreas": [],
    "percentage": "100",
```



```
"finalArea": "20"
},
{
  "name": {
    "label": "Flowerbed",
    "value": "Flowerbed"
  },
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "length1": "3",
  "length2": "00",
  "length": "3.00",
  "width1": "4",
  "width2": "00",
  "width": "4.00",
  "totalArea": "12.00",
  "percentageBeforeTotal": "12.00",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "12"
},
{
  "name": {
    "label": "Flowerbed",
    "value": "Flowerbed"
  },
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "length1": "2",
  "length2": "00",
  "length": "2.00",
  "width1": "10",
  "width2": "00",
  "width": "10.00",
  "totalArea": "20.00",
  "percentageBeforeTotal": "20.00",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
```

```
"finalArea": "20"
},
{
  "name": {
    "label": "Flowerbed",
    "value": "Flowerbed"
  },
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "length1": "2",
  "length2": "00",
  "length": "2.00",
  "width1": "6",
  "width2": "00",
  "width": "6.00",
  "totalArea": "12.00",
  "percentageBeforeTotal": "12.00",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "12"
},
{
  "name": {
    "label": "Terrace",
    "value": "Terrace"
  },
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "length1": "4",
  "length2": "5",
  "length": "4.42",
  "width1": "10",
  "width2": "00",
  "width": "10.00",
  "totalArea": "44.17",
  "percentageBeforeTotal": "44.17",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
```

```
    "finalArea": "44.17"
  }
],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6476ab24b05e530fb6c8d8e1",
    "name": "externallmg_1685498656293_1685498443111_image_0.jpeg",
    "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498656293_1685498443111_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6476ab24b05e530fb6c8d8e2",
    "name": "externallmg_1685498656496_1685498443111_image_1.jpeg",
    "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498656496_1685498443111_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6476ab24b05e530fb6c8d8e3",
    "name": "externallmg_1685498656516_1685498443111_image_2.jpeg",
    "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498656516_1685498443111_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6476ab24b05e530fb6c8d8e4",
    "name": "externallmg_1685498656846_1685498443111_image_3.jpeg",
    "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498656846_1685498443111_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6476ab24b05e530fb6c8d8e5",
    "name": "externallmg_1685498656867_1685498443111_image_4.jpeg",
    "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498656867_1685498443111_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6476ab24b05e530fb6c8d8e6",
    "name": "externallmg_1685498656896_1685498443111_image_5.jpeg",
    "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498656896_1685498443111_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6476ab24b05e530fb6c8d8e7",
    "name": "externallmg_1685498656926_1685498443111_image_6.jpeg",
    "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498656926_1685498443111_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6476ab24b05e530fb6c8d8e8",
    "name": "externallmg_1685498656951_1685498443111_image_7.jpeg",
    "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498656951_1685498443111_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6476ab24b05e530fb6c8d8e9",
    "name": "externallmg_1685498656966_1685498443111_image_8.jpeg",
    "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498656966_1685498443111_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "6476ab24b05e530fb6c8d8ea",
    "name": "externallmg_1685498656996_1685498443111_image_9.jpeg",
    "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498656996_1685498443111_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6476ab24b05e530fb6c8d8eb",
    "name": "externallmg_1685498657006_1685498443111_image_10.jpeg",
    "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498657006_1685498443111_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6476ab24b05e530fb6c8d8ec",
    "name": "externallmg_1685498657031_1685498443111_image_11.jpeg",
    "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498657031_1685498443111_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6476ab24b05e530fb6c8d8ed",
    "name": "externallmg_1685498657066_1685498443111_image_12.jpeg",
    "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498657066_1685498443111_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6476ab24b05e530fb6c8d8ee",
    "name": "externallmg_1685498657106_1685498443111_image_13.jpeg",
    "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498657106_1685498443111_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6476ab24b05e530fb6c8d8ef",
```

```
    "name": "externallmg_1685498658387_1685498443111_image_14.jpeg",
    "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498658387_1685498443111_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6476ab24b05e530fb6c8d8f0",
    "name": "externallmg_1685498658388_1685498443111_image_15.jpeg",
    "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498658388_1685498443111_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6476ab24b05e530fb6c8d8f1",
    "name": "externallmg_1685498658391_1685498443111_image_16.jpeg",
    "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498658391_1685498443111_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6476ab24b05e530fb6c8d8f2",
    "name": "externallmg_1685498658392_1685498443111_image_17.jpeg",
    "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498658392_1685498443111_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6476ab24b05e530fb6c8d8f3",
    "name": "externallmg_1685498658401_1685498443111_image_18.jpeg",
    "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498658401_1685498443111_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6476ab24b05e530fb6c8d8f4",
    "name": "externallmg_1685498658402_1685498443111_image_19.jpeg",
```

```
    "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498658402_1685498443111_image_19.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6476ab24b05e530fb6c8d8f5",
    "name": "externallmg_1685498624985_1685498404873_image_0.jpeg",
    "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498624985_1685498404873_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6476ab24b05e530fb6c8d8f6",
    "name": "externallmg_1685498625311_1685498404873_image_1.jpeg",
    "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498625311_1685498404873_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6476ab24b05e530fb6c8d8f7",
    "name": "externallmg_1685498625856_1685498404873_image_2.jpeg",
    "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498625856_1685498404873_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6476ab24b05e530fb6c8d8f8",
    "name": "externallmg_1685498625916_1685498404873_image_3.jpeg",
    "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498625916_1685498404873_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6476ab24b05e530fb6c8d8f9",
    "name": "externallmg_1685498625956_1685498404873_image_4.jpeg",
    "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498625956_1685498404873_image_4.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6476ab24b05e530fb6c8d8fa",
  "name": "externallmg_1685498625986_1685498404873_image_5.jpeg",
  "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498625986_1685498404873_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6476ab24b05e530fb6c8d8fb",
  "name": "externallmg_1685498626036_1685498404873_image_6.jpeg",
  "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498626036_1685498404873_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6476ab24b05e530fb6c8d8fc",
  "name": "externallmg_1685498626071_1685498404873_image_7.jpeg",
  "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498626071_1685498404873_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6476ab24b05e530fb6c8d8fd",
  "name": "externallmg_1685498626086_1685498404873_image_8.jpeg",
  "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498626086_1685498404873_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6476ab24b05e530fb6c8d8fe",
  "name": "externallmg_1685498626158_1685498404873_image_9.jpeg",
  "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498626158_1685498404873_image_9.jpeg",
  "orientation": "portrait"
}
```



```
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6476ab24b05e530fb6c8d8ff",
      "name": "externallmg_1685498626181_1685498404873_image_10.jpeg",
      "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498626181_1685498404873_image_10.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6476ab24b05e530fb6c8d900",
      "name": "externallmg_1685498626216_1685498404873_image_11.jpeg",
      "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498626216_1685498404873_image_11.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6476ab24b05e530fb6c8d901",
      "name": "externallmg_1685498626282_1685498404873_image_12.jpeg",
      "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498626282_1685498404873_image_12.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6476ab24b05e530fb6c8d902",
      "name": "externallmg_1685498626326_1685498404873_image_13.jpeg",
      "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498626326_1685498404873_image_13.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6476ab24b05e530fb6c8d903",
      "name": "externallmg_1685498628746_1685498404873_image_14.jpeg",
      "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498628746_1685498404873_image_14.jpeg",
      "orientation": "portrait"
    },
  ],
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6476ab24b05e530fb6c8d904",
  "name": "externallmg_1685498628747_1685498404873_image_15.jpeg",
  "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498628747_1685498404873_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6476ab24b05e530fb6c8d905",
  "name": "externallmg_1685498628748_1685498404873_image_16.jpeg",
  "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498628748_1685498404873_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6476ab24b05e530fb6c8d906",
  "name": "externallmg_1685498628749_1685498404873_image_17.jpeg",
  "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498628749_1685498404873_image_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6476ab24b05e530fb6c8d907",
  "name": "externallmg_1685498628786_1685498404873_image_18.jpeg",
  "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498628786_1685498404873_image_18.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6476ab24b05e530fb6c8d908",
  "name": "externallmg_1685498628792_1685498404873_image_19.jpeg",
  "path": "cases/64743e9eb05e530fb6c7a85b/
externallmg_1685498628792_1685498404873_image_19.jpeg",
  "orientation": "portrait"
}
],
```

```

"externalDocuments": [],
"createdAt": "2023-05-29T05:56:46.697Z",
"updatedAt": "2023-05-31T02:13:58.935Z",
"__v": 0,
"updatedBy": "60f9343b45132d6a6bdd96e8",
"fullAddress": " Flat No. 402, 4th Floor, Shree Shankar Heights, Plot No. 56, Sector 36,
Village - Kamothe, Navi Mumbai, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Vijay Murlidhar Jadhav",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9797074211",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Passage + 2 Toilet",
"carpetTotal": "648.3600000000001",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "108.17"

```

Name	Length	Width	Total
Composition :			
Bedroom	12'00"	10'4"	124.00
Living Room	9'10"	17'4"	170.44
Passage	3'10"	14'00"	53.67
Passage	4'10"	5'5"	26.18
Kitchen	9'9"	9'11"	96.69
Toilet	6'10"	3'10"	26.19
Bedroom	12'00"	10'5"	125.00
Toilet	6'10"	3'10"	26.19
Other Composition :			
Flower Bed Area	10'00"	2'00"	20.00
Flowerbed	3'00"	4'00"	12.00

Flowerbed	2'00"	10'00"	20.00
Flowerbed	2'00"	6'00"	12.00
Terrace	4'5"	10'00"	44.17