

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63b26511191f7b344b008a1d"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b8b",
    "email": "coorddesk.rasmecbhy@sbi.co.in",
    "firstName": "SHASHI RANJAN",
    "mobileNo": "",
    "workMobileNo": "9867369914",
    "lastName": "RANJAN"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "4300000",
    "discussWithPerson": "SHASHI RANJAN",
    "expectedFees": 2150,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
    "city": "Mumbai"
  }
}
```

```
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63b26511191f7b344b008a1d",
  "name": "RASMECC BHAYANDAR",
  "branchCode": "",
  "mobileNo": "022-28149108",
  "alternateMobileNo": "",
  "email": "Coorddesk.rasmecbhy@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "RASMECCC Bhayandar Branch\nUnit No. 101, 102, 103B, 1st Floor, IT
Landmark Building, 150ft. Road, Near Hotel Shree Nidhi, \nOpp. Maxus Mall,
Bhayander (West), Thane – 401 101, \nState – Maharashtra, Country – India."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "627219d6afd7d55eddedd283",
    "role": "PICKUPPERSON",
    "firstName": "Mangesh ",
    "email": "mangeshpalande17@gmail.com",
    "lastName": "Palande",
    "mobileNo": "9833030550",
    "shortName": "MP",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users/627219d6afd7d55eddedd283/
profilePhoto_1668055836118_WhatsApp_Image_20221110_at_101725_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62720a36afd7d55eddedc4a7",
  "role": "SITEENGINEER",
  "firstName": "Anwar",
  "email": "anwar21786@gmail.com",
  "lastName": "Shaikh",
  "mobileNo": "8552884500",
  "designation": "",
  "shortName": "AS",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62720a36afd7d55eddedc4a7/
profilePhoto_1668059819446_anwar_2.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER+CHECKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
  "lastName": "Bodke",
  "mobileNo": "9821740317",
  "designation": "",
  "shortName": "SB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eebe33f3dd69653a5837ae\\
\\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
```

```
"checker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER+CHECKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyam_Photo.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      }
    ]
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  }
],
}
```

```
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.473370",
  "longitude": "72.804000"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.804,
    19.47337
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-05-31T18:30:00.000Z",
```

```
    "remark": ""
  },
  {
    "dateTime": "2023-05-31T18:30:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-05-31T18:30:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-05-31T18:30:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-05-31T18:30:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-05-31T18:30:00.000Z",
    "remark": ""
  }
],
"visitedDate": [
  {
    "remark": "MANUAL",
    "status": "COMPLETED",
    "dateTime": "2023-06-01T04:30:00.000Z"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Wed May 31 2023 14:45:58 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
```

```
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Dongre (Narangi)",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "8",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "2",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Palghar",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Virar (West)",
  "label": false
}
```

```
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Vasai",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Avenue - I",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Naranggi Baypass Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
```



```
"key": "street2",
"value": "",
"label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Global City Complex, Near Yazoo Park",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Rustomjee Evershine Global City Avenue - I, Bldg. No. 1 to 3 Co-op. Hsg.
Soc. Ltd.",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "5, 5B, 5D, 5F & 5G ",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
}
```

```
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "803",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
```

```
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "401 303",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
}
```

```

"windows": {
  "value": "Powder_coated_Aluminum_sliding_windows",
  "label": "Powder coated Aluminum sliding windows"
},
"fittings": {
  "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Vasai_Virar_City_Municipal_Corporation",
    "label": "Vasai Virar City Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Avenue G Road",
    "west": "Open Plot",
    "south": "Under Construction Building",
    "east": "Internal Road & Avenue I Bldg. No. 3 "
  },
  "asPerDocumentAgreement": {
    "north": "Details not available ",
    "west": "Details not available ",
    "south": "Details not available ",
    "east": "Details not available "
  }
}

```

```
    },
    "extraDetailOfProperty": ""
  },
  "compositeRate": {
    "remark": "",
    "depreciationPercentage": "9",
    "depreciationRatioOfBuilding": "",
    "salvageValue": "10",
    "depreciatedCostOfConstruction": "8475",
    "depreciatedBuildingRate": "2275"
  },
  "igrRate": {
    "propertyName": "Residential Flat",
    "rate": "76200",
    "landRate": "18400",
    "igrImage": "cases/647707b0b05e530fb6c95c5c/igr_1685683845332_Image.png",
    "squareMeterGuideLineRate": "80010.00",
    "squareFeetGuideLineRate": "7433.00"
  },
  "igrFinalRate": {
    "rate": "7090.00",
    "squareFeetGuideLineRate": "7090.00",
    "squareMeterGuideLineRate": "76313.00"
  },
  "outgoingDetail": {
    "areaStatusList": {
      "value": "Medium",
      "label": "Medium"
    },
    "propertyTypeOfUseList": {
      "value": "Residential_Purpose",
      "label": "Residential Purpose"
    },
    "propertyOccupiedByList": {
      "value": "Vacant",
      "label": "Vacant"
    },
    "monthlyRent": "10,000",
    "assessmentNo": "Details not available ",
    "taxPaidHolderName": "Details not available ",
    "taxAmount": "Details not available ",
    "electricityServiceConnectionNo": "Consume No. 001524224492",
    "meterCardHolderName": "Rustomjee Evershine Joint Venture",
    "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
    "floorSpaceIndex": "As per VVCMC norms",
    "tenantName": ""
  }
}
```

```
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": {
    "value": "Stilt+_Open_Car_Parking",
    "label": "Stilt + Open Car Parking"
  },
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2017",
    "fullDate": "1/1/2017"
  },
  "planningArea": {
```

```
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C._Framed_Structure",
"label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
"materialUsedList": {
"value": "Good",
"label": "Good"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Good",
"label": "Good"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
}
```

```
},
"maintenanceIssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "6",
"totalLifeBuilding": "60",
"estimatedAge": "54",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "14",
"flatFloorNo": "8",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
  "area": "700.80",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
```



```
    "label": "Railway Station"
  },
  "routeMapImg": "cases/647707b0b05e530fb6c95c5c/
routeMap_1685684651934_Image.png",
  "routeLat": "19.473370",
  "routeLng": "72.804000",
  "stationName": "Virar",
  "routeDistance": "2.6 Km."
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "5c8kck",
    "name": "5c8kck",
    "image": "cases/647707b0b05e530fb6c95c5c/
routeMap_1685684581666_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
```

```
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "4949400.00",
"bookValue": "0",
"finalValue": "4949400.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEM_GENERATED",
  "date": "Fri Jun 02 2023 11:19:09 GMT+0530 (India Standard Time)",
  "number": "046839",
  "dayCount": "1",
  "monthCount": "16",
  "generatedBy": "60eebe33f3dd69653a5837ae"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
```

```
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```

```
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "4968672.00",
  "selectedBuildUpValue": "700.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "647981c4ed3c1271b2cce3cf",
      "name":
"externallmg_1685684675215_WhatsApp_Image_20230601_at_10249_PM.jpeg",
      "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684675215_WhatsApp_Image_20230601_at_10249_PM.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "647981cfed3c1271b2cce412",
      "name":
"externallmg_1685684686845_WhatsApp_Image_20230601_at_10254_PM_3.jpeg",
      "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684686845_WhatsApp_Image_20230601_at_10254_PM_3.jpeg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "647981c4ed3c1271b2cce3d6",
      "name":
"externallmg_1685684675328_WhatsApp_Image_20230601_at_10253_PM_1.jpeg",
      "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684675328_WhatsApp_Image_20230601_at_10253_PM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "647981c4ed3c1271b2cce3d5",
    "name":
"externallmg_1685684675316_WhatsApp_Image_20230601_at_10252_PM.jpeg",
    "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684675316_WhatsApp_Image_20230601_at_10252_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "647981c4ed3c1271b2cce3d1",
    "name":
"externallmg_1685684675255_WhatsApp_Image_20230601_at_10251_PM_1.jpeg",
    "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684675255_WhatsApp_Image_20230601_at_10251_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "647981c4ed3c1271b2cce3d0",
    "name":
"externallmg_1685684675234_WhatsApp_Image_20230601_at_10250_PM.jpeg",
    "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684675234_WhatsApp_Image_20230601_at_10250_PM.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "647981c4ed3c1271b2cce3d4",
    "name":
"externallmg_1685684675298_WhatsApp_Image_20230601_at_10252_PM_2.jpeg",
    "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684675298_WhatsApp_Image_20230601_at_10252_PM_2.jpeg",
    "orientation": "landscape"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "647981cfed3c1271b2cce41d",
```

```
    "name": "Bedroom",
    "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684686916_WhatsApp_Image_20230601_at_10258_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "647981cfed3c1271b2cce41b",
    "name": "Bedroom",
    "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684686901_WhatsApp_Image_20230601_at_10257_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "647981cfed3c1271b2cce415",
    "name": "Kitchen",
    "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684686863_WhatsApp_Image_20230601_at_10255_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "647981cfed3c1271b2cce410",
    "name": "Living Room",
    "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684686822_WhatsApp_Image_20230601_at_10254_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "647981cfed3c1271b2cce416",
    "name": "Living Room",
    "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684686869_WhatsApp_Image_20230601_at_10255_PM.jpeg",
    "orientation": "landscape"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
```

```
"max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
```



```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
```

```
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": true,
  "CHECKER": true,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "584.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"status": true,
"caseStatus": "REPORTGENERATED",
"_id": "647707b0b05e530fb6c95c5c",
"ownerName": "Mr. Avinash Shamrao More & Mrs. Maya Avinash More",
"ownerPhoneNo": "9594279875",
"appAddress": "flat no 803 bldg no 2 avanue I rustumjee global city evershine avanue
i. bldg no 1 to bldg no 3,rustumjee global city complex virar w",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "30/05/2023",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      }
    }
  },

```

```
"Transferor": "Ms. Deepashri Ashok Boga",
"to": {
  "value": "Transferee",
  "label": "Transferee"
},
"Transferee": "Mr. Avinash Shamrao More & Mrs. Maya Avinash More"
},
"isHardCopy": false,
"displayStatus": true,
"id": "650925",
"path": "cases/647707b0b05e530fb6c95c5c/
document_1685524095053_Agreement_.pdf",
"fileName": "document_1685524095053_Agreement_.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "29/07/2017",
    "nameOfApprovingAuthority": {
      "value": "Vasai_Virar_City_Municipal_Corporation",
      "label": "Vasai Virar City Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "VVCMC / TP / OC / VP-0453 / 56 / 2017-18"
},
"isHardCopy": false,
"displayStatus": false,
"path": "cases/647707b0b05e530fb6c95c5c/
document_1685679030760_94288.pdf",
"id": "956702",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Fri Jun 02 2023 09:44:19 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1249aa6d152c1801b2f1",
    "label": "Society Maintenance Bill"
  },
  "inputs": {
    "documentDate": "01/01/2023",
```

```
"number": {
  "value": "No",
  "label": "No"
},
"No": "01737"
},
"isHardCopy": false,
"displayStatus": false,
"path": "cases/647707b0b05e530fb6c95c5c/
document_1685679110552_100732.pdf",
"id": "568038",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Fri Jun 02 2023 09:44:19 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1249aa6d152c1801b2f3",
    "label": "Electricity Bill"
  },
  "inputs": {
    "documentDate": "23/05/2023",
    "to": {
      "value": "Beneficiary",
      "label": "Beneficiary"
    },
    "Beneficiary": "Rustomjee Evershine Joint Venture ",
    "number": {
      "value": "Consumer_No",
      "label": "Consumer No"
    },
    "Consumer_No": "001524224492"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/647707b0b05e530fb6c95c5c/
document_1685679244076_395746.pdf",
  "id": "119156",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Fri Jun 02 2023 09:44:19 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "001777",
"createdBy": "627219d6afd7d55eddedd283",
"caseHistory": [
  {
    "id": "698446",
```

```
"title": "Create Lead",
"description": "Create Lead",
"datetime": "Wed May 31 2023 14:09:12 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
"name": "Mr. Avinash Shamrao More & Mrs. Maya Avinash More",
"phone": "9594279875",
"ownershipShare": "",
"email": "",
"id": "232594"
}
],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "699852",
"name": "Bedroom",
"length": "10.00",
"length1": "10",
"length2": "00",
"width": "10.00",
"width1": "10",
"width2": "00",
"totalArea": "100.00",
"images": [],
"extraAreas": [],
"finalArea": "100.00"
},
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "5",
"name": "Passage",
"length": "",
"length1": "3",
"length2": "2",
"width": "",
"width1": "2",
```

```
"width2": "1",
"totalArea": "6.60",
"images": [],
"finalArea": "25.35",
"extraAreas": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "_id": "64797b36ed3c1271b2ccbf2b",
    "name": "Extra",
    "extraAreaType": "Add",
    "length": "3.00",
    "length1": "3",
    "length2": "0",
    "width": "6.25",
    "width1": "6",
    "width2": "3",
    "totalArea": "18.75"
  }
],
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Toilet",
  "length": "7.42",
  "length1": "7",
  "length2": "5",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "29.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "29.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
}
```

```
"id": "3",
"name": "Bedroom",
"length": "10.00",
"length1": "10",
"length2": "00",
"width": "12.33",
"width1": "12",
"width2": "4",
"totalArea": "123.33",
"images": [],
"extraAreas": [],
"finalArea": "123.33"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Kitchen",
  "length": "10.08",
  "length1": "10",
  "length2": "1",
  "width": "7.00",
  "width1": "7",
  "width2": "0",
  "totalArea": "70.58",
  "images": [],
  "extraAreas": [],
  "finalArea": "70.58"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "7.00",
  "width1": "7",
  "width2": "00",
  "totalArea": "28.00",
  "images": [],
```

```
"extraAreas": [],
"finalArea": "28.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Dining",
  "length": "7.67",
  "length1": "7",
  "length2": "8",
  "width": "5.33",
  "width1": "5",
  "width2": "4",
  "totalArea": "40.89",
  "images": [],
  "extraAreas": [],
  "finalArea": "40.89"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Living Room",
  "length": "10.00",
  "length1": "10",
  "length2": "00",
  "width": "15.00",
  "width1": "15",
  "width2": "00",
  "totalArea": "150.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "150.00"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    }
  },

```



```
"name": {
  "value": "Niche",
  "label": "Niche"
},
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "0",
"length1": "2",
"length2": "00",
"length": "2.00",
"width1": "5",
"width2": "9",
"width": "5.75",
"totalArea": "11.50",
"percentageBeforeTotal": "27.33",
"images": [],
"extraAreas": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "_id": "64796f04ed3c1271b2ccb292",
    "name": "Extra",
    "extraAreaType": "Add",
    "length": "1.58",
    "length1": "1",
    "length2": "7",
    "width": "10.00",
    "width1": "10",
    "width2": "0",
    "totalArea": "15.83"
  }
],
"percentage": "100",
"finalArea": "27.33"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "value": "Dry_balcony",
```

```
    "label": "Dry Balcony"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length1": "2",
  "length2": "6",
  "length": "2.50",
  "width1": "7",
  "width2": "00",
  "width": "7.00",
  "totalArea": "17.50",
  "percentageBeforeTotal": "17.50",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "17.5"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "value": "Flowerbed",
    "label": "Flowerbed"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "length1": "3",
  "length2": "7",
  "length": "3.58",
  "width1": "8",
  "width2": "3",
  "width": "8.25",
  "totalArea": "29.56",
  "percentageBeforeTotal": "29.56",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "29.56"
```

```
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "value": "Cupboard",
    "label": "Cupboard"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "length1": "2",
  "length2": "2",
  "length": "2.17",
  "width1": "6",
  "width2": "00",
  "width": "6.00",
  "totalArea": "13.00",
  "percentageBeforeTotal": "13.00",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "13"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "725561",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "584",
    "squareMeterArea": "54.25",
    "docFinalBuiltUp": "700.8",
    "docFinalBuiltUpSquareMeter": "65.1",
```

```
    "docBuiltpPercentage": "20",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "64797d33ed3c1271b2ccce2b",
    "id": "1",
    "property": "Residential Flat",
    "area": "535",
    "builtUpPercentage": "20",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "",
    "source": "square_yards",
    "expectedPrice": "4800000",
    "expectedRate": "8971.96",
    "builtUpExpectedRate": "7476.64",
    "image": "cases/647707b0b05e530fb6c95c5c/
indicator_1685683506959_Image.png"
  },
  {
    "printlnReport": true,
    "_id": "64797d4eed3c1271b2cccea5",
    "id": "2",
    "property": "Residential Flat",
    "area": "512",
    "builtUpPercentage": "20",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "",
    "source": "square_yards",
    "expectedPrice": "5000000",
    "expectedRate": "9765.63",
    "builtUpExpectedRate": "8138.02",
    "image": "cases/647707b0b05e530fb6c95c5c/
indicator_1685683534208_Image.png"
  },
  {
    "printlnReport": true,
```

```
"_id": "64797d6eed3c1271b2cccecd",
"id": "3",
"property": "Residential Flat",
"area": "584",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "5000000",
"expectedRate": "8561.64",
"builtUpExpectedRate": "7134.70",
"image": "cases/647707b0b05e530fb6c95c5c/
indicator_1685683566070_Image.png"
},
{
  "printlnReport": true,
  "_id": "64797d85ed3c1271b2cccff9",
  "id": "4",
  "property": "Residential Flat",
  "area": "584",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "https://www.99acres.com/",
  "expectedPrice": "6000000",
  "expectedRate": "10273.97",
  "builtUpExpectedRate": "8561.64",
  "image": "cases/647707b0b05e530fb6c95c5c/
indicator_1685683589137_Image.png"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647981c4ed3c1271b2cce3cc",
    "name":
"externalImg_1685684675193_WhatsApp_Image_20230601_at_10246_PM.jpeg",
    "path": "cases/647707b0b05e530fb6c95c5c/
externalImg_1685684675193_WhatsApp_Image_20230601_at_10246_PM.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "647981c4ed3c1271b2cce3cd",
  "name":
"externallmg_1685684675197_WhatsApp_Image_20230601_at_10247_PM.jpeg",
  "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684675197_WhatsApp_Image_20230601_at_10247_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "647981c4ed3c1271b2cce3ce",
  "name":
"externallmg_1685684675206_WhatsApp_Image_20230601_at_10248_PM.jpeg",
  "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684675206_WhatsApp_Image_20230601_at_10248_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "647981c4ed3c1271b2cce3cf",
  "name":
"externallmg_1685684675215_WhatsApp_Image_20230601_at_10249_PM.jpeg",
  "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684675215_WhatsApp_Image_20230601_at_10249_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "647981c4ed3c1271b2cce3d0",
  "name":
"externallmg_1685684675234_WhatsApp_Image_20230601_at_10250_PM.jpeg",
  "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684675234_WhatsApp_Image_20230601_at_10250_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "647981c4ed3c1271b2cce3d1",
  "name":
"externallmg_1685684675255_WhatsApp_Image_20230601_at_10251_PM_1.jpeg",
```

```
    "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684675255_WhatsApp_Image_20230601_at_10251_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647981c4ed3c1271b2cce3d2",
    "name":
"externallmg_1685684675270_WhatsApp_Image_20230601_at_10251_PM.jpeg",
    "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684675270_WhatsApp_Image_20230601_at_10251_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647981c4ed3c1271b2cce3d3",
    "name":
"externallmg_1685684675285_WhatsApp_Image_20230601_at_10252_PM_1.jpeg",
    "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684675285_WhatsApp_Image_20230601_at_10252_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647981c4ed3c1271b2cce3d4",
    "name":
"externallmg_1685684675298_WhatsApp_Image_20230601_at_10252_PM_2.jpeg",
    "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684675298_WhatsApp_Image_20230601_at_10252_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647981c4ed3c1271b2cce3d5",
    "name":
"externallmg_1685684675316_WhatsApp_Image_20230601_at_10252_PM.jpeg",
    "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684675316_WhatsApp_Image_20230601_at_10252_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "647981c4ed3c1271b2cce3d6",
  "name":
"externallmg_1685684675328_WhatsApp_Image_20230601_at_10253_PM_1.jpeg",
  "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684675328_WhatsApp_Image_20230601_at_10253_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "647981c4ed3c1271b2cce3d7",
  "name":
"externallmg_1685684675337_WhatsApp_Image_20230601_at_10253_PM_2.jpeg",
  "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684675337_WhatsApp_Image_20230601_at_10253_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "647981cfed3c1271b2cce40f",
  "name":
"externallmg_1685684686810_WhatsApp_Image_20230601_at_10253_PM.jpeg",
  "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684686810_WhatsApp_Image_20230601_at_10253_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "647981cfed3c1271b2cce410",
  "name":
"externallmg_1685684686822_WhatsApp_Image_20230601_at_10254_PM_1.jpeg",
  "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684686822_WhatsApp_Image_20230601_at_10254_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "647981cfed3c1271b2cce411",
  "name":
"externallmg_1685684686829_WhatsApp_Image_20230601_at_10254_PM_2.jpeg",
  "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684686829_WhatsApp_Image_20230601_at_10254_PM_2.jpeg",
```



```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647981cfed3c1271b2cce412",
    "name":
"externallmg_1685684686845_WhatsApp_Image_20230601_at_10254_PM_3.jpeg",
    "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684686845_WhatsApp_Image_20230601_at_10254_PM_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647981cfed3c1271b2cce413",
    "name":
"externallmg_1685684686849_WhatsApp_Image_20230601_at_10254_PM.jpeg",
    "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684686849_WhatsApp_Image_20230601_at_10254_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647981cfed3c1271b2cce414",
    "name":
"externallmg_1685684686858_WhatsApp_Image_20230601_at_10255_PM_1.jpeg",
    "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684686858_WhatsApp_Image_20230601_at_10255_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647981cfed3c1271b2cce415",
    "name":
"externallmg_1685684686863_WhatsApp_Image_20230601_at_10255_PM_2.jpeg",
    "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684686863_WhatsApp_Image_20230601_at_10255_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647981cfed3c1271b2cce416",
```

```
    "name":
"externallmg_1685684686869_WhatsApp_Image_20230601_at_10255_PM.jpeg",
    "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684686869_WhatsApp_Image_20230601_at_10255_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647981cfed3c1271b2cce417",
    "name":
"externallmg_1685684686874_WhatsApp_Image_20230601_at_10256_PM_1.jpeg",
    "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684686874_WhatsApp_Image_20230601_at_10256_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647981cfed3c1271b2cce418",
    "name":
"externallmg_1685684686883_WhatsApp_Image_20230601_at_10256_PM_2.jpeg",
    "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684686883_WhatsApp_Image_20230601_at_10256_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647981cfed3c1271b2cce419",
    "name":
"externallmg_1685684686888_WhatsApp_Image_20230601_at_10256_PM.jpeg",
    "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684686888_WhatsApp_Image_20230601_at_10256_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647981cfed3c1271b2cce41a",
    "name":
"externallmg_1685684686894_WhatsApp_Image_20230601_at_10257_PM_1.jpeg",
    "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684686894_WhatsApp_Image_20230601_at_10257_PM_1.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "647981cfed3c1271b2cce41b",
  "name":
"externallmg_1685684686901_WhatsApp_Image_20230601_at_10257_PM_2.jpeg",
  "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684686901_WhatsApp_Image_20230601_at_10257_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "647981cfed3c1271b2cce41c",
  "name":
"externallmg_1685684686908_WhatsApp_Image_20230601_at_10257_PM.jpeg",
  "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684686908_WhatsApp_Image_20230601_at_10257_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "647981cfed3c1271b2cce41d",
  "name":
"externallmg_1685684686916_WhatsApp_Image_20230601_at_10258_PM.jpeg",
  "path": "cases/647707b0b05e530fb6c95c5c/
externallmg_1685684686916_WhatsApp_Image_20230601_at_10258_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"createdAt": "2023-05-31T08:39:12.299Z",
"updatedAt": "2023-06-03T04:05:23.135Z",
"__v": 0,
"fullAddress": "Residential Flat No. 803, 8th Floor, Building No 2, Avenue - I,
Rustomjee Evershine Global City Avenue - I, Bldg. No. 1 to 3 Co-op. Hsg. Soc. Ltd.,
Global City Complex, Near Yazoo Park, Narangi Baypass Road, Village - Dongre
(Narangi), Taluka - Vasai, District - Palghar, Virar (West), 401 303, State - Maharashtra,
India",
"updatedBy": "60eeaeddf3dd69653a581316",
"addressForMap": "",
"caseReferredBy": "627219d6afd7d55eddedd283",
"contactPersonName": "Mr. Sanjay ",
"email": "",
"isExternal": "false",
```

```

"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Agent",
"siteVisitContactNo": "8329345260",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Passage + 2 Toilet +
Dining",
"carpetTotal": "417.82",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "87.39",
"builtupPercentage": "10",
"finalBuiltupArea": "720.73",
"finalCarpetArea": "655.21",
"finalSalableArea": "792.80",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "87.39",
"otherCompositionSaleableTotal": "0.00",
"buildingServicesRate": "2500",
"flatRate": "8700",
"landOtherRate": "6200",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 584.00",
"reason": "",
"siteVisitDate": "2023-06-01"

```

Name	Length	Width	Total
Composition :			
Bedroom	10'00"	10'00"	100.00
Passage	3'2"	2'1"	6.60
Toilet	7'5"	4'00"	29.67
Bedroom	10'00"	12'4"	123.33
Kitchen	10'1"	7'0"	70.58

Toilet	4'00"	7'00"	28.00
Dining	7'8"	5'4"	40.89
Living Room	10'00"	15'00"	150.00
Other Composition :			
Niche	2'00"	5'9"	11.50
Dry Balcony	2'6"	7'00"	17.50
Flowerbed	3'7"	8'3"	29.56
Cupboard	2'2"	6'00"	13.00