

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb63"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b9423133e",
    "firstName": "Sailaja singh",
    "email": "0_default_",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-9869383607"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "3000"
  },
  "organization": {
    "_id": "6418456a96b58848585f8cb2",
    "name": "Thane",
    "email": "thane@vastukala.com",
    "phone": "1234567890",
    "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) - 400 601",
```

```
"city": "Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb63",
  "branchCode": "000355",
  "type": "BRANCH",
  "name": "RACPC Kalyan",
  "email": "rasecc.thane@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "Main Branch, 1st Floor, Near LIC Office\nMurbad Road, Kalyan West.
421301.\n\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62720e52afd7d55eddedc887",
    "role": "SITEENGINEER",
    "firstName": "Harshad",
    "email": "harshad@vastukala.org",
    "lastName": "Panchal",
    "mobileNo": "9029575553",
```

```
"shortName": "HP",
"workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62ea09ea4e679b264caf07d7",
  "role": "SITEENGINEER",
  "firstName": "Suraj",
  "email": "suraj@vastukala.org",
  "lastName": "Zore",
  "mobileNo": "8652448654",
  "designation": "",
  "shortName": "SZ",
  "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER+CHECKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "MAKER",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": "",
  "shortName": "PSH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": {
```

```

"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER+CHECKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{

```

```
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.18240806269532",
  "longitude": "72.93888666441791"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-06-02T04:30:00.000Z",
      "remark": ""
    }
  ]
}
```

```
    },
    {
      "dateTime": "2023-06-02T04:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-06-02T04:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-06-02T04:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-06-02T04:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-06-02T04:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-06-02T04:30:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "remark": "MANUAL",
      "status": "COMPLETED",
      "dateTime": "2023-06-03T06:30:00.000Z"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Thu Jun 01 2023 17:54:11 GMT+0530 (India Standard Time)"
},
```

```
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Mulund",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "3",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Mumbai Suburban",
    "label": true
  },
  "city": {
    "status": true,
    "name": "City",
```

```
"key": "city",
"value": "Mulund (West)",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Redwoods",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Off. L.B.S. Marg",
  "label": false
},
}
```



```
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Behind Veena Nagar, Vasant Gardens",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "D",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Redwoods Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
```

```
"value": "",
"label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "29, 32(P), 617 & 618, New C.T.S. No. 29, 29/1 to 19",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "302",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
```

```
"status": false,
"name": "SRO",
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400 080",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "Carpet",
    "label": "Carpet"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door_with_M.S_Safety_door",
```

```
"label": "Teak Wood Door frame with Solid flush door with M.S Safety door"
},
"windows": {
  "value": "Powder_coated_Aluminum_sliding_windows",
  "label": "Powder coated Aluminum sliding windows"
},
"fittings": {
  "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering_+_POP_Finish",
  "label": "Cement Plastering + POP Finish"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Wing - C",
    "west": "Pinewood CHSL",
    "south": "Wing - E",
    "east": "Internal Road"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
```

```
"south": "Details not available",
"east": "Details not available"
},
"extraDetailOfProperty": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "33",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "18076",
  "depreciatedBuildingRate": "1876"
},
"igrRate": {
  "propertyName": "Mulund Village",
  "rate": "151460",
  "landRate": "73360",
  "igrImage": "cases/64788ddced3c1271b2cc8d1e/igr_1685948587729_Image.png",
  "squareMeterGuideLineRate": "151460.00",
  "squareFeetGuideLineRate": "14071.00"
},
"igrFinalRate": {
  "rate": "12475.00",
  "squareFeetGuideLineRate": "12475.00",
  "squareMeterGuideLineRate": "134278.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "32,500",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
```

```
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": {
    "value": "Basement_Parking",
    "label": "Basement Parking"
  },
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2001",
    "fullDate": "1/1/2001"
```

```
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
```

```
"value": "Good",
"label": "Good"
},
"maintenanceIssues": {
"value": "Information_not_available",
"label": "Information not available"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "Information_not_available",
"label": "Information not available"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "ground",
"label": "Ground"
},
"yearOfConstructionAsPer": {
"value": "as_per_occupancy_certificate",
"label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "22",
"totalLifeBuilding": "60",
"estimatedAge": "38",
"noOfBasement": "01",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "3",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
"area": "860.00",
"measurementType": "Sq. Ft.",
"areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
"routeMapDetail": {
```



```
"routeStation": {
  "value": "Railway_Station",
  "label": "Railway Station"
},
"routeMapImg": "cases/64788ddced3c1271b2cc8d1e/
routeMap_1685947506558_Image.png",
"routeLat": "19.182709",
"routeLng": "72.939123",
"stationName": "Mulund",
"routeDistance": "2.8Km"
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": true,
  "finallatLng": true
},
"locationMapImg": [
  {
    "id": "g2xxq",
    "name": "g2xxq",
    "image": "cases/64788ddced3c1271b2cc8d1e/
routeMap_1685947148511_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
```

```
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "15545360.00",
"bookValue": "0",
"finalValue": "15545360.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEM_GENERATED",
  "date": "Mon Jun 05 2023 13:01:55 GMT+0530 (India Standard Time)",
  "number": "046856",
  "dayCount": "5",
  "monthCount": "33",
  "generatedBy": "627222afafd7d55eddeddd82"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "10728500.00",
"selectedBuildUpValue": "860.00",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "647d8e130ab64c23c9fc1583",
"name":
"externalImg_1685949970200_WhatsApp_Image_20230605_at_103327_AM.jpeg",
"path": "cases/64788ddced3c1271b2cc8d1e/
externalImg_1685949970200_WhatsApp_Image_20230605_at_103327_AM.jpeg",
"orientation": "portrait"
}
],
"selfieWithSiteVisitImages": [
{
"status": false,
"_id": "647d8e130ab64c23c9fc1591",
"name":
"externalImg_1685949970904_WhatsApp_Image_20230605_at_103334_AM.jpeg",
"path": "cases/64788ddced3c1271b2cc8d1e/
externalImg_1685949970904_WhatsApp_Image_20230605_at_103334_AM.jpeg",
"orientation": "landscape"
}
],
"externalPhotos": [
{
"status": false,
"_id": "647d8e130ab64c23c9fc1584",
"name":
"externalImg_1685949970289_WhatsApp_Image_20230605_at_103328_AM_1.jpeg",
```

```
    "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949970289_WhatsApp_Image_20230605_at_103328_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "647d8e130ab64c23c9fc1583",
    "name":
"externallmg_1685949970200_WhatsApp_Image_20230605_at_103327_AM.jpeg",
    "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949970200_WhatsApp_Image_20230605_at_103327_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "647d8e130ab64c23c9fc1585",
    "name":
"externallmg_1685949970337_WhatsApp_Image_20230605_at_103328_AM.jpeg",
    "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949970337_WhatsApp_Image_20230605_at_103328_AM.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "647d8e130ab64c23c9fc1580",
    "name":
"externallmg_1685949969980_WhatsApp_Image_20230605_at_103326_AM_1.jpeg",
    "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949969980_WhatsApp_Image_20230605_at_103326_AM_1.jpeg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "647d8e130ab64c23c9fc1588",
    "name": "Living Room",
    "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949970485_WhatsApp_Image_20230605_at_103330_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
```

```
    "_id": "647d8e130ab64c23c9fc1589",
    "name": "Living Room",
    "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949970525_WhatsApp_Image_20230605_at_103330_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "647d8e130ab64c23c9fc1586",
    "name": "Dining",
    "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949970400_WhatsApp_Image_20230605_at_103329_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "647d8e130ab64c23c9fc1590",
    "name": "Bedroom",
    "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949970862_WhatsApp_Image_20230605_at_103333_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "647d8e130ab64c23c9fc158e",
    "name": "Bedroom",
    "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949970760_WhatsApp_Image_20230605_at_103332_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "647d8e130ab64c23c9fc158a",
    "name": "Kitchen",
    "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949970572_WhatsApp_Image_20230605_at_103331_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "647d8e130ab64c23c9fc158b",
    "name": "Passage",
    "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949970611_WhatsApp_Image_20230605_at_103331_AM.jpeg",
    "orientation": "portrait"
  }
}
```

```
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
```



```
"title": "Superfine finish",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": true,
  "CHECKER": true,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "860.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"status": true,
"caseStatus": "REPORTGENERATED",
"_id": "64788ddced3c1271b2cc8d1e",
"ownerName": "Mr. Deepak Arvind Kesaria & Mrs. Bhavisha Deepak Kesaria",
"ownerPhoneNo": "9870195411",
"fullAddress": "Residential Flat No. 302, 3rd Floor, Wing - D, Redwoods, Redwoods Co-
op. Hsg. Soc. Ltd., Behind Veena Nagar, Vasant Gardens, Off. L.B.S. Marg, Village -
Mulund, Taluka - Kurla, District - Mumbai Suburban, Mulund (West), 400 080, State -
Maharashtra, India",
"remark": "",
"documents": [
```

```
{
  "documentType": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "inputs": {
    "documentDate": "22/05/2023",
    "from": {
      "value": "The_Transferor",
      "label": "The Transferor"
    },
    "The_Transferor": "Shri Udho Metharam Godhwani & Smt. Sangeeta Udho
Godhwani",
    "to": {
      "value": "The_Transferee",
      "label": "The Transferee"
    },
    "The_Transferee": "Mr. Deepak Arvind Kesaria & Mrs. Bhavisha Deepak Kesaria"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1685942255879_Agreement_3_1.pdf",
  "path": "cases/64788ddced3c1271b2cc8d1e/
document_1685942255879_Agreement_3_1.pdf",
  "id": "382569",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Mon Jun 05 2023 11:18:54 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "27/09/2001",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CE / 4192 / BPES / AT (No)"
  },
  "isHardCopy": false,

```

```
    "displayStatus": true,
    "id": "705302",
    "path": "cases/64788ddced3c1271b2cc8d1e/
document_1685942444710_262679.pdf"
  },
  {
    "documentType": {
      "value": "60ae1257aa6d152c1801b335",
      "label": "Society Registration Certificate"
    },
    "inputs": {
      "documentDate": "21/11/2001",
      "number": {
        "value": "Registration_No",
        "label": "Registration No"
      },
      "Registration_No": "BOM / HSG / (T. C. ) / 8723 / 2000 - 2001 / 2001"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "path": "cases/64788ddced3c1271b2cc8d1e/
document_1685943614917_274274.pdf",
    "id": "726340",
    "uploadedBy": "627222afafd7d55eddeddd82",
    "createdAt": "Mon Jun 05 2023 11:18:54 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1252aa6d152c1801b31d",
      "label": "Society Letter"
    },
    "inputs": {
      "documentDate": "25/04/2023",
      "nameOfApprovingAuthority": {
        "value": "SOCIETY",
        "label": "SOCIETY"
      }
    }
  },
  "isHardCopy": false,
  "displayStatus": true,
  "path": "cases/64788ddced3c1271b2cc8d1e/
document_1685951776748_167730.pdf",
  "id": "321849",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Mon Jun 05 2023 13:26:23 GMT+0530 (India Standard Time)"
}
```

```
],
"caseNumber": "001797",
"createdBy": "6430f74691d7c62df11f3f15",
"caseHistory": [
  {
    "id": "276357",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Jun 01 2023 17:53:56 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Deepak Arvind Kesaria & Mrs. Bhavisha Deepak Kesaria",
    "phone": "9870195411",
    "ownershipShare": "",
    "email": "",
    "id": "385100"
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "880411",
    "name": "Living Room",
    "length": "18.00",
    "length1": "18",
    "length2": "00",
    "width": "10.00",
    "width1": "10",
    "width2": "00",
    "totalArea": "180.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "180.00"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
```

```
"name": "Dining",
"length": "6.00",
"length1": "6",
"length2": "00",
"width": "8.00",
"width1": "8",
"width2": "00",
"totalArea": "48.00",
"images": [],
"extraAreas": [],
"finalArea": "48.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "7.00",
  "length1": "7",
  "length2": "00",
  "width": "11.00",
  "width1": "11",
  "width2": "00",
  "totalArea": "77.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "77.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "9.00",
  "length1": "9",
  "length2": "00",
  "width": "13.00",
  "width1": "13",
  "width2": "00",
  "totalArea": "117.00",
  "images": [],
  "extraAreas": [],
```

```
"finalArea": "117.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "13.00",
  "length1": "13",
  "length2": "00",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "130.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "130.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "8.00",
  "length1": "8",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "32.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "32.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Toilet",
  "length": "8.00",
```

```
"length1": "8",
"length2": "00",
"width": "4.00",
"width1": "4",
"width2": "0",
"totalArea": "32.00",
"images": [],
"finalArea": "32.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Passage",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "8.00",
  "width1": "8",
  "width2": "00",
  "totalArea": "24.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "24.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Passage",
  "length": "3.00",
  "length1": "3",
  "length2": "0",
  "width": "3.00",
  "width1": "3",
  "width2": "0",
  "totalArea": "9.00",
  "images": [],
  "finalArea": "9.00",
  "extraAreas": []
},
```



```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Balcony Area",
  "length": "3.00",
  "length1": "3",
  "length2": "0",
  "width": "3.00",
  "width1": "3",
  "width2": "0",
  "totalArea": "9.00",
  "images": [],
  "finalArea": "9.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "10",
  "name": "Flowered Area",
  "length": "10.00",
  "length1": "10",
  "length2": "00",
  "width": "2.00",
  "width1": "2",
  "width2": "00",
  "totalArea": "20.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "20.00"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "value": "Cupboard",
      "label": "Cupboard"
    }
  }
]
```

```
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length1": "2",
    "length2": "00",
    "length": "2.00",
    "width1": "3",
    "width2": "00",
    "width": "3.00",
    "totalArea": "6.00",
    "percentageBeforeTotal": "6.00",
    "images": [],
    "extraAreas": [],
    "percentage": "100",
    "finalArea": "6"
  }
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "130165",
    "selectAreaTypeDocument": "Built_Up",
    "totalAreaDocument": "860",
    "squareMeterArea": "79.9",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docBultupPercentage": "",
    "docSaleablePercentage": "10",
    "docFinalSaleable": "946",
    "docFinalSaleableSquareMeter": "87.89"
  }
],
"images": [],
"indicatorArr": [
  {
```

```
"printlnReport": true,
  "_id": "647d87df0ab64c23c9fc01e4",
  "id": "1",
  "property": "Redwoods Apartment, Mulund West",
  "area": "860",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "5",
  "source": "https://www.99acres.com/",
  "expectedPrice": "15500000",
  "expectedRate": "18023.26",
  "builtUpExpectedRate": "15500000",
  "image": "cases/64788ddced3c1271b2cc8d1e/
indicator_1685948383800_Image.png"
},
{
  "printlnReport": true,
  "_id": "647d882b0ab64c23c9fc029e",
  "id": "2",
  "property": "Redwood Apartment, Mulund West",
  "area": "765",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Housing.Com",
  "expectedPrice": "14500000",
  "expectedRate": "18954.25",
  "builtUpExpectedRate": "14500000",
  "image": "cases/64788ddced3c1271b2cc8d1e/
indicator_1685948459488_Image.png"
},
{
  "printlnReport": true,
  "_id": "647d88ee0ab64c23c9fc040f",
  "id": "3",
  "property": "Redwood apartment, Mulund West",
  "area": "855",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "Ground",
```

```
    "source": "https://www.99acres.com/",
    "expectedPrice": "16200000",
    "expectedRate": "18947.37",
    "builtUpExpectedRate": "16200000",
    "image": "cases/64788ddced3c1271b2cc8d1e/
indicator_1685948654295_Image.png"
  },
  {
    "printlnReport": true,
    "_id": "647d897b0ab64c23c9fc052e",
    "id": "4",
    "property": "Redwood Apartment, Mulund",
    "area": "440",
    "builtUpPercentage": "20",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "4",
    "source": "https://www.99acres.com/",
    "expectedPrice": "11000000",
    "expectedRate": "25000.00",
    "builtUpExpectedRate": "20833.33",
    "image": "cases/64788ddced3c1271b2cc8d1e/
indicator_1685948795769_Image.png"
  }
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647d8e130ab64c23c9fc157e",
    "name":
"externallmg_1685949969866_WhatsApp_Image_20230605_at_103325_AM_1.jpeg",
    "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949969866_WhatsApp_Image_20230605_at_103325_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647d8e130ab64c23c9fc157f",
    "name":
"externallmg_1685949969902_WhatsApp_Image_20230605_at_103325_AM.jpeg",
    "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949969902_WhatsApp_Image_20230605_at_103325_AM.jpeg",
    "orientation": "portrait"
  }
]
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "647d8e130ab64c23c9fc1580",
  "name":
"externallmg_1685949969980_WhatsApp_Image_20230605_at_103326_AM_1.jpeg",
  "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949969980_WhatsApp_Image_20230605_at_103326_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "647d8e130ab64c23c9fc1581",
  "name":
"externallmg_1685949970052_WhatsApp_Image_20230605_at_103326_AM.jpeg",
  "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949970052_WhatsApp_Image_20230605_at_103326_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "647d8e130ab64c23c9fc1582",
  "name":
"externallmg_1685949970094_WhatsApp_Image_20230605_at_103327_AM_1.jpeg",
  "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949970094_WhatsApp_Image_20230605_at_103327_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "647d8e130ab64c23c9fc1583",
  "name":
"externallmg_1685949970200_WhatsApp_Image_20230605_at_103327_AM.jpeg",
  "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949970200_WhatsApp_Image_20230605_at_103327_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "647d8e130ab64c23c9fc1584",
  "name":
"externallmg_1685949970289_WhatsApp_Image_20230605_at_103328_AM_1.jpeg",
```

```
    "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949970289_WhatsApp_Image_20230605_at_103328_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647d8e130ab64c23c9fc1585",
    "name":
"externallmg_1685949970337_WhatsApp_Image_20230605_at_103328_AM.jpeg",
    "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949970337_WhatsApp_Image_20230605_at_103328_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647d8e130ab64c23c9fc1586",
    "name":
"externallmg_1685949970400_WhatsApp_Image_20230605_at_103329_AM_1.jpeg",
    "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949970400_WhatsApp_Image_20230605_at_103329_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647d8e130ab64c23c9fc1587",
    "name":
"externallmg_1685949970440_WhatsApp_Image_20230605_at_103329_AM.jpeg",
    "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949970440_WhatsApp_Image_20230605_at_103329_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647d8e130ab64c23c9fc1588",
    "name":
"externallmg_1685949970485_WhatsApp_Image_20230605_at_103330_AM_1.jpeg",
    "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949970485_WhatsApp_Image_20230605_at_103330_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "647d8e130ab64c23c9fc1589",
  "name":
"externallmg_1685949970525_WhatsApp_Image_20230605_at_103330_AM.jpeg",
  "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949970525_WhatsApp_Image_20230605_at_103330_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "647d8e130ab64c23c9fc158a",
  "name":
"externallmg_1685949970572_WhatsApp_Image_20230605_at_103331_AM_1.jpeg",
  "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949970572_WhatsApp_Image_20230605_at_103331_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "647d8e130ab64c23c9fc158b",
  "name":
"externallmg_1685949970611_WhatsApp_Image_20230605_at_103331_AM.jpeg",
  "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949970611_WhatsApp_Image_20230605_at_103331_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "647d8e130ab64c23c9fc158c",
  "name":
"externallmg_1685949970653_WhatsApp_Image_20230605_at_103332_AM_1.jpeg",
  "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949970653_WhatsApp_Image_20230605_at_103332_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "647d8e130ab64c23c9fc158d",
  "name":
"externallmg_1685949970707_WhatsApp_Image_20230605_at_103332_AM_2.jpeg",
  "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949970707_WhatsApp_Image_20230605_at_103332_AM_2.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647d8e130ab64c23c9fc158e",
    "name":
"externallmg_1685949970760_WhatsApp_Image_20230605_at_103332_AM.jpeg",
    "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949970760_WhatsApp_Image_20230605_at_103332_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647d8e130ab64c23c9fc158f",
    "name":
"externallmg_1685949970799_WhatsApp_Image_20230605_at_103333_AM_1.jpeg",
    "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949970799_WhatsApp_Image_20230605_at_103333_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647d8e130ab64c23c9fc1590",
    "name":
"externallmg_1685949970862_WhatsApp_Image_20230605_at_103333_AM.jpeg",
    "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949970862_WhatsApp_Image_20230605_at_103333_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647d8e130ab64c23c9fc1591",
    "name":
"externallmg_1685949970904_WhatsApp_Image_20230605_at_103334_AM.jpeg",
    "path": "cases/64788ddced3c1271b2cc8d1e/
externallmg_1685949970904_WhatsApp_Image_20230605_at_103334_AM.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"createdAt": "2023-06-01T12:23:56.978Z",
"updatedAt": "2023-06-05T10:21:22.765Z",
```



```

    "__v": 0,
    "addressForMap": "",
    "caseReferredBy": "62720e52afd7d55eddedc887",
    "contactPersonName": "Mr. Chandru",
    "email": "",
    "isExternal": "false",
    "isUrgent": "false",
    "ownershipShare": "",
    "purchaseValueAsPerDocument": "",
    "relationWithOwner": "Broker",
    "siteVisitContactNo": "7021211692",
    "updatedBy": "627222afafd7d55eddedd82",
    "briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Dining + 2 Toilet + 2
    Passage + Balcony Area + Flowered Area",
    "carpetTotal": "678",
    "finalMeasurementType": "Sq. Ft.",
    "otherCarpetTotal": "6.00",
    "otherCompositionBuiltUpTotal": "0.00",
    "otherCompositionCarpetTotal": "6.00",
    "otherCompositionSaleableTotal": "0.00",
    "builtupPercentage": "10",
    "finalBuiltupArea": "752.40",
    "finalCarpetArea": "684.00",
    "finalSalableArea": "827.64",
    "salablePercentage": "10",
    "toBeAdded": "",
    "extendOfSiteRemark": "",
    "siteMeasurementRemark": "Carpet Area in Sq. Ft. = 647.00\nCupboard Area in Sq.
    Ft. = 7.00\nBalcony Area in Sq. Ft. = 9.00\nFlowerbed Area in Sq. Ft. = 21.00\nTotal
    Carpet Area in Sq. Ft. = 684.00\n(Area as per Actual site measurement) ",
    "finalAreaType": "Built Up Area",
    "finalAsPerArea": "Agreement for sale",
    "finalBuiltUpPercentage": "10",
    "finalCarpetConvertToBuiltUpPer": "10",
    "finalSaleablePercentage": "10",
    "finalValuationAreaString": "Built Up Area in Sq. Ft. = 860.00",
    "buildingServicesRate": "2800",
    "flatRate": "19000.00",
    "landOtherRate": "16200",
    "reason": "",
    "siteVisitDate": "2023-06-03"
}

```

Name	Length	Width	Total
Composition :			

Living Room	18'00"	10'00"	180.00
Dining	6'00"	8'00"	48.00
Kitchen	7'00"	11'00"	77.00
Bedroom	9'00"	13'00"	117.00
Bedroom	13'00"	10'00"	130.00
Toilet	8'00"	4'00"	32.00
Toilet	8'00"	4'0"	32.00
Passage	3'00"	8'00"	24.00
Passage	3'0"	3'0"	9.00
Balcony Area	3'0"	3'0"	9.00
Flowered Area	10'00"	2'00"	20.00
Other Composition :			
Cupboard	2'00"	3'00"	6.00