

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f9"
    },
    "type": "CREDITOFFICER",
    "_id": "640ace424dda382753e5057d",
    "firstName": "Rajeev kumar Ranjan",
    "lastName": "Ranjan",
    "mobileNo": "",
    "workMobileNo": "9967159553",
    "email": "rajeevracpc.borivali@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "3152500",
    "discussWithPerson": "Rajeev kumar Ranjan",
    "expectedFees": 1576.25,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
    "city": "Mumbai"
  }
}
```

```
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f9",
  "branchCode": "000066",
  "type": "BRANCH",
  "name": "RACPC Borivali (West) Branch",
  "email": "racpc.borivali@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "MTNL Building, Devidas Road, Borivali (West), Mumbai, State - Maharashtra, Country - India. ",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
    "role": "PICKUPPERSON",
    "firstName": "Sunil",
    "email": "misalsunil87@gmail.com",
    "lastName": "Misal",
    "mobileNo": "8422982721",
    "shortName": "SM",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af6ae22ffdf65bcd65861d\
\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc4680ce84bf289ba9c7fc",
  "role": "SITEENGINEER",
  "firstName": "Nikhil ",
  "email": "valtechnical2022@gmail.com",
  "lastName": "Sonawane",
  "mobileNo": "9819470709",
  "designation": "",
  "shortName": "NS",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdfc2",
  "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1681380664371_WhatsApp_Image_20230413_at_33801_PM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER+CHECKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
  "lastName": "Bodke",
  "mobileNo": "9821740317",
  "designation": "",
  "shortName": "SB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
```

```
"checker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER+CHECKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    }
  ],
}
```

```
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.225878",
  "longitude": "73.145410"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.14541,
    19.225878
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-06-02T08:00:00.000Z",
```

```
    "remark": ""
  },
  {
    "dateTime": "2023-06-02T08:00:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-06-02T08:00:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-06-02T08:00:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-06-02T08:00:00.000Z",
    "remark": ""
  }
],
"visitedDate": [
  {
    "remark": "MANUAL",
    "status": "COMPLETED",
    "dateTime": "2023-06-03T10:30:00.000Z"
  },
  {
    "remark": "MANUAL",
    "status": "COMPLETED",
    "dateTime": "2023-06-03T06:00:00.000Z"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Fri Jun 02 2023 13:04:46 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
```

```
"status": true,
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Katemanivali",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "3",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "1",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Kalyan (East)",
```

```
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan ",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "A",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Eknath Heights - 1",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
```



```
"name": "Street 2",
"key": "street2",
"value": "",
"label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Pandurang Nagar",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "123",
  "label": true
},
"hissaNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "3",
  "label": true
}
```

```
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "301",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
```

```
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "421 306",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
}
```

```
"windows": {
  "value": "Powder_coated_Aluminum_sliding_windows",
  "label": "Powder coated Aluminum sliding windows"
},
"fittings": {
  "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering+_POP_Finish",
  "label": "Cement Plastering + POP Finish"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Kalyan_Dombivali_Municipal_Corporation",
    "label": "Kalyan Dombivali Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Road",
    "west": "Under Construction Building ",
    "south": "Building No. 2",
    "east": "Chawls"
  },
  "asPerDocumentAgreement": {
    "north": "15 Mtrs. Road",
    "west": "S. N. 123, H. N. 7 property of Smt. Fulaji Pawashe",
    "south": "9 Mtrs. Road",
    "east": "S. N. 123, H. N. 4/2 property of Shri Bapu Pawashe"
```

```
    },
    "extraDetailOfProperty": "",
  },
  "compositeRate": {
    "remark": "",
    "depreciationPercentage": "",
    "depreciationRatioOfBuilding": "",
    "salvageValue": "",
    "depreciatedCostOfConstruction": "",
    "depreciatedBuildingRate": ""
  },
  "igrRate": {
    "propertyName": "Residential Flat",
    "rate": "46900",
    "landRate": "11600",
    "igrImage": "cases/647995c3ed3c1271b2cd1335/igr_1686025742799_Image.png",
    "squareMeterGuideLineRate": "46900.00",
    "squareFeetGuideLineRate": "4357.00"
  },
  "igrFinalRate": {
    "rate": "46900",
    "squareMeterGuideLineRate": "46900.00",
    "squareFeetGuideLineRate": "4357.00"
  },
  "outgoingDetail": {
    "areaStatusList": {
      "value": "Middle_Class",
      "label": "Middle Class"
    },
    "propertyTypeOfUseList": {
      "value": "Residential_Purpose",
      "label": "Residential Purpose"
    },
    "propertyOccupiedByList": {
      "value": "Vacant",
      "label": "Vacant"
    },
    "monthlyRent": "7,000",
    "assessmentNo": "Details not available",
    "taxPaidHolderName": "Details not available",
    "taxAmount": "Details not available",
    "electricityServiceConnectionNo": "Details not available",
    "meterCardHolderName": "Details not available",
    "undividedAreaOfLandAsPerSaleDeed": "Details not available",
    "floorSpaceIndex": "As per KDMC norms",
    "tenantName": ""
  }
}
```

```
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": {
    "value": "Stilt+_Open_Car_Parking",
    "label": "Stilt + Open Car Parking"
  },
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2022",
    "fullDate": "1/1/2022"
  },
  "planningArea": {
```

```
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C._Framed_Structure",
"label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
"materialUsedList": {
"value": "Good",
"label": "Good"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Good",
"label": "Good"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
}
```

```
},
"maintenanceIssues": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "1",
"totalLifeBuilding": "60",
"estimatedAge": "59",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "8",
"flatFloorNo": "3",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "2"
},
"finalPlinthArea": {
  "area": "438.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
```



```
    "label": "Railway Station"
  },
  "routeMapImg": "cases/647995c3ed3c1271b2cd1335/
routeMap_1685959704698_Image.png",
  "routeLat": "19.225878",
  "routeLng": "73.145410",
  "stationName": "Vithalwadi",
  "routeDistance": "500 Mtr."
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "khlq3b",
    "name": "khlq3b",
    "image": "cases/647995c3ed3c1271b2cd1335/
routeMap_1685959624131_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
```

```
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "3580500.00",
"bookValue": "0",
"finalValue": "3580500.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEM_GENERATED",
  "date": "Tue Jun 06 2023 10:00:00 GMT+0530 (India Standard Time)",
  "number": "046858",
  "dayCount": "2",
  "monthCount": "35",
  "generatedBy": "60eebe33f3dd69653a5837ae"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
```

```
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```

```
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "1908366.00",
  "selectedBuildUpValue": "438.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "647db4360ab64c23c9fc5357",
      "name":
"externallmg_1685959733731_WhatsApp_Image_20230603_at_33056_PM_2.jpeg",
      "path": "cases/647995c3ed3c1271b2cd1335/
externallmg_1685959733731_WhatsApp_Image_20230603_at_33056_PM_2.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "647db4360ab64c23c9fc5362",
      "name":
"externallmg_1685959733833_WhatsApp_Image_20230603_at_33057_PM_7.jpeg",
      "path": "cases/647995c3ed3c1271b2cd1335/
externallmg_1685959733833_WhatsApp_Image_20230603_at_33057_PM_7.jpeg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "647db4360ab64c23c9fc5358",
      "name":
"externallmg_1685959733742_WhatsApp_Image_20230603_at_33056_PM_3.jpeg",
      "path": "cases/647995c3ed3c1271b2cd1335/
externallmg_1685959733742_WhatsApp_Image_20230603_at_33056_PM_3.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "647db4360ab64c23c9fc5356",
    "name":
"externallmg_1685959733667_WhatsApp_Image_20230603_at_33056_PM_1.jpeg",
    "path": "cases/647995c3ed3c1271b2cd1335/
externallmg_1685959733667_WhatsApp_Image_20230603_at_33056_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "647db4360ab64c23c9fc535a",
    "name":
"externallmg_1685959733767_WhatsApp_Image_20230603_at_33056_PM_5.jpeg",
    "path": "cases/647995c3ed3c1271b2cd1335/
externallmg_1685959733767_WhatsApp_Image_20230603_at_33056_PM_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "647db4360ab64c23c9fc5365",
    "name":
"externallmg_1685959733855_WhatsApp_Image_20230603_at_33057_PM.jpeg",
    "path": "cases/647995c3ed3c1271b2cd1335/
externallmg_1685959733855_WhatsApp_Image_20230603_at_33057_PM.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "647db4360ab64c23c9fc5359",
    "name":
"externallmg_1685959733753_WhatsApp_Image_20230603_at_33056_PM_4.jpeg",
    "path": "cases/647995c3ed3c1271b2cd1335/
externallmg_1685959733753_WhatsApp_Image_20230603_at_33056_PM_4.jpeg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "647db4360ab64c23c9fc535c",
```

```
    "name": "Living Room",
    "path": "cases/647995c3ed3c1271b2cd1335/
externallmg_1685959733787_WhatsApp_Image_20230603_at_33057_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "647db4360ab64c23c9fc5360",
    "name": "Bedroom",
    "path": "cases/647995c3ed3c1271b2cd1335/
externallmg_1685959733815_WhatsApp_Image_20230603_at_33057_PM_5.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "647db4360ab64c23c9fc535d",
    "name": "Passage",
    "path": "cases/647995c3ed3c1271b2cd1335/
externallmg_1685959733794_WhatsApp_Image_20230603_at_33057_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "647db4360ab64c23c9fc535e",
    "name": "Kitchen",
    "path": "cases/647995c3ed3c1271b2cd1335/
externallmg_1685959733800_WhatsApp_Image_20230603_at_33057_PM_3.jpeg",
    "orientation": "landscape"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
```



```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": true,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
```

```
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "465.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"status": true,
"caseStatus": "READYFORCHECKER",
"_id": "647995c3ed3c1271b2cd1335",
"ownerName": "Mrs. Sujata Sandeep Jadhav & Mr. Pravin Niranjn Jadhav",
"ownerPhoneNo": "9923572078",
"appAddress": "Flat No.301,3 rd floor,Bldg no.1, Eknath Height -1, Village-
Katemanivali Kalyan ",
"remark": "SSL - Jagat patel ka cesa hey ",
"documents": [
  {
    "documentType": {
      "value": "60ae1254aa6d152c1801b326",
      "label": "Agreement For Sale"
    },
    "inputs": {
      "documentDate": "24/03/2023",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Omkar Enterprises",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Mrs. Sujata Sandeep Jadhav & Mr. Pravin Niranjn Jadhav"
    },
    "isHardCopy": false,
```

```
"displayStatus": true,
"id": "923913",
"path": "cases/647995c3ed3c1271b2cd1335/document_1685689827284_Sujata_Sa
ndeepJadhav_SBI_Racpc_Borivali_SSL__Jagat_patel.pdf",
"fileName": "document_1685689827284_Sujata_SandeepJadhav_SBI_Racpc_Boriv
ali_SSL__Jagat_patel.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "14/06/2021",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Mahanagarpalika",
      "label": "Kalyan Dombivli Mahanagarpalika"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "KDMC / TPD / BP / KD / 2016-17 / 58 / 108"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1685957469285_1_Commencement_Certificates__NA_Or
der_for_plotted_development.pdf",
  "path": "cases/647995c3ed3c1271b2cd1335/document_1685957469285_1_Comme
ncement_Certificates__NA_Order_for_plotted_development.pdf",
  "id": "404414",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Mon Jun 05 2023 15:10:31 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "18/10/2022",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Mahanagarpalika",
      "label": "Kalyan Dombivli Mahanagarpalika"
    },
    "number": {
```

```
    "value": "No",
    "label": "No"
  },
  "No": "KDMC / TPD / CC / KD / 292"
},
"isHardCopy": false,
"displayStatus": false,
"path": "cases/647995c3ed3c1271b2cd1335/document_1685957677699_1_Occupa
ncy_Certificate__Completion_Certificate__Architects_certificate_of_completion_for_plot
ted_development.pdf",
"fileName": "document_1685957677699_1_Occupancy_Certificate__Completion_C
ertificate__Architects_certificate_of_completion_for_plotted_development.pdf",
"id": "509326",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Mon Jun 05 2023 15:10:31 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "14/06/2021",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Mahanagarpalika",
      "label": "Kalyan Dombivli Mahanagarpalika"
    },
    "remark": "Downloaded form RERA site",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "KDMC / TPD / BP / KD / 2016-17 / 58 / 108"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/647995c3ed3c1271b2cd1335/document_1685957776088_2_Building
_Plan_Approval__NA_Order_for_plotted_development.pdf",
  "fileName": "document_1685957776088_2_Building_Plan_Approval__NA_Order_f
or_plotted_development.pdf",
  "id": "729171",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Mon Jun 05 2023 15:10:31 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
```

```
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "26/07/2021",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "Registration_No",
      "label": "Registration No"
    },
    "Registration_No": "P51700030031"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1685958020128_P51700030031.pdf",
  "path": "cases/647995c3ed3c1271b2cd1335/
document_1685958020128_P51700030031.pdf",
  "id": "675606",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Mon Jun 05 2023 15:10:31 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "001803",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "724206",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Jun 02 2023 12:39:55 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Sujata Sandeep Jadhav & Mr. Pravin Niranjan Jadhav",
    "phone": "9923572078",
    "ownershipShare": "",
    "email": "",
    "id": "621387"
  }
],
"siteInspection": [],
"composition": [
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "788650",
  "name": "Bedroom",
  "length": "10.42",
  "length1": "10",
  "length2": "5",
  "width": "9.08",
  "width1": "9",
  "width2": "1",
  "totalArea": "94.62",
  "images": [],
  "extraAreas": [],
  "finalArea": "94.62"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Toilet",
  "length": "6.42",
  "length1": "6",
  "length2": "5",
  "width": "4.08",
  "width1": "4",
  "width2": "1",
  "totalArea": "26.20",
  "images": [],
  "extraAreas": [],
  "finalArea": "26.20"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Toilet",
  "length": "6.58",
  "length1": "6",
  "length2": "7",
```

```
"width": "4.08",
"width1": "4",
"width2": "1",
"totalArea": "26.88",
"images": [],
"extraAreas": [],
"finalArea": "26.88"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "8.17",
  "length1": "8",
  "length2": "2",
  "width": "4.08",
  "width1": "4",
  "width2": "1",
  "totalArea": "33.35",
  "images": [],
  "extraAreas": [],
  "finalArea": "33.35"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Kitchen",
  "length": "6.58",
  "length1": "6",
  "length2": "7",
  "width": "9.50",
  "width1": "9",
  "width2": "6",
  "totalArea": "62.54",
  "images": [],
  "extraAreas": [],
  "finalArea": "62.54"
},
{
  "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Living Room",
  "length": "9.17",
  "length1": "9",
  "length2": "2",
  "width": "15.25",
  "width1": "15",
  "width2": "3",
  "totalArea": "139.79",
  "images": [],
  "extraAreas": [],
  "finalArea": "139.79"
}
],
"otherComposition": [
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "value": "Flowerbed",
    "label": "Flowerbed"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length1": "9",
  "length2": "00",
  "length": "9.00",
  "width1": "2",
  "width2": "00",
  "width": "2.00",
  "totalArea": "18.00",
  "percentageBeforeTotal": "18.00",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "18"
},
{
```



```
"toBeAdded": {
  "label": "Carpet",
  "value": "Carpet"
},
"name": {
  "value": "Cupboard",
  "label": "Cupboard"
},
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "1",
"length1": "3",
"length2": "9",
"length": "3.75",
"width1": "2",
"width2": "4",
"width": "2.33",
"totalArea": "8.75",
"percentageBeforeTotal": "8.75",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "8.75"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "value": "Flowerbed",
    "label": "Flowerbed"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length1": "9",
  "length2": "1",
  "length": "9.08",
  "width1": "2",
  "width2": "00",
  "width": "2.00",
```

```
"totalArea": "18.17",
"percentageBeforeTotal": "18.17",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "18.17"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "value": "Flowerbed",
    "label": "Flowerbed"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "length1": "6",
  "length2": "6",
  "length": "6.50",
  "width1": "2",
  "width2": "1",
  "width": "2.08",
  "totalArea": "13.54",
  "percentageBeforeTotal": "13.54",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "13.54"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1254aa6d152c1801b326",
      "label": "Agreement For Sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  },

```

```
"id": "136555",
"selectAreaTypeDocument": "Carpet",
"totalAreaDocument": "465",
"squareMeterArea": "43.2",
"docFinalBuiltUp": "511.5",
"docFinalBuiltUpSquareMeter": "47.52",
"docBuiltupPercentage": "10",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
},
{
  "typeOfDocument": {
    "value": "60ae1254aa6d152c1801b326",
    "label": "Agreement For Sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "284111",
  "selectAreaTypeDocument": "Built_Up",
  "totalAreaDocument": "438",
  "squareMeterArea": "40.69",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docBuiltupPercentage": "",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "647eb49a0ab64c23c9fc9b16",
    "id": "1",
    "property": "Residential Flat",
    "area": "420",
    "builtUpPercentage": "20",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "",
    "source": "Housing.Com",
```

```
    "expectedPrice": "3800000",
    "expectedRate": "9047.62",
    "builtUpExpectedRate": "7539.68",
    "image": "cases/647995c3ed3c1271b2cd1335/
indicator_1686025370425_Image.png"
```

```
  },
  {
```

```
    "printlnReport": true,
    "_id": "647eb4e30ab64c23c9fc9b25",
    "id": "2",
    "property": "Residential Flat",
    "area": "450",
    "builtUpPercentage": "20",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "Higher Floor",
    "source": "Housing.Com",
    "expectedPrice": "4000000",
    "expectedRate": "8888.89",
    "builtUpExpectedRate": "7407.41",
    "image": "cases/647995c3ed3c1271b2cd1335/
indicator_1686025443036_Image.png"
```

```
  },
  {
```

```
    "printlnReport": true,
    "_id": "647eb5270ab64c23c9fc9c69",
    "id": "3",
    "property": "Residential Flat",
    "area": "452",
    "builtUpPercentage": "20",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "",
    "source": "Housing.Com",
    "expectedPrice": "3500000",
    "expectedRate": "7743.36",
    "builtUpExpectedRate": "6452.80",
    "image": "cases/647995c3ed3c1271b2cd1335/
indicator_1686025511323_Image.png"
```

```
  },
  {
```

```
    "printlnReport": true,
    "_id": "647eb5a00ab64c23c9fca083",
    "id": "4",
```

```
"property": "Residential Flat",
"area": "648",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "10 ",
"source": "https://www.99acres.com/",
"expectedPrice": "4200000",
"expectedRate": "6481.48",
"builtUpExpectedRate": "4200000",
"image": "cases/647995c3ed3c1271b2cd1335/
indicator_1686025632645_Image.png"
},
{
  "printInReport": true,
  "_id": "647eb82f0ab64c23c9fca9ce",
  "id": "5",
  "property": "Residential Flat",
  "area": "393",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "6",
  "source": "Index_no.2",
  "expectedPrice": "2386500",
  "expectedRate": "6072.52",
  "builtUpExpectedRate": "5520.47",
  "image": "cases/647995c3ed3c1271b2cd1335/
indicator_1686026287455_Image.png"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647db4360ab64c23c9fc5356",
    "name":
"externallmg_1685959733667_WhatsApp_Image_20230603_at_33056_PM_1.jpeg",
    "path": "cases/647995c3ed3c1271b2cd1335/
externallmg_1685959733667_WhatsApp_Image_20230603_at_33056_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "647db4360ab64c23c9fc5357",
    "name":
"externallmg_1685959733731_WhatsApp_Image_20230603_at_33056_PM_2.jpeg",
    "path": "cases/647995c3ed3c1271b2cd1335/
externallmg_1685959733731_WhatsApp_Image_20230603_at_33056_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647db4360ab64c23c9fc5358",
    "name":
"externallmg_1685959733742_WhatsApp_Image_20230603_at_33056_PM_3.jpeg",
    "path": "cases/647995c3ed3c1271b2cd1335/
externallmg_1685959733742_WhatsApp_Image_20230603_at_33056_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647db4360ab64c23c9fc5359",
    "name":
"externallmg_1685959733753_WhatsApp_Image_20230603_at_33056_PM_4.jpeg",
    "path": "cases/647995c3ed3c1271b2cd1335/
externallmg_1685959733753_WhatsApp_Image_20230603_at_33056_PM_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647db4360ab64c23c9fc535a",
    "name":
"externallmg_1685959733767_WhatsApp_Image_20230603_at_33056_PM_5.jpeg",
    "path": "cases/647995c3ed3c1271b2cd1335/
externallmg_1685959733767_WhatsApp_Image_20230603_at_33056_PM_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647db4360ab64c23c9fc535b",
    "name":
"externallmg_1685959733772_WhatsApp_Image_20230603_at_33056_PM.jpeg",
    "path": "cases/647995c3ed3c1271b2cd1335/
externallmg_1685959733772_WhatsApp_Image_20230603_at_33056_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647db4360ab64c23c9fc535c",
    "name":
"externallmg_1685959733787_WhatsApp_Image_20230603_at_33057_PM_1.jpeg",
    "path": "cases/647995c3ed3c1271b2cd1335/
externallmg_1685959733787_WhatsApp_Image_20230603_at_33057_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647db4360ab64c23c9fc535d",
    "name":
"externallmg_1685959733794_WhatsApp_Image_20230603_at_33057_PM_2.jpeg",
    "path": "cases/647995c3ed3c1271b2cd1335/
externallmg_1685959733794_WhatsApp_Image_20230603_at_33057_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647db4360ab64c23c9fc535e",
    "name":
"externallmg_1685959733800_WhatsApp_Image_20230603_at_33057_PM_3.jpeg",
    "path": "cases/647995c3ed3c1271b2cd1335/
externallmg_1685959733800_WhatsApp_Image_20230603_at_33057_PM_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647db4360ab64c23c9fc535f",
    "name":
"externallmg_1685959733809_WhatsApp_Image_20230603_at_33057_PM_4.jpeg",
    "path": "cases/647995c3ed3c1271b2cd1335/
externallmg_1685959733809_WhatsApp_Image_20230603_at_33057_PM_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "647db4360ab64c23c9fc5360",
```

```
    "name":
"externallmg_1685959733815_WhatsApp_Image_20230603_at_33057_PM_5.jpeg",
  "path": "cases/647995c3ed3c1271b2cd1335/
externallmg_1685959733815_WhatsApp_Image_20230603_at_33057_PM_5.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "647db4360ab64c23c9fc5361",
  "name":
"externallmg_1685959733823_WhatsApp_Image_20230603_at_33057_PM_6.jpeg",
  "path": "cases/647995c3ed3c1271b2cd1335/
externallmg_1685959733823_WhatsApp_Image_20230603_at_33057_PM_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "647db4360ab64c23c9fc5362",
  "name":
"externallmg_1685959733833_WhatsApp_Image_20230603_at_33057_PM_7.jpeg",
  "path": "cases/647995c3ed3c1271b2cd1335/
externallmg_1685959733833_WhatsApp_Image_20230603_at_33057_PM_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "647db4360ab64c23c9fc5363",
  "name":
"externallmg_1685959733839_WhatsApp_Image_20230603_at_33057_PM_8.jpeg",
  "path": "cases/647995c3ed3c1271b2cd1335/
externallmg_1685959733839_WhatsApp_Image_20230603_at_33057_PM_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "647db4360ab64c23c9fc5364",
  "name":
"externallmg_1685959733843_WhatsApp_Image_20230603_at_33057_PM_9.jpeg",
  "path": "cases/647995c3ed3c1271b2cd1335/
externallmg_1685959733843_WhatsApp_Image_20230603_at_33057_PM_9.jpeg",
  "orientation": "portrait"
},
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "647db4360ab64c23c9fc5365",
  "name":
"externallmg_1685959733855_WhatsApp_Image_20230603_at_33057_PM.jpeg",
  "path": "cases/647995c3ed3c1271b2cd1335/
externallmg_1685959733855_WhatsApp_Image_20230603_at_33057_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"createdAt": "2023-06-02T07:09:55.990Z",
"updatedAt": "2023-06-06T04:58:04.870Z",
"__v": 0,
"updatedBy": "60eebe33f3dd69653a5837ae",
"fullAddress": "Residential Flat No. 301, 3rd Floor, Building No 1, Eknath Heights - 1,
Pandurang Nagar, Plot No. A, Village - Katemanivali, Taluka - Kalyan , District - Thane,
Kalyan (East), 421 306, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Mr. Dipendra Batala ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Watchmen",
"siteVisitContactNo": "9923572078",
"reason": "",
"siteVisitDate": "2023-06-03",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + 2 Toilet + Passage",
"carpetTotal": "383.38",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "58.46",
"builtupPercentage": "10",
"extendOfSiteRemark": "",
"finalBuiltupArea": "486.02",
"finalCarpetArea": "441.84",
"finalSalableArea": "534.63",
"salablePercentage": "10",
"siteMeasurementRemark": "\nCarpet Area in Sq. Ft. = 398.00\nOpen Terrace Area in
Sq. Ft. = 67.00\nTotal Carpet Area in Sq. Ft. = 465.00\n(Area as per Agreement For
Sale)\n",
"toBeAdded": "",
"otherCompositionBuiltUpTotal": "0.00",
```

"otherCompositionCarpetTotal": "58.46",  
 "otherCompositionSaleableTotal": "0.00",  
 "finalAreaType": "Carpet Area",  
 "finalAsPerArea": "Agreement For Sale",  
 "finalBuiltUpPercentage": "10",  
 "finalCarpetConvertToBuiltUpPer": "10",  
 "finalSaleablePercentage": "0",  
 "finalValuationAreaString": "Carpet Area in Sq. Ft. = 465.00",  
 "buildingServicesRate": "2500",  
 "flatRate": "7700",  
 "landOtherRate": "5200"

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Bedroom	10'5"	9'1"	94.62
Toilet	6'5"	4'1"	26.20
Toilet	6'7"	4'1"	26.88
Passage	8'2"	4'1"	33.35
Kitchen	6'7"	9'6"	62.54
Living Room	9'2"	15'3"	139.79
Other Composition :			
Flowerbed	9'00"	2'00"	18.00
Cupboard	3'9"	2'4"	8.75
Flowerbed	9'1"	2'00"	18.17
Flowerbed	6'6"	2'1"	13.54