

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63ae95ee191f7b344b005873"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b47",
    "email": "swapnil.deshmukh@cosmosbank.in",
    "firstName": "Swapnil Deshmukh",
    "mobileNo": "9923243343",
    "workMobileNo": "9923243343",
    "lastName": "Deshmukh"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "19000000",
    "discussWithPerson": "Swapnil Deshmukh",
    "expectedFees": 9500,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
    "city": "Mumbai"
  }
}
```

```
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63ae95ee191f7b344b005873",
  "name": "Malad (East) Branch",
  "branchCode": "",
  "mobileNo": " 022 2881 0731",
  "alternateMobileNo": "",
  "email": "swapnil.deshmukh@cosmosbank.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Shop No. 1, 2 & 3 Khandwala Lane, Khandwala Arcade, Off Daffatry
Road, Malad East, Mumbai 400097"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
    "role": "PICKUPPERSON",
    "firstName": "Sunil",
    "email": "misalsunil87@gmail.com",
    "lastName": "Misal",
    "mobileNo": "8422982721",
    "shortName": "SM",
    "workWithDocumentMaker": ""
  }
}
```

```
"profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "627208c1afd7d55eddedc372",
  "role": "SITEENGINEER+MAKAR",
  "firstName": "Aniket",
  "email": "aniket@vastukala.org",
  "lastName": "Navale",
  "mobileNo": "9892222307",
  "designation": "",
  "shortName": "AN",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627208c1afd7d55eddedc372/
profilePhoto_1667995077581_WhatsApp_Image_20221109_at_52453_PM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER+CHECKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
  "lastName": "Bodke",
  "mobileNo": "9821740317",
  "designation": "",
  "shortName": "SB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eebe33f3dd69653a5837ae\\
\\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
```

```
"type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER+CHECKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    }
  }
]
```

```
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.187405361194916",
  "longitude": "72.84200240840518"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.84200240840518,
    19.187405361194916
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-06-06T09:00:00.000Z",
      "remark": "vikas customer ka mob no hey sir Tomorrow Visit time deya hey Pooja"
    }
  ]
}
```

```
madam ne - 12:00 to 2::00 Urgent hey valuation report"
  },
  {
    "dateTime": "2023-06-06T09:00:00.000Z",
    "remark": "vikas customer ka mob no hey sir Tomorrow Visit time deya hey Pooja
madam ne - 12:00 to 2::00 Urgent hey valuation report"
  }
],
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2023-06-09T05:43:01.911Z",
    "remark": ""
  },
  {
    "status": "COMPLETED",
    "dateTime": "2023-06-09T05:43:05.183Z",
    "remark": ""
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "0",
  "lumpsumValue": "0",
  "rateMax": "0",
  "areaType": {
    "Name": "Carpet",
    "Value": "Carpet",
    "name": "Carpet",
    "value": "Carpet"
  }
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Tue Jun 06 2023 15:45:23 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  }
}
```

```
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Malad",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "25",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
```

```
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Levels",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
}
```



```
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
```

```
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "2503",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
```

```
"status": false,
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Malad East",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Italian Marble Flooring",
    "value": "ItalianMarbleFlooring"
  },
  "doors": {
    "label": "Teak Wood Door frame with Solid flush door",
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door"
  },
  "windows": {
    "label": "Aluminium Sliding Window ",
    "value": "Aluminium_Sliding_Window_"
  },
  "fittings": {
```

```
"label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring",
"value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring"
},
"finishing": {
  "label": "Cement Plastering + POP Finish",
  "value": "Cement_Plastering+_POP_Finish"
}
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Municipal Corporation of Greater Mumbai (MCGM)",
    "value": "MCGM"
  },
  "asPerActualAgreement": {
    "north": "Passport Office",
    "west": "Kathiwadi Chowk",
    "south": "K.D Heights",
    "east": "Slums"
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  }
}
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Owner Occupied",
    "value": "Owner_Occupied"
  }
}
```

```
},
"monthlyRent": "",
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MuncipalWaterSupply"
  },
  "pavementLaid": {
    "label": "Yes",
    "value": "Yes"
  },
  "carParking": {
    "label": "Silt+Podium Car Parking",
    "value": "Silt+Podium_Car_Parking"
  },
  "constructionWorkStatus": {
    "label": "Completed",
    "value": "Completed"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2020",
    "fullDate": "1/1/2020"
  },
  "propertyTypeList": {
    "value": "Residential",
    "label": "Residential"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "label": "R.C.C. Framed Structure",
    "value": "R.C.C._Framed_Structure"
  },
  "qualityOfConstruction": {
    "label": "Good",
    "value": "Good"
  },
}
```

```
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"maintenanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Lower Ground + Upper Ground Floor",
  "value": "Lower_Ground+_Upper_Ground_Floor"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "57",
"ageOfBuilding": "3",
"noOfBasement": "0",
"noOfPodium": "2",
"noOfAmenityFloors": "0",
"noOfFloors": "41",
"flatFloorNo": "",
"noOfLifts": "3",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": true,
  "remark": "SYSTEM_GENERATED",
  "date": "Thu Jun 08 2023 15:06:05 GMT+0530 (India Standard Time)",
```

```
"number": "046878",
"dayCount": "12",
"monthCount": "55",
"generatedBy": "63f31d626f9c2254a9b39144"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```



```
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
}
```

```
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"_id": "647f04700ab64c23c9fd448e",
"ownerName": "Pinky Vikas Jain",
"ownerPhoneNo": "9870624908",
"appAddress": "Flat no.2503 A-wing Levels Rani Sati Marg Malad East Mumbai-400097",
"remark": "vikas customer ka mob no hey sir Tomorrow Visit time deya hey Pooja madam ne - 12:00 to 2::00 Urgent hey valuation report",
"documents": [
```

```
{
  "documentType": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "isHardCopy": false,
  "path": "cases/647f04700ab64c23c9fd448e/
document_1686045715517_PinkyVikasJain_Cosmos_Malad_East.pdf",
  "fileName": "document_1686045715517_PinkyVikasJain_Cosmos_Malad_East.pdf",
  "displayStatus": false,
  "id": "858166",
  "uploadedBy": "60af6ae22ffdf65bcd65861d",
  "createdAt": "Tue Jun 06 2023 15:33:17 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "001864",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "748900",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Jun 06 2023 15:33:28 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Pinky Vikas Jain",
    "phone": "9870624908",
    "ownershipShare": "",
    "email": "",
    "id": "340388"
  }
],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Other",
      "value": "Other"
    },
    "_id": "6482bc199c1ac80fee493b60",
    "area": "1052.97",
```

```
    "providedByName": "Site Visit Measurements",
    "providedByContactNo": "0000000000"
  }
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "740232",
    "name": "Passage",
    "length": "6.17",
    "length1": "6",
    "length2": "2",
    "width": "5.25",
    "width1": "5",
    "width2": "3",
    "totalArea": "32.37",
    "images": [
      {
        "path": "cases/647f04700ab64c23c9fd448e/
compositionImg_r_1686288708830_image.jpg",
        "orientation": "portrait"
      }
    ],
    "extraAreas": [],
    "finalArea": "32.37"
  },
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "1",
    "name": "Living Room",
    "length": "24.42",
    "length1": "24",
    "length2": "5",
    "width": "10.58",
    "width1": "10",
    "width2": "7",
    "totalArea": "258.41",
    "images": [
      {
        "path": "cases/647f04700ab64c23c9fd448e/
compositionImg_r_1686288743859_image.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "path": "cases/647f04700ab64c23c9fd448e/
compositionImg_r_1686288885811_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "258.41"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Balcony Area",
  "length": "10.92",
  "length1": "10",
  "length2": "11",
  "width": "3.58",
  "width1": "3",
  "width2": "7",
  "totalArea": "39.12",
  "images": [
    {
      "path": "cases/647f04700ab64c23c9fd448e/
compositionImg_r_1686288777105_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "39.12"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Kitchen",
  "length": "11.25",
  "length1": "11",
  "length2": "3",
  "width": "7.83",
```

```
"width1": "7",
"width2": "10",
"totalArea": "88.12",
"images": [
  {
    "path": "cases/647f04700ab64c23c9fd448e/
compositionImg_r_1686288811538_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "88.12"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Dry Balcony",
  "length": "7.75",
  "length1": "7",
  "length2": "9",
  "width": "4.92",
  "width1": "4",
  "width2": "11",
  "totalArea": "38.10",
  "images": [
    {
      "path": "cases/647f04700ab64c23c9fd448e/
compositionImg_r_1686288857677_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "38.10"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "Passage",
  "length": "8.92",
  "length1": "8",
```



```
"length2": "11",
"width": "5.58",
"width1": "5",
"width2": "7",
"totalArea": "49.78",
"images": [
  {
    "path": "cases/647f04700ab64c23c9fd448e/
compositionImg_r_1686288932462_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "49.78"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "11.33",
  "length1": "11",
  "length2": "4",
  "width": "10.17",
  "width1": "10",
  "width2": "2",
  "totalArea": "115.22",
  "images": [
    {
      "path": "cases/647f04700ab64c23c9fd448e/
compositionImg_r_1686288982698_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "115.22"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "7",
  "name": "Passage",
```

```
"length": "10.92",
"length1": "10",
"length2": "11",
"width": "3.33",
"width1": "3",
"width2": "4",
"totalArea": "36.39",
"images": [
  {
    "path": "cases/647f04700ab64c23c9fd448e/
compositionImg_r_1686289039369_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "36.39"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "8",
  "name": "Toilet",
  "length": "8.42",
  "length1": "8",
  "length2": "5",
  "width": "4.75",
  "width1": "4",
  "width2": "9",
  "totalArea": "39.98",
  "images": [
    {
      "path": "cases/647f04700ab64c23c9fd448e/
compositionImg_r_1686289089095_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "39.98"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
}
```

```
"id": "9",
"name": "Bedroom",
"length": "11.58",
"length1": "11",
"length2": "7",
"width": "10.25",
"width1": "10",
"width2": "3",
"totalArea": "118.73",
"images": [
  {
    "path": "cases/647f04700ab64c23c9fd448e/
compositionImg_r_1686289170220_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "118.73"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "10",
  "name": "Toilet",
  "length": "7.17",
  "length1": "7",
  "length2": "2",
  "width": "4.17",
  "width1": "4",
  "width2": "2",
  "totalArea": "29.86",
  "images": [
    {
      "path": "cases/647f04700ab64c23c9fd448e/
compositionImg_r_1686289196521_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "29.86"
},
{
  "measurementType": {
    "label": "Square Feet",
```

```
    "value": "Square_Feet"
  },
  "id": "11",
  "name": "Passage",
  "length": "4.17",
  "length1": "4",
  "length2": "2",
  "width": "3.17",
  "width1": "3",
  "width2": "2",
  "totalArea": "13.19",
  "images": [
    {
      "path": "cases/647f04700ab64c23c9fd448e/
compositionImg_r_1686289222793_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "13.19"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "12",
  "name": "Toilet",
  "length": "9.17",
  "length1": "9",
  "length2": "2",
  "width": "5.25",
  "width1": "5",
  "width2": "3",
  "totalArea": "48.12",
  "images": [
    {
      "path": "cases/647f04700ab64c23c9fd448e/
compositionImg_r_1686289253523_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "48.12"
},
{
```

```
"measurementType": {
  "label": "Square Feet",
  "value": "Square_Feet"
},
"id": "13",
"name": "Bedroom",
"length": "15.25",
"length1": "15",
"length2": "3",
"width": "10.58",
"width1": "10",
"width2": "7",
"totalArea": "161.40",
"images": [
  {
    "path": "cases/647f04700ab64c23c9fd448e/
compositionImg_r_1686289292860_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "161.40"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6482bc5d9c1ac80fee493c56",
    "name": "externalImg_r_1686289498647_image.jpg",
    "path": "cases/647f04700ab64c23c9fd448e/
externalImg_r_1686289498647_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6482bc5d9c1ac80fee493c57",
    "name": "externalImg_r_1686289498302_image.jpg",
    "path": "cases/647f04700ab64c23c9fd448e/
externalImg_r_1686289498302_image.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6482bc5d9c1ac80fee493c58",
  "name": "externallmg_r_1686289497772_image.jpg",
  "path": "cases/647f04700ab64c23c9fd448e/
externallmg_r_1686289497772_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6482bc5d9c1ac80fee493c59",
  "name": "externallmg_r_1686289498059_image.jpg",
  "path": "cases/647f04700ab64c23c9fd448e/
externallmg_r_1686289498059_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6482bc5d9c1ac80fee493c5a",
  "name": "externallmg_r_1686289499054_image.jpg",
  "path": "cases/647f04700ab64c23c9fd448e/
externallmg_r_1686289499054_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6482bc5d9c1ac80fee493c5b",
  "name": "externallmg_r_1686289499227_image.jpg",
  "path": "cases/647f04700ab64c23c9fd448e/
externallmg_r_1686289499227_image.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6482bc5d9c1ac80fee493c5c",
  "name": "externallmg_r_1686289498755_image.jpg",
  "path": "cases/647f04700ab64c23c9fd448e/
externallmg_r_1686289498755_image.jpg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6482bc5d9c1ac80fee493c5d",
      "name": "externalImg_r_1686289499377_image.jpg",
      "path": "cases/647f04700ab64c23c9fd448e/
externalImg_r_1686289499377_image.jpg",
      "orientation": "portrait"
    }
  ],
  "externalDocuments": [
    {
      "originalname": "Valuation_Report_Pinky Vikas Jain.pdf",
      "filename": "1686216975762_Valuation_Report__Pinky_Vikas_Jain.pdf",
      "path": "cases/647f04700ab64c23c9fd448e/
externalDocuments/1686216975762_Valuation_Report__Pinky_Vikas_Jain.pdf",
      "size": "877603",
      "documentType": {
        "value": "60ae124caa6d152c1801b300",
        "label": "Signed Report"
      },
      "createdAt": "Thu Jun 08 2023 15:06:15 GMT+0530 (India Standard Time)",
      "uploadedBy": "63f31d626f9c2254a9b39144"
    }
  ],
  "createdAt": "2023-06-06T10:03:28.259Z",
  "updatedAt": "2023-06-09T05:46:27.730Z",
  "__v": 0,
  "fullAddress": "Residential Flat No. 2503, 25th Floor, Wing - A, Levels, Village - Malad,
Malad East, Mumbai, State - Maharashtra, India",
  "updatedAt": "627208c1afd7d55eddedc372",
  "addressForMap": "",
  "caseReferredBy": "60af6ae22ffdf65bcd65861d",
  "contactPersonName": "Pinky Vikas Jain",
  "email": "",
  "isExternal": "false",
  "isUrgent": "false",
  "ownershipShare": "",
  "purchaseValueAsPerDocument": "",
  "relationWithOwner": "self",
  "siteVisitContactNo": "9870624908",
  "reason": "",
  "briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + 4 Passage + Balcony
Area + Dry Balcony + 3 Toilet",
  "carpetTotal": "1068.7900000000002",
```

"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0",
"siteVisitDate": "2023-06-09"

}

Name	Length	Width	Total
Composition :			
Passage	6'2"	5'3"	32.37
Living Room	24'5"	10'7"	258.41
Balcony Area	10'11"	3'7"	39.12
Kitchen	11'3"	7'10"	88.12
Dry Balcony	7'9"	4'11"	38.10
Passage	8'11"	5'7"	49.78
Bedroom	11'4"	10'2"	115.22
Passage	10'11"	3'4"	36.39
Toilet	8'5"	4'9"	39.98
Bedroom	11'7"	10'3"	118.73
Toilet	7'2"	4'2"	29.86
Passage	4'2"	3'2"	13.19
Toilet	9'2"	5'3"	48.12
Bedroom	15'3"	10'7"	161.40
Other Composition :			