

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "648ae0c9719c32253ddcc159"
    },
    "type": "CREDITOFFICER",
    "_id": "648ae0c9719c32253ddcc15b",
    "firstName": "KUnal",
    "lastName": "SHah",
    "mobileNo": "",
    "workMobileNo": "8097819553",
    "email": "fort@cosmosbank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "12500000",
    "discussWithPerson": "Percy ",
    "expectedFees": 6250,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
    "city": "Mumbai"
  }
}
```

```
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1860",
  "type": "BANK",
  "name": "The Zoroastrian Co-operative Bank Ltd",
  "displayName": "",
  "initial": "TZCBL",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "648ae0c9719c32253ddcc159",
  "name": "Fort Branch\t",
  "branchCode": "",
  "mobileNo": "02222632983",
  "alternateMobileNo": "",
  "email": "fort@cosmosbank.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "229/231, Perin Nariman Street, Bazar Gate, Fort 400001\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60fbb61bf1938001e0f4d6f3",
  "zoneName": "PAN INDIA"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af3d172ffdf65bcd6585cd",
    "role": "PICKUPPERSON",
    "firstName": "Sachin",
    "email": "sachin.joshi@vastukala.org",
    "lastName": "Joshi",
    "mobileNo": "9167204063",
    "shortName": "SJ",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af3d172ffdf65bcd6585cd\
```

```
\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "627208c1afd7d55eddedc372",
  "role": "SITEENGINEER+MAKAR",
  "firstName": "Aniket",
  "email": "aniket@vastukala.org",
  "lastName": "Navale",
  "mobileNo": "9892222307",
  "designation": "",
  "shortName": "AN",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627208c1afd7d55eddedc372/
profilePhoto_1667995077581_WhatsApp_Image_20221109_at_52453_PM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER+CHECKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
  "mobileNo": "9529385821",
  "designation": "",
  "shortName": "PR",
  "workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
  "profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
```

```
    "_id": "60f915d3f3dd69653a592199",
    "role": "MAKER+CHECKER",
    "firstName": "Shobha",
    "email": "shobha@vastukala.org",
    "lastName": "Kuperkar",
    "mobileNo": "9004134140",
    "designation": "",
    "shortName": "SH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
  },
  "valuers": [],
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.21118470496674",
  "longitude": " 72.83614872150402"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.83614872150402,
    19.21118470496674
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-06-15T10:00:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Thu Jun 15 2023 15:32:20 GMT+0530 (India Standard Time)"
}
```

```
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Poisar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "9",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
    "value": "",
    "label": true
  },
  "city": {
    "status": true,
```

```
"name": "City",
"key": "city",
"value": "Mumbai",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Maitri Residencney 1 CHSL\t",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Behind Poisar Gymkhanat",
  "label": false
}
```

```
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
```

```
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "906t",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
}
```



```
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kandivali West\t",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "VerifiedTileFlooring"
  },
  "doors": {
```

```
"label": "Teak Wood Door frame with Solid door with safety door",
"value": "Teak_Wood_Door_frame_with_Solid_door_with_safety_door"
},
"windows": {
  "label": "Aluminium Sliding Window ",
  "value": "Aluminium_Sliding_Window_"
},
"fittings": {
  "label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring",
  "value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring"
},
"finishing": {
  "label": "Cement Plastering",
  "value": "Cement_Plastering"
}
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Municipal Corporation of Greater Mumbai (MCGM)",
    "value": "MCGM"
  },
  "asPerActualAgreement": {
    "north": "Shree Vallabh CHSL",
    "west": "Kamla Vihar Park",
    "south": "Ground",
    "east": "Maitri Residency II"
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  }
}
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  }
}
```

```
},
"propertyTypeOfUseList": {
  "label": "Residential Purpose",
  "value": "Residential_Purpose"
},
"propertyOccupiedByList": {
  "label": "Owner Occupied",
  "value": "Owner_Occupied"
},
"monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  },
  "pavementLaid": {
    "label": "Yes",
    "value": "Yes"
  },
  "carParking": {
    "label": "Open Parking",
    "value": "Open_Parking"
  },
  "constructionWorkStatus": {
    "label": "Completed",
    "value": "Completed"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "1999",
    "fullDate": "1/1/1999"
  },
  "propertyTypeList": {
    "value": "Residential",
    "label": "Residential"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
}
```

```
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"qualityOfConstruction": {
  "label": "Good",
  "value": "Good"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"maintenanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Stilt",
  "value": "stilt"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "36",
"ageOfBuilding": "24",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "12",
"flatFloorNo": "",
"noOfLifts": "2",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
```

```
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
```

```
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "NEW",
"_id": "648a9d74da662768e994e4d1",
"ownerName": "Paresh Jyotindra Raval\t",
"ownerPhoneNo": "9820263157",
"appAddress": "Maitry Recedancy\n9th 906 \nMahavir Nagar\nkandivali w 400 067",
"remark": "All Documents in Mumbai id ",
```

```
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/648a9d74da662768e994e4d1/
document_1686805730501_906Agreement_for_Paresh_Raval.pdf",
    "fileName": "document_1686805730501_906Agreement_for_Paresh_Raval.pdf",
    "displayStatus": false,
    "id": "984040",
    "uploadedBy": "62727444afd7d55eddee092c",
    "createdAt": "Thu Jun 15 2023 10:41:04 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "001950",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "149521",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Jun 15 2023 10:41:15 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Paresh Jyotindra Raval",
    "phone": "9820263157",
    "ownershipShare": "",
    "email": "",
    "id": "263374"
  }
],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Other",
      "value": "Other"
    }
  },
  {
    "_id": "648d462c07df79469f4054a4",
```

```
"area": "725.17",
"providedByName": "Site Visit Measurements",
"providedByContactNo": "0000000000"
}
],
"composition": [
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "581308",
  "name": "Living Room",
  "length": "20.50",
  "length1": "20",
  "length2": "6",
  "width": "10.42",
  "width1": "10",
  "width2": "5",
  "totalArea": "213.54",
  "images": [],
  "extraAreas": [],
  "finalArea": "213.54"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "name": "Bedroom",
  "length": "15.25",
  "length1": "15",
  "length2": "3",
  "width": "10.83",
  "width1": "10",
  "width2": "10",
  "totalArea": "165.21",
  "images": [],
  "extraAreas": [],
  "finalArea": "165.21"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  }
}
```

```
},
  "id": "2",
  "name": "Toilet",
  "length": "6.33",
  "length1": "6",
  "length2": "4",
  "width": "3.83",
  "width1": "3",
  "width2": "10",
  "totalArea": "24.28",
  "images": [],
  "extraAreas": [],
  "finalArea": "24.28"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "10.42",
  "length1": "10",
  "length2": "5",
  "width": "3.17",
  "width1": "3",
  "width2": "2",
  "totalArea": "32.99",
  "images": [],
  "extraAreas": [],
  "finalArea": "32.99"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "14.83",
  "length1": "14",
  "length2": "10",
  "width": "10.67",
  "width1": "10",
  "width2": "8",
  "totalArea": "158.22",
```

```
"images": [],
"extraAreas": [],
"finalArea": "158.22"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "6.92",
  "length1": "6",
  "length2": "11",
  "width": "3.92",
  "width1": "3",
  "width2": "11",
  "totalArea": "27.09",
  "images": [],
  "extraAreas": [],
  "finalArea": "27.09"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "6",
  "name": "Passage",
  "length": "4.50",
  "length1": "4",
  "length2": "6",
  "width": "4.17",
  "width1": "4",
  "width2": "2",
  "totalArea": "18.75",
  "images": [],
  "extraAreas": [],
  "finalArea": "18.75"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "7",
```

```
"name": "Kitchen",
"length": "11.42",
"length1": "11",
"length2": "5",
"width": "6.83",
"width1": "6",
"width2": "10",
"totalArea": "78.01",
"images": [],
"extraAreas": [],
"finalArea": "78.01"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "8",
  "name": "Dry Balcony",
  "length": "3.92",
  "length1": "3",
  "length2": "11",
  "width": "3.25",
  "width1": "3",
  "width2": "3",
  "totalArea": "12.73",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.73"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [],
"externalDocuments": [],
"createdAt": "2023-06-15T05:11:16.019Z",
"updatedAt": "2023-06-17T06:12:52.251Z",
"__v": 0,
"fullAddress": " Flat No. 906\t, 9th Floor, Maitri Residency 1 CHSL\t, Behind Poisar Gymkhana\t, Village - Poisar, Kandivali West\t, Mumbai, State - Maharashtra, India",
"updatedBy": "627208c1afd7d55eddedc372",
"addressForMap": "",
"caseReferredBy": "62727444afd7d55eddee092c",
```

"contactPersonName": "Paresh Jyotindra Raval",
 "email": "",
 "isExternal": "false",
 "isUrgent": "false",
 "ownershipShare": "",
 "purchaseValueAsPerDocument": "",
 "relationWithOwner": "self",
 "siteVisitContactNo": "9820263157",
 "briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Toilet + 2 Passage +
 Dry Balcony",
 "carpetTotal": "730.82",
 "finalMeasurementType": "Sq. Ft.",
 "otherCarpetTotal": "0"

}

Name	Length	Width	Total
Composition :			
Living Room	20'6"	10'5"	213.54
Bedroom	15'3"	10'10"	165.21
Toilet	6'4"	3'10"	24.28
Passage	10'5"	3'2"	32.99
Bedroom	14'10"	10'8"	158.22
Toilet	6'11"	3'11"	27.09
Passage	4'6"	4'2"	18.75
Kitchen	11'5"	6'10"	78.01
Dry Balcony	3'11"	3'3"	12.73
Other Composition :			