

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Education Loan",
    "value": "Education_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856ba28"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b9423124f",
    "firstName": "Santosh Vaidya",
    "email": "0_default_",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-8452048541"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "7500000",
    "discussWithPerson": "Santosh Vaidya",
    "expectedFees": 3750,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
    "city": "Mumbai"
  },
}
```

```
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856ba28",
  "branchCode": "000240",
  "type": "BRANCH",
  "name": "RACPC - Santacruz (West)",
  "email": "cord1.racpcbkc@sbi.co.in",
  "mobileNo": "022-26719265",
  "alternateMobileNo": "",
  "address": "1st Floor, Jeevan Seva Annex Bldg., LIC Complex, S. V. Road, Santacruz
(West), Mumbai - 400 054, State - Maharashtra, Country - India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
    "role": "PICKUPPERSON",
    "firstName": "Sunil",
    "email": "misalsunil87@gmail.com",
    "lastName": "Misal",
    "mobileNo": "8422982721",
    "shortName": "SM",
    "workWithDocumentMaker": ""
  }
}
```

```
"profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f949ce45132d6a6bddbcc3",
  "role": "SITEENGINEER",
  "firstName": "Tushar ",
  "email": "tusharbhuwad90@gmail.com",
  "lastName": "Bhuwad",
  "mobileNo": "9082053889",
  "designation": "",
  "shortName": "TSB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f949ce45132d6a6bddbcc3/
profilePhoto_1668058314746_WhatsApp_Image_20221110_at_105931_AM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "0123456789",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
  "lastName": "Bodke",
  "mobileNo": "9821740317",
  "designation": "",
  "shortName": "SB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eebe33f3dd69653a5837ae\\
\\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
```

```
"type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "0123456789",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": []
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.084235",
  "longitude": "72.852992"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.852992,
    19.084235
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-06-15T07:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-06-15T07:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-06-15T07:30:00.000Z",
      "remark": ""
    }
  ]
},
],
```

```
"visitedDate": [
  {
    "remark": "MANUAL",
    "status": "COMPLETED",
    "dateTime": "2023-06-19T06:00:00.000Z"
  }
],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1RK",
  "label": "1 RK"
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Thu Jun 15 2023 13:30:34 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kolekalyan",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
```

```
"value": "2",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Santacruz (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
```

```
"status": true,
"name": "Building Name",
"key": "buildingName",
"value": "Sohini Apartments Co-op. Hsg. Soc. Ltd.",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Datta Mandir Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Vakola",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
```

```
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "27B",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "202",
  "label": false
},
"municipalityWardNo": {
  "status": true,
```



```
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "H-East",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400 055",
  "label": false
}
```

```

},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {

```

```
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "MCGM",
"label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Slum Area ",
"west": "Internal Road & Slum Area ",
"south": "Internal Road",
"east": "Silver Thread Building "
},
"asPerDocumentAgreement": {
"north": "Details not available",
"west": "Details not available",
"south": "Details not available",
"east": "Details not available"
},
"extraDetailOfProperty": "As per site inspection 1 HK Flat converted into 1 BH by
converting Kitchen into bedroom. "
},
"compositeRate": {
"remark": "At the time of inspection we found that Flat No. 201 & 202 on 2nd floor is
internally merged having separate entrances. There is an internal door provision for
both the flats. Flats can be easily demarcated. Kitchen is in Flat No. 201. The said
valuation is only for Flat No. 202.",
"depreciationPercentage": "31.499999999999996",
"depreciationRatioOfBuilding": "",
"salvageValue": "10",
"depreciatedCostOfConstruction": "18555",
"depreciatedBuildingRate": "2055"
},
"igrRate": {
"propertyName": "Flat",
"rate": "151360",
"landRate": "79550",
"igrImage": "cases/648abcdbda662768e995206f/igr_1687327613238_Image.png",
"squareMeterGuideLineRate": "136224.00",
"squareFeetGuideLineRate": "12656.00"
},
"igrFinalRate": {
```

```
"rate": "11550.00",
"squareFeetGuideLineRate": "11550.00",
"squareMeterGuideLineRate": "124322.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "17,000",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MCGM norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
```

```
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
},
"carParking": {
"value": "Open_Car_Parking",
"label": "Open Car Parking"
},
"constructionWorkStatus": {
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2002",
"fullDate": "1/1/2002"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C._Framed_Structure",
"label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Normal",
"label": "Normal"
},
"materialUsedList": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"buildingSpecification": {
```

```
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"structuralSafety": {
"value": "Normal",
"label": "Normal"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
},
"maintenanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
},
"maintenanceIssues": {
"value": "Information_not_available",
"label": "Information not available"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"provisionOfFirefighting": {
"value": "Information_not_available",
"label": "Information not available"
},
"groundStilt": {
"value": "ground",
"label": "Ground"
}
```

```
    },
    "yearOfConstructionAsPer": {
      "value": "as_per_occupancy_certificate",
      "label": "As per occupancy certificate"
    },
    "isSiteVisitAllowed": true,
    "ageOfBuilding": "21",
    "totalLifeBuilding": "60",
    "estimatedAge": "39",
    "noOfBasement": "",
    "noOfPodium": "",
    "noOfAmenityFloors": "",
    "noOfFloors": "3",
    "flatFloorNo": "2",
    "noOfLifts": "",
    "noOfDwellingUnitsInBuilding": "4"
  },
  "finalPlinthArea": {
    "area": "444.00",
    "measurementType": "Sq. Ft.",
    "areaAsPer": "Area As per Agreement for sale"
  },
  "routeMap": {
    "routeMapDetail": {
      "routeStation": {
        "value": "Railway_Station",
        "label": "Railway Station"
      },
      "routeMapImg": "cases/648abcbdbda662768e995206f/
routeMap_1687241691230_Image.png",
      "routeLat": "19.084235",
      "routeLng": "72.852992",
      "stationName": "Santacruz ",
      "routeDistance": "1.2 Km"
    },
    "finalLatLng": {
      "coordinates": [
        null,
        null
      ],
      "type": "Point"
    },
    "showLocation": {
      "latLng": true,
      "finallatLng": true
    }
  },
}
```

```
"locationMapImg": [
  {
    "id": "09gdwa",
    "name": "09gdwa",
    "image": "cases/648abcdbda662768e995206f/
routeMap_1687241589761_Image.png"
  }
],
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "8238420.00",
  "bookValue": "0",
  "finalValue": "8238420.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEM_GENERATED",
  "date": "Wed Jun 21 2023 11:57:25 GMT+0530 (India Standard Time)",
  "number": "047008",
```



```
"dayCount": "2",
"monthCount": "185",
"generatedBy": "60eebe33f3dd69653a5837ae"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "5128200.00",
  "selectedBuildUpValue": "444.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "64914420ff2e4a17ce87c39d",
    }
  ]
}
```

```
    "name": "externallmg_r_1687241759300_IMG20230618154933.jpg",
    "path": "cases/648abcbda662768e995206f/
externallmg_r_1687241759300_IMG20230618154933.jpg",
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "64914413ff2e4a17ce87c2f4",
    "name": "externallmg_r_1687241747047_IMG20230618154620.jpg",
    "path": "cases/648abcbda662768e995206f/
externallmg_r_1687241747047_IMG20230618154620.jpg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "64914413ff2e4a17ce87c2f3",
    "name": "externallmg_r_1687241747052_IMG20230618154713.jpg",
    "path": "cases/648abcbda662768e995206f/
externallmg_r_1687241747052_IMG20230618154713.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64914413ff2e4a17ce87c2fc",
    "name": "externallmg_r_1687241747071_IMG20230618154823.jpg",
    "path": "cases/648abcbda662768e995206f/
externallmg_r_1687241747071_IMG20230618154823.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64914420ff2e4a17ce87c39c",
    "name": "externallmg_r_1687241759288_IMG20230618154916.jpg",
    "path": "cases/648abcbda662768e995206f/
externallmg_r_1687241759288_IMG20230618154916.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
```

```
    "_id": "6491440aff2e4a17ce87c25d",
    "name": "externallmg_r_1687241737751_IMG20230618153433.jpg",
    "path": "cases/648abfdbda662768e995206f/
externallmg_r_1687241737751_IMG20230618153433.jpg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "6491440aff2e4a17ce87c261",
    "name": "Living Room",
    "path": "cases/648abfdbda662768e995206f/
externallmg_r_1687241737769_IMG20230618153645.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64914413ff2e4a17ce87c2f1",
    "name": "Living Room",
    "path": "cases/648abfdbda662768e995206f/
externallmg_r_1687241747045_IMG20230618153722.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64914413ff2e4a17ce87c2f2",
    "name": "Living Room",
    "path": "cases/648abfdbda662768e995206f/
externallmg_r_1687241747050_IMG20230618154634.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
```

```
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": true,
```

```
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "444.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"_id": "648abcdbda662768e995206f",
"ownerName": "Mrs. Saili Sudhakar Salvi ",
"ownerPhoneNo": "9867842289",
"appAddress": "Flat no.202,3 nd floor,A+Wing,Sohini Apartment Co-operative HSG
Soc Ltd, Datta Mandir road Kole Kalyan Santacruz East ",
"remark": "9892275149 Tomorrow Visit karo sir aaj customer nahi hey Home pey ",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "27/09/2022",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Mr. George Dennis Gomes ",
      "to": {
        "value": "Transferee",
        "label": "Transferee"
      }
    }
  }
]
```



```
    },
    "Transferee": "Mrs. Saili Sudhakar Salvi"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "531481",
  "path": "cases/648abcdbda662768e995206f/
document_1686813670920_Saili_Salvi_Santacruz_West.pdf",
  "fileName": "document_1686813670920_Saili_Salvi_Santacruz_West.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "03/05/2002",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CE / 6267 / BSII / AH"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "609694",
  "path": "cases/648abcdbda662768e995206f/
document_1686813765384_Salili_Salvi_Santacruz_West__OC_copy_.pdf",
  "fileName":
"document_1686813765384_Salili_Salvi_Santacruz_West__OC_copy_.pdf"
}
],
"caseNumber": "001961",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "309172",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Jun 15 2023 12:55:15 GMT+0530 (India Standard Time)"
  }
],
```

```
"owners": [
  {
    "name": "Mrs. Saili Sudhakar Salvi ",
    "phone": "9867842289",
    "ownershipShare": "",
    "email": "",
    "id": "622233"
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "261240",
    "name": "Living Room",
    "length": "9.67",
    "length1": "9",
    "length2": "8",
    "width": "20.58",
    "width1": "20",
    "width2": "7",
    "totalArea": "198.97",
    "images": [],
    "extraAreas": [],
    "finalArea": "198.97"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Passage",
    "length": "6.83",
    "length1": "6",
    "length2": "10",
    "width": "2.67",
    "width1": "2",
    "width2": "8",
    "totalArea": "18.22",
    "images": [],
    "extraAreas": [],
    "finalArea": "18.22"
  }
]
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "WC",
  "length": "2.83",
  "length1": "2",
  "length2": "10",
  "width": "3.75",
  "width1": "3",
  "width2": "9",
  "totalArea": "10.62",
  "images": [],
  "extraAreas": [],
  "finalArea": "10.62"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bathroom",
  "length": "3.25",
  "length1": "3",
  "length2": "3",
  "width": "6.25",
  "width1": "6",
  "width2": "3",
  "totalArea": "20.31",
  "images": [],
  "extraAreas": [],
  "finalArea": "20.31"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "9.92",
  "length1": "9",
```

```
"length2": "11",
"width": "9.83",
"width1": "9",
"width2": "10",
"totalArea": "97.51",
"images": [],
"extraAreas": [],
"finalArea": "97.51"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "948063",
  "selectAreaTypeDocument": "Built_Up",
  "totalAreaDocument": "444",
  "squareMeterArea": "41.25",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docBultupPercentage": "",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "64929163ff2e4a17ce88d34e",
  "id": "1",
  "property": "Flat",
  "area": "420",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
}
```

```
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "8200000",
"expectedRate": "19523.81",
"builtUpExpectedRate": "8200000",
"image": "cases/648abcdbda662768e995206f/
indicator_1687327075807_Image.png"
},
{
  "printlnReport": true,
  "_id": "64929163ff2e4a17ce88d34f",
  "id": "2",
  "property": "Flat",
  "area": "420",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Nobroker.com",
  "expectedPrice": "8200000",
  "expectedRate": "19523.81",
  "builtUpExpectedRate": "8200000",
  "image": "cases/648abcdbda662768e995206f/
indicator_1687327075830_Image.png"
},
{
  "printlnReport": true,
  "_id": "649291bcff2e4a17ce88d36e",
  "id": "3",
  "property": "Flat",
  "area": "419",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Nobroker.com",
  "expectedPrice": "8000000",
  "expectedRate": "19093.08",
  "builtUpExpectedRate": "8000000",
  "image": "cases/648abcdbda662768e995206f/
indicator_1687327164808_Image.png"
},
{
  "printlnReport": true,
```

```
  "_id": "64929230ff2e4a17ce88d48b",
  "id": "4",
  "property": "Flat",
  "area": "348",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Housing.Com",
  "expectedPrice": "7000000",
  "expectedRate": "20114.94",
  "builtUpExpectedRate": "7000000",
  "image": "cases/648abcdbda662768e995206f/
indicator_1687327279985_Image.png"
},
{
  "printlnReport": true,
  "_id": "649292cfff2e4a17ce88d573",
  "id": "5",
  "property": "Flat",
  "area": "485",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "1",
  "source": "Index_no.2",
  "expectedPrice": "7700000",
  "expectedRate": "15876.29",
  "builtUpExpectedRate": "7700000",
  "image": "cases/648abcdbda662768e995206f/
indicator_1687327439121_Image.png"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6491440aff2e4a17ce87c25c",
    "name": "externalImg_r_1687241737759_IMG20230618153441.jpg",
    "path": "cases/648abcdbda662768e995206f/
externalImg_r_1687241737759_IMG20230618153441.jpg",
    "orientation": "landscape"
  },
  {
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6491440aff2e4a17ce87c25d",
    "name": "externallmg_r_1687241737751_IMG20230618153433.jpg",
    "path": "cases/648abcdbda662768e995206f/
externallmg_r_1687241737751_IMG20230618153433.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6491440aff2e4a17ce87c25e",
    "name": "externallmg_r_1687241737756_IMG20230618153440.jpg",
    "path": "cases/648abcdbda662768e995206f/
externallmg_r_1687241737756_IMG20230618153440.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6491440aff2e4a17ce87c25f",
    "name": "externallmg_r_1687241737753_IMG20230618153435.jpg",
    "path": "cases/648abcdbda662768e995206f/
externallmg_r_1687241737753_IMG20230618153435.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6491440aff2e4a17ce87c260",
    "name": "externallmg_r_1687241737761_IMG20230618153632.jpg",
    "path": "cases/648abcdbda662768e995206f/
externallmg_r_1687241737761_IMG20230618153632.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6491440aff2e4a17ce87c261",
    "name": "externallmg_r_1687241737769_IMG20230618153645.jpg",
    "path": "cases/648abcdbda662768e995206f/
externallmg_r_1687241737769_IMG20230618153645.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6491440aff2e4a17ce87c262",
  "name": "externalimg_r_1687241737765_IMG20230618153635.jpg",
  "path": "cases/648abfdbda662768e995206f/
externalimg_r_1687241737765_IMG20230618153635.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6491440aff2e4a17ce87c263",
  "name": "externalimg_r_1687241737767_IMG20230618153644.jpg",
  "path": "cases/648abfdbda662768e995206f/
externalimg_r_1687241737767_IMG20230618153644.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6491440aff2e4a17ce87c264",
  "name": "externalimg_r_1687241737770_IMG20230618153649.jpg",
  "path": "cases/648abfdbda662768e995206f/
externalimg_r_1687241737770_IMG20230618153649.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6491440aff2e4a17ce87c265",
  "name": "externalimg_r_1687241737776_IMG20230618153713.jpg",
  "path": "cases/648abfdbda662768e995206f/
externalimg_r_1687241737776_IMG20230618153713.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6491440aff2e4a17ce87c266",
  "name": "externalimg_r_1687241737778_IMG20230618153720.jpg",
  "path": "cases/648abfdbda662768e995206f/
externalimg_r_1687241737778_IMG20230618153720.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```



```
    "_id": "6491440aff2e4a17ce87c267",
    "name": "externalimg_r_1687241737774_IMG20230618153703.jpg",
    "path": "cases/648abcbda662768e995206f/
externalimg_r_1687241737774_IMG20230618153703.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64914413ff2e4a17ce87c2f1",
    "name": "externalimg_r_1687241747045_IMG20230618153722.jpg",
    "path": "cases/648abcbda662768e995206f/
externalimg_r_1687241747045_IMG20230618153722.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64914413ff2e4a17ce87c2f2",
    "name": "externalimg_r_1687241747050_IMG20230618154634.jpg",
    "path": "cases/648abcbda662768e995206f/
externalimg_r_1687241747050_IMG20230618154634.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64914413ff2e4a17ce87c2f3",
    "name": "externalimg_r_1687241747052_IMG20230618154713.jpg",
    "path": "cases/648abcbda662768e995206f/
externalimg_r_1687241747052_IMG20230618154713.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64914413ff2e4a17ce87c2f4",
    "name": "externalimg_r_1687241747047_IMG20230618154620.jpg",
    "path": "cases/648abcbda662768e995206f/
externalimg_r_1687241747047_IMG20230618154620.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64914413ff2e4a17ce87c2f5",
```

```
    "name": "externallmg_r_1687241747057_IMG20230618154717.jpg",
    "path": "cases/648abcbda662768e995206f/
externallmg_r_1687241747057_IMG20230618154717.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64914413ff2e4a17ce87c2f6",
    "name": "externallmg_r_1687241747055_IMG20230618154715.jpg",
    "path": "cases/648abcbda662768e995206f/
externallmg_r_1687241747055_IMG20230618154715.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64914413ff2e4a17ce87c2f7",
    "name": "externallmg_r_1687241747059_IMG20230618154755.jpg",
    "path": "cases/648abcbda662768e995206f/
externallmg_r_1687241747059_IMG20230618154755.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64914413ff2e4a17ce87c2f8",
    "name": "externallmg_r_1687241747062_IMG20230618154759.jpg",
    "path": "cases/648abcbda662768e995206f/
externallmg_r_1687241747062_IMG20230618154759.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64914413ff2e4a17ce87c2f9",
    "name": "externallmg_r_1687241747064_IMG20230618154800.jpg",
    "path": "cases/648abcbda662768e995206f/
externallmg_r_1687241747064_IMG20230618154800.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64914413ff2e4a17ce87c2fa",
    "name": "externallmg_r_1687241747069_IMG20230618154821.jpg",
```

```
    "path": "cases/648abcbda662768e995206f/
externallmg_r_1687241747069_IMG20230618154821.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64914413ff2e4a17ce87c2fb",
    "name": "externallmg_r_1687241747066_IMG20230618154812.jpg",
    "path": "cases/648abcbda662768e995206f/
externallmg_r_1687241747066_IMG20230618154812.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64914413ff2e4a17ce87c2fc",
    "name": "externallmg_r_1687241747071_IMG20230618154823.jpg",
    "path": "cases/648abcbda662768e995206f/
externallmg_r_1687241747071_IMG20230618154823.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64914420ff2e4a17ce87c394",
    "name": "externallmg_1687241759502_Screenshot_2023061815514104_3d9111e2
d3171bf4882369f490c087b4.jpg",
    "path": "cases/648abcbda662768e995206f/externallmg_1687241759502_Screens
hot_2023061815514104_3d9111e2d3171bf4882369f490c087b4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64914420ff2e4a17ce87c395",
    "name": "externallmg_r_1687241759259_IMG20230618154852.jpg",
    "path": "cases/648abcbda662768e995206f/
externallmg_r_1687241759259_IMG20230618154852.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64914420ff2e4a17ce87c396",
    "name": "externallmg_r_1687241759266_IMG20230618154908.jpg",
```

```
    "path": "cases/648abcbda662768e995206f/
externallmg_r_1687241759266_IMG20230618154908.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64914420ff2e4a17ce87c397",
    "name": "externallmg_r_1687241759245_IMG20230618154824.jpg",
    "path": "cases/648abcbda662768e995206f/
externallmg_r_1687241759245_IMG20230618154824.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64914420ff2e4a17ce87c398",
    "name": "externallmg_r_1687241759248_IMG20230618154839.jpg",
    "path": "cases/648abcbda662768e995206f/
externallmg_r_1687241759248_IMG20230618154839.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64914420ff2e4a17ce87c399",
    "name": "externallmg_r_1687241759280_IMG20230618154910.jpg",
    "path": "cases/648abcbda662768e995206f/
externallmg_r_1687241759280_IMG20230618154910.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64914420ff2e4a17ce87c39a",
    "name": "externallmg_r_1687241759284_IMG20230618154912.jpg",
    "path": "cases/648abcbda662768e995206f/
externallmg_r_1687241759284_IMG20230618154912.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64914420ff2e4a17ce87c39b",
    "name": "externallmg_r_1687241759292_IMG20230618154919.jpg",
    "path": "cases/648abcbda662768e995206f/
externallmg_r_1687241759292_IMG20230618154919.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64914420ff2e4a17ce87c39c",
  "name": "externallmg_r_1687241759288_IMG20230618154916.jpg",
  "path": "cases/648abdcdbda662768e995206f/
externallmg_r_1687241759288_IMG20230618154916.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64914420ff2e4a17ce87c39d",
  "name": "externallmg_r_1687241759300_IMG20230618154933.jpg",
  "path": "cases/648abdcdbda662768e995206f/
externallmg_r_1687241759300_IMG20230618154933.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64914420ff2e4a17ce87c39e",
  "name": "externallmg_r_1687241759296_IMG20230618154928.jpg",
  "path": "cases/648abdcdbda662768e995206f/
externallmg_r_1687241759296_IMG20230618154928.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64914420ff2e4a17ce87c39f",
  "name": "externallmg_r_1687241759304_IMG20230618154938.jpg",
  "path": "cases/648abdcdbda662768e995206f/
externallmg_r_1687241759304_IMG20230618154938.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64914420ff2e4a17ce87c3a0",
  "name": "externallmg_r_1687241759422_IMG20230619011348.jpg",
  "path": "cases/648abdcdbda662768e995206f/
externallmg_r_1687241759422_IMG20230619011348.jpg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64914420ff2e4a17ce87c3a1",
      "name": "externalImg_r_1687241759307_IMG20230619011329.jpg",
      "path": "cases/648abfdbda662768e995206f/
externalImg_r_1687241759307_IMG20230619011329.jpg",
      "orientation": "portrait"
    }
  ],
  "externalDocuments": [],
  "createdAt": "2023-06-15T07:25:15.495Z",
  "updatedAt": "2023-06-21T06:46:14.021Z",
  "__v": 0,
  "fullAddress": "Residential Flat No. 202, 2nd Floor, Wing - A, Sohini Apartments Co-op.
Hsg. Soc. Ltd., Vakola, Datta Mandir Road, Village - Kolekalyan, Municipality Ward No.
H-East, District - Mumbai, Santacruz (East), 400 055, State - Maharashtra, India",
  "updatedBy": "5fc78e26625ecd20ec1f88e9",
  "addressForMap": "",
  "caseReferredBy": "60af6ae22ffdf65bcd65861d",
  "contactPersonName": "Mr. Yash Salvi ",
  "email": "",
  "isExternal": "false",
  "isUrgent": "false",
  "ownershipShare": "",
  "purchaseValueAsPerDocument": "",
  "relationWithOwner": "Owner's Son",
  "siteVisitContactNo": "9892275149",
  "reason": "",
  "siteVisitDate": "2023-06-19",
  "briefDescOfProperty": "1 Bedroom + Living Room + Passage + WC + Bathroom",
  "carpetTotal": "345.63",
  "finalMeasurementType": "Sq. Ft.",
  "otherCarpetTotal": "0.00",
  "builtupPercentage": "10",
  "finalBuiltupArea": "380.19",
  "finalCarpetArea": "345.63",
  "finalSalableArea": "418.21",
  "salablePercentage": "10",
  "toBeAdded": "",
  "extendOfSiteRemark": "",
  "siteMeasurementRemark": "",
  "finalAreaType": "Built Up Area",
  "finalAsPerArea": "Agreement For Sale",
  "finalBuiltUpPercentage": "10",
```

"finalCarpetConvertToBuiltUpPer": "10",
 "finalSaleablePercentage": "0",
 "finalValuationAreaString": "Built Up Area in Sq. Ft. = 444.00",
 "buildingServicesRate": "3000",
 "flatRate": "19500",
 "landOtherRate": "16500",
 "otherCompositionBuiltUpTotal": "0.00",
 "otherCompositionCarpetTotal": "0.00",
 "otherCompositionSaleableTotal": "0.00"

}

Name	Length	Width	Total
Composition :			
Living Room	9'8"	20'7"	198.97
Passage	6'10"	2'8"	18.22
WC	2'10"	3'9"	10.62
Bathroom	3'3"	6'3"	20.31
Bedroom	9'11"	9'10"	97.51
Other Composition :			