

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9ff"
    },
    "type": "CREDITOFFICER",
    "_id": "635f7d78e363ef22db2f2888",
    "firstName": "Amita ",
    "lastName": "Patel",
    "mobileNo": "",
    "email": "me2@me.com",
    "workMobileNo": "8691048841"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "36450000",
    "discussWithPerson": "Amita ",
    "expectedFees": 18225,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
    "city": "Mumbai"
  }
}
```

```
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9ff",
  "branchCode": "000220",
  "type": "BRANCH",
  "name": "RASMECCC Panvel",
  "email": "cord.21117@sbi.co.in",
  "mobileNo": "02227572748",
  "alternateMobileNo": "",
  "address": "Shop No 5,Ground Floor,Sharda Terrace, Plot No 65,Sector-11,CBD
Belapur, Navi Mumbai, Taluka & District - Thane, State - Maharashtra, Country - India",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7189d2ffdf65bcd65882b",
    "role": "PICKUPPERSON",
    "firstName": "Ravindra",
    "email": "ravindrakasare186@gmail.com",
    "lastName": "Kasare",
    "mobileNo": "9167204055",
    "shortName": "RBK",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users\\60b7189d2ffdf65bcd65882b\
\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "640c34384dda382753e651f2",
  "role": "SITEENGINEER",
  "firstName": "PRASHANT ",
  "email": "kasarprashant121@gmail.com",
  "lastName": "KASAR",
  "mobileNo": "9892524464",
  "designation": "",
  "shortName": "PK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/640c34384dda382753e651f2/
profilePhoto_1678521400647_WhatsApp_Image_20230311_at_12047_PM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER+CHECKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
  "lastName": "Bodke",
  "mobileNo": "9821740317",
  "designation": "",
  "shortName": "SB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
```

```
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER+CHECKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    }
  ],
}
```

```
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.213919",
  "longitude": "73.142137"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.142137,
    19.213919
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-06-16T04:30:00.000Z",
```

```
    "remark": ""
  },
  {
    "dateTime": "2023-06-16T04:30:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-06-16T04:30:00.000Z",
    "remark": ""
  }
],
"visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Fri Jun 16 2023 10:05:33 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Chinchpada",
    "label": true
  }
}
```

```
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "6",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Kalyan (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Ambernath",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
```

```
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Vaishnavi Heights Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Pada Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
}
```



```
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "20",
  "label": true
},
"hissaNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "22",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
```

```
"value": "608",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
```

```
"status": true,
"name": "Postal Code",
"key": "postalCode",
"value": "421 306",
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills",
    "label": "Powder coated Aluminum sliding windows with M. S. Grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
}
```

```
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "Kalyan_Dombivali_Municipal_Corporation",
  "label": "Kalyan Dombivali Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Slum Area ",
  "west": "Pada Road",
  "south": "Open Plot",
  "east": "Open Plot"
},
"asPerDocumentAgreement": {
  "north": "Vaishnavi Apartment",
  "west": "Open Plot",
  "south": "Open Plot",
  "east": "Open Plot"
},
"extraDetailOfProperty": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  }
}
```

```
},
"propertyOccupiedByList": {
  "value": "Owner_Occupied",
  "label": "Owner Occupied"
},
"monthlyRent": "5,000",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per KDMC norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\\_Thk._Brick_Masonry",
    "label": "6\\ Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": {
    "value": "Stilt_Parking",
    "label": "Stilt Parking"
  },
  "constructionWorkStatus": {
```

```
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2020",
"fullDate": "1/1/2020"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C._Framed_Structure",
"label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
"materialUsedList": {
"value": "Good",
"label": "Good"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Good",
"label": "Good"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
```

```
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceIssues": {
"value": "Information_not_available",
"label": "Information not available"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "stilt",
"label": "Stilt"
},
"yearOfConstructionAsPer": {
"value": "as_per_site_information",
"label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "57",
"ageOfBuilding": "3",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
```

```
"noOfFloors": "7",
"flatFloorNo": "6",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "10"
},
"finalPlinthArea": {
  "area": "496.10",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/648b19b8719c32253ddd4185/
routeMap_1686908742412_Image.png",
    "routeLat": "19.213919",
    "routeLng": "73.142137",
    "stationName": "Vithalwadi ",
    "routeDistance": "2.8 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "ykazz07",
      "name": "ykazz07",
      "image": "cases/648b19b8719c32253ddd4185/
routeMap_1686908662589_Image.png"
    }
  ]
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
```



```
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0.00",
  "selectedBuildUpValue": "496.10",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "648c2f6e07df79469f3fb0bd",
      "name": "externalimg_1686908782231_IMG20230616WA0005.jpg",
      "path": "cases/648b19b8719c32253ddd4185/
externalimg_1686908782231_IMG20230616WA0005.jpg",
```

```
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [
  {
    "status": false,
    "_id": "648c2f6e07df79469f3fb0bf",
    "name": "externallmg_1686908782239_IMG20230616WA0007.jpg",
    "path": "cases/648b19b8719c32253ddd4185/
externallmg_1686908782239_IMG20230616WA0007.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "648c2f6e07df79469f3fb0bc",
    "name": "externallmg_1686908782229_IMG20230616WA0004.jpg",
    "path": "cases/648b19b8719c32253ddd4185/
externallmg_1686908782229_IMG20230616WA0004.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "648c2f7c07df79469f3fb127",
    "name": "externallmg_1686908795717_IMG20230616WA0019.jpg",
    "path": "cases/648b19b8719c32253ddd4185/
externallmg_1686908795717_IMG20230616WA0019.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "648c2f7c07df79469f3fb128",
    "name": "externallmg_1686908795722_IMG20230616WA0020.jpg",
    "path": "cases/648b19b8719c32253ddd4185/
externallmg_1686908795722_IMG20230616WA0020.jpg",
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "648c2f6e07df79469f3fb0be",
    "name": "externallmg_1686908782235_IMG20230616WA0006.jpg",
    "path": "cases/648b19b8719c32253ddd4185/
externallmg_1686908782235_IMG20230616WA0006.jpg",
```

```
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "648c2f6e07df79469f3fb0c0",
    "name": "Terrace Area",
    "path": "cases/648b19b8719c32253ddd4185/
externallmg_1686908782240_IMG20230616WA0008.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "648c2f7c07df79469f3fb126",
    "name": "Living Room",
    "path": "cases/648b19b8719c32253ddd4185/
externallmg_1686908795714_IMG20230616WA0018.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "648c2f6e07df79469f3fb0c2",
    "name": "Bedroom",
    "path": "cases/648b19b8719c32253ddd4185/
externallmg_1686908782246_IMG20230616WA0010.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "648c2f6e07df79469f3fb0bb",
    "name": "Bedroom",
    "path": "cases/648b19b8719c32253ddd4185/
externallmg_1686908782223_IMG20230616WA0003.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "648c2f6e07df79469f3fb0b9",
    "name": "Living Room",
    "path": "cases/648b19b8719c32253ddd4185/
externallmg_1686908782214_IMG20230616WA0001.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
```

```
    "_id": "648c2f6e07df79469f3fb0ba",
    "name": "Kitchen",
    "path": "cases/648b19b8719c32253ddd4185/
externallmg_1686908782217_IMG20230616WA0002.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
```

```
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "451.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "Draft_Completed",
"_id": "648b19b8719c32253ddd4185",
"ownerName": "Mrs. Sharmila Vinod Mulamootil & Mr. Vinod Kuttappai Mulamootil",
"ownerPhoneNo": "8983538619",
"appAddress": "flat no 608 6 th floor vaishnavi Heights chinchpada Ambernath ",
```



```
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "05/11/2020",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Vaishnavi Developers",
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      },
      "Allottee": "Mrs. Sharmila Vinod Mulamootil & Mr. Vinod Kuttappai Mulamootil"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "469914",
    "path": "cases/648b19b8719c32253ddd4185/
document_1686889970306_Doc_May_29_2023.pdf",
    "fileName": "document_1686889970306_Doc_May_29_2023.pdf"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    },
    "inputs": {
      "documentDate": "14/11/2019",
      "nameOfApprovingAuthority": {
        "value": "Kalyan_Dombivli_Mahanagarpalika",
        "label": "Kalyan Dombivli Mahanagarpalika"
      },
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "KDMC / NRV / BP / 27 Village / 2019-20 / 13"
    },
    "isHardCopy": false,
    "displayStatus": false,
  }
]
```

```
"fileName": "document_1686905698712_1_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
"path": "cases/648b19b8719c32253ddd4185/document_1686905698712_1_Commencement_Certificates___NA_Order_for_plotted_development.pdf",
"id": "476070",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Fri Jun 16 2023 14:29:55 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "08/09/2021",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "Registration_No",
      "label": "Registration No"
    },
    "Registration_No": "P51700023882"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1686905884812_P51700023882.pdf",
  "path": "cases/648b19b8719c32253ddd4185/document_1686905884812_P51700023882.pdf",
  "id": "257400",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Fri Jun 16 2023 14:29:55 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "14/11/2019",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Mahanagarpalika",
      "label": "Kalyan Dombivli Mahanagarpalika"
    },
    "number": {
```

```
    "value": "No",
    "label": "No"
  },
  "No": "KDMC / NRV / BP / 27 Village / 2019-20 / 13"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1686905991204_2_Building_Plan_Approval___NA_Order_f
or_plotted_development.pdf",
"path": "cases/648b19b8719c32253ddd4185/document_1686905991204_2_Buildin
g_Plan_Approval___NA_Order_for_plotted_development.pdf",
"id": "662516",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Fri Jun 16 2023 14:29:55 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "001982",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "160133",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Jun 15 2023 19:31:28 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Sharmila Vinod Mulamootil & Mr. Vinod Kuttappai Mulamootil",
    "phone": "8983538619",
    "email": "",
    "ownershipShare": "",
    "id": "605552"
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "875909",
    "name": "Living Room",
    "length": "9.75",
    "length1": "9",
```

```
"length2": "9",
"width": "12.00",
"width1": "12",
"width2": "0",
"totalArea": "117.00",
"images": [],
"extraAreas": [],
"finalArea": "117.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Dining",
  "length": "7.33",
  "length1": "7",
  "length2": "4",
  "width": "7.42",
  "width1": "7",
  "width2": "5",
  "totalArea": "54.39",
  "images": [],
  "extraAreas": [],
  "finalArea": "54.39"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "6.42",
  "length1": "6",
  "length2": "5",
  "width": "8.58",
  "width1": "8",
  "width2": "7",
  "totalArea": "55.08",
  "images": [],
  "extraAreas": [],
  "finalArea": "55.08"
},
{
  }
```

```
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "3",
"name": "Passage",
"length": "2.08",
"length1": "2",
"length2": "1",
"width": "4.00",
"width1": "4",
"width2": "0",
"totalArea": "8.33",
"images": [],
"extraAreas": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "_id": "648c2b7d07df79469f3fa8b0",
    "name": "Passage 1",
    "extraAreaType": "Add",
    "length": "1.08",
    "length1": "1",
    "length2": "1",
    "width": "6.00",
    "width1": "6",
    "width2": "0",
    "totalArea": "6.50"
  }
],
"finalArea": "14.83"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "9.00",
  "length1": "9",
  "length2": "0",
  "width": "10.00",
  "width1": "10",
```

```
"width2": "00",
"totalArea": "90.00",
"images": [],
"extraAreas": [],
"finalArea": "90.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "3.08",
  "length1": "3",
  "length2": "1",
  "width": "7.00",
  "width1": "7",
  "width2": "00",
  "totalArea": "21.58",
  "images": [],
  "extraAreas": [],
  "finalArea": "21.58"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "9.00",
  "length1": "9",
  "length2": "00",
  "width": "9.00",
  "width1": "9",
  "width2": "00",
  "totalArea": "81.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "81.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  }
}
```

```
},
  "id": "7",
  "name": "Terrace Area",
  "length": "5.08",
  "length1": "5",
  "length2": "1",
  "width": "9.00",
  "width1": "9",
  "width2": "0",
  "totalArea": "45.75",
  "images": [],
  "extraAreas": [],
  "finalArea": "45.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Toilet",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "7.00",
  "width1": "7",
  "width2": "00",
  "totalArea": "28.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "28.00"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "value": "Flowerbed",
      "label": "Flowerbed"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  }
]
```

```
},
  "id": "0",
  "length1": "9",
  "length2": "8",
  "length": "9.67",
  "width1": "2",
  "width2": "4",
  "width": "2.33",
  "totalArea": "22.56",
  "percentageBeforeTotal": "22.56",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "22.56"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "value": "Flowerbed",
    "label": "Flowerbed"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length1": "6",
  "length2": "8",
  "length": "6.67",
  "width1": "2",
  "width2": "4",
  "width": "2.33",
  "totalArea": "15.56",
  "percentageBeforeTotal": "15.56",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "15.56"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  }
}
```



```
},
"name": {
  "value": "Flowerbed",
  "label": "Flowerbed"
},
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"length1": "9",
"length2": "00",
"length": "9.00",
"width1": "2",
"width2": "00",
"width": "2.00",
"totalArea": "18.00",
"percentageBeforeTotal": "18.00",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "18"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "556484",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "451",
    "squareMeterArea": "41.9",
    "docFinalBuiltUp": "496.1",
    "docFinalBuiltUpSquareMeter": "46.089999999999996",
    "docBuiltupPercentage": "10",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
]
```

```
],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648c2f6e07df79469f3fb0b8",
    "name": "externalImg_1686908782211_IMG20230616WA0000.jpg",
    "path": "cases/648b19b8719c32253ddd4185/
externalImg_1686908782211_IMG20230616WA0000.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648c2f6e07df79469f3fb0b9",
    "name": "externalImg_1686908782214_IMG20230616WA0001.jpg",
    "path": "cases/648b19b8719c32253ddd4185/
externalImg_1686908782214_IMG20230616WA0001.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648c2f6e07df79469f3fb0ba",
    "name": "externalImg_1686908782217_IMG20230616WA0002.jpg",
    "path": "cases/648b19b8719c32253ddd4185/
externalImg_1686908782217_IMG20230616WA0002.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648c2f6e07df79469f3fb0bb",
    "name": "externalImg_1686908782223_IMG20230616WA0003.jpg",
    "path": "cases/648b19b8719c32253ddd4185/
externalImg_1686908782223_IMG20230616WA0003.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648c2f6e07df79469f3fb0bc",
    "name": "externalImg_1686908782229_IMG20230616WA0004.jpg",
    "path": "cases/648b19b8719c32253ddd4185/
externalImg_1686908782229_IMG20230616WA0004.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648c2f6e07df79469f3fb0bd",
  "name": "externallmg_1686908782231_IMG20230616WA0005.jpg",
  "path": "cases/648b19b8719c32253ddd4185/
externallmg_1686908782231_IMG20230616WA0005.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648c2f6e07df79469f3fb0be",
  "name": "externallmg_1686908782235_IMG20230616WA0006.jpg",
  "path": "cases/648b19b8719c32253ddd4185/
externallmg_1686908782235_IMG20230616WA0006.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648c2f6e07df79469f3fb0bf",
  "name": "externallmg_1686908782239_IMG20230616WA0007.jpg",
  "path": "cases/648b19b8719c32253ddd4185/
externallmg_1686908782239_IMG20230616WA0007.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648c2f6e07df79469f3fb0c0",
  "name": "externallmg_1686908782240_IMG20230616WA0008.jpg",
  "path": "cases/648b19b8719c32253ddd4185/
externallmg_1686908782240_IMG20230616WA0008.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648c2f6e07df79469f3fb0c1",
  "name": "externallmg_1686908782243_IMG20230616WA0009.jpg",
  "path": "cases/648b19b8719c32253ddd4185/
externallmg_1686908782243_IMG20230616WA0009.jpg",
  "orientation": "portrait"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648c2f6e07df79469f3fb0c2",
    "name": "externallmg_1686908782246_IMG20230616WA0010.jpg",
    "path": "cases/648b19b8719c32253ddd4185/
externallmg_1686908782246_IMG20230616WA0010.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648c2f6e07df79469f3fb0c3",
    "name": "externallmg_1686908782248_IMG20230616WA0011.jpg",
    "path": "cases/648b19b8719c32253ddd4185/
externallmg_1686908782248_IMG20230616WA0011.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648c2f7c07df79469f3fb120",
    "name": "externallmg_1686908795689_IMG20230616WA0012.jpg",
    "path": "cases/648b19b8719c32253ddd4185/
externallmg_1686908795689_IMG20230616WA0012.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648c2f7c07df79469f3fb121",
    "name": "externallmg_1686908795691_IMG20230616WA0013.jpg",
    "path": "cases/648b19b8719c32253ddd4185/
externallmg_1686908795691_IMG20230616WA0013.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648c2f7c07df79469f3fb122",
    "name": "externallmg_1686908795699_IMG20230616WA0014.jpg",
    "path": "cases/648b19b8719c32253ddd4185/
externallmg_1686908795699_IMG20230616WA0014.jpg",
    "orientation": "portrait"
  },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648c2f7c07df79469f3fb123",
  "name": "externallmg_1686908795703_IMG20230616WA0015.jpg",
  "path": "cases/648b19b8719c32253ddd4185/
externallmg_1686908795703_IMG20230616WA0015.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648c2f7c07df79469f3fb124",
  "name": "externallmg_1686908795706_IMG20230616WA0016.jpg",
  "path": "cases/648b19b8719c32253ddd4185/
externallmg_1686908795706_IMG20230616WA0016.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648c2f7c07df79469f3fb125",
  "name": "externallmg_1686908795709_IMG20230616WA0017.jpg",
  "path": "cases/648b19b8719c32253ddd4185/
externallmg_1686908795709_IMG20230616WA0017.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648c2f7c07df79469f3fb126",
  "name": "externallmg_1686908795714_IMG20230616WA0018.jpg",
  "path": "cases/648b19b8719c32253ddd4185/
externallmg_1686908795714_IMG20230616WA0018.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648c2f7c07df79469f3fb127",
  "name": "externallmg_1686908795717_IMG20230616WA0019.jpg",
  "path": "cases/648b19b8719c32253ddd4185/
externallmg_1686908795717_IMG20230616WA0019.jpg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648c2f7c07df79469f3fb128",
    "name": "externalImg_1686908795722_IMG20230616WA0020.jpg",
    "path": "cases/648b19b8719c32253ddd4185/
externalImg_1686908795722_IMG20230616WA0020.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648c2f7c07df79469f3fb129",
    "name": "externalImg_1686908795728_IMG20230616WA0021.jpg",
    "path": "cases/648b19b8719c32253ddd4185/
externalImg_1686908795728_IMG20230616WA0021.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648c2f7c07df79469f3fb12a",
    "name": "externalImg_1686908795733_IMG20230616WA0022.jpg",
    "path": "cases/648b19b8719c32253ddd4185/
externalImg_1686908795733_IMG20230616WA0022.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648c2f7c07df79469f3fb12b",
    "name": "externalImg_1686908795745_IMG20230616WA0023.jpg",
    "path": "cases/648b19b8719c32253ddd4185/
externalImg_1686908795745_IMG20230616WA0023.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-06-15T14:01:28.759Z",
"updatedAt": "2023-06-16T09:51:27.112Z",
"__v": 0,
"fullAddress": "Residential Flat No. 608, 6th Floor, Vaishnavi Heights Co-op. Hsg. Soc.
Ltd., Pada Road, Village - Chinchpada, Taluka - Ambarnath, District - Thane, Kalyan
(East), 421 306, State - Maharashtra, India",
"updatedBy": "60eebe33f3dd69653a5837ae",
"addressForMap": "",
"caseReferredBy": "",
```

"contactPersonName": "Mrs. Sharmila Vinod Mulamootil",  
 "email": "",  
 "isExternal": "false",  
 "isUrgent": "false",  
 "ownershipShare": "",  
 "purchaseValueAsPerDocument": "",  
 "relationWithOwner": "Self",  
 "siteVisitContactNo": "9820163486",  
 "briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Dining + Passage + 2  
 Toilet + Terrace Area",  
 "carpetTotal": "479.63",  
 "finalMeasurementType": "Sq. Ft.",  
 "otherCarpetTotal": "18.00",  
 "otherCompositionBuiltUpTotal": "0.00",  
 "otherCompositionCarpetTotal": "56.12",  
 "otherCompositionSaleableTotal": "0.00",  
 "builtupPercentage": "10",  
 "finalBuiltupArea": "620.12",  
 "finalCarpetArea": "563.75",  
 "finalSalableArea": "682.14",  
 "salablePercentage": "10",  
 "toBeAdded": "",  
 "extendOfSiteRemark": "",  
 "siteMeasurementRemark": "",  
 "finalAreaType": "Carpet Area",  
 "finalAsPerArea": "Agreement for sale",  
 "finalBuiltUpPercentage": "10",  
 "finalCarpetConvertToBuiltUpPer": "10",  
 "finalSaleablePercentage": "0",  
 "finalValuationAreaString": "Carpet Area in Sq. Ft. = 451.00",  
 "reason": ""

Name	Length	Width	Total
Composition :			
Living Room	9'9"	12'0"	117.00
Dining	7'4"	7'5"	54.39
Kitchen	6'5"	8'7"	55.08
Passage	2'1"	4'0"	8.33
Bedroom	9'0"	10'00"	90.00
Toilet	3'1"	7'00"	21.58

Bedroom	9'00"	9'00"	81.00
Terrace Area	5'1"	9'0"	45.75
Toilet	4'00"	7'00"	28.00
Other Composition :			
Flowerbed	9'8"	2'4"	22.56
Flowerbed	6'8"	2'4"	15.56
Flowerbed	9'00"	2'00"	18.00