

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856ba28"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b9423124f",
    "firstName": "Santosh Vaidya",
    "email": "0_default_",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-8452048541"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "4500000",
    "discussWithPerson": "Santosh Vaidya",
    "expectedFees": 2250,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "VCIPL Mumbai",
    "shortName": "VCIPLM",
    "email": "vastukalamumbai@vastukala.com",
    "address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
    "city": "Mumbai"
  }
}
```

```
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856ba28",
  "branchCode": "000240",
  "type": "BRANCH",
  "name": "RACPC - Santacruz (West)",
  "email": "cord1.racpcbkc@sbi.co.in",
  "mobileNo": "022-26719265",
  "alternateMobileNo": "",
  "address": "1st Floor, Jeevan Seva Annex Bldg., LIC Complex, S. V. Road, Santacruz
(West), Mumbai - 400 054, State - Maharashtra, Country - India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
    "role": "PICKUPPERSON",
    "firstName": "Sunil",
    "email": "misalsunil87@gmail.com",
    "lastName": "Misal",
    "mobileNo": "8422982721",
    "shortName": "SM",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af6ae22ffdf65bcd65861d\
\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "627208c1afd7d55eddedc372",
  "role": "SITEENGINEER+MAKAR",
  "firstName": "Aniket",
  "email": "aniket@vastukala.org",
  "lastName": "Navale",
  "mobileNo": "9892222307",
  "designation": "",
  "shortName": "AN",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627208c1afd7d55eddedc372/
profilePhoto_1667995077581_WhatsApp_Image_20221109_at_52453_PM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER+CHECKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shyma_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER+CHECKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shyma_Photo.jpg"
},
```

```

"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "0123456789",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    }
  ],

```

```
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.220489",
  "longitude": "72.869132"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.869132,
    19.220489
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-06-16T07:00:00.000Z",
```

```
"remark": ""
},
{
  "dateTime": "2023-06-16T07:00:00.000Z",
  "remark": ""
},
{
  "dateTime": "2023-06-16T07:00:00.000Z",
  "remark": ""
},
{
  "dateTime": "2023-06-16T07:00:00.000Z",
  "remark": ""
},
{
  "dateTime": "2023-06-16T07:00:00.000Z",
  "remark": ""
},
{
  "dateTime": "2023-06-16T07:00:00.000Z",
  "remark": ""
}
],
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2023-06-17T06:48:33.079Z",
    "remark": ""
  },
  {
    "status": "COMPLETED",
    "dateTime": "2023-06-17T06:48:46.380Z",
    "remark": ""
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "0",
  "lumpsumValue": "0",
  "rateMax": "0",
  "areaType": {
    "Name": "Carpet",
    "Value": "Carpet",
    "name": "Carpet",
```

```
    "value": "Carpet"
  }
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Fri Jun 16 2023 12:28:17 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Magathane",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "4",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "3A, MHADA Building",
```

```
"label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai Suburban",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Swami Co-op. Hsg. Soc. Ltd., Magathane",
  "label": false
},
"selectArea": {
  "status": false,
```



```
"name": "Sector",
"key": "selectArea",
"value": "",
"label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
}
```

```
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "183(Part), 184(Part), 185(Part), 186(Part), 187(Part), 197(Part) & 201
(Part)",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "401",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
```

```
"name": "Khata No",
"key": "khataNo",
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400066",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Borivali East",
  "label": false
}
```

```
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Ceramic Tile Flooring",
    "value": "CeramicTileFlooring"
  },
  "doors": {
    "label": "Teak Wood Door frame with Solid door with safety door",
    "value": "Teak_Wood_Door_frame_with_Solid_door_with_safety_door"
  },
  "windows": {
    "label": "Aluminium Sliding Window ",
    "value": "Aluminium_Sliding_Window_"
  },
  "fittings": {
    "value": "Open-Conduit_plumbing_with_Casing_Capping_Electrical_wiring_",
    "label": "Open-Conduit plumbing with Casing Capping Electrical wiring "
  },
  "finishing": {
    "label": "Normal",
    "value": "Normal"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Municipal Corporation of Greater Mumbai (MCGM)",
    "value": "MCGM"
  },
  "whetherCoveredUnderAnyState": {
```

```
"value": "Yes",
"label": "Yes"
},
"asPerActualAgreement": {
  "north": "Garden",
  "west": "Road / Building No. 14",
  "south": "Trimurti CHSL",
  "east": "MHADA Society "
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"extraDetailOfProperty": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "12",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "20",
  "depreciatedCostOfConstruction": "19700",
  "depreciatedBuildingRate": "2200"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "156390",
  "landRate": "69980",
  "igrImage": "cases/648bfa82719c32253ddd8d12/igr_1687158519263_Image.png",
  "squareMeterGuideLineRate": "156390.00",
  "squareFeetGuideLineRate": "14529.00"
},
"igrFinalRate": {
  "rate": "13807.00",
  "squareFeetGuideLineRate": "13807.00",
  "squareMeterGuideLineRate": "148613.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  }
}
```

```
},
"propertyOccupiedByList": {
  "label": "Seller Occupied",
  "value": "Seller_Occupied"
},
"monthlyRent": "11,000.00",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Details not available"
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "No",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  },
  "pavementLaid": {
    "label": "Yes",
    "value": "Yes"
  },
  "carParking": {
    "label": "Open Car Parking",
    "value": "Open_Car_Parking"
  },
  "constructionWorkStatus": {
```

```
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2014",
"fullDate": "1/1/2014"
},
"propertyTypeList": {
"value": "Residential",
"label": "Residential"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"label": "R.C.C. Framed Structure",
"value": "R.C.C._Framed_Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"label": "Normal",
"value": "Normal"
},
"materialUsedList": {
"value": "Good",
"label": "Good"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Good",
"label": "Good"
},
"protAgainstNatDis": {
```

```
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"label": "Yes",
"value": "1"
},
"appearanceOfTheBuilding": {
"value": "Normal",
"label": "Normal"
},
"maintenanceOfTheBuilding": {
"label": "Normal",
"value": "Normal"
},
"maintenanceIssues": {
"value": "1",
"label": "Yes"
},
"visibleDamageInBuilding": {
"label": "No",
"value": "0"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"label": "Ground",
"value": "ground"
},
"yearOfConstructionAsPer": {
"value": "as_per_occupancy_certificate",
"label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "51",
```



```
"ageOfBuilding": "9",
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "7",
"flatFloorNo": "4",
"noOfLifts": "1",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "323.18",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/648bfa82719c32253ddd8d12/
routeMap_1687158671330_Image.png",
    "routeLat": "19.220500",
    "routeLng": "72.869139",
    "stationName": "Borivali",
    "routeDistance": "2.4"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finalLatLng": true
  },
  "locationMapImg": [
    {
      "id": "gkwn59",
      "name": "gkwn59",
      "image": "cases/648bfa82719c32253ddd8d12/
routeMap_1687158682550_Image.png"
    }
  ]
}
```

```
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "5299300.00",
  "bookValue": "0",
  "finalValue": "5299300.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEM_GENERATED",
  "date": "Mon Jun 19 2023 12:47:37 GMT+0530 (India Standard Time)",
  "number": "046972",
  "dayCount": "10",
  "monthCount": "149",
  "generatedBy": "60eeaeddf3dd69653a581316"
},
"rateVerify": {
  "status": false
},
}
```

```
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "4462146.00",
  "selectedBuildUpValue": "323.18",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6490000f8e00593b1af09cb8",
      "name":
"externallmg_1687158798229_WhatsApp_Image_20230617_at_143715.jpeg",
      "path": "cases/648bfa82719c32253ddd8d12/
externallmg_1687158798229_WhatsApp_Image_20230617_at_143715.jpeg",
      "orientation": "portrait"
    }
  ],
}
```

```
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "6490000f8e00593b1af09cba",
    "name":
"externallmg_1687158798272_WhatsApp_Image_20230617_at_143718.jpeg",
    "path": "cases/648bfa82719c32253ddd8d12/
externallmg_1687158798272_WhatsApp_Image_20230617_at_143718.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "6490000f8e00593b1af09cb8",
    "name":
"externallmg_1687158798229_WhatsApp_Image_20230617_at_143715.jpeg",
    "path": "cases/648bfa82719c32253ddd8d12/
externallmg_1687158798229_WhatsApp_Image_20230617_at_143715.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6490000f8e00593b1af09cbb",
    "name":
"externallmg_1687158798280_WhatsApp_Image_20230617_at_143719_1.jpeg",
    "path": "cases/648bfa82719c32253ddd8d12/
externallmg_1687158798280_WhatsApp_Image_20230617_at_143719_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6490000f8e00593b1af09cbe",
    "name":
"externallmg_1687158798306_WhatsApp_Image_20230617_at_143720.jpeg",
    "path": "cases/648bfa82719c32253ddd8d12/
externallmg_1687158798306_WhatsApp_Image_20230617_at_143720.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6490000f8e00593b1af09cb9",
    "name":
"externallmg_1687158798260_WhatsApp_Image_20230617_at_143717.jpeg",
    "path": "cases/648bfa82719c32253ddd8d12/
externallmg_1687158798260_WhatsApp_Image_20230617_at_143717.jpeg",
```

```
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "6490000f8e00593b1af09cbf",
    "name":
"externallmg_1687158798315_WhatsApp_Image_20230617_at_143721.jpeg",
    "path": "cases/648bfa82719c32253ddd8d12/
externallmg_1687158798315_WhatsApp_Image_20230617_at_143721.jpeg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "6490000f8e00593b1af09cb2",
    "name": "Living Room",
    "path": "cases/648bfa82719c32253ddd8d12/
externallmg_1687158798155_compositionlmg_r_1686983064933_image.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6490000f8e00593b1af09cb4",
    "name": "Bedroom",
    "path": "cases/648bfa82719c32253ddd8d12/
externallmg_1687158798187_compositionlmg_r_1686983177241_image.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6490000f8e00593b1af09cb3",
    "name": "Kitchen",
    "path": "cases/648bfa82719c32253ddd8d12/
externallmg_1687158798170_compositionlmg_r_1686983120091_image.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
```

```
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```



```
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": true,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "269.32",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "DELIVERED",
"_id": "648bfa82719c32253ddd8d12",
"ownerName": "Mr. Ritesh B. Rane & Mrs. Rupali Ritesh Rane",
"ownerPhoneNo": "9702813389",
"appAddress": "Flat no.401,4 th floor, Swami Co-op HSG Soc Ltd,Bldg no - A-3 ,
MHADA Bldg, Magathane Borivali East Mumbai- 400066",
"remark": "Rupali Rane - 8652565790",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    }
  },
  "inputs": {
    "documentDate": "09/06/2023",
```

```
"amount": "4500000",
"from": {
  "value": "Seller",
  "label": "Seller"
},
" Seller": "Ms. Geetanjali Gajanan Shirke nee Mrs. Geetanjali Ganesh Kadam",
"to": {
  "value": "purchaser",
  "label": "purchaser"
},
"purchaser": "Mr. Ritesh B. Rane & Mrs. Rupali Ritesh Rane"
},
"isHardCopy": false,
"displayStatus": false,
"id": "267192",
"path": "cases/648bfa82719c32253ddd8d12/document_1686895172336_Ritesh_Ran__Rupali_Rane_SBI_Racpc_Santacruz_West.pdf",
"fileName": "document_1686895172336_Ritesh_Ran__Rupali_Rane_SBI_Racpc_Santacruz_West.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "14/03/2014",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CHE / 610 / BPWS / AR"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "454332",
  "path": "cases/648bfa82719c32253ddd8d12/document_1687152432545_306309.pdf"
}
],
"caseNumber": "001986",
"createdBy": "60af6ae22ffdf65bcd65861d",
```

```
"caseHistory": [
  {
    "id": "680757",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Jun 16 2023 11:30:34 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Ritesh B. Rane & Mrs. Rupali Ritesh Rane",
    "phone": "9702813389",
    "ownershipShare": "",
    "email": "",
    "id": "131635"
  }
],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Other",
      "value": "Other"
    },
    "_id": "648d554d07df79469f406a3e",
    "area": "259.63",
    "providedByName": "Site Visit æ`ormation ",
    "providedByContactNo": "0000000000"
  }
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "652410",
    "name": "Living Room",
    "length": "8.25",
    "length1": "8",
    "length2": "3",
    "width": "10.75",
    "width1": "10",
```

```
"width2": "9",
"totalArea": "88.69",
"images": [
  {
    "path": "cases/648bfa82719c32253ddd8d12/
compositionImg_r_1686983064933_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "88.69"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "6.50",
  "length1": "6",
  "length2": "6",
  "width": "8.25",
  "width1": "8",
  "width2": "3",
  "totalArea": "53.62",
  "images": [
    {
      "path": "cases/648bfa82719c32253ddd8d12/
compositionImg_r_1686983120091_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "53.62"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "9.75",
  "length1": "9",
  "length2": "9",
```

```
"width": "8.25",
"width1": "8",
"width2": "3",
"totalArea": "80.44",
"images": [
  {
    "path": "cases/648bfa82719c32253ddd8d12/
compositionImg_r_1686983177241_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "80.44"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "3.58",
  "length1": "3",
  "length2": "7",
  "width": "3.83",
  "width1": "3",
  "width2": "10",
  "totalArea": "13.74",
  "images": [
    {
      "path": "cases/648bfa82719c32253ddd8d12/
compositionImg_r_1686983228483_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "13.74"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Bathroom",
  "length": "3.50",
```

```
"length1": "3",
"length2": "6",
"width": "3.42",
"width1": "3",
"width2": "5",
"totalArea": "11.96",
"images": [
  {
    "path": "cases/648bfa82719c32253ddd8d12/
compositionImg_r_1686983299847_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "11.96"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "W.C",
  "length": "3.83",
  "length1": "3",
  "length2": "10",
  "width": "2.92",
  "width1": "2",
  "width2": "11",
  "totalArea": "11.18",
  "images": [
    {
      "path": "cases/648bfa82719c32253ddd8d12/
compositionImg_r_1686983337759_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "11.18"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
```

```
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "300265",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "269.32",
  "squareMeterArea": "25.02",
  "docFinalBuiltUp": "323.18399999999997",
  "docFinalBuiltUpSquareMeter": "30.024",
  "docBuiltupPercentage": "20",
  "docSaleablePercentage": "20",
  "docFinalSaleable": "387.82079999999996",
  "docFinalSaleableSquareMeter": "36.028800000000004"
}
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "648feb111b499c2d52dcb43d",
    "id": "1",
    "property": "Residential Flat",
    "area": "270",
    "builtUpPercentage": "20",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "",
    "source": "square_yards",
    "expectedPrice": "6000000",
    "expectedRate": "22222.22",
    "builtUpExpectedRate": "18518.52",
    "image": "cases/648bfa82719c32253ddd8d12/
indicator_1687153425500_Image.png"
  },
  {
    "printlnReport": true,
    "_id": "648feb461b499c2d52dcb463",
    "id": "2",
    "property": "Residential Flat",
    "area": "325",
    "builtUpPercentage": "20",
```



```
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "square_yards",
"expectedPrice": "6000000",
"expectedRate": "18461.54",
"builtUpExpectedRate": "6000000",
"image": "cases/648bfa82719c32253ddd8d12/
indicator_1687153478745_Image.png"
},
{
  "printlnReport": true,
  "_id": "64901aef8e00593b1af0db18",
  "id": "4",
  "property": "Residential Flat",
  "area": "270",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "Nobroker.com",
  "expectedPrice": "4500000",
  "expectedRate": "16666.67",
  "builtUpExpectedRate": "13888.89",
  "image": "cases/648bfa82719c32253ddd8d12/
indicator_1687165679785_Image.png"
}
],
"externallimages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6490000f8e00593b1af09cb2",
    "name":
"externallmg_1687158798155_compositionlmg_r_1686983064933_image.jpg",
    "path": "cases/648bfa82719c32253ddd8d12/
externallmg_1687158798155_compositionlmg_r_1686983064933_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6490000f8e00593b1af09cb3",
    "name":
"externallmg_1687158798170_compositionlmg_r_1686983120091_image.jpg",
```

```
    "path": "cases/648bfa82719c32253ddd8d12/
externallmg_1687158798170_compositionlmg_r_1686983120091_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6490000f8e00593b1af09cb4",
    "name":
"externallmg_1687158798187_compositionlmg_r_1686983177241_image.jpg",
    "path": "cases/648bfa82719c32253ddd8d12/
externallmg_1687158798187_compositionlmg_r_1686983177241_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6490000f8e00593b1af09cb5",
    "name":
"externallmg_1687158798209_compositionlmg_r_1686983228483_image.jpg",
    "path": "cases/648bfa82719c32253ddd8d12/
externallmg_1687158798209_compositionlmg_r_1686983228483_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6490000f8e00593b1af09cb6",
    "name":
"externallmg_1687158798218_compositionlmg_r_1686983299847_image.jpg",
    "path": "cases/648bfa82719c32253ddd8d12/
externallmg_1687158798218_compositionlmg_r_1686983299847_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6490000f8e00593b1af09cb7",
    "name":
"externallmg_1687158798224_compositionlmg_r_1686983337759_image.jpg",
    "path": "cases/648bfa82719c32253ddd8d12/
externallmg_1687158798224_compositionlmg_r_1686983337759_image.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6490000f8e00593b1af09cb8",
    "name":
"externallmg_1687158798229_WhatsApp_Image_20230617_at_143715.jpeg",
    "path": "cases/648bfa82719c32253ddd8d12/
externallmg_1687158798229_WhatsApp_Image_20230617_at_143715.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6490000f8e00593b1af09cb9",
    "name":
"externallmg_1687158798260_WhatsApp_Image_20230617_at_143717.jpeg",
    "path": "cases/648bfa82719c32253ddd8d12/
externallmg_1687158798260_WhatsApp_Image_20230617_at_143717.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6490000f8e00593b1af09cba",
    "name":
"externallmg_1687158798272_WhatsApp_Image_20230617_at_143718.jpeg",
    "path": "cases/648bfa82719c32253ddd8d12/
externallmg_1687158798272_WhatsApp_Image_20230617_at_143718.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6490000f8e00593b1af09cbb",
    "name":
"externallmg_1687158798280_WhatsApp_Image_20230617_at_143719_1.jpeg",
    "path": "cases/648bfa82719c32253ddd8d12/
externallmg_1687158798280_WhatsApp_Image_20230617_at_143719_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6490000f8e00593b1af09cbc",
    "name":
"externallmg_1687158798286_WhatsApp_Image_20230617_at_143719_2.jpeg",
    "path": "cases/648bfa82719c32253ddd8d12/
externallmg_1687158798286_WhatsApp_Image_20230617_at_143719_2.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6490000f8e00593b1af09cbd",
  "name":
  "externallmg_1687158798301_WhatsApp_Image_20230617_at_143719.jpeg",
  "path": "cases/648bfa82719c32253ddd8d12/
externallmg_1687158798301_WhatsApp_Image_20230617_at_143719.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6490000f8e00593b1af09cbe",
  "name":
  "externallmg_1687158798306_WhatsApp_Image_20230617_at_143720.jpeg",
  "path": "cases/648bfa82719c32253ddd8d12/
externallmg_1687158798306_WhatsApp_Image_20230617_at_143720.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6490000f8e00593b1af09cbf",
  "name":
  "externallmg_1687158798315_WhatsApp_Image_20230617_at_143721.jpeg",
  "path": "cases/648bfa82719c32253ddd8d12/
externallmg_1687158798315_WhatsApp_Image_20230617_at_143721.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [
  {
    "originalname": "Valuation_Report _Ritesh B. Rane & Mrs. Rupali Ritesh Rane
(1).pdf",
    "filename": "1687177109386_Valuation_Report__Ritesh_B_Rane__Mrs_Rupali_Rit
esh_Rane_1.pdf",
    "path": "cases/648bfa82719c32253ddd8d12/externalDocuments/1687177109386_V
aluation_Report __Ritesh_B_Rane __Mrs_Rupali_Ritesh_Rane_1.pdf",
    "size": "1268621",
    "documentType": {
      "value": "60ae124caa6d152c1801b300",
      "label": "Signed Report"
    }
  },

```

```
"createdAt": "Mon Jun 19 2023 17:48:29 GMT+0530 (India Standard Time)",
"uploadedBy": "63f31d626f9c2254a9b39144"
}
],
"createdAt": "2023-06-16T06:00:34.670Z",
"updatedAt": "2023-06-20T06:44:09.170Z",
"__v": 0,
"fullAddress": "Residential Flat No. 401, 4th Floor, Building No 3A, MHADA Building,
Swami Co-op. Hsg. Soc. Ltd., Magathane, Village - Magathane, Borivali East, Taluka -
Borivali, Mumbai Suburban, 400066, State - Maharashtra, India",
"updatedAt": "627208c1afd7d55eddedc372",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Mr. Ritesh B. Rane ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "4500000",
"relationWithOwner": "self",
"siteVisitContactNo": "9702813389",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + Bathroom +
W.C",
"carpetTotal": "259.63",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0",
"siteVisitDate": "2023-06-17",
"builtupPercentage": "20",
"finalBuiltupArea": "311.56",
"finalCarpetArea": "259.63",
"finalSalableArea": "342.71",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalSaleablePercentage": "20",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 269.32",
"buildingServicesRate": "2500",
"flatRate": "20000",
"landOtherRate": "17500",
"reason": "",
"otherCompositionBuiltUpTotal": "0.00",
```

"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"

}

Name	Length	Width	Total
Composition :			
Living Room	8'3"	10'9"	88.69
Kitchen	6'6"	8'3"	53.62
Bedroom	9'9"	8'3"	80.44
Passage	3'7"	3'10"	13.74
Bathroom	3'6"	3'5"	11.96
W.C	3'10"	2'11"	11.18
Other Composition :			