

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b951"
    },
    "type": "CREDITOFFICER",
    "_id": "635f732fe363ef22db2f1c80",
    "firstName": "Ravindra Sir",
    "lastName": "sir",
    "mobileNo": "",
    "email": "me1@me.com",
    "workMobileNo": "7738642220"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2945000",
    "discussWithPerson": "KIRAN ",
    "expectedFees": 1472.5,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "VCIPL Mumbai",
    "shortName": "VCIPLM",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
```

```
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b951",
  "branchCode": "000167",
  "type": "BRANCH",
  "name": "RACPC Belapur ",
  "email": "sbi.14677@sbi.co.in",
  "mobileNo": "022-27524090",
  "alternateMobileNo": "",
  "address": "Estate Department Corporate Centre, 4th Floor, CIDCO Tower No. 4,
Railway Station Building, C.B.D. Belapur, Navi Mumbai - 400 614, State - Maharashtra,
Country - India.",
  "ledgerName": "STATE BANK OF INDIA - CBD Estate Department",
  "fax": "022 2757 7002",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7189d2ffdf65bcd65882b",
    "role": "PICKUPPERSON",
    "firstName": "Ravindra",
    "email": "ravindrakasare186@gmail.com",
```

```
"lastName": "Kasare",
"mobileNo": "9167204055",
"shortName": "RBK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60b7189d2ffdf65bcd65882b\
\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63fc4680ce84bf289ba9c7fc",
"role": "SITEENGINEER",
"firstName": "Nikhil ",
"email": "valtechnical2022@gmail.com",
"lastName": "Sonawane",
"mobileNo": "9819470709",
"designation": "",
"shortName": "NS",
"workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2",
"profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1681380664371_WhatsApp_Image_20230413_at_33801_PM.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
```

```
"profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyam_Photo.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "0123456789",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "6084131a13f01f158c6ea1f3",
    "PANNo": "AEAPC7114Q",
    "role": "VALUER",
    "firstName": "Sharadkumar",
    "fatherName": "Baburao",
    "email": "cmd@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9422171100",
    "designation": "CMD",
    "registrationNo": [
      {
        "title": {
          "value": "Wealth_Tax",
          "label": "Wealth Tax"
        },
        "_id": "6084131a13f01f158c6ea1f4",
        "number": "[N]C.C.I.T/I -14/52/2008-09"
      }
    ],
    "shortName": "SBC",
```

```
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.149023",
  "longitude": "73.080451"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.080451,
    19.149023
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-06-17T07:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-06-17T07:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-06-17T07:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-06-17T07:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-06-17T07:30:00.000Z",
      "remark": ""
    }
  ]
}
```

```
    "remark": ""
  },
  {
    "dateTime": "2023-06-17T07:30:00.000Z",
    "remark": ""
  }
],
"visitedDate": [
  {
    "remark": "MANUAL",
    "status": "COMPLETED",
    "dateTime": "2023-06-28T10:00:00.000Z"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft."
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Sat Jun 17 2023 13:45:56 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  }
},
```

```
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Nilje - Ghesar",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "4",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Dombivali (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
```

```
"value": "Kalyan",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Arabiana Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
```



```
"status": true,
"name": "Wing",
"key": "wing",
"value": "G",
"label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Casa Rio",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "63/1, 96/1, 123/1, 2, 92/1 and others",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
```

```
"label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "406",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
```

```
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "421204",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_/_Glass_Door",
    "label": "Teak Wood / Glass Door"
  },
  "windows": {
    "value": "Wooden_frame_openable_widow_with_M._S._Grill",
    "label": "Wooden frame openable widow with M. S. Grill"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring",
    "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring"
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
}
```

```
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Kalyan_Dombivali_Municipal_Corporation",
    "label": "Kalyan Dombivali Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "4th Ave St",
    "west": "F Wing",
    "south": "Internal Road / Club House",
    "east": "Adriatica F"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "extraDetailOfProperty": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "12",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "7200",
  "depreciatedBuildingRate": "2200"
},
"igrRate": {
  "propertyName": "Residential Flat",
```

```
"rate": "39900",
"landRate": "4300",
"igrImage": "cases/648c976907df79469f402dee/igr_1688030363912_Image.png",
"squareMeterGuideLineRate": "39900.00",
"squareFeetGuideLineRate": "3707.00"
},
"igrFinalRate": {
  "rate": "3442.00",
  "squareFeetGuideLineRate": "3442.00",
  "squareMeterGuideLineRate": "37052.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "7000",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MMRDA norms",
  "tenantName": "",
  "maintenanceOfFlat": "Details not available"
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
```

```
"label": "R. C. C. Slab"
},
"partitions": {
  "value": "6\"_Thk._Brick_Masonry",
  "label": "6\" Thk. Brick Masonery"
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "One Open Car Parking Space No. G5-126",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2015",
  "fullDate": "1/1/2015"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
```

```
"value": "Good",
"label": "Good"
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
"structuralSafety": {
"value": "Good",
"label": "Good"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
"walls": {
"value": "1",
"label": "Yes"
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
"maintenanceIssues": {
"value": "0",
"label": "No"
},
"visibleDamageInBuilding": {
"value": "1",
"label": "Yes"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
}
```

```
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "8",
"totalLifeBuilding": "60",
"estimatedAge": "52",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "8",
"flatFloorNo": "4",
"noOfLifts": "6",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "538.80",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/648c976907df79469f402dee/
routeMap_1688029002657_Image.png",
    "routeLat": "19.149023",
    "routeLng": "73.080451",
    "stationName": "Nilje",
    "routeDistance": "1.7 Km"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
}
```



```
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "ktkenf",
    "name": "ktkenf",
    "image": "cases/648c976907df79469f402dee/
routeMap_1688029302806_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "3232800.00",
  "bookValue": "0",
  "finalValue": "3232800.00"
},
"outward": {
```

```
"status": true,
"remark": "SYSTEMGENERATED",
"date": "Thu Jun 29 2023 15:14:09 GMT+0530 (India Standard Time)",
"number": "2301352",
"dayCount": "7",
"monthCount": "453",
"generatedBy": "5fc78e26625ecd20ec1f88e9"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "1854550.00",
  "selectedBuildUpValue": "538.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
```

```
"frontPageImages": [
  {
    "status": false,
    "_id": "649d47a4d83f66572f93df14",
    "name":
"externallmg_1688029092155_WhatsApp_Image_20230628_at_75452_PM_2.jpeg",
    "path": "cases/648c976907df79469f402dee/
externallmg_1688029092155_WhatsApp_Image_20230628_at_75452_PM_2.jpeg",
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "649d4785d83f66572f93dee5",
    "name":
"externallmg_1688029061100_WhatsApp_Image_20230628_at_75453_PM_8.jpeg",
    "path": "cases/648c976907df79469f402dee/
externallmg_1688029061100_WhatsApp_Image_20230628_at_75453_PM_8.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "649d479cd83f66572f93defc",
    "name":
"externallmg_1688029083454_WhatsApp_Image_20230628_at_75452_PM_5.jpeg",
    "path": "cases/648c976907df79469f402dee/
externallmg_1688029083454_WhatsApp_Image_20230628_at_75452_PM_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "649d47a4d83f66572f93df14",
    "name":
"externallmg_1688029092155_WhatsApp_Image_20230628_at_75452_PM_2.jpeg",
    "path": "cases/648c976907df79469f402dee/
externallmg_1688029092155_WhatsApp_Image_20230628_at_75452_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "649d47bed83f66572f93df79",
    "name":
"externallmg_1688029118427_WhatsApp_Image_20230628_at_75452_PM_7.jpeg",
```

```
    "path": "cases/648c976907df79469f402dee/
externallmg_1688029118427_WhatsApp_Image_20230628_at_75452_PM_7.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "649d47b5d83f66572f93df5e",
    "name":
"externallmg_1688029108744_WhatsApp_Image_20230628_at_75452_PM_4.jpeg",
    "path": "cases/648c976907df79469f402dee/
externallmg_1688029108744_WhatsApp_Image_20230628_at_75452_PM_4.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "649d475ad83f66572f93de93",
    "name": "Living Room",
    "path": "cases/648c976907df79469f402dee/
externallmg_1688029018270_WhatsApp_Image_20230628_at_75453_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "649d4766d83f66572f93dea6",
    "name": "Bedroom",
    "path": "cases/648c976907df79469f402dee/
externallmg_1688029029517_WhatsApp_Image_20230628_at_75453_PM_7.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "649d477ad83f66572f93decf",
    "name": "Kitchen",
    "path": "cases/648c976907df79469f402dee/
externallmg_1688029050470_WhatsApp_Image_20230628_at_75453_PM_4.jpeg",
    "orientation": "landscape"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
```

```
"max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
```

```
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
```



```
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": true,
  "CHECKER": true,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "449.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86A/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REPORTGENERATED",
"_id": "648c976907df79469f402dee",
"ownerName": "Mr. Malikram M. Verma & Mrs. Anita Malikram Verma ",
"ownerPhoneNo": "9930439634",
"appAddress": "flat no 406 4 th floor G wing Bldg Arabiana casa ria village Nilje
Dombivli ",
"remark": "m m verma 2 ) 9833767858",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
  },
  "inputs": {
```

```
"documentDate": "29/05/2023",
"amount": "2945000",
"from": {
  "value": "Seller",
  "label": "Seller"
},
"seller": "Mr. Gaurishankar Virkumar Mathapati & Mrs. Trupti Gaurishankar
Mathapati",
"to": {
  "value": "purchaser",
  "label": "purchaser"
},
"purchaser": "Mr. Malikram M. Verma & Mrs. Anita Malikram Verma "
},
"isHardCopy": false,
"displayStatus": true,
"id": "805442",
"path": "cases/648c976907df79469f402dee/
document_1686935353896_Sbi_Racpc_Belapur_varma.pdf",
"fileName": "document_1686935353896_Sbi_Racpc_Belapur_varma.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "06/11/2015",
    "nameOfApprovingAuthority": {
      "value": "Mumbai_Metropolitan_Region_Development_Authority",
      "label": "Mumbai Metropolitan Region Development Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "SROT / MCP - 03 / L.D.P.L. / OC - II / CI-7 / 795 / 2015"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "path": "cases/648c976907df79469f402dee/
document_1688027531252_983529.pdf",
  "id": "533586",
  "uploadedBy": "60eeaeddf3dd69653a581316",
  "createdAt": "Thu Jun 29 2023 14:02:17 GMT+0530 (India Standard Time)"
}
```

```
],
"caseNumber": "002004",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "986634",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Jun 16 2023 22:40:01 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Malikram M. Verma & Mrs. Anita Malikram Verma ",
    "phone": "9930439634",
    "ownershipShare": "",
    "email": "",
    "id": "191980"
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "9",
    "name": "Living Room",
    "length": "15.17",
    "length1": "15",
    "length2": "2",
    "width": "10.33",
    "width1": "10",
    "width2": "4",
    "totalArea": "156.72",
    "images": [
      {
        "path": "cases/648c976907df79469f402dee/
compositionImg_1688027910023_WhatsApp_Image_20230628_at_75453_PM.jpeg",
        "orientation": "landscape"
      }
    ]
  },
  "finalArea": "156.72",
  "extraAreas": []
],
},
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Bedroom",
  "length": "9.50",
  "length1": "9",
  "length2": "6",
  "width": "10.50",
  "width1": "10",
  "width2": "6",
  "totalArea": "99.75",
  "images": [
    {
      "path": "cases/648c976907df79469f402dee/
compositionImg_1688027928631_WhatsApp_Image_20230628_at_75453_PM_6.jpeg",
      "orientation": "landscape"
    }
  ],
  "finalArea": "99.75",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Kitchen",
  "length": "7.08",
  "length1": "7",
  "length2": "1",
  "width": "8.25",
  "width1": "8",
  "width2": "3",
  "totalArea": "58.44",
  "images": [
    {
      "path": "cases/648c976907df79469f402dee/
compositionImg_1688027981844_WhatsApp_Image_20230628_at_75453_PM_4.jpeg",
      "orientation": "landscape"
    }
  ],
  "finalArea": "58.44",
```

```
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Balcony Area",
  "length": "3.25",
  "length1": "3",
  "length2": "3",
  "width": "6.58",
  "width1": "6",
  "width2": "7",
  "totalArea": "21.40",
  "images": [],
  "finalArea": "21.40",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Passage",
  "length": "9.42",
  "length1": "9",
  "length2": "5",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "28.25",
  "images": [],
  "extraAreas": [],
  "finalArea": "28.25"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Passage",
  "length": "",
```

```
"length1": "3",
"length2": "0",
"width": "",
"width1": "4",
"width2": "0",
"totalArea": "12.00",
"images": [],
"finalArea": "12.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "WC",
  "length": "",
  "length1": "3",
  "length2": "9",
  "width": "",
  "width1": "4",
  "width2": "0",
  "totalArea": "15.00",
  "images": [],
  "finalArea": "15.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Bathroom",
  "length": "4.58",
  "length1": "4",
  "length2": "7",
  "width": "3.67",
  "width1": "3",
  "width2": "8",
  "totalArea": "16.81",
  "images": [],
  "finalArea": "16.81",
  "extraAreas": []
},
}
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Dry Balcony",
  "length": "3.25",
  "length1": "3",
  "length2": "3",
  "width": "4.50",
  "width1": "4",
  "width2": "6",
  "totalArea": "14.62",
  "images": [],
  "finalArea": "14.62",
  "extraAreas": []
}
],
"otherComposition": [
  {
    "name": {
      "value": "Cupboard",
      "label": "Cupboard"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length1": "4",
    "length2": "6",
    "length": "4.50",
    "width1": "2",
    "width2": "0",
    "width": "2.00",
    "totalArea": "9.00",
    "percentageBeforeTotal": "9.00",
    "images": [],
    "extraAreas": [],
    "percentage": "100",
    "finalArea": "9"
  }
],
"externalReport": [],
"documentPerArea": [
```

```

{
  "typeOfDocument": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "619418",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "449",
  "squareMeterArea": "41.71",
  "docFinalBuiltUp": "538.8",
  "docFinalBuiltUpSquareMeter": "50.052",
  "docBuiltupPercentage": "20",
  "docSaleablePercentage": "20",
  "docFinalSaleable": "646.56",
  "docFinalSaleableSquareMeter": "60.0624"
}
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "649d4618d83f66572f93dc86",
    "id": "1",
    "property": "Residential Flat",
    "area": "445",
    "builtUpPercentage": "20",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "",
    "source": "https://www.99acres.com/",
    "expectedPrice": "3100000",
    "expectedRate": "6966.29",
    "builtUpExpectedRate": "5805.24",
    "image": "cases/648c976907df79469f402dee/
indicator_1688028696250_Image.png"
  },
  {
    "printlnReport": true,
    "_id": "649d462cd83f66572f93dc97",
    "id": "2",
    "property": "Residential Flat",

```



```
"area": "495",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "3500000",
"expectedRate": "7070.71",
"builtUpExpectedRate": "5892.26",
"image": "cases/648c976907df79469f402dee/
indicator_1688028716507_Image.png"
},
{
  "printlnReport": true,
  "_id": "649d4641d83f66572f93dca9",
  "id": "3",
  "property": "Residential Flat",
  "area": "449",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "https://www.99acres.com/",
  "expectedPrice": "3450000",
  "expectedRate": "7683.74",
  "builtUpExpectedRate": "6403.12",
  "image": "cases/648c976907df79469f402dee/
indicator_1688028736973_Image.png"
},
{
  "printlnReport": true,
  "_id": "649d465ed83f66572f93dcbc",
  "id": "4",
  "property": "Residential Flat",
  "area": "594",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Saleable",
  "floor": "",
  "source": "square_yards",
  "expectedPrice": "3200000",
  "expectedRate": "5387.21",
  "builtUpExpectedRate": "6464.65",
```

```
    "image": "cases/648c976907df79469f402dee/
indicator_1688028766554_Image.png"
  }
],
"externallimages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "649d475ad83f66572f93de93",
    "name":
"externallmg_1688029018270_WhatsApp_Image_20230628_at_75453_PM.jpeg",
    "path": "cases/648c976907df79469f402dee/
externallmg_1688029018270_WhatsApp_Image_20230628_at_75453_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "649d4766d83f66572f93dea6",
    "name":
"externallmg_1688029029517_WhatsApp_Image_20230628_at_75453_PM_7.jpeg",
    "path": "cases/648c976907df79469f402dee/
externallmg_1688029029517_WhatsApp_Image_20230628_at_75453_PM_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "649d4771d83f66572f93deba",
    "name":
"externallmg_1688029040902_WhatsApp_Image_20230628_at_75453_PM_6.jpeg",
    "path": "cases/648c976907df79469f402dee/
externallmg_1688029040902_WhatsApp_Image_20230628_at_75453_PM_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "649d477ad83f66572f93decf",
    "name":
"externallmg_1688029050470_WhatsApp_Image_20230628_at_75453_PM_4.jpeg",
    "path": "cases/648c976907df79469f402dee/
externallmg_1688029050470_WhatsApp_Image_20230628_at_75453_PM_4.jpeg",
    "orientation": "landscape"
  },
  {

```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "649d4785d83f66572f93dee5",
    "name":
"externallmg_1688029061100_WhatsApp_Image_20230628_at_75453_PM_8.jpeg",
    "path": "cases/648c976907df79469f402dee/
externallmg_1688029061100_WhatsApp_Image_20230628_at_75453_PM_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "649d479cd83f66572f93defc",
    "name":
"externallmg_1688029083454_WhatsApp_Image_20230628_at_75452_PM_5.jpeg",
    "path": "cases/648c976907df79469f402dee/
externallmg_1688029083454_WhatsApp_Image_20230628_at_75452_PM_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "649d47a4d83f66572f93df14",
    "name":
"externallmg_1688029092155_WhatsApp_Image_20230628_at_75452_PM_2.jpeg",
    "path": "cases/648c976907df79469f402dee/
externallmg_1688029092155_WhatsApp_Image_20230628_at_75452_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "649d47acd83f66572f93df44",
    "name":
"externallmg_1688029099981_WhatsApp_Image_20230628_at_75452_PM_3.jpeg",
    "path": "cases/648c976907df79469f402dee/
externallmg_1688029099981_WhatsApp_Image_20230628_at_75452_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "649d47b5d83f66572f93df5e",
    "name":
"externallmg_1688029108744_WhatsApp_Image_20230628_at_75452_PM_4.jpeg",
    "path": "cases/648c976907df79469f402dee/
externallmg_1688029108744_WhatsApp_Image_20230628_at_75452_PM_4.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "649d47bed83f66572f93df79",
  "name":
"externallmg_1688029118427_WhatsApp_Image_20230628_at_75452_PM_7.jpeg",
  "path": "cases/648c976907df79469f402dee/
externallmg_1688029118427_WhatsApp_Image_20230628_at_75452_PM_7.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"createdAt": "2023-06-16T17:10:01.039Z",
"updatedAt": "2023-07-01T10:25:19.557Z",
"__v": 0,
"fullAddress": "Residential Flat No. 406, 4th Floor, Wing - G, Arabiana Co-op. Hsg.
Soc. Ltd., Casa Rio, Village - Nilje - Ghesar, Taluka - Kalyan, District - Thane, Dombivali
(East), 421204, State - Maharashtra, India",
"updatedBy": "60eeaeddf3dd69653a581316",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Mr. Suresh Iyer",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "2945000",
"relationWithOwner": "Agent",
"siteVisitContactNo": "8108295236",
"reason": "",
"siteVisitDate": "2023-06-28",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Balcony Area + 2
Passage + WC + Bathroom + Dry Balcony",
"carpetTotal": "422.62",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "9.00",
"builtupPercentage": "10",
"extendOfSiteRemark": "",
"finalBuiltupArea": "465.29",
"finalCarpetArea": "422.99",
"finalSalableArea": "511.82",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
```

```

"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalSaleablePercentage": "20",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 449.00",
"buildingServicesRate": "2500",
"flatRate": "7500",
"landOtherRate": "5000",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"
}

```

Name	Length	Width	Total
Composition :			
Living Room	15'2"	10'4"	156.72
Bedroom	9'6"	10'6"	99.75
Kitchen	7'1"	8'3"	58.44
Balcony Area	3'3"	6'7"	21.40
Passage	9'5"	3'00"	28.25
Passage	3'0"	4'0"	12.00
WC	3'9"	4'0"	15.00
Bathroom	4'7"	3'8"	16.81
Dry Balcony	3'3"	4'6"	14.62
Other Composition :			
Cupboard	4'6"	2'0"	9.00