

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b951"
    },
    "type": "CREDITOFFICER",
    "_id": "635f732fe363ef22db2f1c80",
    "firstName": "Ravindra Sir",
    "lastName": "sir",
    "mobileNo": "",
    "email": "me1@me.com",
    "workMobileNo": "7738642220"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2400000",
    "discussWithPerson": "Ravindra Sir",
    "expectedFees": 1200,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
    "city": "Mumbai"
  }
}
```

```
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b951",
  "branchCode": "000167",
  "type": "BRANCH",
  "name": "RACPC Belapur ",
  "email": "sbi.14677@sbi.co.in",
  "mobileNo": "022-27524090",
  "alternateMobileNo": "",
  "address": "Estate Department Corporate Centre, 4th Floor, CIDCO Tower No. 4,
Railway Station Building, C.B.D. Belapur, Navi Mumbai - 400 614, State - Maharashtra,
Country - India.",
  "ledgerName": "STATE BANK OF INDIA - CBD Estate Department",
  "fax": "022 2757 7002",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7189d2ffdf65bcd65882b",
    "role": "PICKUPPERSON",
    "firstName": "Ravindra",
    "email": "ravindrakasare186@gmail.com",
    "lastName": "Kasare",
    "mobileNo": "9167204055",
```

```
    "shortName": "RBK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\
\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "640c34384dda382753e651f2",
    "role": "SITEENGINEER",
    "firstName": "Prashant ",
    "email": "kasarprashant121@gmail.com",
    "lastName": "Kasar",
    "mobileNo": "9892524464",
    "designation": "",
    "shortName": "PK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/640c34384dda382753e651f2/
profilePhoto_1678521400647_WhatsApp_Image_20230311_at_12047_PM.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60eebe33f3dd69653a5837ae",
    "role": "MAKER",
    "firstName": "Shamal",
    "email": "shamal@vastukala.org",
    "lastName": "Bodke",
    "mobileNo": "9821740317",
    "designation": "",
    "shortName": "SB",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "60eebe33f3dd69653a5837ae",
    "role": "MAKER",
    "firstName": "Shamal",
    "email": "shamal@vastukala.org",
    "lastName": "Bodke",
    "mobileNo": "9821740317",
    "designation": "",
    "shortName": "SB",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
```

```
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyam_Photo.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.159288",
  "longitude": "73.232356"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.232356,
    19.159288
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
```

```
    "dateTime": "2023-06-21T06:30:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-06-21T06:30:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-06-21T06:30:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-06-21T06:30:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-06-21T06:30:00.000Z",
    "remark": ""
  }
],
"visitedDate": [
  {
    "remark": "MANUAL",
    "status": "COMPLETED",
    "dateTime": "2023-06-22T06:30:00.000Z"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Wed Jun 21 2023 12:16:06 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
```

```
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Shirgaon",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "3",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Badlapur",
  "label": false
},
"tahsilNo": {
  "status": false,
```

```
"name": "Tahasil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Ambernath",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "7 & 8 ",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "New Shree Krupa Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
}
```



```
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Sachin Samir Society, Aptewadi",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "38/1, A5, 3 A/7, 1 A/6",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
```

```
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "305",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
```

```
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Alluminum_sliding_windows_with_M._S._Grills",
    "label": "Alluminum sliding windows with M. S. Grills"
  },
}
```

```
"fittings": {
  "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Kulgaon_Badlapur_Municipal_Council",
    "label": "Kulgaon Badlapur Municipal Council"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Open Plot",
    "west": "Khatri Grand Building",
    "south": "Bungalow & Sachin Sameer Society",
    "east": "Internal Road & Trimbkeshwar Apartment"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "extraDetailOfProperty": ""
},
"compositeRate": {
```

```
"remark": "",
"depreciationPercentage": "13.5",
"depreciationRatioOfBuilding": "",
"salvageValue": "10",
"depreciatedCostOfConstruction": "5462.5",
"depreciatedBuildingRate": "2162.5"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "52400",
  "landRate": "8290",
  "igrImage": "cases/64927378ff2e4a17ce88b02e/igr_1687506583816_Image.png",
  "squareMeterGuideLineRate": "52400.00",
  "squareFeetGuideLineRate": "4868.00"
},
"igrFinalRate": {
  "rate": "4499.00",
  "squareFeetGuideLineRate": "4499.00",
  "squareMeterGuideLineRate": "48430.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "6,000",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "021666533591",
  "meterCardHolderName": "Shri. Shabhudev Yamaji Khade",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per KBMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
```

```
"value": "Good",
"label": "Good"
},
"anyFavouringForExtraPotentialValue": "Located in developed area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
"roof": {
"value": "rcc_Slab",
"label": "R. C. C. Slab"
},
"partitions": {
"value": "6\"_Thk._Brick_Masonry",
"label": "6\" Thk. Brick Masonery"
},
"waterTank": {
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
},
"carParking": {
"value": "Open_Car_Parking",
"label": "Open Car Parking"
},
"constructionWorkStatus": {
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2014",
"fullDate": "1/1/2014"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
```

```
"value": "R.C.C._Framed_Structure",
"label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
},
"materialUsedList": {
"value": "Good",
"label": "Good"
},
},
"buildingSpecification": {
"value": "Standard",
"label": "Standard"
},
},
"structuralSafety": {
"value": "Good",
"label": "Good"
},
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
},
"sewerageSystem": {
"value": "MunicipalSewerageSystem",
"label": "Connected to Municipal Sewerage System"
},
},
"walls": {
"value": "1",
"label": "Yes"
},
},
"appearanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
},
"maintenanceOfTheBuilding": {
"value": "Good",
"label": "Good"
},
},
"maintenancelssues": {
"value": "Information_not_available",
"label": "Information not available"
}
```

```
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "9",
"totalLifeBuilding": "60",
"estimatedAge": "51",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "5",
"flatFloorNo": "3",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "5"
},
"finalPlinthArea": {
  "area": "616.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "routeMapImg": "cases/64927378ff2e4a17ce88b02e/
routeMap_1687506899953_Image.png",
```



```
"routeLat": "19.159288",
"routeLng": "73.232356",
"stationName": "Badlapur",
"routeDistance": "2.2 Km"
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "b27rmt",
    "name": "b27rmt",
    "image": "cases/64927378ff2e4a17ce88b02e/
routeMap_1687506689145_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
```

```
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "2802519.00",
"bookValue": "0",
"finalValue": "2802519.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEM_GENERATED",
  "date": "Fri Jun 23 2023 13:31:55 GMT+0530 (India Standard Time)",
  "number": "047032",
  "dayCount": "6",
  "monthCount": "209",
  "generatedBy": "60eebe33f3dd69653a5837ae"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
```

```
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
```

```
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "2769584.00",
  "selectedBuildUpValue": "615.60",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "64954ff3c3eaaa5554d3018a",
      "name": "externallmg_1687506930375_IMG20230622WA0028.jpg",
      "path": "cases/64927378ff2e4a17ce88b02e/
externallmg_1687506930375_IMG20230622WA0028.jpg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "64954ff3c3eaaa5554d30189",
      "name": "externallmg_1687506930358_IMG20230622WA0027.jpg",
      "path": "cases/64927378ff2e4a17ce88b02e/
externallmg_1687506930358_IMG20230622WA0027.jpg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "64954fe9c3eaaa5554d30148",
      "name": "externallmg_1687506920970_IMG20230622WA0013.jpg",
      "path": "cases/64927378ff2e4a17ce88b02e/
externallmg_1687506920970_IMG20230622WA0013.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "64954ff3c3eaaa5554d3018b",
      "name": "externallmg_1687506930401_IMG20230622WA0029.jpg",
      "path": "cases/64927378ff2e4a17ce88b02e/
externallmg_1687506930401_IMG20230622WA0029.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64954ff3c3eaaa5554d30188",
    "name": "externallmg_1687506930333_IMG20230622WA0026.jpg",
    "path": "cases/64927378ff2e4a17ce88b02e/
externallmg_1687506930333_IMG20230622WA0026.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64954ff3c3eaaa5554d30186",
    "name": "externallmg_1687506930305_IMG20230622WA0024.jpg",
    "path": "cases/64927378ff2e4a17ce88b02e/
externallmg_1687506930305_IMG20230622WA0024.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "64954fe9c3eaaa5554d30149",
    "name": "externallmg_1687506920989_IMG20230622WA0014.jpg",
    "path": "cases/64927378ff2e4a17ce88b02e/
externallmg_1687506920989_IMG20230622WA0014.jpg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "64954ff3c3eaaa5554d30183",
    "name": "Living Room",
    "path": "cases/64927378ff2e4a17ce88b02e/
externallmg_1687506930249_IMG20230622WA0021.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "64954ff3c3eaaa5554d30184",
    "name": "Living Room",
    "path": "cases/64927378ff2e4a17ce88b02e/
externallmg_1687506930272_IMG20230622WA0022.jpg",
    "orientation": "landscape"
  }
]
```

```
    },
    {
      "status": false,
      "_id": "64954fe9c3eaaa5554d30147",
      "name": "Bedroom",
      "path": "cases/64927378ff2e4a17ce88b02e/
externallmg_1687506920952_IMG20230622WA0012.jpg",
      "orientation": "landscape"
    },
    {
      "status": false,
      "_id": "64954fe9c3eaaa5554d3014c",
      "name": "Kitchen",
      "path": "cases/64927378ff2e4a17ce88b02e/
externallmg_1687506921049_IMG20230622WA0017.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "64954fe9c3eaaa5554d30145",
      "name": "Balcony",
      "path": "cases/64927378ff2e4a17ce88b02e/
externallmg_1687506920902_IMG20230622WA0010.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "64954fe9c3eaaa5554d30146",
      "name": "Balcony",
      "path": "cases/64927378ff2e4a17ce88b02e/
externallmg_1687506920924_IMG20230622WA0011.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "64954fe9c3eaaa5554d3014a",
      "name": "Balcony",
      "path": "cases/64927378ff2e4a17ce88b02e/
externallmg_1687506921018_IMG20230622WA0015.jpg",
      "orientation": "portrait"
    }
  ]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
```

```
"max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
```



```
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": true,
"CHECKER": true,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
"label": "Lead",
"value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "513.00",
"empanelmentNo": [
"SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REPORTGENERATED",
"_id": "64927378ff2e4a17ce88b02e",
"ownerName": "Mr. Deepak Balu Sapkal & Mrs. Vina Deepak Sapkal",
"ownerPhoneNo": "9967225524",
"appAddress": "flat no 305 3rd floor New shree krupa chs Ltd shirgaon Badlapur ",
"remark": "",
"documents": [
{
"documentType": {
"label": "Agreement For Sale",
"value": "60ae1254aa6d152c1801b326"
},
"inputs": {
"documentDate": "21/09/2019",
```

```
"from": {
  "value": "Seller",
  "label": "Seller"
},
"Seller": "Mrs. Saylee Sandeep Ghagare ",
"to": {
  "value": "Purchasers",
  "label": "Purchasers"
},
"Purchasers": "Mr. Deepak Balu Sapkal & Mrs. Vina Deepak Sapkal"
},
"isHardCopy": false,
"displayStatus": true,
"id": "532713",
"path": "cases/64927378ff2e4a17ce88b02e/
document_1687319329899_Release_Deed.pdf",
"fileName": "document_1687319329899_Release_Deed.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "15/04/2014",
    "nameOfApprovingAuthority": {
      "value": "Kulgaon_Badlapur_Municipal_Council",
      "label": "Kulgaon Badlapur Municipal Council"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "KBNP / NRV / 687 / 2014-15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/64927378ff2e4a17ce88b02e/
document_1687502532679_111899.pdf",
  "id": "711208",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Fri Jun 23 2023 12:22:31 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "6077c791395bc80714864a30",
```

```
"label": "Electricity Bill"
},
"inputs": {
  "documentDate": "19/06/2023",
  "nameOfApprovingAuthority": {
    "value": "MSEDCL",
    "label": "MSEDCL"
  },
  "to": {
    "value": "Beneficiary",
    "label": "Beneficiary"
  },
  "Beneficiary": "Shri. Shabhudev Yamaji Khade",
  "number": {
    "value": "Consumer_No",
    "label": "Consumer No"
  },
  "Consumer_No": "021666533591"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1687502890068_LT_Energy_Bill.pdf",
"path": "cases/64927378ff2e4a17ce88b02e/
document_1687502890068_LT_Energy_Bill.pdf",
"id": "712112",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Fri Jun 23 2023 12:22:31 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "26/07/2011",
    "nameOfApprovingAuthority": {
      "value": "Kulgaon_Badlapur_Municipal_Council",
      "label": "Kulgaon Badlapur Municipal Council"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "KBNP / NRV / BP / 910 / 140"
  },
  "isHardCopy": false,
```

```
    "displayStatus": false,
    "path": "cases/64927378ff2e4a17ce88b02e/
document_1687503148620_208799.pdf",
    "id": "630953",
    "uploadedBy": "60eebe33f3dd69653a5837ae",
    "createdAt": "Fri Jun 23 2023 12:22:31 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "002058",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "483903",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Jun 21 2023 09:20:16 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Deepak Balu Sapkal & Mrs. Vina Deepak Sapkal",
    "phone": "9967225524",
    "ownershipShare": "",
    "email": "",
    "id": "522070"
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "6",
    "name": "Living Room",
    "length": "9.83",
    "length1": "9",
    "length2": "10",
    "width": "13.42",
    "width1": "13",
    "width2": "5",
    "totalArea": "131.93",
    "images": [],
    "finalArea": "131.93",
    "extraAreas": []
  }
]
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Passage",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "16.58",
  "width1": "16",
  "width2": "7",
  "totalArea": "49.75",
  "images": [],
  "extraAreas": [
    {
      "measurementType": {
        "value": "Square_Feet",
        "label": "Square Feet"
      },
      "_id": "6495433b17cefc0f57250271",
      "name": "Extra",
      "extraAreaType": "Add",
      "length": "3.17",
      "length1": "3",
      "length2": "2",
      "width": "3.25",
      "width1": "3",
      "width2": "3",
      "totalArea": "10.29"
    }
  ],
  "finalArea": "60.04"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "7.08",
  "length1": "7",
  "length2": "1",
```

```
"width": "9.50",
"width1": "9",
"width2": "6",
"totalArea": "67.29",
"images": [],
"extraAreas": [],
"finalArea": "67.29"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "9.67",
  "length1": "9",
  "length2": "8",
  "width": "10.33",
  "width1": "10",
  "width2": "4",
  "totalArea": "99.89",
  "images": [],
  "extraAreas": [],
  "finalArea": "99.89"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "WC",
  "length": "3.00",
  "length1": "3",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "12.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.00"
},
{
  "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bathroom",
  "length": "3.17",
  "length1": "3",
  "length2": "2",
  "width": "5.00",
  "width1": "5",
  "width2": "00",
  "totalArea": "15.83",
  "images": [],
  "extraAreas": [],
  "finalArea": "15.83"
}
],
"otherComposition": [
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "value": "Balcony",
    "label": "Balcony"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length1": "9",
  "length2": "9",
  "length": "9.75",
  "width1": "4",
  "width2": "1",
  "width": "4.08",
  "totalArea": "39.81",
  "percentageBeforeTotal": "39.81",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "39.81"
},
{
```



```
"toBeAdded": {
  "label": "Carpet",
  "value": "Carpet"
},
"name": {
  "value": "Dry_balcony",
  "label": "Dry Balcony"
},
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "1",
"length1": "2",
"length2": "9",
"length": "2.75",
"width1": "7",
"width2": "6",
"width": "7.50",
"totalArea": "20.62",
"percentageBeforeTotal": "20.62",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "20.62"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "value": "Balcony",
    "label": "Balcony"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length1": "9",
  "length2": "7",
  "length": "9.58",
  "width1": "4",
  "width2": "0",
  "width": "4.00",
```

```
"totalArea": "38.33",
"percentageBeforeTotal": "38.33",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "38.33"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "value": "Dry_balcony",
    "label": "Dry Balcony"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "length1": "4",
  "length2": "00",
  "length": "4.00",
  "width1": "4",
  "width2": "00",
  "width": "4.00",
  "totalArea": "16.00",
  "percentageBeforeTotal": "16.00",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "16"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  },

```

```
"id": "800413",
"selectAreaTypeDocument": "Carpet",
"totalAreaDocument": "513",
"squareMeterArea": "47.66",
"docFinalBuiltUp": "615.6",
"docFinalBuiltUpSquareMeter": "57.19199999999999",
"docBuiltupPercentage": "20",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "649548e7c3eaaa5554d2f753",
  "id": "1",
  "property": "Flat",
  "area": "452",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "https://www.99acres.com/",
  "expectedPrice": "2874000",
  "expectedRate": "6358.41",
  "builtUpExpectedRate": "5298.67",
  "image": "cases/64927378ff2e4a17ce88b02e/
indicator_1687505127279_Image.png"
},
{
  "printlnReport": true,
  "_id": "6495496dc3eaaa5554d2f847",
  "id": "2",
  "property": "Flat",
  "area": "469",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "Housing.Com",
  "expectedPrice": "2650000",
  "expectedRate": "5650.32",
```

```
    "builtUpExpectedRate": "4708.60",
    "image": "cases/64927378ff2e4a17ce88b02e/
indicator_1687505261595_Image.png"
  },
  {
    "printlnReport": true,
    "_id": "64954dc7c3eaaa5554d2fd78",
    "id": "3",
    "property": "Flat",
    "area": "468.99",
    "builtUpPercentage": "20",
    "saleablePercentage": "20",
    "rateType": "sale_Instance",
    "areaType": "Carpet",
    "floor": "1st Floor",
    "source": "Index_no.2",
    "expectedPrice": "2400000",
    "expectedRate": "5117.38",
    "builtUpExpectedRate": "4264.47",
    "image": "cases/64927378ff2e4a17ce88b02e/
indicator_1687506375026_Image.jpeg"
  },
  {
    "printlnReport": true,
    "_id": "64954df5c3eaaa5554d2fd8b",
    "id": "4",
    "property": "Flat",
    "area": "468.99",
    "builtUpPercentage": "20",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "6th Floor",
    "source": "Index_no.2",
    "expectedPrice": "2525000",
    "expectedRate": "5383.91",
    "builtUpExpectedRate": "4486.58",
    "image": "cases/64927378ff2e4a17ce88b02e/
indicator_1687506420998_Image.jpeg"
  }
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64954fe9c3eaaa5554d30143",
```

```
    "name": "externalImg_1687506920836_IMG20230622WA0008.jpg",
    "path": "cases/64927378ff2e4a17ce88b02e/
externalImg_1687506920836_IMG20230622WA0008.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64954fe9c3eaaa5554d30144",
    "name": "externalImg_1687506920861_IMG20230622WA0009.jpg",
    "path": "cases/64927378ff2e4a17ce88b02e/
externalImg_1687506920861_IMG20230622WA0009.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64954fe9c3eaaa5554d30145",
    "name": "externalImg_1687506920902_IMG20230622WA0010.jpg",
    "path": "cases/64927378ff2e4a17ce88b02e/
externalImg_1687506920902_IMG20230622WA0010.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64954fe9c3eaaa5554d30146",
    "name": "externalImg_1687506920924_IMG20230622WA0011.jpg",
    "path": "cases/64927378ff2e4a17ce88b02e/
externalImg_1687506920924_IMG20230622WA0011.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64954fe9c3eaaa5554d30147",
    "name": "externalImg_1687506920952_IMG20230622WA0012.jpg",
    "path": "cases/64927378ff2e4a17ce88b02e/
externalImg_1687506920952_IMG20230622WA0012.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64954fe9c3eaaa5554d30148",
    "name": "externalImg_1687506920970_IMG20230622WA0013.jpg",
```

```
    "path": "cases/64927378ff2e4a17ce88b02e/
externallmg_1687506920970_IMG20230622WA0013.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64954fe9c3eaaa5554d30149",
    "name": "externallmg_1687506920989_IMG20230622WA0014.jpg",
    "path": "cases/64927378ff2e4a17ce88b02e/
externallmg_1687506920989_IMG20230622WA0014.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64954fe9c3eaaa5554d3014a",
    "name": "externallmg_1687506921018_IMG20230622WA0015.jpg",
    "path": "cases/64927378ff2e4a17ce88b02e/
externallmg_1687506921018_IMG20230622WA0015.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64954fe9c3eaaa5554d3014b",
    "name": "externallmg_1687506921036_IMG20230622WA0016.jpg",
    "path": "cases/64927378ff2e4a17ce88b02e/
externallmg_1687506921036_IMG20230622WA0016.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64954fe9c3eaaa5554d3014c",
    "name": "externallmg_1687506921049_IMG20230622WA0017.jpg",
    "path": "cases/64927378ff2e4a17ce88b02e/
externallmg_1687506921049_IMG20230622WA0017.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64954fe9c3eaaa5554d3014d",
    "name": "externallmg_1687506921071_IMG20230622WA0018.jpg",
    "path": "cases/64927378ff2e4a17ce88b02e/
externallmg_1687506921071_IMG20230622WA0018.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64954fe9c3eaaa5554d3014e",
  "name": "externallmg_1687506921092_IMG20230622WA0019.jpg",
  "path": "cases/64927378ff2e4a17ce88b02e/
externallmg_1687506921092_IMG20230622WA0019.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64954ff3c3eaaa5554d30182",
  "name": "externallmg_1687506930235_IMG20230622WA0020.jpg",
  "path": "cases/64927378ff2e4a17ce88b02e/
externallmg_1687506930235_IMG20230622WA0020.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64954ff3c3eaaa5554d30183",
  "name": "externallmg_1687506930249_IMG20230622WA0021.jpg",
  "path": "cases/64927378ff2e4a17ce88b02e/
externallmg_1687506930249_IMG20230622WA0021.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64954ff3c3eaaa5554d30184",
  "name": "externallmg_1687506930272_IMG20230622WA0022.jpg",
  "path": "cases/64927378ff2e4a17ce88b02e/
externallmg_1687506930272_IMG20230622WA0022.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64954ff3c3eaaa5554d30185",
  "name": "externallmg_1687506930286_IMG20230622WA0023.jpg",
  "path": "cases/64927378ff2e4a17ce88b02e/
externallmg_1687506930286_IMG20230622WA0023.jpg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64954ff3c3eaaa5554d30186",
  "name": "externalimg_1687506930305_IMG20230622WA0024.jpg",
  "path": "cases/64927378ff2e4a17ce88b02e/
externalimg_1687506930305_IMG20230622WA0024.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64954ff3c3eaaa5554d30187",
  "name": "externalimg_1687506930321_IMG20230622WA0025.jpg",
  "path": "cases/64927378ff2e4a17ce88b02e/
externalimg_1687506930321_IMG20230622WA0025.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64954ff3c3eaaa5554d30188",
  "name": "externalimg_1687506930333_IMG20230622WA0026.jpg",
  "path": "cases/64927378ff2e4a17ce88b02e/
externalimg_1687506930333_IMG20230622WA0026.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64954ff3c3eaaa5554d30189",
  "name": "externalimg_1687506930358_IMG20230622WA0027.jpg",
  "path": "cases/64927378ff2e4a17ce88b02e/
externalimg_1687506930358_IMG20230622WA0027.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64954ff3c3eaaa5554d3018a",
  "name": "externalimg_1687506930375_IMG20230622WA0028.jpg",
  "path": "cases/64927378ff2e4a17ce88b02e/
externalimg_1687506930375_IMG20230622WA0028.jpg",
  "orientation": "landscape"
},
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64954ff3c3eaaa5554d3018b",
  "name": "externalImg_1687506930401_IMG20230622WA0029.jpg",
  "path": "cases/64927378ff2e4a17ce88b02e/
externalImg_1687506930401_IMG20230622WA0029.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64954ff3c3eaaa5554d3018c",
  "name": "externalImg_1687506930430_IMG20230622WA0030.jpg",
  "path": "cases/64927378ff2e4a17ce88b02e/
externalImg_1687506930430_IMG20230622WA0030.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64954ff3c3eaaa5554d3018d",
  "name": "externalImg_1687506930450_IMG20230622WA0031.jpg",
  "path": "cases/64927378ff2e4a17ce88b02e/
externalImg_1687506930450_IMG20230622WA0031.jpg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"createdAt": "2023-06-21T03:50:16.908Z",
"updatedAt": "2023-06-23T11:54:17.158Z",
"__v": 0,
"fullAddress": "Residential Flat No. 305, 3rd Floor, Wing - A, New Shree Krupa Co-op.
Hsg. Soc. Ltd., Near Sachin Samir Society, Aptewadi, Plot No. 7 & 8 , Village -
Shirgaon, Taluka - Ambernath, District - Thane, Badlapur, State - Maharashtra, India",
"updatedBy": "60eeaeddf3dd69653a581316",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Mrs. Vina Sapkal",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Self",
"siteVisitContactNo": "9967225524",
```

```

"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + WC + Bathroom",
"carpetTotal": "386.97999999999996",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "74.95",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "114.76",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "602.09",
"finalCarpetArea": "501.74",
"finalSalableArea": "662.30",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 513.00",
"buildingServicesRate": "2500",
"flatRate": "5800",
"landOtherRate": "3300",
"reason": "",
"siteVisitDate": "2023-06-22"
}

```

Name	Length	Width	Total
Composition :			
Living Room	9'10"	13'5"	131.93
Passage	3'00"	16'7"	49.75
Kitchen	7'1"	9'6"	67.29
Bedroom	9'8"	10'4"	99.89
WC	3'00"	4'00"	12.00
Bathroom	3'2"	5'00"	15.83

Other
Composition :

Balcony	9'9"	4'1"	39.81
Dry Balcony	2'9"	7'6"	20.62
Balcony	9'7"	4'0"	38.33
Dry Balcony	4'00"	4'00"	16.00