

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b951"
    },
    "type": "CREDITOFFICER",
    "_id": "635f732fe363ef22db2f1c80",
    "firstName": "Ravindra Sir",
    "lastName": "sir",
    "mobileNo": "",
    "email": "me1@me.com",
    "workMobileNo": "7738642220"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "100000000",
    "discussWithPerson": "Ravindra Sir",
    "expectedFees": 50000,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
    "city": "Mumbai"
  }
}
```

```
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b951",
  "branchCode": "000167",
  "type": "BRANCH",
  "name": "RACPC Belapur ",
  "email": "sbi.14677@sbi.co.in",
  "mobileNo": "022-27524090",
  "alternateMobileNo": "",
  "address": "Estate Department Corporate Centre, 4th Floor, CIDCO Tower No. 4,
Railway Station Building, C.B.D. Belapur, Navi Mumbai - 400 614, State - Maharashtra,
Country - India.",
  "ledgerName": "STATE BANK OF INDIA - CBD Estate Department",
  "fax": "022 2757 7002",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7189d2ffdf65bcd65882b",
    "role": "PICKUPPERSON",
    "firstName": "Ravindra",
    "email": "ravindrakasare186@gmail.com",
    "lastName": "Kasare",
    "mobileNo": "9167204055",
```

```
"shortName": "RBK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60b7189d2ffdf65bcd65882b\
\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "60f9343b45132d6a6bdd96e8",
"role": "SITEENGINEER",
"firstName": "Rajesh",
"email": "rajeshb.ghadi@gmail.com",
"lastName": "Ghadi",
"mobileNo": "8652092666",
"designation": "",
"shortName": "RHG",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"maker": {
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
```

```
"type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    }
  }
]
```

```
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.100392069220312",
  "longitude": "73.00735925461575"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.00735925461575,
    19.100392069220312
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-06-21T06:00:00.000Z",
      "remark": ""
    }
  ]
}
```

```
    },
    {
      "dateTime": "2023-06-21T06:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-06-21T06:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-06-21T06:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-06-21T06:00:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "remark": "MANUAL",
      "dateTime": "2023-07-03",
      "status": "COMPLETED"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft."
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Wed Jun 21 2023 11:30:13 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
```

```
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Koparkhairne",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "4",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
}
```

```
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "17",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Gami Vivaan ",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "7",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
```



```
"value": "",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
```

```
"status": false,
"name": "CTS No.",
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "403",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
```

```
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 709",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Wooden_frame_openable_widow_with_M._S._Grill",
```

```

    "label": "Wooden frame openable widow with M. S. Grill"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement Plastering + POP Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "NMMC",
    "label": "Navi Mumbai Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Vision Apartment",
    "west": "Play Ground",
    "south": "Bonkode Road",
    "east": "Anmol Apartment"
  },
  "asPerDocumentAgreement": {
    "north": "Plot No. 11 & 12",
    "west": "Plot for Play Ground",
    "south": "15 Mtrs. Wide Road",
    "east": "Plot No. 15"
  },
  "extraDetailOfProperty": "Details not available"

```

```

    },
    "compositeRate": {
      "remark": "As per Approved Plan Total area of the flat is 537.00 Sq. Ft. (Including Enclosed Balcony + Cupboard Area + Flowerbed Area + Terrace). As per measurement Carpet area is 340 Sq. Ft. (Including Terrace + Balcony). However in the Agreement only 340.00 Sq. Ft. Carpet area is mentioned. Extra area which is mentioned in the Approved Plan and also found at site is not mentioned. For the purpose of valuation we have considered the area as per Agreement. Hence to give proper weightage to the value of the property, higher rate i.e. Rs. 30,800/- per Sq. Ft. considered.<br />\nRate on 340 Sq. Ft. Carpet comes to Rs. 30800/- per Sq. Ft. If we consider area as per Plan of 537.00 Sq. Ft. then the rate will come Rs. 19,500/- per Sq. Ft. Difference is due to RERA Carpet area mentioned in the Agreement and Total Carpet area mentioned in the Approved Plan.\n ",
      "depreciationPercentage": "",
      "depreciationRatioOfBuilding": "",
      "salvageValue": "",
      "depreciatedCostOfConstruction": "",
      "depreciatedBuildingRate": ""
    },
    },
    "igrRate": {
      "propertyName": "Flat",
      "rate": "121800",
      "landRate": "53400",
      "igrImage": "cases/649285ebff2e4a17ce88c508/igr_1688974320521_Image.png",
      "squareMeterGuideLineRate": "121800.00",
      "squareFeetGuideLineRate": "11316.00"
    },
    },
    "igrFinalRate": {
      "rate": "10998.00",
      "squareFeetGuideLineRate": "10998.00",
      "squareMeterGuideLineRate": "118380.00"
    },
    },
    "outgoingDetail": {
      "areaStatusList": {
        "value": "Medium",
        "label": "Medium"
      },
      },
      "propertyTypeOfUseList": {
        "value": "Residential_Purpose",
        "label": "Residential Purpose"
      },
      },
      "propertyOccupiedByList": {
        "value": "Owner_Occupied",
        "label": "Owner Occupied"
      },
      },
      "monthlyRent": "26,000",

```

```
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per NMMC norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed Area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt Car Parking Space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
```

```
"month": "1",
"year": "2020",
"fullDate": "1/1/2020"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
```

```
"label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "3",
"totalLifeBuilding": "60",
"estimatedAge": "57",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "18",
"flatFloorNo": "4",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "5"
},
"finalPlinthArea": {
  "area": "590.70",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
```



```
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/649285ebff2e4a17ce88c508/
routeMap_1688641426626_Image.png",
    "routeLat": "19.100137",
    "routeLng": "73.007168",
    "stationName": "Kopar Khairane",
    "routeDistance": "1.5 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finalLatLng": true
  },
  "locationMapImg": [
    {
      "id": "h45u7",
      "name": "h45u7",
      "image": "cases/649285ebff2e4a17ce88c508/
routeMap_1688641171865_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",

```

```
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "10472000.00",
"bookValue": "0",
"finalValue": "10472000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
```

```
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```

```
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "4113252.00",
  "selectedBuildUpValue": "374.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "64a69ff1c325d356190d7fad",
      "name": "externallmg_1688641520283_IMG_20230704_184849.jpg",
      "path": "cases/649285ebff2e4a17ce88c508/
externallmg_1688641520283_IMG_20230704_184849.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "64a69ff1c325d356190d7fb3",
      "name": "Living Room",
      "path": "cases/649285ebff2e4a17ce88c508/externallmg_r_1688641520256_JKFan
tasy_aHE_ew_AwaEAWAaAzWwaa_aaAssZwa_Zss_aWR___20230704_064100PM__
_xrrddrrxz2223murism___1961_N_7302org.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "64a69ff1c325d356190d7fb5",
      "name": "Living Room",
      "path": "cases/649285ebff2e4a17ce88c508/externallmg_r_1688641520263_JKFan
tasy_aHE_ew_AwaEAWAaAzWwaa_aaAssZwa_Zss_aWR___20230704_064109PM__
```

```
_xrddrrxz2223murism___1961_N_7302org.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "64a69ff1c325d356190d7fb9",
  "name": "Living Room",
  "path": "cases/649285ebff2e4a17ce88c508/externallmg_r_1688641520275_JKFan
tasy_aHE_ew_AwaEAWAaAzWwaa_aaAssZwa_Zss_aWR___20230704_064126PM___
_xrddrrxz2223murism___1961_N_7302org.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "64a69ff1c325d356190d7fba",
  "name": "Living Room",
  "path": "cases/649285ebff2e4a17ce88c508/externallmg_r_1688641520279_JKFan
tasy_aHE_ew_AwaEAWAaAzWwaa_aaAssZwa_Zss_aWR___20230704_064137PM___
_xrddrrxz2223murism___1961_N_7302org.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "64a69ff1c325d356190d7fb7",
  "name": "Living Room",
  "path": "cases/649285ebff2e4a17ce88c508/externallmg_r_1688641520272_JKFan
tasy_aHE_ew_AwaEAWAaAzWwaa_aaAssZwa_Zss_aWR___20230704_064121PM___
_xrddrrxz2223murism___1961_N_7302org.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "64a69ff1c325d356190d7fb4",
  "name": "Living Room",
  "path": "cases/649285ebff2e4a17ce88c508/externallmg_r_1688641520237_JKFan
tasy_aHE_ew_AwaEAWAaAzWwaa_aaAssZwa_Zss_aWR___20230704_063447PM___
_xrddrrxz2223murism___1960_N_7302org.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "64a69ff1c325d356190d7fae",
  "name": "Living Room",
  "path": "cases/649285ebff2e4a17ce88c508/
externallmg_1688641520291_IMG_20230704_184850.jpg",
  "orientation": "portrait"
}
```

```
    },
    {
      "status": false,
      "_id": "64a69ff1c325d356190d7fad",
      "name": "Living Room",
      "path": "cases/649285ebff2e4a17ce88c508/
externallmg_1688641520283_IMG_20230704_184849.jpg",
      "orientation": "portrait"
    }
  ]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```



```
"isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "340.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
```

```
"caseStatus": "READYFORCHECKER",
"_id": "649285ebff2e4a17ce88c508",
"ownerName": "Mr. Prashant Dinkar Kamble & Mrs. Snehal Harish Sakpal",
"ownerPhoneNo": "9821885033",
"appAddress": "flat no. 403 4 th floor Gami vivaan plot no. 17 sec. 07 koparkhairne ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "20/01/2020",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. New Path Developers ",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Mr. Prashant Dinkar Kamble & Mrs. Snehal Harish Sakpal"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "613039",
    "path": "cases/649285ebff2e4a17ce88c508/
document_1687327194110_Sbi_Racpc_belapur_prashant__kamble.pdf",
    "fileName":
"document_1687327194110_Sbi_Racpc_belapur_prashant__kamble.pdf"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    },
    "inputs": {
      "documentDate": "03/05/2018",
      "nameOfApprovingAuthority": {
        "value": "Navi_Mumbai_Municipal_Corporation.",
        "label": "Navi Mumbai Municipal Corporation."
      },
      "number": {
        "value": "Document_No",
```

```
    "label": "Document No"
  },
  "Document_No": "NMMC / TPD / BP / Online No. 2018CNMMC12860 / 1841 /
2018"
},
"isHardCopy": false,
"displayStatus": false,
"id": "151785",
"path": "cases/649285ebff2e4a17ce88c508/document_1688637250810_CC.pdf",
"fileName": "document_1688637250810_CC.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "09/01/2020",
    "nameOfApprovingAuthority": {
      "value": "Navi_Mumbai_Municipal_Corporation.",
      "label": "Navi Mumbai Municipal Corporation."
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "NRV / OC / P. K. 2019BONMMC56261 / 126 / 2020"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1688637517883_OC.pdf",
"path": "cases/649285ebff2e4a17ce88c508/document_1688637517883_OC.pdf",
"id": "694739",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Thu Jul 06 2023 15:28:38 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "13/07/2018",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  }
}
```

```
    },
    "Document_No": "P51700017119"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/649285ebff2e4a17ce88c508/
document_1688637582757_593002.pdf",
  "id": "104417",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Thu Jul 06 2023 15:29:42 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "03/05/2018",
    "nameOfApprovingAuthority": {
      "value": "Navi_Mumbai_Municipal_Corporation.",
      "label": "Navi Mumbai Municipal Corporation."
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "20181C / NMMC / 12860 / NRV / BP / A / 1841"
},
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1688708469305_Project_report.pdf",
  "path": "cases/649285ebff2e4a17ce88c508/
document_1688708469305_Project_report.pdf",
  "id": "939972",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Fri Jul 07 2023 11:11:09 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "002060",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "288567",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Jun 21 2023 10:38:59 GMT+0530 (India Standard Time)"
  }
]
```

```
}
],
"owners": [
  {
    "name": "Mr. Prashant Dinkar Kamble & Mrs. Snehal Harish Sakpal",
    "phone": "9821885033",
    "email": "",
    "ownershipShare": "",
    "id": "281693"
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "221522",
    "name": "Living Room",
    "length": "12.67",
    "length1": "12",
    "length2": "8",
    "width": "10.17",
    "width1": "10",
    "width2": "2",
    "totalArea": "128.78",
    "images": [],
    "extraAreas": [],
    "finalArea": "128.78"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Living Room",
    "length": "7.42",
    "length1": "7",
    "length2": "5",
    "width": "7.42",
    "width1": "7",
    "width2": "5",
    "totalArea": "55.01",
    "images": [],
```

```
"extraAreas": [],
"finalArea": "55.01"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "9.25",
  "length1": "9",
  "length2": "3",
  "width": "6.17",
  "width1": "6",
  "width2": "2",
  "totalArea": "57.04",
  "images": [],
  "extraAreas": [],
  "finalArea": "57.04"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "3.08",
  "length1": "3",
  "length2": "1",
  "width": "4.08",
  "width1": "4",
  "width2": "1",
  "totalArea": "12.59",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.59"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
```

```
"length": "9.67",
"length1": "9",
"length2": "8",
"width": "10.67",
"width1": "10",
"width2": "8",
"totalArea": "103.11",
"images": [],
"extraAreas": [],
"finalArea": "103.11"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "8.67",
  "length1": "8",
  "length2": "8",
  "width": "11.25",
  "width1": "11",
  "width2": "3",
  "totalArea": "97.50",
  "images": [],
  "extraAreas": [],
  "finalArea": "97.50"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "WC",
  "length": "3.50",
  "length1": "3",
  "length2": "6",
  "width": "5.75",
  "width1": "5",
  "width2": "9",
  "totalArea": "20.12",
  "images": [],
  "extraAreas": [],
  "finalArea": "20.12"
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Bathroom",
  "length": "6.50",
  "length1": "6",
  "length2": "6",
  "width": "3.75",
  "width1": "3",
  "width2": "9",
  "totalArea": "24.37",
  "images": [],
  "extraAreas": [],
  "finalArea": "24.37"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "value": "Terrace",
      "label": "Terrace"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length1": "5",
    "length2": "0",
    "length": "5.00",
    "width1": "10",
    "width2": "0",
    "width": "10.00",
    "totalArea": "50.00",
    "percentageBeforeTotal": "50.00",
    "images": [],
    "extraAreas": [],
    "percentage": "100",
```



```
    "finalArea": "50"
  }
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "369297",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "340",
    "squareMeterArea": "31.59",
    "docFinalBuiltUp": "374",
    "docFinalBuiltUpSquareMeter": "34.749",
    "docBuiltupPercentage": "10",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  },
  {
    "typeOfDocument": {
      "value": "60ae1277aa6d152c1801b3cc",
      "label": "Approved Building Plan"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "615689",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "537",
    "squareMeterArea": "49.89",
    "docFinalBuiltUp": "590.7",
    "docFinalBuiltUpSquareMeter": "54.879",
    "docBuiltupPercentage": "10",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
```

```
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "64ababd406d6ec1749856ede",
    "id": "1",
    "property": "Flat",
    "area": "520",
    "builtUpPercentage": "10",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "",
    "source": "https://www.99acres.com/",
    "expectedPrice": "10200000",
    "expectedRate": "19615.38",
    "builtUpExpectedRate": "17832.17",
    "image": "cases/649285ebff2e4a17ce88c508/indicator_1688972243980_Image.png"
  },
  {
    "printlnReport": true,
    "_id": "64abaea806d6ec1749857b8d",
    "id": "3",
    "property": "Flat",
    "area": "400",
    "builtUpPercentage": "10",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "",
    "source": "https://www.99acres.com/",
    "expectedPrice": "8000000",
    "expectedRate": "20000.00",
    "builtUpExpectedRate": "18181.82",
    "image": "cases/649285ebff2e4a17ce88c508/indicator_1688972968524_Image.png"
  },
  {
    "printlnReport": true,
    "_id": "64abaef206d6ec1749857ceb",
    "id": "4",
    "property": "Flat",
    "area": "430",
    "builtUpPercentage": "10",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
```

```
"floor": "",
"source": "magic_bricks",
"expectedPrice": "8500000",
"expectedRate": "19767.44",
"builtUpExpectedRate": "17970.40",
"image": "cases/649285ebff2e4a17ce88c508/indicator_1688973042897_Image.png"
},
{
  "printlnReport": true,
  "_id": "64abb1f906d6ec1749858ee8",
  "id": "5",
  "property": "Flat",
  "area": "419",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "magic_bricks",
  "expectedPrice": "7800000",
  "expectedRate": "18615.75",
  "builtUpExpectedRate": "16923.41",
  "image": "cases/649285ebff2e4a17ce88c508/indicator_1688973817200_Image.png"
},
{
  "printlnReport": true,
  "_id": "64ad0e3ad9a15943959f3abc",
  "id": "5",
  "property": "Flat",
  "area": "350",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "Housing.Com",
  "expectedPrice": "11500000",
  "expectedRate": "32857.14",
  "builtUpExpectedRate": "29870.13",
  "image": "cases/649285ebff2e4a17ce88c508/indicator_1689062970140_Image.png"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
  }
]
```

```
    "_id": "64a69ff1c325d356190d7fad",
    "name": "externallmg_1688641520283_IMG_20230704_184849.jpg",
    "path": "cases/649285ebff2e4a17ce88c508/
externallmg_1688641520283_IMG_20230704_184849.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64a69ff1c325d356190d7fae",
    "name": "externallmg_1688641520291_IMG_20230704_184850.jpg",
    "path": "cases/649285ebff2e4a17ce88c508/
externallmg_1688641520291_IMG_20230704_184850.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64a69ff1c325d356190d7faf",
    "name": "externallmg_1688641520299_IMG_20230704_184852.jpg",
    "path": "cases/649285ebff2e4a17ce88c508/
externallmg_1688641520299_IMG_20230704_184852.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64a69ff1c325d356190d7fb0",
    "name": "externallmg_1688641520303_Screenshot_20230705_085505.jpg",
    "path": "cases/649285ebff2e4a17ce88c508/
externallmg_1688641520303_Screenshot_20230705_085505.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64a69ff1c325d356190d7fb1",
    "name": "externallmg_r_1688641520251_JKFantasy_aHE_ew_AwaEAWAaAzWwaa_
_aaAssZwa_Zss_aWR___20230704_064058PM___xrddrrxz2223murism___1961_N_
7302org.jpg",
    "path": "cases/649285ebff2e4a17ce88c508/externallmg_r_1688641520251_JKFant
asy_aHE_ew_AwaEAWAaAzWwaa_aaAssZwa_Zss_aWR___20230704_064058PM___
xrddrrxz2223murism___1961_N_7302org.jpg",
    "orientation": "portrait"
  },
  {
```

```
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "64a69ff1c325d356190d7fb4",
"name": "externallmg_r_1688641520237_JKFantasy_aHE_ew_AwaEAWAaAzWwaa_aaAssZwa_Zss_aWR___20230704_063447PM___xrddrrxz2223murism___1960_N_7302org.jpg",
"path": "cases/649285ebff2e4a17ce88c508/externallmg_r_1688641520237_JKFantasy_aHE_ew_AwaEAWAaAzWwaa_aaAssZwa_Zss_aWR___20230704_063447PM___xrddrrxz2223murism___1960_N_7302org.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "64a69ff1c325d356190d7fb5",
"name": "externallmg_r_1688641520263_JKFantasy_aHE_ew_AwaEAWAaAzWwaa_aaAssZwa_Zss_aWR___20230704_064109PM___xrddrrxz2223murism___1961_N_7302org.jpg",
"path": "cases/649285ebff2e4a17ce88c508/externallmg_r_1688641520263_JKFantasy_aHE_ew_AwaEAWAaAzWwaa_aaAssZwa_Zss_aWR___20230704_064109PM___xrddrrxz2223murism___1961_N_7302org.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "64a69ff1c325d356190d7fb6",
"name": "externallmg_r_1688641520268_JKFantasy_aHE_ew_AwaEAWAaAzWwaa_aaAssZwa_Zss_aWR___20230704_064114PM___xrddrrxz2223murism___1961_N_7302org.jpg",
"path": "cases/649285ebff2e4a17ce88c508/externallmg_r_1688641520268_JKFantasy_aHE_ew_AwaEAWAaAzWwaa_aaAssZwa_Zss_aWR___20230704_064114PM___xrddrrxz2223murism___1961_N_7302org.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "64a69ff1c325d356190d7fb7",
"name": "externallmg_r_1688641520272_JKFantasy_aHE_ew_AwaEAWAaAzWwaa_aaAssZwa_Zss_aWR___20230704_064121PM___xrddrrxz2223murism___1961_N_7302org.jpg",
"path": "cases/649285ebff2e4a17ce88c508/externallmg_r_1688641520272_JKFantasy_aHE_ew_AwaEAWAaAzWwaa_aaAssZwa_Zss_aWR___20230704_064121PM___xrddrrxz2223murism___1961_N_7302org.jpg",
"orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64a69ff1c325d356190d7fb8",
      "name": "externallmg_r_1688641520260_JKFantasy_aHE_ew_AwaEAWAaAzWwaa_aaAssZwa_Zss_aWR___20230704_064103PM___xrddrrxz2223murism___1961_N_7302org.jpg",
      "path": "cases/649285ebff2e4a17ce88c508/externallmg_r_1688641520260_JKFantasy_aHE_ew_AwaEAWAaAzWwaa_aaAssZwa_Zss_aWR___20230704_064103PM___xrddrrxz2223murism___1961_N_7302org.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64a69ff1c325d356190d7fb9",
      "name": "externallmg_r_1688641520275_JKFantasy_aHE_ew_AwaEAWAaAzWwaa_aaAssZwa_Zss_aWR___20230704_064126PM___xrddrrxz2223murism___1961_N_7302org.jpg",
      "path": "cases/649285ebff2e4a17ce88c508/externallmg_r_1688641520275_JKFantasy_aHE_ew_AwaEAWAaAzWwaa_aaAssZwa_Zss_aWR___20230704_064126PM___xrddrrxz2223murism___1961_N_7302org.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64a69ff1c325d356190d7fba",
      "name": "externallmg_r_1688641520279_JKFantasy_aHE_ew_AwaEAWAaAzWwaa_aaAssZwa_Zss_aWR___20230704_064137PM___xrddrrxz2223murism___1961_N_7302org.jpg",
      "path": "cases/649285ebff2e4a17ce88c508/externallmg_r_1688641520279_JKFantasy_aHE_ew_AwaEAWAaAzWwaa_aaAssZwa_Zss_aWR___20230704_064137PM___xrddrrxz2223murism___1961_N_7302org.jpg",
      "orientation": "portrait"
    }
  ],
  "externalDocuments": [],
  "createdAt": "2023-06-21T05:08:59.161Z",
  "updatedAt": "2023-07-11T12:04:30.201Z",
  "__v": 0,
  "fullAddress": "Residential Flat No. 403, 4th Floor, Gami Vivaan , Plot No. 17, Sector 7, Village - Koparkhairne, Taluka - Thane, District - Thane, Navi Mumbai, PIN - 400 709, State - Maharashtra, India",
  "updatedBy": "5fc78e26625ecd20ec1f88e9",
```

```

"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Prashant Dinkar Kamble",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9821885033",
"briefDescOfProperty": "2 Bedroom + 2 Living Room + Kitchen + Passage + WC +
Bathroom",
"carpetTotal": "498.52",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "50.00",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "50.00",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "603.37",
"finalCarpetArea": "548.52",
"finalSalableArea": "663.71",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "Carpet Area in Sq. Ft. = 340.00\nEnclosed Balcony Area in
Sq. Ft. = 65.00\nCup Board Area in Sq. Ft. = 48.00\nFlower Bed Area in Sq. Ft. =
36.00\nTerrace Area in Sq. Ft. = 48.00<br />\nTotal Carpet Area in Sq. Ft. = 537.00\n",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 499.00\nTerrace Area in Sq. Ft. =
50.00\nTotal Carpet Area in Sq. Ft. = 549.00<br />\n\n\n",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 340.00",
"buildingServicesRate": "2500",
"flatRate": "30800",
"landOtherRate": "28300"
}

```

| Name | Length | Width | Total |
|---------------|--------|-------|--------|
| Composition : | | | |
| Living Room | 12'8" | 10'2" | 128.78 |
| Living Room | 7'5" | 7'5" | 55.01 |

| | | | |
|------------------------|------|-------|--------|
| Kitchen | 9'3" | 6'2" | 57.04 |
| Passage | 3'1" | 4'1" | 12.59 |
| Bedroom | 9'8" | 10'8" | 103.11 |
| Bedroom | 8'8" | 11'3" | 97.50 |
| WC | 3'6" | 5'9" | 20.12 |
| Bathroom | 6'6" | 3'9" | 24.37 |
| Other Composition : | | | |
| Terrace | 5'0" | 10'0" | 50.00 |