


# Valuation Report of the Immovable Property



Details of the property under consideration:

Name of Owner: Mr. Vijendra Ranka

Commercial Office No. 320, 3<sup>rd</sup> Floor, East Wing, **"Aurora Towers Premises Co-op. Soc. Ltd."**, 9, Moledina Road, Taluka – Haveli, District – Pune, Pin Code – 411 001, State - Maharashtra, Country – India.

Longitude Latitude: 18°31'05.4"N 73°52'43.5"E

Valuation Done for:

Thin Union Bank of India Create SAMB Fort Branch Bharat House, Ground Floor, 104, M. S. Marg, Fort, Mumbai - 400001, State - Maharashtra, Country - India



 Our Pan India Presence at :

 <sup>o</sup> Mumbai

 <sup>o</sup> Aurangabad

 <sup>o</sup> Pune

 <sup>o</sup> Rajkot

 <sup>o</sup> Thane

 <sup>o</sup> Nanded

 <sup>o</sup> Indore

 <sup>o</sup> Raipur

 <sup>o</sup> Delhi NCR

 <sup>o</sup> Nashik

 <sup>o</sup> Ahmedabad

 <sup>o</sup> Jaipur

 Regd. Office : B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Andheri (East),
 Mumbai - 400 072, (M.S.), INDIA
 TeleFax : +91 22 28371325/24

⊠ mumbai@vastukala.org





Valuation Report Prepared For: Union Bank of India / SAMB Fort Branch / Mr. Vijendra Ranka (2184/2301343) Page 2 of 22

Vastu/Mumbai/06/2023/2184/2301343 28/31-444-PSH Date: 28.06.2023

## VALUATION OPINION REPORT

This is to certify that the property bearing Commercial Office No. 320, 3<sup>rd</sup> Floor, East Wing, **"Aurora Towers Premises Co-op. Soc. Ltd."**, 9, Moledina Road, Taluka – Haveli, District – Pune, Pin Code – 411 001, State -Maharashtra, Country – India belongs to **Mr. Vijendra Ranka**.

#### Boundaries of the property.

North:Aurora Hotel & Moledina RoadSouth:Bootee St. RoadEast:Mumbai Pandharpur RoadWest:Clover Centre Market

Considering various parameters recorded, existing economic scenario, and the information that is available with reference to the development of neighborhood and method selected for valuation, we are of the opinion that, the property premises can be assessed and valued for Securitisation and Reconstruction of Financial Assets and Enforcement of Security Interest Act, 2002 purpose at ₹ 84,11,000.00 (Rupees Eighty Four Lakh Eleven Thousand Only).

The valuation of the property is based on the documents produced by the concern. Legal aspects have not been taken into considerations while preparing this valuation report.

Hence certified

For VASTUKALA CONSULTANTS (I) PVT. LTD. Think.Innovate.CI

#### Valuer A Appriates Periode a Introf Degister Charter Espiners Charter Espiners Charter Espiners Charter Espiners MH2010 PTU<sup>NIN</sup>

# Director

Auth. Sign.

## Sharadkumar B. Chalikwar

Govt. Reg. Valuer Chartered Engineer (India) Reg. No. (N) CCIT/1-14/52/2008-09 Encl: Valuation report.



 Our Pan India Presence at :

 Mumbai
 Aurangabad
 Pune
 Aurangabad
 Pune
 Pune
 Rajkot
 Raipur
 Delhi NCR
 Nashik
 Ahmedabad
 Pune
 Aurangabat
 Pune
 Pune

 Regd. Office : B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Andheri (East),
 Mumbai - 400 072, (M.S.), INDIA
 TeleFax : +91 22 28371325/24

✓ mumbai@vastukala.org

## Vastukala Consultants (I) Pvt. Ltd.

B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai, Andheri (East), Mumbai – 400 072

Τo,

#### The Branch Manager, Union Bank of India

## SAMB – Fort Branch

Bharat House, Ground Floor, 104, M. S. Marg, Fort, Mumbai - 400001, State - Maharashtra, Country – India.

## VALUATION REPORT (IN RESPECT OF OFFICE)

Ι	Gene	ral		
1.	Purpose for which the valuation is made		:	As per the request from Union Bank of India, SAMB Fort Branch to assess fair market value of the property for SARFAESI Securitisation and Reconstruction of Financial Assets and Enforcement of Security Interest Act, 2002 purpose
2.	a) Date of inspection		:	21.06.2023
	b)	Date on which the valuation is made	:	28.06.2023
3.	Ranka (The Donee)		neni e)	/w. Mr. Yogesh Saraswate (The Donor) and Mr. Vijendra : dated 28.03.2007 b/w Mrs. Rattan Pasricha (Assignor)
4.		e of the owner(s) and his / their address	:	Mr. Vijendra Ranka
	(es) with Phone no. (details of share of each owner in case of joint ownership) Think.Innc			Address: Commercial Office No. 320, 3 <sup>rd</sup> Floor, East Wing, <b>"Aurora Towers Premises Co-op. Soc. Ltd."</b> , 9, Moledina Road, Taluka – Haveli, District – Pune, Pin Code – 411 001, State - Maharashtra, Country – India. Contact Person: Mrs. Sadhana (Bank Officer) Contact No.: 9769197822 Sole Ownership
5.		description of the property (Including	:	The property is a Commercial Office located on 3 <sup>rd</sup> Floor. The composition of Office consists of Working
	Leasehold / freehold etc.)			Area. The property is 2.1 Km. travelling distance from nearest railway station Pune.
6.	Locat	ion of property	:	
	a)	Plot No. / Survey No.	:	Survey No. 249 of Village - Pune Cantonment Area
	b)	Door No.	:	Commercial Office No. 320
	c)	C.T.S. No. / Village	:	Village - Pune Cantonment Area
	d)	Ward / Taluka	:	Taluka – Haveli
	e)	Mandal / District	:	District – Pune
	f)	Date of issue and validity of layout of	:	Copy of approved building plans were not provided and
		approved map / plan		not verified.





r	1 1				
	g)	Approved map / plan issuing authority	:		
	h)	Whether genuineness or authenticity of approved map/ plan is verified	:	N.A.	
	i)	Any other comments by our			
	''	empanelled valuers on authentic of			
		approved plan			
7.	Posta	address of the property	:	Commercial Office No	320, 3 <sup>rd</sup> Floor, East Wing,
1.	1 03(0)	address of the property	•		ses Co-op. Soc. Ltd.", 9,
					Haveli, District – Pune, Pin
					aharashtra, Country – India.
8.	City /	Town	:	Pune	
		ential area	:	No	
		nercial area		Yes	
		rial area	1:	No	
9.		fication of the area	1:		
<i>.</i>		n / Middle / Poor	<u>:</u>	Middle Class	
	, -	an / Semi Urban / Rural		Urban	
10.	,	ng under Corporation limit / Village		Village - Pune Cantonmen	t Area
10.		ayat / Municipality	· ·	Pune Municipal Corporatio	
11.		her covered under any State / Central	:	No	11
' ' '		enactments (e.g., Urban Land Ceiling			
		r notified under agency area/ scheduled			
	,	cantonment area			
12.		laries of the property		As per Site	As per Documents
	North	<u> </u>		Aurora Hotel & Moledina	Details not available
	literat		/		
				Road	
	South			Bootee St. Road	Details not available
	East			Mumbai Pandharpur	Details not available
		Think Inc.		Road	
	West	Innk.inn(	V	Clover Centre Market	Details not available
13	Dimer	isions of the site	1	N. A. as property under co Office in a building.	onsideration is a Commercial
				A	В
				As per the Deed	Actuals
	North		:	-	-
	South		:	-	-
	East		:	-	-
1			1.		_
	West		:	-	-
14.		t of the site	:	- Carpet Area in Sq. Ft. = 60	7.00
14.		t of the site	_	Carpet Area in Sq. Ft. = 60 (Area as per actual site me	
14.		t of the site	_		easurement)





Extent of the site considered for Valuation (least of 13A& 13B)       :       Built Up Area in Sq. Ft. = 647.00 (Area as per Deed of Gift)         16       Whether occupied by the owner / tenant? If occupied by tenant since how long? Rent received per month.       :       Tenant Occupied – M/s. Balaji Global         II       APARTMENT BUILDING       :       Commercial         1.       Nature of the Apartment       :       Commercial         2.       Location       :       Survey No. 249         Block No.       :       -         Village / Municipality / Corporation       :       -         Village / Municipality / Corporation       :       Village - Pune Cantonment Area Pune Municipal Corporation         Door No., Street or Road (Pin Code)       :       Commercial Office No. 320, 3rd Floor, East Wing, "Aurora Towers Premises Co-op. Soc. Ltd.", 9,				
15.       (least of 13A& 13B)       (Area as per Deed of Gift)         16       Whether occupied by the owner / tenant? If occupied by tenant since how long? Rent received per month.       Tenant Occupied – M/s. Balaji Global         11       APARTMENT BUILDING       Image: Commercial for the state of the Apartment for the Apartment Apar	14.1	Latitude, Longitude & Co-ordinates of Office	:	18°31'05.4"N 73°52'43.5"E
16       Whether occupied by the owner / tenant? If cocupied by tenant since how long? Rent received per month.       Image: Tenant Occupied – M/s. Balaji Global         II       APARTMENT BUILDING       Image: Tenant Occupied – M/s. Balaji Global         1.       Nature of the Apartment       Image: Commercial         2.       Location       Image: C.T.S. No.       Image: Survey No. 249         Block No.       Image: C.T.S. No.       Image: Survey No. 249         Block No.       Image: C.T.S. No.       Image: Survey No. 249         Village / Municipality / Corporation       Image: Village - Pune Cantonment Area Pune Municipal Corporation         Door No., Street or Road (Pin Code)       Image: Commercial Office No. 320, 3rd Floor, East Wing, "Aurora Towers Premises Co-op. Soc. Ltd.", 9, Moledina Road, Taluka – Haveli, District – Pune, Pin Code – 411 001, State - Maharashtra, Country – India.         3.       Description of the locality Residential / Imdustrial / Mixed       Image: Ground + 5 Upper Floors         4.       Year of Construction       Image: Rec.C. Framed Structure         7.       Number of Floors       Image: Rec.C. Framed Structure         8.       Quality of Construction       Image: Normal         9.       Appearance of the Building       Normal         9.       Normal       Image: Normal         10.       Maintenance of the Building       Image: No			:	• •
occupied by tenant since how long? Rent received per month.       Image: Application of the Apartment is commercial         I.       Nature of the Apartment is commercial         2.       Location is commercial         C.T.S. No.       Survey No. 249         Block No.       is commercial         Village / Municipality / Corporation       Village - Pune Cantonment Area Pune Municipal Corporation         Door No., Street or Road (Pin Code)       Commercial Office No. 320, 3rd Floor, East Wing, "Aurora Towers Premises Co-op. Soc. Ltd.", 9, Moledina Road, Taluka – Haveli, District – Pune, Pin Code – 411 001, State - Maharashtra, Country – India.         3.       Description of the locality Residential / Industrial / Mixed       Commercial         4.       Year of Construction       Image: Society and Structure         5.       Number of Floors       Ground + 5 Upper Floors         6.       Type of Structure       R.C.C. Framed Structure         7.       Number of Dwelling Offices in the building       22 Offices on 3rd Floor         8.       Quality of Construction       Normal         9.       Normal       Normal         10.       Maintenance of the Building       Normal         11.       Facilities Available       Municipal Water supply         Underground Sewerage       Municipal Water supply         Underground Sewera				· · · ·
received per month.         II       APARTMENT BUILDING         1.       Nature of the Apartment       :         2.       Location       :         C.T.S. No.       :       Survey No. 249         Block No.       :       -         Ward No.       :       -         Village / Municipality / Corporation       :       :         Door No., Street or Road (Pin Code)       :       Commercial Office No. 320, 3rd Floor, East Wing, "Aurora Towers Premises Co-op. Soc. Ltd.", 9, Moledina Road, Taluka – Haveli, District – Pune, Pin Code – 411 001, State - Maharashtra, Country – India.         3.       Description of the locality Residential / I.       :       Commercial         Industrial / Mixed       :       :       Commercial         4.       Year of Construction       :       1983 (Approx.)         5.       Number of Floors       :	16	Whether occupied by the owner / tenant? If		Tenant Occupied – M/s. Balaji Global
II       APARTMENT BUILDING         1.       Nature of the Apartment       :       Commercial         2.       Location       :       Survey No. 249         Block No.       :       -         Ward No.       :       -         Village / Municipality / Corporation       :       -         Ward No.       :       -         Village / Municipality / Corporation       :       Village - Pune Cantonment Area Pune Municipal Corporation         Door No., Street or Road (Pin Code)       :       Commercial Office No. 320, 3rd Floor, East Wing, "Aurora Towers Premises Co-op. Soc. Ltd.", 9, Moledina Road, Taluka – Haveli, District – Pune, Pin Code – 411 001, State - Maharashtra, Country – India.         3.       Description of the locality Residential / Industrial / Mixed       :       Commercial         4.       Year of Construction       :       1983 (Approx.)         5.       Number of Floors       :       Ground + 5 Upper Floors         6.       Type of Structure       :       R.C.C. Framed Structure         7.       Number of Dwelling Offices in the building       :       22 Offices on 3rd Floor         8.       Quality of Construction       :       Normal         10.       Maintenance of the Building       :       Normal         11		occupied by tenant since how long? Rent		
1.       Nature of the Apartment       :       Commercial         2.       Location       :       Survey No. 249         Block No.       :       -         Ward No.       :       -         Village / Municipality / Corporation       :       -         Door No., Street or Road (Pin Code)       :       Commercial Office No. 320, 3rd Floor, East Wing, "Aurora Towers Premises Co-op. Soc. Ltd.", 9, Moledina Road, Taluka – Haveli, District – Pune, Pin Code – 411 001, State - Maharashtra, Country – India.         3.       Description of the locality Residential / Industrial / Mixed       :       Commercial         4.       Year of Construction       :       1983 (Approx.)       :         5.       Number of Floors       :       Ground + 5 Upper Floors       :         6.       Type of Structure       :       R.C.C. Framed Structure         7.       Number of Dwelling Offices in the building       :       22 Offices on 3rd Floor         8.       Quality of Construction       :       Normal         9.       Appearance of the Building       :       Norma		received per month.		
2.       Location       :         C.T.S. No.       :       Survey No. 249         Block No.       :       -         Ward No.       :       -         Village / Municipality / Corporation       :       -         Village / Municipality / Corporation       :       -         Door No., Street or Road (Pin Code)       :       Commercial Office No. 320, 3rd Floor, East Wing, "Aurora Towers Premises Co-op. Soc. Ltd.", 9, Moledina Road, Taluka – Haveli, District – Pune, Pin Code – 411 001, State - Maharashtra, Country – India.         3.       Description of the locality Residential / Industrial / Mixed       :       Commercial Industrial / Mixed         4.       Year of Construction       :       1983 (Approx.)         5.       Number of Floors       :       R.C.C. Framed Structure         7.       Number of Structure       :       Normal         9.       Appearance of the Building       :       Normal         10.       Maintenance of the Building       :       Normal         11.       Facilities Available       :       :         Lift       :       1 Lift       :       1 Lift         Protected Water Supply       :       Municipal Water supply       Underground Sewerage System         Car parking - Open / Covere	II	APARTMENT BUILDING		
C.T.S. No.       :       Survey No. 249         Block No.       :       -         Ward No.       :       -         Village / Municipality / Corporation       :       -         Village / Municipality / Corporation       :       -         Door No., Street or Road (Pin Code)       :       Commercial Office No. 320, 3rd Floor, East Wing, "Aurora Towers Premises Co-op. Soc. Ltd.", 9, Moledina Road, Taluka – Haveli, District – Pune, Pin Code – 411 001, State - Maharashtra, Country – India.         3.       Description of the locality Residential / Industrial / Mixed       :       Commercial         4.       Year of Construction       :       1983 (Approx.)         5.       Number of Floors       :       Ground + 5 Upper Floors         6.       Type of Structure       :       R. C.C. Framed Structure         7.       Number of Dwelling Offices in the building       :       22 Offices on 3rd Floor         8.       Quality of Construction       :       Normal         10.       Maintenance of the Building       :       Normal         11.       Facilities Available       :          Lift       :       1 Lift           Protected Water Supply       :       Municipal Water supply	1.	Nature of the Apartment	:	Commercial
Block No.       :       .         Ward No.       :       .         Village / Municipality / Corporation       :       Village - Pune Cantonment Area Pune Municipal Corporation         Door No., Street or Road (Pin Code)       :       Commercial Office No. 320, 3rd Floor, East Wing, "Aurora Towers Premises Co-op. Soc. Ltd.", 9, Moledina Road, Taluka – Haveli, District – Pune, Pin Code – 411 001, State - Maharashtra, Country – India.         3.       Description of the locality Residential / Industrial / Mixed       :       Commercial         4.       Year of Construction       :       1983 (Approx.)         5.       Number of Floors       :       Ground + 5 Upper Floors         6.       Type of Structure       :       R.C.C. Framed Structure         7.       Number of Dwelling Offices in the building       :       22 Offices on 3rd Floor         8.       Quality of Construction       :       Normal         9.       Appearance of the Building       :       Normal         10.       Maintenance of the Building       :       Normal         11.       Facilities Available       :       1 Lift         Protected Water Supply       :       Municipal Water supply         Underground Sewerage       :       Open Parking         Is Compound wall existing?       <	2.	Location	:	
Ward No.       :       -         Village / Municipality / Corporation       :       Village - Pune Cantonment Area Pune Municipal Corporation         Door No., Street or Road (Pin Code)       :       Commercial Office No. 320, 3rd Floor, East Wing, "Aurora Towers Premises Co-op. Soc. Ltd.", 9, Moledina Road, Taluka – Haveli, District – Pune, Pin Code – 411 001, State - Maharashtra, Country – India.         3.       Description of the locality Residential / Industrial / Mixed       :       Commercial         4.       Year of Construction       :       1983 (Approx.)         5.       Number of Floors       :       Ground + 5 Upper Floors         6.       Type of Structure       :       R.C.C. Framed Structure         7.       Number of Dwelling Offices in the building       :       22 Offices on 3rd Floor         8.       Quality of Construction       :       Normal         9.       Appearance of the Building       :       Normal         10.       Maintenance of the Building       :       Normal         11.       Facilities Available       :          12.       Underground Sewerage       V       Connected to Municipal Sewerage System         Car parking - Open / Covered       :       Open Parking       Is Yes		C.T.S. No.	:	Survey No. 249
Village / Municipality / Corporation       :       Village - Pune Cantonment Area Pune Municipal Corporation         Door No., Street or Road (Pin Code)       :       Commercial Office No. 320, 3rd Floor, East Wing, "Aurora Towers Premises Co-op. Soc. Ltd.", 9, Moledina Road, Taluka – Haveli, District – Pune, Pin Code – 411 001, State - Maharashtra, Country – India.         3.       Description of the locality Residential / Industrial / Mixed       :       Commercial         4.       Year of Construction       :       1983 (Approx.)         5.       Number of Floors       :       Ground + 5 Upper Floors         6.       Type of Structure       :       R.C.C. Framed Structure         7.       Number of Dwelling Offices in the building       :       22 Offices on 3rd Floor         8.       Quality of Construction       :       Normal         9.       Appearance of the Building       :       Normal         10.       Maintenance of the Building       :       Normal         11.       Facilities Available       :          Lift       :       1 Lift       :         Protected Water Supply       :       Municipal Water supply         Underground Sewerage       :       Open Parking         Is Compound wall existing?       :       Yes <td></td> <td>Block No.</td> <td>:</td> <td>(B)</td>		Block No.	:	(B)
Pune Municipal Corporation         Door No., Street or Road (Pin Code)       :       Commercial Office No. 320, 3rd Floor, East Wing, "Aurora Towers Premises Co-op. Soc. Ltd.", 9, Moledina Road, Taluka – Haveli, District – Pune, Pin Code – 411 001, State - Maharashtra, Country – India.         3.       Description of the locality Residential / Industrial / Mixed       :       Commercial         4.       Year of Construction       :       1983 (Approx.)         5.       Number of Floors       :       Ground + 5 Upper Floors         6.       Type of Structure       :       R.C.C. Framed Structure         7.       Number of Dwelling Offices in the building       :       22 Offices on 3rd Floor         8.       Quality of Construction       :       Normal         9.       Appearance of the Building       :       Normal         10.       Maintenance of the Building       :       Normal         11.       Facilities Available       :       Inft         11.       Facilities Available       :          12.       Underground Sewerage       V       Connected to Municipal Sewerage System         Car parking - Open / Covered       :       Open Parking       :       Yes		Ward No.	:/	-
Door No., Street or Road (Pin Code)       :       Commercial Office No. 320, 3rd Floor, East Wing, "Aurora Towers Premises Co-op. Soc. Ltd.", 9, Moledina Road, Taluka – Haveli, District – Pune, Pin Code – 411 001, State - Maharashtra, Country – India.         3.       Description of the locality Residential / Industrial / Mixed       :       Commercial         4.       Year of Construction       :       1983 (Approx.)         5.       Number of Floors       :       Ground + 5 Upper Floors         6.       Type of Structure       :       R.C.C. Framed Structure         7.       Number of Dwelling Offices in the building       :       22 Offices on 3rd Floor         8.       Quality of Construction       :       Normal         9.       Appearance of the Building       :       Normal         10.       Maintenance of the Building       :       Normal         11.       Facilities Available       :       1 Lift         Protected Water Supply       :       Municipal Water supply         Underground Sewerage       V       Connected to Municipal Sewerage System         Car parking - Open / Covered       :       Open Parking       :         Is Compound wall existing?       :       Yes		Village / Municipality / Corporation	/	Village - Pune Cantonment Area
"Aurora Towers Premises Co-op. Soc. Ltd.", 9,         Moledina Road, Taluka – Haveli, District – Pune, Pin         Code – 411 001, State - Maharashtra, Country – India.         3.       Description of the locality Residential / Industrial / Mixed         4.       Year of Construction         5.       Number of Floors         6.       Type of Structure         7.       Number of Dwelling Offices in the building         8.       Quality of Construction         9.       Appearance of the Building         10.       Maintenance of the Building         11.       Facilities Available         12.       Ift         13.       Protected Water Supply         14.       Yees			/	Pune Municipal Corporation
Moledina Road, Taluka – Haveli, District – Pune, Pin Code – 411 001, State - Maharashtra, Country – India.         3.       Description of the locality Residential / industrial / Mixed         4.       Year of Construction         5.       Number of Floors         6.       Type of Structure         7.       Number of Dwelling Offices in the building         8.       Quality of Construction         9.       Appearance of the Building         10.       Maintenance of the Building         11.       Facilities Available         12.       1 Lift         Protected Water Supply       :         Vunderground Sewerage       V         Car parking - Open / Covered       :         Is Compound wall existing?       :		Door No., Street or Road (Pin Code)	:	Commercial Office No. 320, 3rd Floor, East Wing,
Code – 411 001, State - Maharashtra, Country – India.         3.       Description of the locality Residential / industrial / Mixed         4.       Year of Construction       : 1983 (Approx.)         5.       Number of Floors       : Ground + 5 Upper Floors         6.       Type of Structure       : R.C.C. Framed Structure         7.       Number of Dwelling Offices in the building       : 22 Offices on 3rd Floor         8.       Quality of Construction       : Normal         9.       Appearance of the Building       : Normal         10.       Maintenance of the Building       : Normal         11.       Facilities Available       :         Lift       : 1 Lift       :         Protected Water Supply       : Municipal Water supply         Underground Sewerage       : Open Parking         Is Compound wall existing?       : Yes				"Aurora Towers Premises Co-op. Soc. Ltd.", 9,
3.       Description of the locality Residential / : Industrial / Mixed       Commercial         4.       Year of Construction       : 1983 (Approx.)         5.       Number of Floors       : Ground + 5 Upper Floors         6.       Type of Structure       : R.C.C. Framed Structure         7.       Number of Dwelling Offices in the building       : 22 Offices on 3rd Floor         8.       Quality of Construction       : Normal         9.       Appearance of the Building       : Normal         10.       Maintenance of the Building       : Normal         11.       Facilities Available       : Industrial / Lift         11.       Facilities Available       : Industrial / Lift         12.       Connected to Municipal Sewerage System         13.       Car parking - Open / Covered       : Open Parking         14.       Scompound wall existing?       : Yes				Moledina Road, Taluka – Haveli, District – Pune, Pin
Industrial / Mixed       Industrial / Mixed         4. Year of Construction       : 1983 (Approx.)         5. Number of Floors       : Ground + 5 Upper Floors         6. Type of Structure       : R.C.C. Framed Structure         7. Number of Dwelling Offices in the building       : 22 Offices on 3rd Floor         8. Quality of Construction       : Normal         9. Appearance of the Building       : Normal         10. Maintenance of the Building       : Normal         11. Facilities Available       :         Lift       : 1 Lift         Protected Water Supply       : Municipal Water supply         Underground Sewerage       : Open Parking         Is Compound wall existing?       : Yes				Code – 411 001, State - Maharashtra, Country – India.
4.       Year of Construction       :       1983 (Approx.)         5.       Number of Floors       :       Ground + 5 Upper Floors         6.       Type of Structure       :       R.C.C. Framed Structure         7.       Number of Dwelling Offices in the building       :       22 Offices on 3rd Floor         8.       Quality of Construction       :       Normal         9.       Appearance of the Building       :       Normal         10.       Maintenance of the Building       :       Normal         11.       Facilities Available       :       Image: Connected Water Supply         12.       Underground Sewerage       :       Municipal Water supply         Underground Sewerage       :       Open Parking         Is Compound wall existing?       :       Yes	3.	Description of the locality Residential /	:	Commercial
5.       Number of Floors       :       Ground + 5 Upper Floors         6.       Type of Structure       :       R.C.C. Framed Structure         7.       Number of Dwelling Offices in the building       :       22 Offices on 3rd Floor         8.       Quality of Construction       :       Normal         9.       Appearance of the Building       :       Normal         10.       Maintenance of the Building       :       Normal         11.       Facilities Available       :       Image: Connected Water Supply         11.       Protected Water Supply       :       Municipal Water supply         Underground Sewerage       :       Open Parking         Is Compound wall existing?       :       Yes		Industrial / Mixed		
6.       Type of Structure       :       R.C.C. Framed Structure         7.       Number of Dwelling Offices in the building       :       22 Offices on 3rd Floor         8.       Quality of Construction       :       Normal         9.       Appearance of the Building       :       Normal         10.       Maintenance of the Building       :       Normal         11.       Facilities Available       :          Lift       :       1 Lift       :         Protected Water Supply       :       Municipal Water supply         Underground Sewerage       :       Open Parking         Is Compound wall existing?       :       Yes	4.	Year of Construction	:	1983 (Approx.)
7.       Number of Dwelling Offices in the building       :       22 Offices on 3rd Floor         8.       Quality of Construction       :       Normal         9.       Appearance of the Building       :       Normal         10.       Maintenance of the Building       :       Normal         11.       Facilities Available       :       Image: Construction         12.       Lift       :       1 Lift         Protected Water Supply       :       Municipal Water supply         Underground Sewerage       :       Connected to Municipal Sewerage System         Car parking - Open / Covered       :       Open Parking         Is Compound wall existing?       :       Yes	5.	Number of Floors	:	Ground + 5 Upper Floors
8.       Quality of Construction       : Normal         9.       Appearance of the Building       : Normal         10.       Maintenance of the Building       : Normal         11.       Facilities Available       :         Lift       : 1 Lift         Protected Water Supply       : Municipal Water supply         Underground Sewerage       : Open Parking         Car parking - Open / Covered       : Open Parking         Is Compound wall existing?       : Yes	6.	Type of Structure	:	R.C.C. Framed Structure
9.       Appearance of the Building       :       Normal         10.       Maintenance of the Building       :       Normal         11.       Facilities Available       :       Image: Constraint of the state of the sta	7.	Number of Dwelling Offices in the building	:	22 Offices on 3 <sup>rd</sup> Floor
10.       Maintenance of the Building       :       Normal         11.       Facilities Available       :       Image: Constant of the Supply         Lift       :       1 Lift         Protected Water Supply       :       Municipal Water supply         Underground Sewerage       :       Connected to Municipal Sewerage System         Car parking - Open / Covered       :       Open Parking         Is Compound wall existing?       :       Yes	8.	Quality of Construction	•	Normal
11.       Facilities Available       :         Lift       :       1 Lift         Protected Water Supply       :       Municipal Water supply         Underground Sewerage       :       Municipal Sewerage System         Car parking - Open / Covered       :       Open Parking         Is Compound wall existing?       :       Yes	9.	Appearance of the Building		Normal
Lift       :       1 Lift         Protected Water Supply       :       Municipal Water supply         Underground Sewerage       :       Connected to Municipal Sewerage System         Car parking - Open / Covered       :       Open Parking         Is Compound wall existing?       :       Yes	10.	Maintenance of the Building	:	Normal
Protected Water Supply       :       Municipal Water supply         Underground Sewerage       :       Connected to Municipal Sewerage System         Car parking - Open / Covered       :       Open Parking         Is Compound wall existing?       :       Yes	11.	Facilities Available	:	
Underground Sewerage         Connected to Municipal Sewerage System           Car parking - Open / Covered         :         Open Parking           Is Compound wall existing?         :         Yes		Lift	•	11Lift
Car parking - Open / Covered     :     Open Parking       Is Compound wall existing?     :     Yes		Protected Water Supply	:	Municipal Water supply
Is Compound wall existing? : Yes		Underground Sewerage NINK.INNO	V	Connected to Municipal Sewerage System
		Car parking - Open / Covered	:	Open Parking
Is pavement laid around the building : Yes		Is Compound wall existing?	:	Yes
		Is pavement laid around the building	:	Yes

III	OFFICE		
1	The floor in which the Office is situated	:	3 <sup>rd</sup> Floor
2	Door No. of the Office	:	Commercial Office No. 320
3	Specifications of the Office	:	
	Roof	:	R.C.C. Slab
	Flooring	:	Ceramic tiles flooring
	Doors	:	Teak wood door framed with flush door + Glass door
	Windows	:	Aluminum sliding windows
	Fittings	:	Open plumbing with C.P. fittings. Casing Capping wiring
	Finishing	:	Cement Plastering





4	House Tax	:	
	Assessment No.	:	Details not provided
	Tax paid in the name of:	:	Details not provided
	Tax amount:	:	Details not provided
5	Electricity Service connection No.:	:	Details not provided
	Meter Card is in the name of:	:	Details not provided
6	How is the maintenance of the Office?	•••	Normal
7	Sale Deed executed in the name of	:	Mr. Vijendra Ranka
8	What is the undivided area of land as per Sale Deed?	:	Details not available
9	What is the plinth area of the Office?	:	Built Up Area in Sq. Ft. = 647.00 (Area as per Deed of Gift)
10	What is the floor space index (app.)	:/	As per PMC norms
11	What is the Carpet Area of the Office?	/	Carpet Area in Sq. Ft. = 607.00
		/	(Area as per actual site measurement)
12	Is it Posh / I Class / Medium / Ordinary?	:	Medium
13	Is it being used for Residential or Industrial purpose?	:	Commercial
14	Is it Owner-occupied or let out?	J	Tenant Occupied – M/s. Balaji Global
15	If rented, what is the monthly rent?	:	₹ 21,000.00 Expected rental income per month.
IV	MARKETABILITY	:	
1	How is the marketability?	:	Good
2	What are the factors favouring for an extra	:	Located in developed area
	Potential Value?		
3	Any negative factors are observed which	:	No
	affect the market value in general?		
V	Rate	:/	
1	After analyzing the comparable sale instances, what is the composite rate for a similar Office with same specifications in the adjoining locality? - (Along with details / reference of at - least two latest deals / transactions with respect to adjacent properties in the areas)	: 	₹ 13,000.00 to ` 15,000.00 per Sq. Ft. on Built up Area
2	Assuming it is a new construction, what is the adopted basic composite rate of the Office under valuation after comparing with the specifications and other factors with the Office under comparison (give details).	:	₹ 14,500.00 per Sq. Ft.
3	Break – up for the rate	:	
	I. Building + Services	:	₹ 2,500.00 per Sq. Ft.
	II. Land + others	:	₹ 12,000.00 per Sq. Ft.
4	Guideline rate obtained from the Registrar's Office (an evidence thereof to be enclosed)	:	₹ 90,020.00 per Sq. M. i.e. ₹ 8,363.00 per Sq. Ft.
	Guideline rate obtained from the Registrar's	:	₹ 63,520.00 per Sq. M. i.e.





Valuation Report Prepared For: Union Bank of India / SAMB Fort Branch / Mr. Vijendra Ranka (2184/2301343) Page 7 of 22

	In case of variation of 20% or more in the	:	It is a foregone conclusion that market value is always
		•	
	valuation proposed by the Valuer and the		more than the RR price. As the RR Rates area Fixed by
	Guideline value provided in the State Govt.		respective State Government for computing Stamp Duty
	notification or Income Tax Gazette		/ Rgstn. Fees. Thus, the differs from place to place and
	justification on variation has to be given		Location, Amenities per se as evident from the fact than
			even RR Rates Decided by Government Differs.
VI	COMPOSITE RATE ADOPTED AFTER		
	DEPRECIATION		
а	Depreciated building rate	:	
	Replacement cost of Office with Services	:	₹ 2,500.00 per Sq. Ft.
	(v(3)i)		$\bigcirc$ $\bigcirc$ $\bigcirc$
	Age of the building	:	40 years (Approx.)
	Life of the building estimated	:/	20 years Subject to proper, preventive periodic
			maintenance & structural repairs.
	Depreciation percentage assuming the	(:	60.00%
	salvage value as 10%		
	Depreciated Ratio of the building	:	
b	Total composite rate arrived for Valuation		
	Depreciated building rate VI (a)	J	₹ 1,000.00 per Sq. Ft.
	Rate for Land & other V (3) ii	:	₹ 12,000.00 per Sq. Ft.
	Total Composite Rate	:	₹ 13,000.00 per Sq. Ft.
	Remarks:	1	

## Details of Valuation:

Sr. No.	Description	Qty.	Rate per Unit (₹)	Estimated Value (₹)
1	Present total value of the Office	647.00 Sq. Ft.	13,000.00	84,11,000.00
2	Wardrobes			
3	Showcases /			
4	Kitchen arrangements			
5	Superfine finish			
6	Interior Decorations			
7	Electricity deposits / electrical fittings, etc.	ovate.C	reate	
8	Extra collapsible gates / grill works etc.			
9	Potential value, if any			
10	Others			
	Total Value of the Property			84,11,000.00
	The realizable value of the property			71,49,350.00
	Distress value of the property			58,87,700.00
	Insurable value of the property			16,17,500.00
	Guideline value of the property			38,17,947.00





## Justification for price / rate

The Market Value of the property is based on facts of markets discovered by us during our enquiries, however the government rate value in this case is less than the market value arrived by us. We are of the opinion that the value arrive by us will prove to be correct if an Auction of the subject property is carried out. As far as Market Value in Index II is concerned, it is not possible to comment on same, may be government rates are fixed by sampling during same point of time in part and whereas, Market values change every month.

In most of the cases the actual deal amount or Transaction value is not reflected in Index II because of various Market practices. As Valuer, we always try to give a value which is correct reflection of actual transaction value irrespective of any factors in market

# Method of Valuation / Approach

The sales comparison approach uses the market data of sale prices to estimate the value of a real estate property. Property valuation in this method is done by comparing a property to other similar properties that have been recently sold. Comparable properties, also known as comparables, or comps, must share certain features with the property in question. Some of these include physical features such as square footage, number of rooms, condition, and age of the building; however, the most important factor is no doubt the location of the property. Adjustments are usually needed to account for differences as no two properties are exactly the same. To make proper adjustments when comparing properties, real estate appraisers must know the differences between the comparable properties and how to value these differences. The sales comparison approach is commonly used for Commercial Office, where there are typically many comparables available to analyze. As the property is a Commercial Office, we have adopted Sale Comparison Approach Method for the purpose of valuation. The Price for similar type of property in the nearby vicinity is in the range of ₹ 13,000.00 to ₹ 15,000.00 per Sq. Ft. on Built up Area. Considering the rate with attached report, current market conditions, demand and supply position, Office size, location, upswing in real estate prices, sustained demand for Commercial Office, all round development of Industrial application in the locality etc. We estimate ₹ 13,000.00 per Sq. Ft. on Built up Area for valuation.

Impending threat of acquisition by government for road	
widening / publics service purposes, sub merging &	
applicability of CRZ provisions (Distance from sea-cost /	
tidal level must be incorporated) and their effect on	
i) Saleability	Normal
ii) Likely rental values in future in	₹ 21,000.00 Expected rental income per month.
iii) Any likely income it may generate	Rental Income





# Actual Site Photographs








# Actual Site Photographs



# Think.Innovate.Create







Longitude Latitude: 18°31'05.4"N 73°52'43.5"E Note: The Blue line shows the route to site from nearest railway station (Pune – 2.1 Km.)



Type of Area	Urban		Local Body Type	Class "A" Corporation		
Local Body Name Pune Municipal Corporation						
Land Mark Area in Sachapir Road, Dastur Meher Road, Ambedkar Road and Cantonment Boundary (General Land Register G. L. R. 390 S. N.)						
				Rate of Land + I	Building in₹per	sq. m. Built-U
Zone	Sub Zone	Land	Residential	Office	Shop	Industri
36	36/546	23770	78280	90020	97840	0
	10 10 1/ 15 16 17 10	19 20 21 22 23 24	25 35 34 36 37 38 39	40, 41, 42, 43, 44, 45, 46, 47	50 51 53 55 56	57 58 59


# Ready Reckoner Rate

# Think.Innovate.Create





Valuation Report Prepared For: Union Bank of India / SAMB Fort Branch / Mr. Vijendra Ranka (2184/2301343) Page 13 of 22



# **Price Indicators**

agicbricks 🛛	uy v Rent v Sell v Home Loans v		Login V Post Property (FREE)
e > Commercial Property for Sale in 1	une > Office Space for Rant in Pune > Office Space for Rant in Moleclina Road > 4	300 Sq-ft	Posted on: Jun 08, 23 Property ID: 65852
₹5.0 Cr ₹11111/sqft Office Space For Sale in		1	Contact Owner Shalini Khurana -91-88/0000000
THE PART	Crade A+   ≻∏ 50 Seats	편 1Cabins   표 Furnished	Get Phone No.
	Super Area         Carpet           4500 sqft *         3000 s           قال:الالله على         قاد 16.657	sqft = 2 (Out of 4 Floors)	
9 <b>8</b> 9	Units On Floor Pantry 2 Wet Pa		
the state of the	Overlooking Lift Main Road Facing 1		
Contact Owner	Get Phone No.	名 Last contact made 32 days ago	
Price	₹5 Cr		
Booking Amount	₹50.0 Lac		
	Power Back Up, Lift, Reserved Parking, Security	/, Air Conditioned, Intercom Facility,	
Facilities	Internet/WI-FI Connectivity, Conference Room		
Facilities Address		, Pune, Maharashtra	
	Internet/WI-FI ConnectIvity, Conference Room	, Pune, Maharashtra	
Address	Internet/WI-Fi Connectivity, Conference Room 2A Moledina Road, Pune 411001, Moledina Road,	, Pune, Maharashtra	






# **Price Indicators**

magicbricks Buy ~ Rent ~	Sell 🗸 🛛 Home Loan	s ~		Login V Post Property FREE
Home > Commercial Property for Sale in Pune > Office Space for Rent in Pu	une > Office Space for Rent in Camp	> 605 Sq-ft		Posted on: Jun 25, 23 Property ID: 64983917
Cet priority access & benefits with 👾 MB Prime Unlock exclusiv	vely Reserved Owner Pro	perties	Join Prime @ 50% OFF	Contact Owner Amrut Rajendra Arsiddha
<b>₹81.0 Lac</b> ₹13388/sqft <u>Apply for Ioan</u> Office Space For Sale in hermes palazzo, Camp,			:	-91-96X000000X
				Get Phone No.
	Grade A+   )元 7	Seats   🎚 Furnished		
	Commercial Complex <u>hermes palazzo</u>	Super Area <b>605 sqft →</b>	Carpet Area <b>410 sqft -</b>	Download Brochure
- The state of the second state		₹13,388/sqft	₹19,756/sqft	
	Floor	Units On Floor	Pantry	
	2 (Out of 2 Floors)	20	No Personal Pantry	
+5 Photos	Washroom	Overlooking	Facing	
	1	Not Available	East	
Assured Returns of 5.25% per annum      Pro     Contact Owner     Get Phone No.	operty Currently Leased O		ast contact made 61 days ago	

# Think.Innovate.Create







# **Price Indicators**





Valuation Report Prepared For: Union Bank of India / SAMB Fort Branch / Mr. Vijendra Ranka (2184/2301343) Page 16 of 22

As a result of my appraisal and analysis, it is my considered opinion that the present fair market value of the above property in the prevailing condition with aforesaid specifications is ₹ 84,11,000.00 (Rupees Eighty Four Lakh Eleven Thousand Only). The Realizable Value of the above property is ₹ 71,49,350.00 (Rupees Seventy One Lakh Forty Nine Thousand Three Hundred Fifty Only) and The distress value ₹ 58,87,700.00 (Rupees Fifty Eight Lakh Eighty Seven Thousand Seven Hundred Only).

Place: Mumbai	
Date: 28.06.2023	R
For VASTUKALA COI	NSULTANTS (I) PVT. LTD.
Director	Auth. Sign.
Sharadkumar B. Chalikwar Govt. Reg. Valuer Chartered Engineer (India) Reg. No. (N) CCIT/1-14/52/2	
<b>.</b> .	
on ₹	We are satisfied that the fair and reasonable market value of the property is (Rupeesonly).
Date	Think.Innovate.Create

(Name of the Branch Manager with office Seal)

Enclosures			
	Declaration From Valuers	Attached	
	(Annexure- II)		
	Model code of conduct for	Attached	
	valuer - (Annexure III)		





Valuation Report Prepared For: Union Bank of India / SAMB Fort Branch / Mr. Vijendra Ranka (2184/2301343) Page 17 of 22

Annexure-II

### **DECLARATION FROM VALUERS**

I, hereby declare that:

- a. The information furnished in my valuation report dated 28.06.2023 is true and correct to the best of my knowledge and belief and I have made an impartial and true valuation of the property.
- b. I have no direct or indirect interest in the property valued;
- c. I/ my authorized representative have personally inspected the property on 21.06.2023 The work is not sub - contracted to any other valuer and carried out by myself.
- d. I have not been convicted of any offence and sentenced to a term of Imprisonment;
- e. I have not been found guilty of misconduct in my professional capacity.
- f. I have read the Handbook on Policy, Standards and procedure for Real Estate Valuation, 2011 of the IBA and this report is in conformity to the "Standards" enshrined for valuation in the Part B of the above handbook to the best of my ability.
- g. I have read the International Valuation Standards (IVS) and the report submitted to the Bank for the respective asset class is in conformity to the "Standards" as enshrined for valuation in the IVS in "General Standards" and "Asset Standards" as applicable. The valuation report is submitted in the prescribed format of the bank.
- h. I abide by the Model Code of Conduct for empanelment of valuer in the Bank. (Annexure III A signed copy of same to be taken and kept along with this declaration)
- i. I am registered under Section 34 AB of the Wealth Tax Act, 1957.
- j. I am Chairman & Managing Director of the company, who is competent to sign this valuation report. Think.Innovate.Create
- k. Further, I hereby provide the following information.





Valuation Report Prepared For: Union Bank of India / SAMB Fort Branch / Mr. Vijendra Ranka (2184/2301343) Page 18 of 22

Sr. No.	Particulars	Valuer comment
1.	Background information of the asset being valued;	Mr. Yogesh Saraswate to <b>Mr. Vijendra Ranka</b> vide Deed of Gift dated 01.09.2013
2.	Purpose of valuation and appointing authority	As per the request from Union Bank of India, SAMB, Mumbai to assess fair market value of the property for SARFAESI Securitization and Reconstruction of Financial Assets and Enforcement of Security Interest Act, 2002 purpose
3.	Identity of the valuer and any other experts involved in the valuation;	Sharadkumar B. Chalikwar – Regd. Valuer Manoj B. Chalikwar – Regd. Valuer Prayush Parekh – Sr. Valuation Engineer Shobha Kuperkar – Technical Manager Prajakta Patil – Technical Officer
4.	Disclosure of valuer interest or conflict, if any;	We have no interest, either direct or indirect, in the property valued. Further to state that we do not have relation or any connection with property owner / applicant directly or indirectly. Further to state that we are an independent Valuer and in no way related to property owner / applicant
5.	Date of appointment, valuation date and date of report;	Date of Appointment – 21.06.2023 Valuation Date – 28.06.2023 Date of Report – 28.06.2023
6.	Inspections and/or investigations undertaken;	Physical Inspection done 21.06.2023
7.	Nature and sources of the information used or relied upon;	Market Survey at the time of site visit Ready Reckoner rates / Circle rates Online search for Registered Transactions Online Price Indicators on real estate portals Enquiries with Real estate consultants Existing data of Valuation assignments carried out by us
8.	Procedures adopted in carrying out the valuation and valuation standards followed;	
9.	Restrictions on use of the report, if any; Think.Innov	This valuation is for the use of the party to whom it is addressed and for no other purpose. No responsibility is accepted to any third party who may use or rely on the whole or any part of this valuation. The valuer has no pecuniary interest that would conflict with the proper valuation of the property.
10.	major factors that were taken into account during the valuation;	
11.	Caveats, limitations and disclaimers to the extent they explain or elucidate the limitations faced by valuer, which shall not be for the purpose of limiting his responsibility for the valuation report.	Attached





### Assumptions, Disclaimers, Limitations & Qualifications

#### Value Subject to Change

The subject appraisal exercise is based on prevailing market dynamics as on **28<sup>th</sup> June 2023** and does not take into account any unforeseeable developments which could impact the same in the future.

#### **Our Investigations**

We are not engaged to carry out all possible investigations in relation to the subject property. Where in our report we identify certain limitations to our investigations, this is to enable the reliant party to instruct further investigations where considered appropriate or where we recommend as necessary prior to reliance. Vastukala Consultants India Pvt. Ltd. (VCIPL) is not liable for any loss occasioned by a decision not to conduct further investigations

#### Assumptions

Assumptions are a necessary part of undertaking valuations. VCIPL adopts assumptions for the purpose of providing valuation advise because some matters are not capable of accurate calculations or fall outside the scope of our expertise, or out instructions. The reliant party accepts that the valuation contains certain specific assumptions and acknowledge and accept the risk of that if any of the assumptions adopted in the valuation are incorrect, then this may have an effect on the valuation.

#### Information Supplied by Others

The appraisal is based on the information provided by the client. The same has been assumed to be correct and has been used for appraisal exercise. Where it is stated in the report that another party has supplied information to VCIPL, this information is believed to be reliable but VCIPL can accept no responsibility if this should prove not to be so.

#### **Future Matters**

To the extent that the valuation includes any statement as to a future matter, that statement is provided as an estimate and/or opinion based on the information known to VCIPL at the date of this document. VCIPL does not warrant that such statements are accurate or correct.

#### Map and Plans

Any sketch, plan or map in this report is included to assist the reader while visualising the property and assume no responsibility in connection with such matters.

#### Site Details

Based on inputs received from Client's representative and site visit conducted, we understand that the subject property is Commercial Office, admeasuring **647.00 Sq. Ft. Built up Area** in the name of **Mr. Vijendra Ranka**. Further, VCIPL has assumed that the subject property is free from any encroachment and is available as on the date of the appraisal.





#### **Property Title**

Based on our discussion with the Client, we understand that the subject property is owned by **Mr. Vijendra Ranka.** For the purpose of this appraisal exercise, we have assumed that the subject property has a clear title and is free from any encumbrances, disputes and claims. VCIPL has made no further enquiries with the relevant local authorities in this regard and does not certify the property as having a clear and marketable title. Further, no legal advice regarding the title and ownership of the subject property has been obtained for the purpose of this appraisal exercise. It has been assumed that the title deeds are clear and marketable.

#### **Environmental Conditions**

We have assumed that the subject property is not contaminated and is not adversely affected by any existing or proposed environmental law and any processes which are carried out on the property are regulated by environmental legislation and are properly licensed by the appropriate authorities.

#### Area

Based on the information provided by the Client's representative, we understand that the Commercial Office, admeasuring **647.00 Sq. Ft. Built up Area** 

#### **Condition & Repair**

In the absence of any information to the contrary, we have assumed that there are no abnormal ground conditions, nor archaeological remains present which might adversely affect the current or future occupation, development or value of the property. The property is free from rat, infestation, structural or latent defect. No currently known deleterious or hazardous materials or suspect techniques will be used in the construction of or subsequent alteration or additions to the property and comments made in the property details do not purport to express an opinion about , or advise upon, the condition of uninspected parts and should not be taken as making an implied representation or statement about such parts

#### Valuation Methodology

For the purpose of this valuation exercise, the valuation methodology used is Direct Comparison Approach Method and proposed Highest and Best Use model is used for analysing development potential.

The Direct Comparison Approach involves a comparison of the property being valued to similar properties that have actually been sold in arms - length transactions or are offered for sale. This approach demonstrates what buyers have historically been willing to pay (and sellers willing to accept) for similar properties in an open and competitive market and is particularly useful in estimating the value of the Office and properties that are typically traded on a Office basis.

In case of inadequate recent transaction activity in the subject micro-market, the appraiser would collate details of older transactions. Subsequently, the appraiser would analyse rental / capital value trends in the subject micro-market in order to calculate the percentage increase / decrease in values since the date of the identified transactions. This percentage would then be adopted to project the current value of the same.

Think.Innovate.Create An ISO 9001:2015 Certified Company

Vastukala Consultants (I) Pvt. Ltd.

www.vastukala.org



Where reliance has been placed upon external sources of information in applying the valuation methodologies, unless otherwise specifically instructed by Client and/or stated in the valuation, VCIPL has not independently verified that information and VCIPL does not advise nor accept it as reliable. The person or entity to whom the report is addressed acknowledges and accepts the risk that if any of the unverified information in the valuation is incorrect, then this may have an effect on the valuation.

#### Not a Structural Survey

We state that this is a valuation report and not a structural survey

#### Other

All measurements, areas and ages quoted in our report are approximate

#### Legal

We have not made any allowances with respect to any existing or proposed local legislation relating to taxation on realization of the sale value of the subject property. VCIPL is not required to give testimony or to appear in court by reason of this appraisal report, with reference to the property in question, unless arrangement has been made thereof. Further, no legal advice on any aspects has been obtained for the purpose of this appraisal exercise

#### Property specific assumptions

Based on inputs received from the client and site visit conducted, we understand that the subject property is Commercial Office, admeasuring **647.00 Sq. Ft. Built up Area**.

### ASSUMPTIONS, CAVEATS, LIMITATION AND DISCLAIMERS

- 1. We assume no responsibility for matters of legal nature affecting the property appraised or the title thereto, nor do we render our opinion as to the title, which is assumed to be good and marketable.
- 2. The property is valued as though under responsible ownership.
- 3. It is assumed that the property is free of liens and encumbrances.
- 4. It is assumed that there are no hidden or unapparent conditions of the subsoil or structure that would render it more or less valuable. No responsibility is assumed for such conditions or for engineering that might be required to discover such factors.
- 5. There is no direct/ indirect interest in the property valued.
- 6. The rates for valuation of the property are in accordance with the Govt. approved rates and prevailing market rates.





#### **DEFINITION OF VALUE FOR THIS SPECIFIC PURPOSE**

This exercise is to assess Fair Market Value of the property under reference for SARFAESI Securitisation and Reconstruction of Financial Assets and Enforcement of Security Interest Act, 2002 purpose as on 28<sup>th</sup> June 2023.

#### The term Fair Market Value is defined as

"The most probable price, as of a specified date, in cash, terms equivalent to cash, or in other precisely revealed terms for which the specified property rights would sell after reasonable exposure in a competitive market under all conditions requisite to a fair sale, with the buyer and seller each acting prudently knowledgeably and for self interest assuming that neither is under undue duress".

Fundamental assumptions and conditions presumed in this definition are:

- 1. Buyer and seller are motivated by self-interest.
- 2. Buyer and seller are well informed and are acting prudently.
- 3. The property is exposed for a reasonable time on the open market.
- 4. Payment is made in cash or equivalent or in specified financing terms.

### **DECLARATION OF PROFESSIONAL FEES CHARGED**

We hereby declare that, our professional fees are not contingent upon the valuation findings. However, if the statute AND/OR clients demands that, the fees should be charged on the percentage of assessed value then, with the full knowledge of the AND/OR end user, it is being charged accordingly.

### VALUATION OF THE PROPERTY PREMISES

Considering various parameters recorded herein above, existing economic scenario, and the information that is available with reference to the development of neighborhood and method selected for valuation, we are of the opinion that, the property premises can be assessed and valued for this particular purpose at ₹84,11,000.00 (Rupees Eighty Four Lakh Eleven Thousand Only)

Vastukala Consultants (I) Pvt. Ltd.

www.vastukala.org

# For VASTUKALA CONSULTANTS (I) PVT. LTD.

## Director

Auth. Sign.

Think.Innovate.Create An ISO 9001:2015 Certified Company

Sharadkumar B. Chalikwar Govt. Reg. Valuer Chartered Engineer (India) Reg. No. (N) CCIT/1-14/52/2008-09

