

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f7"
    },
    "type": "CREDITOFFICER",
    "_id": "63fd9434ce84bf289baab0e9",
    "firstName": "Sharmila",
    "lastName": "Mahto",
    "mobileNo": "",
    "workMobileNo": "9521405151",
    "email": "sharmila.mahto@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "7900000",
    "discussWithPerson": "Sharmila",
    "expectedFees": 3950,
    "quotedAmount": "2500"
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "VCIPL Mumbai",
    "shortName": "VCIPLM",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
```

```
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f7",
  "branchCode": "000064",
  "type": "BRANCH",
  "name": "RACPC Ghatkopar (West)",
  "email": "racpcghatkopar.sanctions@sbi.co.in",
  "mobileNo": "022-25009143",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, 1st Floor, Ashok Silk Mills
Compound, LBS Marg, Ghatkopar (West), Mumbai - 400 086, State - Maharashtra,
Country - India.\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RACPC GHATKOPAR",
  "fax": "022-25009010",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7177d2ffdf65bcd65882a",
    "role": "PICKUPPERSON",
    "firstName": "Saurabh",
    "email": "saurabhvelonde143@gmail.com",
```

```
"lastName": "Velonde",
"mobileNo": "8691048846",
"shortName": "SSV",
"workWithDocumentMaker": "",
"profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "648fcad91b499c2d52dc86f3",
"role": "SITEENGINEER",
"firstName": "Barkat",
"email": "barkathodekar68@gmail.com",
"lastName": "Hodekar",
"mobileNo": "8879011615",
"designation": "Site Engg",
"shortName": "Barkat",
"workWithDocumentMaker": "",
"profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shyma_Photo.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60eebe33f3dd69653a5837ae",
"role": "MAKER",
"firstName": "Shamal",
"email": "shamal@vastukala.org",
"lastName": "Bodke",
"mobileNo": "9821740317",
"designation": "",
"shortName": "SB",
"workWithDocumentMaker": "",
```

```
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\\
\\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "CAT-I-A-1930",
        "label": "Chartered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "60af7d4d2ffdf65bcd658643",
    "PANNo": "AESPC7493M",
    "role": "VALUER",
    "firstName": "Vidhi",
    "fatherName": "Manoj",
    "email": "vids_singh@yahoo.com",
    "lastName": "Chalikwar",
    "mobileNo": "9820549087",
    "designation": "Valuer",
    "registrationNo": [
      {
        "title": {
          "value": "Chartered_Valuer",
          "label": "Chartered Valuer"
        },
        "_id": "60eeb39af3dd69653a58168d",
        "number": "CAT-I-A-1930"
      }
    ],
    "shortName": "VC",
```

```
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af7d4d2ffdf65bcd658643\\
\\profilePhoto_1622113613002_Vidhi C.jpeg"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.096539",
  "longitude": "72.911997"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.911997,
    19.096539
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-06-30T09:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-06-30T09:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-06-30T09:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-06-30T09:00:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "remark": "MANUAL",
      "status": "COMPLETED",
      "dateTime": "2023-07-01T06:30:00.000Z"
    }
  ]
}
```

```
    },
    {
      "remark": "MANUAL",
      "status": "COMPLETED",
      "dateTime": "2023-07-01T07:30:00.000Z"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "area": "358",
  "rate": "23000",
  "yearOfConstruction": "2023",
  "compositionOfBuilding": "Part Ground + Part Stilt + 12 Upper Floors"
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Fri Jun 30 2023 15:26:31 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
```

```
"key": "village",
"value": "Ghatkopar",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "8",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Ghatkopar (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
},
}
```

```
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Trident (Hitesh Apartment)",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Sanghavi Estate, Garden Lane",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
```



```
"value": "B",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "123(P) & 133(P)",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
```

```
"status": true,
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "806",
"label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "N",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
```

```
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400 086",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
}
},
"general": {
  "ownership": {
```

```
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "Slum_Rehabilitation_Authority",
"label": "Slum Rehabilitation Authority"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Internal Road",
"west": "Sai Darshan CHSL",
"south": "Akshay Dham Building",
"east": "Internal Road"
},
"asPerDocumentAgreement": {
"north": "By D. P. Road",
"west": "By 30' Wide Road",
"south": "By Property of Pandit",
"east": "By Sub Divided Plot No. B-1"
},
"extraDetailOfProperty": ""
},
"compositeRate": {
"remark": "",
"depreciationPercentage": "",
"depreciationRatioOfBuilding": "",
"salvageValue": "",
"depreciatedCostOfConstruction": "",
"depreciatedBuildingRate": ""
},
"igrRate": {
"propertyName": "Residential Flat",
"rate": "137730",
"landRate": "65490",
"igrImage": "cases/649e98b8b347aa29db89ec13/igr_1688367435694_Image.png",
```

```
"squareMeterGuideLineRate": "144617.00",
"squareFeetGuideLineRate": "13435.00"
},
"igrFinalRate": {
  "rate": "137730",
  "squareMeterGuideLineRate": "144617.00",
  "squareFeetGuideLineRate": "13435.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "20,500",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per SRA norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
```

```
"value": "6\"_Thk._Brick_Masonry",
"label": "6\" Thk. Brick Masonery"
},
"waterTank": {
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
},
"carParking": "Stilt + Open Car Parking",
"constructionWorkStatus": {
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "2023",
"fullDate": "1/1/2023"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "R.C.C._Framed_Structure",
"label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Good",
"label": "Good"
},
"materialUsedList": {
"value": "Good",
"label": "Good"
},
}
```

```
"buildingSpecification": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
```

```
"label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "0",
"totalLifeBuilding": "60",
"estimatedAge": "60",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "12",
"flatFloorNo": "8",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "357.50",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/649e98b8b347aa29db89ec13/
routeMap_1688364544055_Image.png",
    "routeLat": "19.096539",
    "routeLng": "72.911997",
    "stationName": "Ghatkopar",
    "routeDistance": "1.5"
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  }
}
```



```
},
"locationMapImg": [
  {
    "id": "5f0z4a",
    "name": "5f0z4a",
    "image": "cases/649e98b8b347aa29db89ec13/
routeMap_1688364432545_Image.png"
  },
  {
    "id": "9p7yys",
    "name": "9p7yys",
    "image": "cases/649e98b8b347aa29db89ec13/
routeMap_1688378873956_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "8287500.00",
  "bookValue": "0",
```

```
"finalValue": "8287500.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Mon Jul 03 2023 12:50:42 GMT+0530 (India Standard Time)",
  "number": "2301387",
  "dayCount": "4",
  "monthCount": "12",
  "generatedBy": "60eeaeddf3dd69653a581316"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "4803013.00",
  "selectedBuildUpValue": "357.50",
```

```
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "649feebfb347aa29db9298c0",
      "name":
"externallmg_1688202942788_WhatsApp_Image_20230701_at_21857_PM.jpeg",
      "path": "cases/649e98b8b347aa29db89ec13/
externallmg_1688202942788_WhatsApp_Image_20230701_at_21857_PM.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "649feed1b347aa29db9299de",
      "name":
"externallmg_1688202960421_WhatsApp_Image_20230701_at_21859_PM_1.jpeg",
      "path": "cases/649e98b8b347aa29db89ec13/
externallmg_1688202960421_WhatsApp_Image_20230701_at_21859_PM_1.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "649feed1b347aa29db9299e0",
      "name":
"externallmg_1688202960454_WhatsApp_Image_20230701_at_21900_PM_1.jpeg",
      "path": "cases/649e98b8b347aa29db89ec13/
externallmg_1688202960454_WhatsApp_Image_20230701_at_21900_PM_1.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "649feebfb347aa29db9298bf",
      "name":
"externallmg_1688202942780_WhatsApp_Image_20230701_at_21857_PM_1.jpeg",
      "path": "cases/649e98b8b347aa29db89ec13/
externallmg_1688202942780_WhatsApp_Image_20230701_at_21857_PM_1.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
```

```
    "_id": "649feebfb347aa29db9298ba",
    "name":
"externallmg_1688202942760_WhatsApp_Image_20230701_at_21904_PM_3.jpeg",
    "path": "cases/649e98b8b347aa29db89ec13/
externallmg_1688202942760_WhatsApp_Image_20230701_at_21904_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "649feebfb347aa29db9298bd",
    "name":
"externallmg_1688202942770_WhatsApp_Image_20230701_at_21856_PM_2.jpeg",
    "path": "cases/649e98b8b347aa29db89ec13/
externallmg_1688202942770_WhatsApp_Image_20230701_at_21856_PM_2.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "649feebfb347aa29db9298bb",
    "name": "Living Room",
    "path": "cases/649e98b8b347aa29db89ec13/
externallmg_1688202942764_WhatsApp_Image_20230701_at_21904_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "649feed1b347aa29db9299e3",
    "name": "Living Room",
    "path": "cases/649e98b8b347aa29db89ec13/
externallmg_1688202960462_WhatsApp_Image_20230701_at_21901_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "649feed1b347aa29db9299e1",
    "name": "Living Room",
    "path": "cases/649e98b8b347aa29db89ec13/
externallmg_1688202960456_WhatsApp_Image_20230701_at_21900_PM_2.jpeg",
    "orientation": "portrait"
  }
]
},
```

```
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
```



```
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": true,
  "CHECKER": true,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "325.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86A/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "DELIVERED",
"_id": "649e98b8b347aa29db89ec13",
"ownerName": "Mr. Santosh Bajirao Adole & Mrs. Ratnamala Santosh Adole",
"ownerPhoneNo": "7902901386",
"appAddress": "Flat no. 806, 8th Floor, Wing-B, Trident, Sanghani Estate, GHatkopar West ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
```

```
"value": "60ae1254aa6d152c1801b326"
},
"inputs": {
  "documentDate": "30/03/2023",
  "from": {
    "value": "Promoter",
    "label": "Promoter"
  },
  "Promoter": "M/s. Magnum Cylinders Pvt. Ltd.",
  "to": {
    "value": "Allottee",
    "label": "Allottee"
  },
  "Allottee": "Mr. Santosh Bajirao Adole & Mrs. Ratnamala Santosh Adole"
},
"isHardCopy": false,
"displayStatus": true,
"id": "543646",
"path": "cases/649e98b8b347aa29db89ec13/
document_1688115283081_Racpc_Ghatkopar_Santosh_Adoles.pdf",
"fileName": "document_1688115283081_Racpc_Ghatkopar_Santosh_Adoles.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "09/09/2021",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "Registration_No",
      "label": "Registration No"
    },
    "Registration_No": "P51800008490"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1688360964848_P51800008490.pdf",
  "path": "cases/649e98b8b347aa29db89ec13/
document_1688360964848_P51800008490.pdf",
  "id": "235010",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
```

```
"createdAt": "Mon Jul 03 2023 11:09:08 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "09/10/2020",
    "nameOfApprovingAuthority": {
      "value": "Slum_Rehabilitation_Authority_(SRA)",
      "label": "Slum Rehabilitation Authority (SRA)"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "SRA / ENG / DDTP / 714 / N / PL / AP"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1688362411583_CC.pdf",
"path": "cases/649e98b8b347aa29db89ec13/document_1688362411583_CC.pdf",
"id": "991057",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Mon Jul 03 2023 11:09:08 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "06/03/2017",
    "nameOfApprovingAuthority": {
      "value": "Slum_Rehabilitation_Authority_(SRA)",
      "label": "Slum Rehabilitation Authority (SRA)"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "SRA / DDTP / 714 / N / PL / AP"
},
"isHardCopy": false,
"displayStatus": false,
```

```
    "fileName": "document_1688362737645_4_Building_Plan_Approval_IOD.pdf",
    "path": "cases/649e98b8b347aa29db89ec13/
document_1688362737645_4_Building_Plan_Approval_IOD.pdf",
    "id": "455488",
    "uploadedBy": "60eebe33f3dd69653a5837ae",
    "createdAt": "Mon Jul 03 2023 11:09:08 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1250aa6d152c1801b316",
      "label": "Part Occupancy Certificate"
    },
    "inputs": {
      "documentDate": "27/01/2023",
      "nameOfApprovingAuthority": {
        "value": "Slum_Rehabilitation_Authority_(SRA)",
        "label": "Slum Rehabilitation Authority (SRA)"
      },
      "remark": "Part bare shell OCC for Sale building - Ground (Pt)+ Stilt (Pt) + 1st to
10th upper floor of Wing B of Sale building.",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "SRA / ENG / DDTP / 714 / N / PL / AP "
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName":
"document_1688365627068_Hitesh_Apartment__Part_OC_Letter_27012023.pdf",
    "path": "cases/649e98b8b347aa29db89ec13/
document_1688365627068_Hitesh_Apartment__Part_OC_Letter_27012023.pdf",
    "id": "452420",
    "uploadedBy": "60eebe33f3dd69653a5837ae",
    "createdAt": "Mon Jul 03 2023 11:57:09 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "002244",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "722597",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Jun 30 2023 14:26:24 GMT+0530 (India Standard Time)"
  }
]
```

```
],
"owners": [
  {
    "name": "Mr. Santosh Bajirao Adole & Mrs. Ratnamala Santosh Adole",
    "phone": "7902901386",
    "ownershipShare": "",
    "email": "",
    "id": "363972"
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "742074",
    "name": "Living Room",
    "length": "12.00",
    "length1": "12",
    "length2": "00",
    "width": "10.00",
    "width1": "10",
    "width2": "00",
    "totalArea": "120.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "120.00"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Toilet",
    "length": "6.00",
    "length1": "6",
    "length2": "0",
    "width": "3.25",
    "width1": "3",
    "width2": "3",
    "totalArea": "19.50",
    "images": [],
    "extraAreas": []
  }
]
```

```
"finalArea": "19.50"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Toilet",
  "length": "6.00",
  "length1": "6",
  "length2": "00",
  "width": "3.25",
  "width1": "3",
  "width2": "3",
  "totalArea": "19.50",
  "images": [],
  "extraAreas": [],
  "finalArea": "19.50"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Kitchen",
  "length": "9.25",
  "length1": "9",
  "length2": "3",
  "width": "6.33",
  "width1": "6",
  "width2": "4",
  "totalArea": "58.58",
  "images": [],
  "extraAreas": [],
  "finalArea": "58.58"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "10.00",
```

```
"length1": "10",
"length2": "00",
"width": "9.83",
"width1": "9",
"width2": "10",
"totalArea": "98.33",
"images": [],
"extraAreas": [],
"finalArea": "98.33"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "986446",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "325",
  "squareMeterArea": "30.19",
  "docFinalBuiltUp": "357.5",
  "docFinalBuiltUpSquareMeter": "33.209",
  "docBuiltupPercentage": "10",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "64a27052baf9ee5b13785add",
  "id": "1",
  "property": "Residential Flat",
  "area": "495",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
```

```
"areaType": "Carpet",
"floor": "9",
"source": "magic_bricks",
"expectedPrice": "12600000",
"expectedRate": "25454.55",
"builtUpExpectedRate": "23140.50",
"image": "cases/649e98b8b347aa29db89ec13/
indicator_1688367185983_Image.png"
},
{
  "printlnReport": true,
  "_id": "64a27076baf9ee5b13785b8d",
  "id": "2",
  "property": "Residential Flat",
  "area": "450",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "Housing.Com",
  "expectedPrice": "11300000",
  "expectedRate": "25111.11",
  "builtUpExpectedRate": "22828.28",
  "image": "cases/649e98b8b347aa29db89ec13/
indicator_1688367222899_Image.png"
},
{
  "printlnReport": true,
  "_id": "64a27098baf9ee5b13785ca0",
  "id": "3",
  "property": "Residential Flat",
  "area": "495",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "Housing.Com",
  "expectedPrice": "13200000",
  "expectedRate": "26666.67",
  "builtUpExpectedRate": "24242.42",
  "image": "cases/649e98b8b347aa29db89ec13/
indicator_1688367256256_Image.png"
},
{
```



```
"printlnReport": true,
  "_id": "64a270b5baf9ee5b13785cff",
  "id": "4",
  "property": "Residential Flat",
  "area": "450",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "https://www.proptiger.com/",
  "expectedPrice": "11300000",
  "expectedRate": "25111.11",
  "builtUpExpectedRate": "22828.28",
  "image": "cases/649e98b8b347aa29db89ec13/
indicator_1688367285632_Image.png"
},
{
  "printlnReport": true,
  "_id": "64a270f5baf9ee5b13785dd9",
  "id": "5",
  "property": "Residential Flat",
  "area": "495",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "11561000",
  "expectedRate": "23355.56",
  "builtUpExpectedRate": "21232.32",
  "image": "cases/649e98b8b347aa29db89ec13/
indicator_1688367349124_Image.jpeg"
},
{
  "printlnReport": true,
  "_id": "64a27111baf9ee5b13785e35",
  "id": "6",
  "property": "Residential Flat",
  "area": "313",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
```

```
    "source": "Index_no.2",
    "expectedPrice": "7649000",
    "expectedRate": "24437.70",
    "builtUpExpectedRate": "22216.09",
    "image": "cases/649e98b8b347aa29db89ec13/
indicator_1688367377552_Image.jpeg"
  },
  {
    "printlnReport": true,
    "_id": "64a27125baf9ee5b13785eed",
    "id": "7",
    "property": "Residential Flat",
    "area": "311",
    "builtUpPercentage": "10",
    "saleablePercentage": "20",
    "rateType": "sale_Instance",
    "areaType": "Carpet",
    "floor": "",
    "source": "Index_no.2",
    "expectedPrice": "7884000",
    "expectedRate": "25350.48",
    "builtUpExpectedRate": "23045.89",
    "image": "cases/649e98b8b347aa29db89ec13/
indicator_1688367397228_Image.jpeg"
  }
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "649feebfb347aa29db9298b7",
    "name":
"externallmg_1688202942746_WhatsApp_Image_20230701_at_21903_PM.jpeg",
    "path": "cases/649e98b8b347aa29db89ec13/
externallmg_1688202942746_WhatsApp_Image_20230701_at_21903_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "649feebfb347aa29db9298b8",
    "name":
"externallmg_1688202942751_WhatsApp_Image_20230701_at_21904_PM_1.jpeg",
    "path": "cases/649e98b8b347aa29db89ec13/
externallmg_1688202942751_WhatsApp_Image_20230701_at_21904_PM_1.jpeg",
    "orientation": "portrait"
  }
]
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "649feebfb347aa29db9298b9",
  "name":
"externallmg_1688202942754_WhatsApp_Image_20230701_at_21904_PM_2.jpeg",
  "path": "cases/649e98b8b347aa29db89ec13/
externallmg_1688202942754_WhatsApp_Image_20230701_at_21904_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "649feebfb347aa29db9298ba",
  "name":
"externallmg_1688202942760_WhatsApp_Image_20230701_at_21904_PM_3.jpeg",
  "path": "cases/649e98b8b347aa29db89ec13/
externallmg_1688202942760_WhatsApp_Image_20230701_at_21904_PM_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "649feebfb347aa29db9298bb",
  "name":
"externallmg_1688202942764_WhatsApp_Image_20230701_at_21904_PM.jpeg",
  "path": "cases/649e98b8b347aa29db89ec13/
externallmg_1688202942764_WhatsApp_Image_20230701_at_21904_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "649feebfb347aa29db9298bc",
  "name":
"externallmg_1688202942767_WhatsApp_Image_20230701_at_21856_PM_1.jpeg",
  "path": "cases/649e98b8b347aa29db89ec13/
externallmg_1688202942767_WhatsApp_Image_20230701_at_21856_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "649feebfb347aa29db9298bd",
  "name":
"externallmg_1688202942770_WhatsApp_Image_20230701_at_21856_PM_2.jpeg",
```

```
    "path": "cases/649e98b8b347aa29db89ec13/
externallmg_1688202942770_WhatsApp_Image_20230701_at_21856_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "649feebfb347aa29db9298be",
    "name":
"externallmg_1688202942776_WhatsApp_Image_20230701_at_21856_PM.jpeg",
    "path": "cases/649e98b8b347aa29db89ec13/
externallmg_1688202942776_WhatsApp_Image_20230701_at_21856_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "649feebfb347aa29db9298bf",
    "name":
"externallmg_1688202942780_WhatsApp_Image_20230701_at_21857_PM_1.jpeg",
    "path": "cases/649e98b8b347aa29db89ec13/
externallmg_1688202942780_WhatsApp_Image_20230701_at_21857_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "649feebfb347aa29db9298c0",
    "name":
"externallmg_1688202942788_WhatsApp_Image_20230701_at_21857_PM.jpeg",
    "path": "cases/649e98b8b347aa29db89ec13/
externallmg_1688202942788_WhatsApp_Image_20230701_at_21857_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "649feed1b347aa29db9299dd",
    "name":
"externallmg_1688202960413_WhatsApp_Image_20230701_at_21858_PM.jpeg",
    "path": "cases/649e98b8b347aa29db89ec13/
externallmg_1688202960413_WhatsApp_Image_20230701_at_21858_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "649feed1b347aa29db9299de",
  "name":
"externallmg_1688202960421_WhatsApp_Image_20230701_at_21859_PM_1.jpeg",
  "path": "cases/649e98b8b347aa29db89ec13/
externallmg_1688202960421_WhatsApp_Image_20230701_at_21859_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "649feed1b347aa29db9299df",
  "name":
"externallmg_1688202960445_WhatsApp_Image_20230701_at_21859_PM.jpeg",
  "path": "cases/649e98b8b347aa29db89ec13/
externallmg_1688202960445_WhatsApp_Image_20230701_at_21859_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "649feed1b347aa29db9299e0",
  "name":
"externallmg_1688202960454_WhatsApp_Image_20230701_at_21900_PM_1.jpeg",
  "path": "cases/649e98b8b347aa29db89ec13/
externallmg_1688202960454_WhatsApp_Image_20230701_at_21900_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "649feed1b347aa29db9299e1",
  "name":
"externallmg_1688202960456_WhatsApp_Image_20230701_at_21900_PM_2.jpeg",
  "path": "cases/649e98b8b347aa29db89ec13/
externallmg_1688202960456_WhatsApp_Image_20230701_at_21900_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "649feed1b347aa29db9299e2",
  "name":
"externallmg_1688202960459_WhatsApp_Image_20230701_at_21900_PM.jpeg",
  "path": "cases/649e98b8b347aa29db89ec13/
externallmg_1688202960459_WhatsApp_Image_20230701_at_21900_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "649feed1b347aa29db9299e3",
    "name":
"externallmg_1688202960462_WhatsApp_Image_20230701_at_21901_PM_1.jpeg",
    "path": "cases/649e98b8b347aa29db89ec13/
externallmg_1688202960462_WhatsApp_Image_20230701_at_21901_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "649feed1b347aa29db9299e4",
    "name":
"externallmg_1688202960464_WhatsApp_Image_20230701_at_21901_PM.jpeg",
    "path": "cases/649e98b8b347aa29db89ec13/
externallmg_1688202960464_WhatsApp_Image_20230701_at_21901_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "649feed1b347aa29db9299e5",
    "name":
"externallmg_1688202960468_WhatsApp_Image_20230701_at_21902_PM_1.jpeg",
    "path": "cases/649e98b8b347aa29db89ec13/
externallmg_1688202960468_WhatsApp_Image_20230701_at_21902_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "649feed1b347aa29db9299e6",
    "name":
"externallmg_1688202960470_WhatsApp_Image_20230701_at_21902_PM.jpeg",
    "path": "cases/649e98b8b347aa29db89ec13/
externallmg_1688202960470_WhatsApp_Image_20230701_at_21902_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [
  {
    "originalname": "SANTOSH ADOLE SBI-RACPC GHATKOPAR W.pdf",
```

```
"filename":
"1688375062842_SANTOSH_ADOLE_SBIRACPC_GHATKOPAR_W.pdf",
  "path": "cases/649e98b8b347aa29db89ec13/externalDocuments/1688375062842_S
ANTOSH_ADOLE_SBIRACPC_GHATKOPAR_W.pdf",
  "size": "274395",
  "documentType": {
    "value": "640eb7ac064d015cce16a9f7",
    "label": "Proforma Invoice"
  },
  "createdAt": "Mon Jul 03 2023 14:34:22 GMT+0530 (India Standard Time)",
  "uploadedBy": "62fb6919bc41567298b48f4d"
},
{
  "originalname": "Santosh Bajirao Adole & Mrs. Ratnamala Santosh Adole.pdf",
  "filename":
"1688375143250_Santosh_Bajirao_Adoles_Mrs_Ratnamala_Santosh_Adoles.pdf",
  "path": "cases/649e98b8b347aa29db89ec13/externalDocuments/1688375143250_S
antosh_Bajirao_Adoles_Mrs_Ratnamala_Santosh_Adoles.pdf",
  "size": "11548338",
  "documentType": {
    "value": "640ece6024088f0f94ee4ea8",
    "label": "Final PDF Report"
  },
  "createdAt": "Mon Jul 03 2023 14:35:43 GMT+0530 (India Standard Time)",
  "uploadedBy": "63f31d626f9c2254a9b39144"
},
{
  "originalname": "Valuation_Report_Santosh Bajirao Adole & Mrs. Ratnamala
Santosh Adole.pdf",
  "filename": "1688375163859_Valuation_Report_Santosh_Bajirao_Adoles_Mrs_Ratn
amala_Santosh_Adoles.pdf",
  "path": "cases/649e98b8b347aa29db89ec13/externalDocuments/1688375163859_V
aluation_Report_Santosh_Bajirao_Adoles_Mrs_Ratnamala_Santosh_Adoles.pdf",
  "size": "12995106",
  "documentType": {
    "value": "60ae124caa6d152c1801b300",
    "label": "Signed Report"
  },
  "createdAt": "Mon Jul 03 2023 14:36:04 GMT+0530 (India Standard Time)",
  "uploadedBy": "63f31d626f9c2254a9b39144"
},
{
  "originalname": "OC.pdf",
  "filename": "1688375972282_OC.pdf",
  "path": "cases/649e98b8b347aa29db89ec13/
externalDocuments/1688375972282_OC.pdf",
```

```
"size": "274395",
"documentType": {
  "value": "60ae124daa6d152c1801b307",
  "label": "Office Copy"
},
"createdAt": "Mon Jul 03 2023 14:49:32 GMT+0530 (India Standard Time)",
"uploadedBy": "60eebe33f3dd69653a5837ae"
}
],
"createdAt": "2023-06-30T08:56:24.816Z",
"updatedAt": "2023-07-03T10:08:16.520Z",
"__v": 0,
"invoiceId": "649e98b8b347aa29db89ec19",
"fullAddress": "Residential Flat No. 806, 8th Floor, Wing - B, Trident (Hitesh
Apartment), Sanghavi Estate, Garden Lane, Village - Ghatkopar, Municipality Ward No.
N, Taluka - Kurla, District - Mumbai, Ghatkopar (West), 400 086, State - Maharashtra,
India",
"updatedBy": "60eeaeddf3dd69653a581316",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Mr. Pratik Adole",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner's Son",
"siteVisitContactNo": "7821816072",
"reason": "",
"siteVisitDate": "2023-07-01",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + 2 Toilet",
"carpetTotal": "315.91",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "347.50",
"finalCarpetArea": "315.91",
"finalSalableArea": "382.25",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
```


"finalSaleablePercentage": "0",
 "finalValuationAreaString": "Carpet Area in Sq. Ft. = 325.00",
 "buildingServicesRate": "2700",
 "flatRate": "25500",
 "landOtherRate": "22800",
 "otherCompositionBuiltUpTotal": "0.00",
 "otherCompositionCarpetTotal": "0.00",
 "otherCompositionSaleableTotal": "0.00"

}

Name	Length	Width	Total
Composition :			
Living Room	12'00"	10'00"	120.00
Toilet	6'0"	3'3"	19.50
Toilet	6'00"	3'3"	19.50
Kitchen	9'3"	6'4"	58.58
Bedroom	10'00"	9'10"	98.33
Other Composition :			