

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Market Value",
    "value": "Market_Value"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b951"
    },
    "type": "CREDITOFFICER",
    "_id": "635f732fe363ef22db2f1c80",
    "firstName": "Ravindra Sir",
    "lastName": "sir",
    "mobileNo": "",
    "email": "me1@me.com",
    "workMobileNo": "7738642220"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "Ravindra Sir",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "VCIPL Mumbai",
    "shortName": "VCIPLM",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
```

```
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b951",
  "branchCode": "000167",
  "type": "BRANCH",
  "name": "RACPC Belapur ",
  "email": "sbi.14677@sbi.co.in",
  "mobileNo": "022-27524090",
  "alternateMobileNo": "",
  "address": "Estate Department Corporate Centre, 4th Floor, CIDCO Tower No. 4,
Railway Station Building, C.B.D. Belapur, Navi Mumbai - 400 614, State - Maharashtra,
Country - India.",
  "ledgerName": "STATE BANK OF INDIA - CBD Estate Department",
  "fax": "022 2757 7002",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "checker": {
    "type": "EMPLOYEE",
    "_id": "60f915d3f3dd69653a592199",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shobha",
    "email": "shobha@vastukala.org",
```

```
    "lastName": "Kuperkar",
    "mobileNo": "9004134140",
    "designation": "",
    "shortName": "SH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
  },
  "valuers": []
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.076402574084998",
  "longitude": "73.15419339325278"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.15419339325278,
    19.076402574084998
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-07-07",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": "NO",
  "rateMin": "4000",
  "lumpsumValue": "4000000.00",
  "rateMax": "4500",
  "areaType": {
    "Name": "Saleable",
    "Value": "Saleable",
    "name": "Saleable",
  }
}
```

```
    "value": "Saleable"
  }
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft."
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Thu Jul 06 2023 14:35:52 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Mahodar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "2",
    "label": false
  },
  "buildingNo": {
```

```
"status": true,
"name": "Building No",
"key": "buildingNo",
"value": "B2",
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Raigad",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Taloja",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Panvel",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Arihant Amisha Co-op. Hsg. Soc. Ltd.",
```

```
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Ganesh Mandir Road, Via Palekhurd, Wavanje",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Phase - I",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
```

```
"name": "Old Survey No.",
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "87",
  "label": true
},
"hissaNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "2",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "202",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
}
```

```
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 410 208",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
```



```

    "key": "suburb",
    "value": "",
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "VerifiedTileFlooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "label": "Powder coated Aluminum sliding windows",
    "value": "Powder_coated_Aluminum_sliding_windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "label": "Cement Plastering with POP Finished",
    "value": "Cement_Plastering_with_POP_Finished"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Semi Urban",
    "value": "Semi_Urban"
  },
  "townplanApprovedByList": {

```

```
"value": "CIDCO",
"label": "CIDCO"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Building No. B1",
"south": "Building No. B3",
"east": "Internal Road & Building No. B5",
"west": "Internal Road & Building No. A1"
},
"asPerDocumentAgreement": {
"north": "Details not available",
"west": "Details not available",
"south": "Details not available",
"east": "Details not available"
},
"extraDetailOfProperty": ""
},
"compositeRate": {
"remark": "",
"depreciationPercentage": "7.5",
"depreciationRatioOfBuilding": "",
"salvageValue": "10",
"buildingServicesDepreciatedRate": "187.5",
"depreciatedCostOfConstruction": "7412.50",
"depreciatedBuildingRate": "2312.5"
},
"igrRate": {
"propertyName": "Mahodar Village",
"rate": "44800",
"landRate": "4500",
"igrImage": "cases/649ea7c1b347aa29db8a1ae2/igr_1688727923895_Image.png",
"squareMeterGuideLineRate": "44800.00",
"squareFeetGuideLineRate": "4162.00"
},
"igrFinalRate": {
"rate": "3975.00",
"squareFeetGuideLineRate": "3975.00",
"squareMeterGuideLineRate": "42785.00"
},
"outgoingDetail": {
"areaStatusList": {
"label": "Middle Class",
```

```
"value": "Middle_Class"
},
"propertyTypeOfUseList": {
  "label": "Residential Purpose",
  "value": "Residential_Purpose"
},
"propertyOccupiedByList": {
  "label": "Vacant",
  "value": "Vacant"
},
"monthlyRent": "8,500",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per CIDCO norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "label": "Yes",
    "value": "Yes"
  }
},
```

```
"carParking": "Stilt + Open Car Parking",
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2018",
  "fullDate": "1/1/2018"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
}
```

```
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
  "label": "Stilt",
  "value": "stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "5",
"totalLifeBuilding": "60",
"estimatedAge": "55",
"noOfBasement": "0",
```

```
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "4",
"flatFloorNo": "2",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "616.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/649ea7c1b347aa29db8a1ae2/
routeMap_1688811424141_Image.png",
    "routeLat": "19.076029",
    "routeLng": "73.154483",
    "stationName": "Navade Road",
    "routeDistance": "6.6 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "j45un",
      "name": "j45un",
      "image": "cases/649ea7c1b347aa29db8a1ae2/
routeMap_1688811325527_Image.png"
    }
  ]
},
"valuation": {
```

```
"wardrobesRate": "0",
"totalwardrobesRate": "0",
"wardrobesQty": "0",
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "4151280.00",
"bookValue": "0",
"finalValue": "4151280.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Mon Jul 10 2023 11:35:58 GMT+0530 (India Standard Time)",
  "number": "2301466",
  "dayCount": "2",
  "monthCount": "91",
  "generatedBy": "60f915d3f3dd69653a592199"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
"label": "RCC Plinth",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
}
```



```
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2448600.00",
  "selectedBuildUpValue": "616.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "64a77bc894dfc26ccf85c115",
      "name": "externallmg_1688697794063_1688697592226_image_5.jpeg",
      "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697794063_1688697592226_image_5.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "64a77bc894dfc26ccf85c111",
```

```
    "name": "externallmg_1688697791103_1688697592226_image_1.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697791103_1688697592226_image_1.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "64a77bc894dfc26ccf85c113",
    "name": "externallmg_1688697791178_1688697592226_image_3.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697791178_1688697592226_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64a77bc894dfc26ccf85c114",
    "name": "externallmg_1688697793489_1688697592226_image_4.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697793489_1688697592226_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64a77bc894dfc26ccf85c11c",
    "name": "externallmg_1688697729513_1688697528212_image_5.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697729513_1688697528212_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64a77bc894dfc26ccf85c129",
    "name": "externallmg_1688697735283_1688697528212_image_18.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697735283_1688697528212_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64a77bc894dfc26ccf85c128",
    "name": "externallmg_1688697734518_1688697528212_image_17.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697734518_1688697528212_image_17.jpeg",
    "orientation": "portrait"
  }
]
```

```
}
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "64a77bc894dfc26ccf85c112",
    "name": "externallmg_1688697791138_1688697592226_image_2.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697791138_1688697592226_image_2.jpeg",
    "orientation": "portrait"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "64a77bc894dfc26ccf85c119",
    "name": "Living Room",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697729294_1688697528212_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64a77bc894dfc26ccf85c11b",
    "name": "Living Room",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697729499_1688697528212_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64a77bc894dfc26ccf85c11d",
    "name": "Living Room",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697729529_1688697528212_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64a77bc894dfc26ccf85c121",
    "name": "Living Room",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697732063_1688697528212_image_10.jpeg",
    "orientation": "portrait"
  },
],
```

```
{
  "status": false,
  "_id": "64a77bc894dfc26ccf85c12a",
  "name": "Living Room",
  "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697735293_1688697528212_image_19.jpeg",
  "orientation": "portrait"
}
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "6786",
    "max": "8436"
  },
  "builtUpRateRange": {
    "min": "5655",
    "max": "7031"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
```

```
"title": "Kitchen arrangements",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "560.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REPORTGENERATED",
"_id": "649ea7c1b347aa29db8a1ae2",
"ownerName": "Mr. Aslam Hasan Choche & Mrs. Rajiya Aslam Choche",
```

```
"ownerPhoneNo": "9082128889",
"appAddress": "flat no. B2 202, 2 nd floor ARIHANT AMISHA CO-OP HSG SOC. LTD
Village Mahodar tal Panvel - ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "27/06/2023",
      "from": {
        "value": "Vendor",
        "label": "Vendor"
      },
      "Vendor": "Mr. Pravin Ramesh Chaudhari",
      "to": {
        "value": "Purchaser",
        "label": "Purchaser"
      },
      "Purchaser": "Mr. Aslam Hasan Choche & Mrs. Rajiya Aslam Choche"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1688810461061_Agreement.pdf",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
document_1688810461061_Agreement.pdf",
    "id": "316026",
    "uploadedBy": "60eebe33f3dd69653a5837ae",
    "createdAt": "Sat Jul 08 2023 15:31:01 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124baa6d152c1801b2fd",
      "label": "Occupancy Certificate"
    },
    "inputs": {
      "documentDate": "07/02/2018",
      "nameOfApprovingAuthority": {
        "value": "CIDCO",
        "label": "CIDCO"
      },
      "number": {
        "value": "No",
        "label": "No"
      }
    }
  }
]
```



```
    },
    "No": "CIDCO / NAINA / Panvel / Mahodar / BP-234 / Part OC / 2018 / 1212"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1688810657553_OC.pdf",
  "path": "cases/649ea7c1b347aa29db8a1ae2/document_1688810657553_OC.pdf",
  "id": "377112",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Sat Jul 08 2023 15:34:17 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "07/02/2018",
    "nameOfApprovingAuthority": {
      "value": "CIDCO",
      "label": "CIDCO"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "CIDCO / NAINA / Panvel / Mahodar / BP-234 / Part OC / 2018 / 1212"
},
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1688812141116_7_Building_Plan_Approval_IOD.pdf",
  "path": "cases/649ea7c1b347aa29db8a1ae2/
document_1688812141116_7_Building_Plan_Approval_IOD.pdf",
  "id": "248779",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Sat Jul 08 2023 15:59:01 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "002248",
"createdBy": "64535eb5ee347304f2a3005f",
"caseHistory": [
  {
    "id": "186765",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Jun 30 2023 15:30:33 GMT+0530 (India Standard Time)"
  }
]
```

```
}
],
"owners": [
  {
    "name": "Mr. Aslam Hasan Choche & Mrs. Rajiya Aslam Choche",
    "phone": "9082128889",
    "email": "",
    "ownershipShare": "",
    "id": "315653"
  }
],
"siteInspection": [
  {
    "areaType": {
      "label": "Saleable",
      "value": "Saleable"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    },
    "_id": "64a77d4594dfc26ccf85c1e0",
    "area": "950",
    "providedByName": "Aslam Asan Choche ",
    "providedByContactNo": "9082128889"
  }
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "10",
    "name": "Living Room",
    "length": "",
    "length1": "9",
    "length2": "0",
    "width": "",
    "width1": "7",
    "width2": "7",
    "totalArea": "68.25",
    "images": [],
    "finalArea": "68.25",
    "extraAreas": []
  },
]
```

```
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "name": "Passage",
  "length": "2.50",
  "length1": "2",
  "length2": "6",
  "width": "8.17",
  "width1": "8",
  "width2": "2",
  "totalArea": "20.42",
  "images": [],
  "extraAreas": [],
  "finalArea": "20.42"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "8.58",
  "length1": "8",
  "length2": "7",
  "width": "2.92",
  "width1": "2",
  "width2": "11",
  "totalArea": "25.03",
  "images": [],
  "extraAreas": [],
  "finalArea": "25.03"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Kitchen",
  "length": "8.42",
  "length1": "8",
  "length2": "5",
```

```
"width": "6.75",
"width1": "6",
"width2": "9",
"totalArea": "56.81",
"images": [],
"extraAreas": [],
"finalArea": "56.81"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "3.83",
  "length1": "3",
  "length2": "10",
  "width": "4.67",
  "width1": "4",
  "width2": "8",
  "totalArea": "17.89",
  "images": [],
  "extraAreas": [],
  "finalArea": "17.89"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "Passage",
  "length": "2.00",
  "length1": "2",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "8.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "8.00"
},
{
  "measurementType": {
```

```
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "12.83",
  "length1": "12",
  "length2": "10",
  "width": "8.92",
  "width1": "8",
  "width2": "11",
  "totalArea": "114.43",
  "images": [],
  "extraAreas": [],
  "finalArea": "114.43"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "7",
  "name": "Bedroom",
  "length": "9.83",
  "length1": "9",
  "length2": "10",
  "width": "12.33",
  "width1": "12",
  "width2": "4",
  "totalArea": "121.28",
  "images": [],
  "extraAreas": [],
  "finalArea": "121.28"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "8",
  "name": "Toilet",
  "length": "3.83",
  "length1": "3",
  "length2": "10",
  "width": "7.00",
  "width1": "7",
```

```
"width2": "00",
"totalArea": "26.83",
"images": [],
"extraAreas": [],
"finalArea": "26.83"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "9",
  "name": "Flowered Area",
  "length": "1.67",
  "length1": "1",
  "length2": "8",
  "width": "10.00",
  "width1": "10",
  "width2": "00",
  "totalArea": "16.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "16.67"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Flower Bed Area",
      "value": "Flower_Bed_Area"
    },
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "0",
    "length1": "2",
    "length2": "00",
    "length": "2.00",
    "width1": "6",
    "width2": "00",
    "width": "6.00",
```

```
"totalArea": "12.00",
"percentageBeforeTotal": "12.00",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "12"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flower Bed Area",
    "value": "Flower_Bed_Area"
  },
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "1",
  "length1": "2",
  "length2": "00",
  "length": "2.00",
  "width1": "10",
  "width2": "00",
  "width": "10.00",
  "totalArea": "20.00",
  "percentageBeforeTotal": "20.00",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "20"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Flowerbed",
    "value": "Flowerbed"
  },
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  }
}
```

```
    },
    "id": "2",
    "length1": "2",
    "length2": "00",
    "length": "2.00",
    "width1": "7",
    "width2": "00",
    "width": "7.00",
    "totalArea": "14.00",
    "percentageBeforeTotal": "14.00",
    "images": [],
    "extraAreas": [],
    "percentage": "100",
    "finalArea": "14"
  }
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "449242",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "560",
    "squareMeterArea": "52.03",
    "docFinalBuiltUp": "616",
    "docFinalBuiltUpSquareMeter": "57.233000000000004",
    "docBultupPercentage": "10",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "64a7f48b1c023929367d8e7a",
    "property": "Arihant Amisha Panvel",
    "area": "560",
```



```
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "3",
"source": "magic_bricks",
"expectedPrice": "3800000",
"expectedRate": "6785.71",
"builtUpExpectedRate": "5654.76",
"image": "cases/649ea7c1b347aa29db8a1ae2/
indicator_1688727419673_Image.png",
"squareMeter": "52.03",
"id": "599271"
},
{
  "printlnReport": true,
  "_id": "64a7f48b1c023929367d8e7b",
  "property": "Arihant Amisha Panvel",
  "area": "527",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Middle",
  "source": "square_yards",
  "expectedPrice": "4446000",
  "expectedRate": "8436.43",
  "builtUpExpectedRate": "7030.36",
  "image": "cases/649ea7c1b347aa29db8a1ae2/
indicator_1688727495466_Image.png",
  "squareMeter": "48.96",
  "id": "471405"
},
{
  "printlnReport": true,
  "_id": "64a7f48b1c023929367d8e7c",
  "property": "Arihant Amisha Panvel",
  "area": "352",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "3",
  "source": "magic_bricks",
  "expectedPrice": "2480000",
  "expectedRate": "7045.45",
```

```
"builtUpExpectedRate": "5871.21",
"image": "cases/649ea7c1b347aa29db8a1ae2/
indicator_1688727560989_Image.png",
"squareMeter": "32.70",
"id": "428815"
},
{
  "printlnReport": true,
  "_id": "64a7f48b1c023929367d8e7d",
  "property": "Arihant Amisha Panvel",
  "area": "549",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "2",
  "source": "https://www.99acres.com/",
  "expectedPrice": "4000000",
  "expectedRate": "7285.97",
  "builtUpExpectedRate": "6071.65",
  "image": "cases/649ea7c1b347aa29db8a1ae2/
indicator_1688727641053_Image.png",
  "squareMeter": "51.00",
  "id": "436875"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64a77bc894dfc26ccf85c110",
    "name": "externalImg_1688697791008_1688697592226_image_0.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externalImg_1688697791008_1688697592226_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64a77bc894dfc26ccf85c111",
    "name": "externalImg_1688697791103_1688697592226_image_1.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externalImg_1688697791103_1688697592226_image_1.jpeg",
    "orientation": "portrait"
  },
  {

```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64a77bc894dfc26ccf85c112",
    "name": "externallmg_1688697791138_1688697592226_image_2.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697791138_1688697592226_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64a77bc894dfc26ccf85c113",
    "name": "externallmg_1688697791178_1688697592226_image_3.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697791178_1688697592226_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64a77bc894dfc26ccf85c114",
    "name": "externallmg_1688697793489_1688697592226_image_4.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697793489_1688697592226_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64a77bc894dfc26ccf85c115",
    "name": "externallmg_1688697794063_1688697592226_image_5.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697794063_1688697592226_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64a77bc894dfc26ccf85c116",
    "name": "externallmg_1688697795827_1688697592226_image_6.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697795827_1688697592226_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
    "status": false,
    "_id": "64a77bc894dfc26ccf85c117",
    "name": "externallmg_1688697729113_1688697528212_image_0.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697729113_1688697528212_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64a77bc894dfc26ccf85c118",
    "name": "externallmg_1688697729114_1688697528212_image_1.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697729114_1688697528212_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64a77bc894dfc26ccf85c119",
    "name": "externallmg_1688697729294_1688697528212_image_2.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697729294_1688697528212_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64a77bc894dfc26ccf85c11a",
    "name": "externallmg_1688697729329_1688697528212_image_3.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697729329_1688697528212_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64a77bc894dfc26ccf85c11b",
    "name": "externallmg_1688697729499_1688697528212_image_4.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697729499_1688697528212_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
```

```
    "_id": "64a77bc894dfc26ccf85c11c",
    "name": "externallmg_1688697729513_1688697528212_image_5.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697729513_1688697528212_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64a77bc894dfc26ccf85c11d",
    "name": "externallmg_1688697729529_1688697528212_image_6.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697729529_1688697528212_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64a77bc894dfc26ccf85c11e",
    "name": "externallmg_1688697729564_1688697528212_image_7.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697729564_1688697528212_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64a77bc894dfc26ccf85c11f",
    "name": "externallmg_1688697729578_1688697528212_image_8.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697729578_1688697528212_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64a77bc894dfc26ccf85c120",
    "name": "externallmg_1688697729674_1688697528212_image_9.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697729674_1688697528212_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64a77bc894dfc26ccf85c121",
```

```
    "name": "externallmg_1688697732063_1688697528212_image_10.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697732063_1688697528212_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64a77bc894dfc26ccf85c122",
    "name": "externallmg_1688697732064_1688697528212_image_11.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697732064_1688697528212_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64a77bc894dfc26ccf85c123",
    "name": "externallmg_1688697732065_1688697528212_image_12.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697732065_1688697528212_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64a77bc894dfc26ccf85c124",
    "name": "externallmg_1688697732274_1688697528212_image_13.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697732274_1688697528212_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64a77bc894dfc26ccf85c125",
    "name": "externallmg_1688697733833_1688697528212_image_14.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externallmg_1688697733833_1688697528212_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64a77bc894dfc26ccf85c126",
    "name": "externallmg_1688697733868_1688697528212_image_15.jpeg",
```

```
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externalImg_1688697733868_1688697528212_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64a77bc894dfc26ccf85c127",
    "name": "externalImg_1688697734313_1688697528212_image_16.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externalImg_1688697734313_1688697528212_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64a77bc894dfc26ccf85c128",
    "name": "externalImg_1688697734518_1688697528212_image_17.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externalImg_1688697734518_1688697528212_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64a77bc894dfc26ccf85c129",
    "name": "externalImg_1688697735283_1688697528212_image_18.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externalImg_1688697735283_1688697528212_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64a77bc894dfc26ccf85c12a",
    "name": "externalImg_1688697735293_1688697528212_image_19.jpeg",
    "path": "cases/649ea7c1b347aa29db8a1ae2/
externalImg_1688697735293_1688697528212_image_19.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-06-30T10:00:33.518Z",
"updatedAt": "2023-07-10T06:08:44.376Z",
"__v": 0,
"invoiceId": "649ea7c1b347aa29db8a1ae8",
```

```
"fullAddress": "Residential Flat No. 202, 2nd Floor, Building No B2, Arihant Amisha Co-
op. Hsg. Soc. Ltd., Phase - I, Ganesh Mandir Road, Via Palekhurd, Wavanje, Village -
Mahodar, Taluka - Panvel, District - Raigad, Taloja, PIN - 410 208, State - Maharashtra,
India",
"updatedBy": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "64535eb5ee347304f2a3005f",
"contactPersonName": "Aslam Asan Choche ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9082128889",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 3 Passage + 2 Toilet +
Flowered Area",
"carpetTotal": "475.61",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "46.00",
"siteVisitDate": "2023-07-07",
"buildingServicesRate": "2500.00",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 560.00",
"flatRate": "7600",
"landOtherRate": "5100",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "46.00",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "573.77",
"finalCarpetArea": "521.61",
"finalSalableArea": "631.15",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 522.00\nFlowerbed Area in Sq.
Ft. = 46.00\nTotal Carpet Area in Sq. Ft. = 568.00",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalSaleablePercentage": "0"
}
```


Name	Length	Width	Total
Composition :			
Living Room	9'0"	7'7"	68.25
Passage	2'6"	8'2"	20.42
Passage	8'7"	2'11"	25.03
Kitchen	8'5"	6'9"	56.81
Toilet	3'10"	4'8"	17.89
Passage	2'00"	4'00"	8.00
Bedroom	12'10"	8'11"	114.43
Bedroom	9'10"	12'4"	121.28
Toilet	3'10"	7'00"	26.83
Flowered Area	1'8"	10'00"	16.67
Other Composition :			
Flower Bed Area	2'00"	6'00"	12.00
Flower Bed Area	2'00"	10'00"	20.00
Flowerbed	2'00"	7'00"	14.00