

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b80a"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230ec0",
    "firstName": "Anuj Mehrotra",
    "email": "0_default_a_mehrotra@sbi.co.in",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-9987527007"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "VCIPL Mumbai",
    "shortName": "VCIPLM",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  }
}
```

```
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b80a",
  "branchCode": "000088",
  "type": "BRANCH",
  "name": "RACPC - Chinchpokli ",
  "email": "sbi.17889@sbi.co.in",
  "mobileNo": "022-23707514",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, Mumbai South Voltas
House, 'A', 1st Floor, Dr. Ambedkar Road, Chinchpokli (East), Mumbai - 400 033, State
- Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - CHINCHPOKALI",
  "fax": "022-23707512 / 13",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land & Building / _Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62727444afd7d55eddee092c",
    "role": "PICKUPPERSON",
    "firstName": "Shantilal",
    "email": "shantilal@vastukala.org",
    "lastName": "Patel",
```

```
"mobileNo": "9969039853",
"shortName": "SHP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62550ed0aba01e0af98f2f75",
"role": "SITEENGINEER",
"firstName": "Chandan",
"email": "chandan@vastukala.org",
"lastName": "Singh",
"mobileNo": "8454863607",
"designation": "",
"shortName": "CH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "0123456789",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"maker": {
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
```

```
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "0123456789",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "CAT-I-A-1930",
        "label": "Chartered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "60af7d4d2ffdf65bcd658643",
    "PANNo": "AESPC7493M",
    "role": "VALUER",
    "firstName": "Vidhi",
    "fatherName": "Manoj",
    "email": "vids_singh@yahoo.com",
    "lastName": "Chalikwar",
    "mobileNo": "9820549087",
    "designation": "Valuer",
    "registrationNo": [
      {
        "title": {
          "value": "Chartered_Valuer",
          "label": "Chartered Valuer"
        },
        "_id": "60eeb39af3dd69653a58168d",
        "number": "CAT-I-A-1930"
      }
    ],
    "shortName": "VC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af7d4d2ffdf65bcd658643\\
```

```
\profilePhoto_1622113613002_Vidhi C.jpeg"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "18.96273334800905 ",
  "longitude": "72.81229901241497"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.81229901241497,
    18.96273334800905
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-07-03T10:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-07-03T10:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-07-03T10:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-07-03T10:00:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "remark": "MANUAL",
      "status": "COMPLETED",
      "dateTime": "2023-07-04T06:00:00.000Z"
    }
  ]
}
```

```
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": "No remark",
  "rateMin": "45000",
  "lumpsumValue": "455000",
  "rateMax": "46500",
  "areaType": {
    "Name": "Carpet",
    "Value": "Carpet",
    "name": "Carpet",
    "value": "Carpet"
  }
},
"compositionFlatType": {
  "value": "1RK",
  "label": "1 RK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft."
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Malabar",
    "label": true
  },
  "floorNo": {
    "status": true,
```

```
"name": "Floor No",
"key": "floorNo",
"value": "4",
"label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "1",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Ward - C",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
}
```

```
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shreepati Arcade Annexe - II Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "20, August Kranti Marg",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Nana Chowk, Grant Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "D",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
```



```
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "522, 523 & 524",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "401",
  "label": false
},
}
```

```
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
```

```
"value": "PIN - 400 036",
"label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Mumbai",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Wooden_frame_openable_widow_with_M._S._Grill",
    "label": "Wooden frame openable widow with M. S. Grill"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring",
    "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring"
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "sole_ownership",
    "label": "sole ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  }
}
```

```
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "MCGM",
  "label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Shastri Hall Building",
  "west": "Internal Road",
  "south": "Wing - A",
  "east": "Sanskriti Palace"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"extraDetailOfProperty": "Details not available"
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "37.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "37875",
  "depreciatedBuildingRate": "1875"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "524150",
  "landRate": "278610",
  "igrImage": "cases/64a2a9fd2923d90f978640ff/igr_1688554915880_Image.png",
  "squareMeterGuideLineRate": "524150.00",
  "squareFeetGuideLineRate": "48695.00"
},
"igrFinalRate": {
  "rate": "42992.00",
  "squareFeetGuideLineRate": "42992.00",
```

```
"squareMeterGuideLineRate": "462765.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "17500",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MCGM norms",
  "tenantName": "",
  "maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\\_Thk._Brick_Masonry",
    "label": "6\\ Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  }
}
```

```
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Stilt Car Parking Space",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "1998",
  "fullDate": "1/1/1998"
},
"propertyTypeList": {
  "value": "Residential",
  "label": "Residential"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
```

```
"label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenancelssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
}
```

```
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"noOfLiftsInEachWings": "0",
"ageOfBuilding": "25",
"totalLifeBuilding": "60",
"estimatedAge": "35",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "4",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "7"
},
"finalPlinthArea": {
  "area": "270.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/64a2a9fd2923d90f978640ff/
routeMap_1688555097355_Image.png",
    "routeLat": "18.963619",
    "routeLng": "72.812701",
    "stationName": "Grant Road",
    "routeDistance": "800 Mtr."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
}
```



```
"locationMapImg": [
  {
    "id": "zp89qe",
    "name": "zp89qe",
    "image": "cases/64a2a9fd2923d90f978640ff/
routeMap_1688554983563_Image.png"
  }
],
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "8521875.00",
  "bookValue": "0",
  "finalValue": "8521875.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Wed Jul 05 2023 17:00:46 GMT+0530 (India Standard Time)",
  "number": "2301426",
```

```
"dayCount": "18",
"monthCount": "51",
"generatedBy": "5fc78e26625ecd20ec1f88e9"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "11607840.00",
  "selectedBuildUpValue": "270.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "64a3c95011d5643c3273bef8",
    }
  ]
}
```

```
    "name":
"externallmg_1688455504075_WhatsApp_Image_20230704_at_123402_PM_1.jpeg",
    "path": "cases/64a2a9fd2923d90f978640ff/
externallmg_1688455504075_WhatsApp_Image_20230704_at_123402_PM_1.jpeg",
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "64a3c95d11d5643c3273bf27",
    "name": "Living Room",
    "path": "cases/64a2a9fd2923d90f978640ff/
externallmg_1688455516437_WhatsApp_Image_20230704_at_123404_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64a3c95d11d5643c3273bf2b",
    "name": "Living Room",
    "path": "cases/64a2a9fd2923d90f978640ff/
externallmg_1688455516448_WhatsApp_Image_20230704_at_123405_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "64a3c95011d5643c3273befc",
    "name": "Living Room",
    "path": "cases/64a2a9fd2923d90f978640ff/
externallmg_1688455504092_WhatsApp_Image_20230704_at_123403_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64a3c95d11d5643c3273bf2c",
    "name": "Living Room",
    "path": "cases/64a2a9fd2923d90f978640ff/
externallmg_1688455516450_WhatsApp_Image_20230704_at_123406_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
```

```
    "_id": "64a3c95011d5643c3273befa",
    "name": "Living Room",
    "path": "cases/64a2a9fd2923d90f978640ff/
externallmg_1688455504084_WhatsApp_Image_20230704_at_123402_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64a3c95011d5643c3273bef8",
    "name": "Living Room",
    "path": "cases/64a2a9fd2923d90f978640ff/
externallmg_1688455504075_WhatsApp_Image_20230704_at_123402_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64a3c95011d5643c3273bef9",
    "name": "Living Room",
    "path": "cases/64a2a9fd2923d90f978640ff/
externallmg_1688455504081_WhatsApp_Image_20230704_at_123402_PM_2.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
```

```
"title": "Extra collapsible gates / grill works etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
```



```
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "225.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86A/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"_id": "64a2a9fd2923d90f978640ff",
"ownerName": "Shri. Suhas Shantaram Bavkar",
"ownerPhoneNo": "9869318457",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9869318457",
"contactPersonName": "Suhash Shantaram Baikar",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Shri. Suhas Shantaram Bavkar",
    "phone": "9869318457",
    "ownershipShare": "",
    "email": "",
    "id": "589850"
  }
],
"caseReferredBy": "62727444afd7d55eddee092c",
"relationWithOwner": "self",
"fullAddress": "Residential Flat No. 401, 4th Floor, Building No 1, Wing - D, Shreepati Arcade Annexe - II Co-Op. Hsg. Soc. Ltd., 20, August Kranti Marg, Nana Chowk, Grant Road, Village - Malabar, Mumbai, Taluka - Ward - C, District - Mumbai, Mumbai, PIN - 400 036, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1260aa6d152c1801b35f",
      "label": "Deed of Release"
    },
    "inputs": {
      "documentDate": "09/11/2011",
```

```
"from": {
  "value": "The_Releasers",
  "label": "The Releasers"
},
"The_Releasers": "Mrs. Shailaja Shivaji Padave, Mrs. Neelaxi Nandvijay Desai,
Mrs. Varsha Vasant Divekar & Shri. Anil Shanaram Bavkar",
"to": {
  "value": "The_Releasee",
  "label": "The Releasee"
},
"The_Releasee": "Shri. Suhas Shantaram Bavkar"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1688541202112_Deed_of_release.pdf",
"path": "cases/64a2a9fd2923d90f978640ff/
document_1688541202112_Deed_of_release.pdf",
"id": "696620",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Wed Jul 05 2023 12:45:00 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "04/05/1998",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "EEBPR / 4266 / D / AR"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1688541293994_OC.pdf",
  "path": "cases/64a2a9fd2923d90f978640ff/document_1688541293994_OC.pdf",
  "id": "526256",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Wed Jul 05 2023 12:45:00 GMT+0530 (India Standard Time)"
}
```

```
],
"isUrgent": "false",
"isExternal": "false",
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "002280",
"createdBy": "6006d4ce5080a310ac1fdcf2",
"caseHistory": [
  {
    "id": "344443",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Mon Jul 03 2023 16:29:09 GMT+0530 (India Standard Time)"
  }
],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    },
    "_id": "64a654f743724c0debc5d499",
    "area": "230",
    "providedByName": "Shri. Suhas Shantaram Bavkar",
    "providedByContactNo": "9869318457"
  }
],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "524496",
    "name": "Living Room",
    "length": "16.33",
    "length1": "16",
    "length2": "4",
    "width": "8.58",
    "width1": "8",
    "width2": "7",
    "totalArea": "140.19",
    "images": [],
  }
]
```

```
"extraAreas": [],
"finalArea": "140.19"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Bathroom",
  "length": "5.17",
  "length1": "5",
  "length2": "2",
  "width": "3.83",
  "width1": "3",
  "width2": "10",
  "totalArea": "19.81",
  "images": [],
  "extraAreas": [],
  "finalArea": "19.81"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "WC",
  "length": "3.67",
  "length1": "3",
  "length2": "8",
  "width": "2.75",
  "width1": "2",
  "width2": "9",
  "totalArea": "10.08",
  "images": [],
  "extraAreas": [],
  "finalArea": "10.08"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
```

```
"length": "3.33",
"length1": "3",
"length2": "4",
"width": "2.75",
"width1": "2",
"width2": "9",
"totalArea": "9.17",
"images": [],
"extraAreas": [],
"finalArea": "9.17"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Kitchen",
  "length": "7.42",
  "length1": "7",
  "length2": "5",
  "width": "6.50",
  "width1": "6",
  "width2": "6",
  "totalArea": "48.21",
  "images": [],
  "extraAreas": [],
  "finalArea": "48.21"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1260aa6d152c1801b35f",
      "label": "Deed of Release"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "801363",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "225",
    "squareMeterArea": "20.9",
```

```
"docFinalBuiltUp": "270",
"docFinalBuiltUpSquareMeter": "25.08",
"docBuiltupPercentage": "20",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "64a521e5698d832ead157c97",
  "id": "1",
  "property": "Flat",
  "area": "228",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "4",
  "source": "Index_no.2",
  "expectedPrice": "8500000",
  "expectedRate": "37280.70",
  "builtUpExpectedRate": "31067.25",
  "image": "cases/64a2a9fd2923d90f978640ff/indicator_1688543717567_Image.png"
},
{
  "printlnReport": true,
  "_id": "64a52280698d832ead158aab",
  "id": "2",
  "property": "Flat",
  "area": "300",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "",
  "source": "https://www.99acres.com/",
  "expectedPrice": "10500000",
  "expectedRate": "35000.00",
  "builtUpExpectedRate": "10500000",
  "image": "cases/64a2a9fd2923d90f978640ff/indicator_1688543872481_Image.png"
},
{
  "printlnReport": true,
```

```
    "_id": "64a54a413a0e245f2c0240fb",
    "id": "3",
    "property": "Flat",
    "area": "298",
    "builtUpPercentage": "10",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "floor": "1",
    "source": "https://www.99acres.com/",
    "expectedPrice": "8500000",
    "expectedRate": "28523.49",
    "builtUpExpectedRate": "8500000",
    "image": "cases/64a2a9fd2923d90f978640ff/indicator_1688554049220_Image.png"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64a3c95011d5643c3273bef5",
    "name":
"externalImg_1688455504062_WhatsApp_Image_20230704_at_123401_PM_1.jpeg",
    "path": "cases/64a2a9fd2923d90f978640ff/
externalImg_1688455504062_WhatsApp_Image_20230704_at_123401_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64a3c95011d5643c3273bef6",
    "name":
"externalImg_1688455504066_WhatsApp_Image_20230704_at_123401_PM_2.jpeg",
    "path": "cases/64a2a9fd2923d90f978640ff/
externalImg_1688455504066_WhatsApp_Image_20230704_at_123401_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64a3c95011d5643c3273bef7",
    "name":
"externalImg_1688455504072_WhatsApp_Image_20230704_at_123401_PM.jpeg",
    "path": "cases/64a2a9fd2923d90f978640ff/
externalImg_1688455504072_WhatsApp_Image_20230704_at_123401_PM.jpeg",
    "orientation": "landscape"
  }
]
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64a3c95011d5643c3273bef8",
  "name":
"externallmg_1688455504075_WhatsApp_Image_20230704_at_123402_PM_1.jpeg",
  "path": "cases/64a2a9fd2923d90f978640ff/
externallmg_1688455504075_WhatsApp_Image_20230704_at_123402_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64a3c95011d5643c3273bef9",
  "name":
"externallmg_1688455504081_WhatsApp_Image_20230704_at_123402_PM_2.jpeg",
  "path": "cases/64a2a9fd2923d90f978640ff/
externallmg_1688455504081_WhatsApp_Image_20230704_at_123402_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64a3c95011d5643c3273befa",
  "name":
"externallmg_1688455504084_WhatsApp_Image_20230704_at_123402_PM.jpeg",
  "path": "cases/64a2a9fd2923d90f978640ff/
externallmg_1688455504084_WhatsApp_Image_20230704_at_123402_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64a3c95011d5643c3273befb",
  "name":
"externallmg_1688455504089_WhatsApp_Image_20230704_at_123403_PM_1.jpeg",
  "path": "cases/64a2a9fd2923d90f978640ff/
externallmg_1688455504089_WhatsApp_Image_20230704_at_123403_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64a3c95011d5643c3273befc",
  "name":
"externallmg_1688455504092_WhatsApp_Image_20230704_at_123403_PM_2.jpeg",
```



```
    "path": "cases/64a2a9fd2923d90f978640ff/
externallmg_1688455504092_WhatsApp_Image_20230704_at_123403_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64a3c95011d5643c3273befd",
    "name":
"externallmg_1688455504094_WhatsApp_Image_20230704_at_123403_PM.jpeg",
    "path": "cases/64a2a9fd2923d90f978640ff/
externallmg_1688455504094_WhatsApp_Image_20230704_at_123403_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64a3c95d11d5643c3273bf26",
    "name":
"externallmg_1688455516431_WhatsApp_Image_20230704_at_123404_PM_1.jpeg",
    "path": "cases/64a2a9fd2923d90f978640ff/
externallmg_1688455516431_WhatsApp_Image_20230704_at_123404_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64a3c95d11d5643c3273bf27",
    "name":
"externallmg_1688455516437_WhatsApp_Image_20230704_at_123404_PM_2.jpeg",
    "path": "cases/64a2a9fd2923d90f978640ff/
externallmg_1688455516437_WhatsApp_Image_20230704_at_123404_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64a3c95d11d5643c3273bf28",
    "name":
"externallmg_1688455516440_WhatsApp_Image_20230704_at_123404_PM.jpeg",
    "path": "cases/64a2a9fd2923d90f978640ff/
externallmg_1688455516440_WhatsApp_Image_20230704_at_123404_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "64a3c95d11d5643c3273bf29",
    "name":
"externallmg_1688455516442_WhatsApp_Image_20230704_at_123405_PM_1.jpeg",
    "path": "cases/64a2a9fd2923d90f978640ff/
externallmg_1688455516442_WhatsApp_Image_20230704_at_123405_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64a3c95d11d5643c3273bf2a",
    "name":
"externallmg_1688455516445_WhatsApp_Image_20230704_at_123405_PM_2.jpeg",
    "path": "cases/64a2a9fd2923d90f978640ff/
externallmg_1688455516445_WhatsApp_Image_20230704_at_123405_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64a3c95d11d5643c3273bf2b",
    "name":
"externallmg_1688455516448_WhatsApp_Image_20230704_at_123405_PM.jpeg",
    "path": "cases/64a2a9fd2923d90f978640ff/
externallmg_1688455516448_WhatsApp_Image_20230704_at_123405_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64a3c95d11d5643c3273bf2c",
    "name":
"externallmg_1688455516450_WhatsApp_Image_20230704_at_123406_PM_1.jpeg",
    "path": "cases/64a2a9fd2923d90f978640ff/
externallmg_1688455516450_WhatsApp_Image_20230704_at_123406_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64a3c95d11d5643c3273bf2d",
    "name":
"externallmg_1688455516454_WhatsApp_Image_20230704_at_123406_PM.jpeg",
    "path": "cases/64a2a9fd2923d90f978640ff/
externallmg_1688455516454_WhatsApp_Image_20230704_at_123406_PM.jpeg",
```

```

    "orientation": "landscape"
  }
],
"externalDocuments": [],
"createdAt": "2023-07-03T10:59:09.804Z",
"updatedAt": "2023-07-06T05:53:35.862Z",
"__v": 0,
"addressForMap": "",
"updatedBy": "62550ed0aba01e0af98f2f75",
"reason": "",
"siteVisitDate": "2023-07-04",
"briefDescOfProperty": "Living Room + Kitchen + Bathroom + WC + Passage",
"carpetTotal": "227.46",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "250.21",
"finalCarpetArea": "227.46",
"finalSalableArea": "275.23",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Deed of Release",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 225.00",
"buildingServicesRate": "3000",
"flatRate": "39000",
"landOtherRate": "36000",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"
}

```

Name	Length	Width	Total
Composition :			
Living Room	16'4"	8'7"	140.19
Bathroom	5'2"	3'10"	19.81
WC	3'8"	2'9"	10.08

Passage	3'4"	2'9"	9.17
Kitchen	7'5"	6'6"	48.21
Other Composition :			