

```
{
  "typeOfReport": {
    "label": "APF",
    "value": "APF"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63b26652191f7b344b008cac"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b8f",
    "email": "sbi.04380@sbi.co.in",
    "firstName": "NITIN ",
    "mobileNo": "",
    "workMobileNo": "9969814381",
    "lastName": "SARGAN"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "10000000",
    "discussWithPerson": "NITIN ",
    "expectedFees": 5000,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "VCIPL Mumbai",
    "shortName": "VCIPLM",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
```

```
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63b26652191f7b344b008cac",
  "name": "HLST BKC",
  "branchCode": "",
  "mobileNo": "022-26445021",
  "alternateMobileNo": "",
  "email": "sbi.04380@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "HLST Synergy Building, 1st floor, C – 6, G Block\nBandra Kurla
Complex, Bandra (East),\nMumbai – 400 051."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential_cum_commercial",
  "label": "Residential cum Commercial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62723addafd7d55eddeddfe4",
    "role": "PICKUPPERSON",
    "firstName": "Ramkrishna ",
    "email": "rampatakar1991@gmail.com",
    "lastName": "Patkar",
    "mobileNo": "7045746060",
```

```
    "shortName": "RP",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "62550ed0aba01e0af98f2f75",
    "role": "SITEENGINEER",
    "firstName": "Chandan",
    "email": "chandan@vastukala.org",
    "lastName": "Singh",
    "mobileNo": "8454863607",
    "designation": "",
    "shortName": "CH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60f9147bf3dd69653a591e8c",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Vinita",
    "email": "vinita.surve@vastukala.org",
    "lastName": "Surve",
    "mobileNo": "9820652818",
    "designation": "",
    "shortName": "V",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "60f9147bf3dd69653a591e8c",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Vinita",
    "email": "vinita.surve@vastukala.org",
    "lastName": "Surve",
    "mobileNo": "9820652818",
    "designation": "",
    "shortName": "V",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
```

```
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f9147bf3dd69653a591e8c",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Vinita",
  "email": "vinita.surve@vastukala.org",
  "lastName": "Surve",
  "mobileNo": "9820652818",
  "designation": "",
  "shortName": "V",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.27016335646315",
  "longitude": "72.84782364029151"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.84782364029151,
    19.27016335646315
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
}
```

```
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "0",
  "lumpsumValue": "27000",
  "rateMax": "0",
  "areaType": {
    "Name": "Carpet",
    "Value": "Carpet",
    "name": "Carpet",
    "value": "Carpet"
  }
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft."
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Thu Jul 06 2023 13:58:54 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Mandpeshwar",
    "label": true
  },
  "floorNo": {
```

```
"status": true,
"name": "Floor No",
"key": "floorNo",
"value": "Basement",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
```

```
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "The Castle ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "St Francies School D Assisi School Play Ground",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
```



```
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
}
```

```
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
```

```
"key": "postalCode",
"value": "",
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "Proposed RCC SLab",
    "value": "Proposed_RCC_SLab"
  },
  "flooring": {
    "label": "Proposed Vitrified tiles flooring",
    "value": "Proposed_Vitrified_tiles_flooring"
  },
  "doors": {
    "label": "Proposed Teak wood door frame with flush doors",
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors"
  },
  "windows": {
    "label": "Proposed Powder coated aluminium sliding windows",
    "value": "Proposed_Powder_coated_aluminium_sliding_windows"
  },
  "fittings": {
    "label": "Internal Visit not allowed",
    "value": "Internal_Visit_not_allowed"
  },
  "finishing": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  }
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  }
}
```

```
},
"townplanApprovedByList": {
  "label": "Municipal Corporation of Greater Mumbai (MCGM)",
  "value": "MCGM"
},
"asPerActualAgreement": {
  "north": "Road no. 2",
  "south": "IC Colony road",
  "east": "Shri aurbindo marg",
  "west": "Dora rose building"
},
"asPerDocumentAgreement": {
  "north": "",
  "west": "",
  "south": "",
  "east": ""
}
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Building Under Construction",
    "value": "Building_Under_Construction"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MunicipalWaterSupply"
  },
  "carParking": {
    "label": "Podium Parking",
    "value": "Podium_Parking"
  },
  "constructionWorkStatus": {
    "label": "Under Construction",
    "value": "InProgress"
  }
},
```

```
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2027",
  "fullDate": "1/1/2027"
},
"propertyTypeList": {
  "value": "Residential_cum_commercial",
  "label": "Residential cum Commercial"
},
"planningArea": {
  "value": "Residential_cum_commercial",
  "label": "Residential cum Commercial"
},
"typeOfStructure": {
  "label": "Proposed RCC Slab",
  "value": "Proposed_RCC_Slab"
},
"qualityOfConstruction": {
  "label": "Building Under Construction",
  "value": "UnderConstruction"
},
"walls": {
  "label": "Building Under Construction",
  "value": "Building_Under_Construction"
},
"appearanceOfTheBuilding": {
  "label": "Building Under Construction",
  "value": "UnderConstruction"
},
"maintenanceOfTheBuilding": {
  "label": "Building Under Construction",
  "value": "UnderConstruction"
},
"visibleDamageInBuilding": {
  "label": "Building Under Construction",
  "value": "Building_Under_Construction"
},
"groundStilt": {
  "label": "Ground",
  "value": "ground"
},
"isSiteVisitAllowed": false,
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
```

```
"flatFloorNo": "",
"noOfLiftsInEachWings": "0",
"totalLifeBuilding": "",
"ageOfBuilding": "",
"estimatedAge": "",
"noOfFloors": "13",
"noOfDwellingUnitsInBuilding": "4",
"noOfLifts": "2"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "2",
    "percentage": "5.33",
    "isHideFloor": false,
    "status": true
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```



```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "15.33",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
```

```
"value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": false,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"_id": "64a55c573a0e245f2c02e7fd",
"ownerName": "The Castle ",
"ownerPhoneNo": "9867302774",
"appAddress": "Borivli west ",
"remark": "contact - manoj Joshi ",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/64a55c573a0e245f2c02e7fd/
document_1688558743932_Apf__The_castle__Page_1.pdf",
    "fileName": "document_1688558743932_Apf__The_castle__Page_1.pdf",
    "displayStatus": false,
    "id": "104674",
    "uploadedBy": "62723addafd7d55eddeddfe4",
    "createdAt": "Wed Jul 05 2023 17:36:20 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "002343",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "857897",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Jul 05 2023 17:34:39 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "The Castle ",
    "phone": "9867302774",
    "ownershipShare": "",
    "email": ""
  }
]
```

```
    "id": "269693"
  }
],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64a9548a06d6ec174983a8ab",
    "name": "externalImg_1688818818586_image.jpeg",
    "path": "cases/64a55c573a0e245f2c02e7fd/
externalImg_1688818818586_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64a9548a06d6ec174983a8ac",
    "name": "externalImg_1688818819161_image.jpeg",
    "path": "cases/64a55c573a0e245f2c02e7fd/
externalImg_1688818819161_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64a9548a06d6ec174983a8ad",
    "name": "externalImg_1688818819631_image.jpeg",
    "path": "cases/64a55c573a0e245f2c02e7fd/
externalImg_1688818819631_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64a9548a06d6ec174983a8ae",
    "name": "externalImg_1688818820046_image.jpeg",
    "path": "cases/64a55c573a0e245f2c02e7fd/
externalImg_1688818820046_image.jpeg",
    "orientation": "landscape"
  }
]
```

```

    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64a9548a06d6ec174983a8af",
      "name": "externalImg_1688818820426_image.jpeg",
      "path": "cases/64a55c573a0e245f2c02e7fd/
externalImg_1688818820426_image.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64a9548a06d6ec174983a8b0",
      "name": "externalImg_1688818820789_image.jpeg",
      "path": "cases/64a55c573a0e245f2c02e7fd/
externalImg_1688818820789_image.jpeg",
      "orientation": "landscape"
    }
  ],
  "externalDocuments": [],
  "createdAt": "2023-07-05T12:04:39.058Z",
  "updatedAt": "2023-07-08T12:23:36.193Z",
  "__v": 0,
  "updatedBy": "62550ed0aba01e0af98f2f75",
  "fullAddress": " APF No. Basement Floor, The Castle , St Francies School D Assisi
School Play Ground, Village - Mandpeshwar, State - Maharashtra, India",
  "addressForMap": "",
  "caseReferredBy": "62723addafd7d55eddeddfe4",
  "contactPersonName": "The Castle ",
  "email": "",
  "isExternal": "false",
  "isUrgent": "false",
  "ownershipShare": "",
  "purchaseValueAsPerDocument": "",
  "relationWithOwner": "self",
  "siteVisitContactNo": "9867302774",
  "briefDescOfProperty": "",
  "carpetTotal": "0",
  "finalMeasurementType": "",
  "otherCarpetTotal": "0"
}

```

Name	Length	Width	Total
Composition :			

Other
Composition :
