

```
{
  "typeOfReport": {
    "label": "Proposed Buyer",
    "value": "Proposed_Buyer"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Cost Estimation",
    "value": "Cost_Estimation"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "646aedb6b05e530fb6c29f01"
    },
    "type": "CREDITOFFICER",
    "_id": "646aedb6b05e530fb6c29f03",
    "firstName": " Sanjay ",
    "lastName": "Mane",
    "mobileNo": "",
    "workMobileNo": "9826806511",
    "email": "smane@pnb.co.in"
  },
  "fees": {
    "type": "agreed",
    "propertyValue": "300000",
    "discussWithPerson": " Aditya Gokhre ",
    "expectedFees": 150,
    "quotedAmount": "1000"
  },
  "organization": {
    "_id": "6450f43cba18c8062aad0215",
    "name": "Indore",
    "shortName": "Indore",
    "email": "indore@vastukala.org",
    "address": "106, 1st Floor, Gold Star Tower, ,576, M G Road, Opp T1 Mall,
```

```
Indore-452001, Madhya Pradesh India",
  "city": "Indore"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1812",
  "type": "BANK",
  "name": "Punjab National Bank",
  "displayName": "Punjab National Bank",
  "initial": "PNB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "646aedb6b05e530fb6c29f01",
  "name": "MId Corporate Centre Indore Branch\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "smane@pnb.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "C 21, 2nd floor, Business park Opp Raddison Hotel, Indore ( M P )\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "6437eb9c8989760c1fb67c4c",
  "zoneName": "Indore Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "6421248a695fbc66ee1a7ce3",
    "role": "ADMIN",
    "firstName": "Niti",
    "email": "niti@vastukala.org",
    "lastName": "Kuril",
    "mobileNo": "9926411111",
    "shortName": "NSK",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users/6421248a695fbc66ee1a7ce3/
profilePhoto_1679893769249_WhatsApp_Image_20230324_at_20338_PM_1.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc5f1ace84bf289ba9f3b6",
  "role": "SITEENGINEER+MAKAR+ RATE VERIFIER + CHECKER",
  "firstName": "Aakash ",
  "email": "mouryaaakash83@gmail.com",
  "lastName": "Mourya",
  "mobileNo": "8462826414",
  "designation": "",
  "shortName": "AM",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63fc5f1ace84bf289ba9f3b6/
profilePhoto_1677483802357_Image_1.jpg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60016f965256c07aec8e6dd6",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Akhilesh",
  "email": "akhilesh.yadav@vastukala.org",
  "lastName": "Yadav",
  "mobileNo": "9545753921",
  "designation": "Processing Officer",
  "workWithDocumentMaker": "6009222ca16fab0f2af9b0bf",
  "profilePhoto": "users\\60016f965256c07aec8e6dd6\
\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
  "shortName": "AY"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60016f965256c07aec8e6dd6",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Akhilesh",
  "email": "akhilesh.yadav@vastukala.org",
  "lastName": "Yadav",
  "mobileNo": "9545753921",
  "designation": "Processing Officer",
  "workWithDocumentMaker": "6009222ca16fab0f2af9b0bf",
  "profilePhoto": "users\\60016f965256c07aec8e6dd6\
\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
  "shortName": "AY"
},
}
```

```
"checker": {
  "type": "EMPLOYEE",
  "_id": "60016f965256c07aec8e6dd6",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Akhilesh",
  "email": "akhilesh.yadav@vastukala.org",
  "lastName": "Yadav",
  "mobileNo": "9545753921",
  "designation": "Processing Officer",
  "workWithDocumentMaker": "6009222ca16fab0f2af9b0bf",
  "profilePhoto": "users\\60016f965256c07aec8e6dd6\\
\\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
  "shortName": "AY"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    }
  ],
}
```

```
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "22.733713533659163",
  "longitude": "75.86211327761826"
},
"geo": {
  "type": "Point",
  "coordinates": [
    75.86211327761826,
    22.733713533659163
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
}
```

```
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft."
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Madhya Pradesh",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": false,
    "name": "Floor No",
    "key": "floorNo",
    "value": "",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
```

```
"key": "district",
"value": "",
"label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "385",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
}
```

```
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Sheth Jagannath Ki Chawl",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": " Chitawad Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
```



```
"value": "",
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
```

```
"status": false,
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Indore",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
```

```
},
"flooring": {
  "label": "Vitrified Tile Flooring",
  "value": "VerifiedTileFlooring"
},
"doors": {
  "label": "Teak Wood Door frame with Solid door with safety door",
  "value": "Teak_Wood_Door_frame_with_Solid_door_with_safety_door"
},
"windows": {
  "label": "Alluminum sliding windows with M. S. Grills",
  "value": "Alluminum_sliding_windows_with_M._S._Grills"
},
"fittings": {
  "label": "Open-Conduit plumbing with Casing Capping Electrical wiring ",
  "value": "Open-Conduit_plumbing_with_Casing_Capping_Electrical_wiring_"
},
"finishing": {
  "label": "Normal",
  "value": "Normal"
}
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Medium",
    "value": "Medium"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Vacant",
    "value": "Vacant"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonry",
    "value": "6\"_Thk._Brick_Masonry"
  },
  "waterTank": {
    "label": "Borewell",
    "value": "Borewell"
  },
}
```

```
"pavementLaid": {
  "label": "No",
  "value": "No"
},
"carParking": {
  "label": "Open Car Parking",
  "value": "Open_Car_Parking"
},
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2003",
  "fullDate": "1/1/2003"
},
"propertyTypeList": {
  "value": "Residential",
  "label": "Residential"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed",
  "value": "R.C.C."
},
"qualityOfConstruction": {
  "label": "Good",
  "value": "Good"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"maintenanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
```

```
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": "",
"isSiteVisitAllowed": true,
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "0",
"flatFloorNo": "",
"noOfLifts": "0",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "0",
"totalLifeBuilding": "60",
"ageOfBuilding": "20",
"estimatedAge": "40"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
```

```
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,

```

```
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
```

```
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": false,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"_id": "64abddbc06d6ec174986df82",
"ownerName": "Deepak Bansal ",
"ownerPhoneNo": "7389984185",
"appAddress": "305, Atisha Appartment, \nChitawad road , Navlakha , Indore ",
"remark": "branch is Sneh nagar branch not MCC \npls add Sneh nagar branch in
PNB \n",
"documents": [
  {
    "documentType": {
      "value": "60ae1245aa6d152c1801b2e3",
      "label": "Sale Deed"
    },
    "inputs": {
      "documentDate": "10/07/2023",
      "remark": "Estimate of Interior",
      "amount": "300000",
      "from": {
        "value": "Owner",
        "label": "Owner"
      },
      "Owner": "Bhaawani shankar ",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Deepak bansal",
      "number": {
        "value": "Property_No",
        "label": "Property No"
      }
    }
  }
]
```

```
    },
    "Property_No": "305"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1688990138949_Sale_deed__7.pdf",
  "path": "cases/64abddbc06d6ec174986df82/
document_1688990138949_Sale_deed__7.pdf",
  "id": "146648",
  "uploadedBy": "63fc5f1ace84bf289ba9f3b6",
  "createdAt": "Mon Jul 10 2023 17:26:46 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "002417",
"createdBy": "6421248a695fbc66ee1a7ce3",
"caseHistory": [
  {
    "id": "504511",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Jul 10 2023 16:00:20 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Deepak Bansal ",
    "phone": "7389984185",
    "ownershipShare": "",
    "email": "",
    "id": "851031"
  }
],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64abf85dd9a15943959ccc92",
    "name": "externallmg_1688991835130_image.jpeg",
    "path": "cases/64abddbc06d6ec174986df82/
externallmg_1688991835130_image.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64abf85dd9a15943959ccc93",
  "name": "externallmg_1688991835142_image.jpeg",
  "path": "cases/64abddbc06d6ec174986df82/
externallmg_1688991835142_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64abf85dd9a15943959ccc94",
  "name": "externallmg_1688991835189_image.jpeg",
  "path": "cases/64abddbc06d6ec174986df82/
externallmg_1688991835189_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64abf85dd9a15943959ccc95",
  "name": "externallmg_1688991835197_image.jpeg",
  "path": "cases/64abddbc06d6ec174986df82/
externallmg_1688991835197_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64abf85dd9a15943959ccc96",
  "name": "externallmg_1688991835211_image.jpeg",
  "path": "cases/64abddbc06d6ec174986df82/
externallmg_1688991835211_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64abf85dd9a15943959ccc97",
  "name": "externallmg_1688991835241_image.jpeg",
  "path": "cases/64abddbc06d6ec174986df82/
externallmg_1688991835241_image.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64abf85dd9a15943959ccc98",
      "name": "externalImg_1688991835267_image.jpeg",
      "path": "cases/64abddbc06d6ec174986df82/
externalImg_1688991835267_image.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64abf85dd9a15943959ccc99",
      "name": "externalImg_1688991835278_image.jpeg",
      "path": "cases/64abddbc06d6ec174986df82/
externalImg_1688991835278_image.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64abf85dd9a15943959ccc9a",
      "name": "externalImg_1688991835336_image.jpeg",
      "path": "cases/64abddbc06d6ec174986df82/
externalImg_1688991835336_image.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64abf85dd9a15943959ccc9b",
      "name": "externalImg_1688991835347_image.jpeg",
      "path": "cases/64abddbc06d6ec174986df82/
externalImg_1688991835347_image.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64abf85dd9a15943959ccc9c",
      "name": "externalImg_1688991835355_image.jpeg",
      "path": "cases/64abddbc06d6ec174986df82/
externalImg_1688991835355_image.jpeg",
      "orientation": "portrait"
    },
  ],
```

```

{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64abf85dd9a15943959ccc9d",
  "name": "externalImg_1688991835361_image.jpeg",
  "path": "cases/64abddbc06d6ec174986df82/
externalImg_1688991835361_image.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"createdAt": "2023-07-10T10:30:20.466Z",
"updatedAt": "2023-07-10T12:29:59.798Z",
"__v": 0,
"invoiceId": "64abddbc06d6ec174986df89",
"addressForMap": "",
"caseReferredBy": "6421248a695fbc66ee1a7ce3",
"contactPersonName": "Deepak Bansal ",
"email": "",
"fullAddress": "Residential Proposed Buyer No. Plot No. 385, Sheth Jagannath Ki
Chawl, Chitawad Road, Indore, State - Madhya Pradesh, India",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "7389984185",
"updatedBy": "63fc5f1ace84bf289ba9f3b6",
"briefDescOfProperty": "",
"carpetTotal": "0",
"finalMeasurementType": "",
"otherCarpetTotal": "0"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			