

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7fb"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230c4a",
    "firstName": "Ashok Wagh",
    "email": "0_default_ashok.wagh@sbi.co.in",
    "mobileNo": "0_DEFAULT_022-27759214",
    "workMobileNo": "0_DEFAULT_91-8879150156"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "4270000",
    "discussWithPerson": "Ashok Wagh",
    "expectedFees": 2135,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072.",
    "city": "Mumbai"
  }
}
```

```
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7fb",
  "branchCode": "000068",
  "type": "BRANCH",
  "name": "RBO Sanpada Branch",
  "email": "sbi.05141@sbi.co.in",
  "mobileNo": "022-27759215",
  "alternateMobileNo": "",
  "address": "Regional Business Office (II), E/202, 2nd Floor, Sanpada Rly. Station  
Complex, Navi Mumbai - 400 705, State - Maharashtra, Country - India.\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - RBO SANPADA",
  "fax": "022-27752206",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7189d2ffdf65bcd65882b",
    "role": "PICKUPPERSON",
    "firstName": "Ravindra",
    "email": "ravindrakasare186@gmail.com",
    "lastName": "Kasare",
    "mobileNo": "9167204055",
    "shortName": "RBK",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users\\60b7189d2ffdf65bcd65882b\
\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "Rajesh",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "Ghadi",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "636a29b64d42487767af43ea",
  "role": "NASHIK (LEAD + VISIT + RATE)",
  "firstName": "Sachin",
  "email": "sachinraundal9021@gmail.com",
  "lastName": "Raundal",
  "mobileNo": "9021337843",
  "designation": "Site Engg",
  "shortName": "Sachin",
  "workWithDocumentMaker": "62724142afd7d55eddede405",
  "profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
},
"maker": "",
"checker": "",
"valuers": []
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "18.977515849301952",
  "longitude": "73.10224497208796"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.10224497208796,
```

```
18.977515849301952
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-07-17",
      "remark": ""
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": "KITCHEN CONVERT IN BED AND TEREK CONVART IN KITHEN (1BHJ
CONVERTED IN 2BHK WC BATH",
  "rateMin": "6000",
  "lumpsumValue": "4200000.00",
  "rateMax": "6500",
  "areaType": {
    "Name": "Saleable",
    "Value": "Saleable",
    "name": "Saleable",
    "value": "Saleable"
  }
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft."
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  }
}
```

```
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "karanjade",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi MUmbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
```

```
"key": "taluka",
"value": "",
"label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "12",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Meghana Shivam CHSL",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "4",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
}
```

```
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
```

```
"value": "",
"label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "202",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
```



```
"status": false,
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vinyl Flooring / Carpet",
    "value": "VinylFlooringCarpet"
  },
  "doors": {
    "label": "Teak Wood Door frame with Solid door with safety door",
    "value": "Teak_Wood_Door_frame_with_Solid_door_with_safety_door"
  },
  "windows": {
    "label": "Powder coated Aluminum sliding windows",
    "value": "Powder_coated_Aluminum_sliding_windows"
  },
  "fittings": {
    "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring",
    "value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring"
  },
  "finishing": {
    "label": "Cement Plastering + POP Finish",
    "value": "Cement_Plastering_+_POP_Finish"
  }
}
```

```
}
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "CIDCO",
    "value": "CIDCO"
  },
  "asPerActualAgreement": {
    "north": "Open ",
    "south": "open",
    "east": "open",
    "west": "Road"
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  }
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Owner Occupied",
    "value": "Owner_Occupied"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
```

```
"value": "6\"_Thk._Brick_Masonry"
},
"waterTank": {
  "label": "CIDCO",
  "value": "CIDCO"
},
"pavementLaid": {
  "label": "Yes",
  "value": "Yes"
},
"carParking": {
  "label": "Open Parking",
  "value": "Open_Parking"
},
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2016",
  "fullDate": "1/1/2016"
},
"propertyTypeList": {
  "value": "Residential",
  "label": "Residential"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"qualityOfConstruction": {
  "label": "Good",
  "value": "Good"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Good",
```

```
"value": "Good"
},
"maintenanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Part Ground + Part Stilt",
  "value": "Part_Ground_and_Part_Stilt"
},
"isSiteVisitAllowed": true,
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"flatFloorNo": "",
"noOfLiftsInEachWings": "0",
"totalLifeBuilding": "60",
"ageOfBuilding": "7",
"estimatedAge": "53",
"noOfBasement": "",
"noOfFloors": "07",
"noOfDwellingUnitsInBuilding": "06",
"noOfLifts": "01"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
"label": "RCC Plinth",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
}
```

```
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
```

```
"max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
```



```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
"title": "Electricity deposits / electrical fittings, etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
"title": "Extra collapsible gates / grill works etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
"title": "Potential value, if any",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
```

```
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": false,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"_id": "64acf0aed9a15943959dc10d",
"ownerName": "Chandrashekhar Lalsingh Kashyap",
"ownerPhoneNo": "7506404281",
"appAddress": "flat no. 202 2th floor B wi g plot no 12 . sector no 4 karanjade ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/64acf0aed9a15943959dc10d/
document_1689055298681_Chandrashekhar__kashingh__sbi_Rbo_sanpada.pdf",
    "fileName":
"document_1689055298681_Chandrashekhar__kashingh__sbi_Rbo_sanpada.pdf",
    "displayStatus": false,
    "id": "491700",
    "uploadedBy": "60b7189d2ffdf65bcd65882b",
```

```
    "createdAt": "Tue Jul 11 2023 11:33:05 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "002445",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "962484",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Jul 11 2023 11:33:26 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Chandrashekhar Lalsingh Kashyap",
    "phone": "7506404281",
    "ownershipShare": "",
    "email": "",
    "id": "186574"
  }
],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64b4a967d8e04f08a37b175e",
    "name": "externalImg_1689561443198_1689561212845_image_0.jpeg",
    "path": "cases/64acf0aed9a15943959dc10d/externalImg_1689561443198_1689561212845_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64b4a967d8e04f08a37b175f",
    "name": "externalImg_1689561443244_1689561212845_image_1.jpeg",
    "path": "cases/64acf0aed9a15943959dc10d/externalImg_1689561443244_1689561212845_image_1.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b4a967d8e04f08a37b1760",
  "name": "externallmg_1689561443270_1689561212845_image_2.jpeg",
  "path": "cases/64acf0aed9a15943959dc10d/
externallmg_1689561443270_1689561212845_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b4a967d8e04f08a37b1761",
  "name": "externallmg_1689561443295_1689561212845_image_3.jpeg",
  "path": "cases/64acf0aed9a15943959dc10d/
externallmg_1689561443295_1689561212845_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b4a967d8e04f08a37b1762",
  "name": "externallmg_1689561444300_1689561212845_image_4.jpeg",
  "path": "cases/64acf0aed9a15943959dc10d/
externallmg_1689561444300_1689561212845_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b4a967d8e04f08a37b1763",
  "name": "externallmg_1689561445276_1689561212845_image_5.jpeg",
  "path": "cases/64acf0aed9a15943959dc10d/
externallmg_1689561445276_1689561212845_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b4a967d8e04f08a37b1764",
  "name": "externallmg_1689561445290_1689561212845_image_6.jpeg",
  "path": "cases/64acf0aed9a15943959dc10d/
externallmg_1689561445290_1689561212845_image_6.jpeg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b4a967d8e04f08a37b1765",
  "name": "externallmg_1689561445309_1689561212845_image_7.jpeg",
  "path": "cases/64acf0aed9a15943959dc10d/
externallmg_1689561445309_1689561212845_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b4a967d8e04f08a37b1766",
  "name": "externallmg_1689561445340_1689561212845_image_8.jpeg",
  "path": "cases/64acf0aed9a15943959dc10d/
externallmg_1689561445340_1689561212845_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b4a967d8e04f08a37b1767",
  "name": "externallmg_1689561445360_1689561212845_image_9.jpeg",
  "path": "cases/64acf0aed9a15943959dc10d/
externallmg_1689561445360_1689561212845_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b4a967d8e04f08a37b1768",
  "name": "externallmg_1689561445390_1689561212845_image_10.jpeg",
  "path": "cases/64acf0aed9a15943959dc10d/
externallmg_1689561445390_1689561212845_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b4a967d8e04f08a37b1769",
  "name": "externallmg_1689561445415_1689561212845_image_11.jpeg",
  "path": "cases/64acf0aed9a15943959dc10d/
externallmg_1689561445415_1689561212845_image_11.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b4a967d8e04f08a37b176a",
  "name": "externallmg_1689561445565_1689561212845_image_12.jpeg",
  "path": "cases/64acf0aed9a15943959dc10d/
externallmg_1689561445565_1689561212845_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b4a967d8e04f08a37b176b",
  "name": "externallmg_1689561445680_1689561212845_image_13.jpeg",
  "path": "cases/64acf0aed9a15943959dc10d/
externallmg_1689561445680_1689561212845_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b4a967d8e04f08a37b176c",
  "name": "externallmg_1689561445705_1689561212845_image_14.jpeg",
  "path": "cases/64acf0aed9a15943959dc10d/
externallmg_1689561445705_1689561212845_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b4a967d8e04f08a37b176d",
  "name": "externallmg_1689561445710_1689561212845_image_15.jpeg",
  "path": "cases/64acf0aed9a15943959dc10d/
externallmg_1689561445710_1689561212845_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64b4a967d8e04f08a37b176e",
  "name": "externallmg_1689561406244_1689561156062_image_0.jpeg",
  "path": "cases/64acf0aed9a15943959dc10d/
externallmg_1689561406244_1689561156062_image_0.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64b4a967d8e04f08a37b176f",
    "name": "externallmg_1689561406550_1689561156062_image_1.jpeg",
    "path": "cases/64acf0aed9a15943959dc10d/
externallmg_1689561406550_1689561156062_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64b4a967d8e04f08a37b1770",
    "name": "externallmg_1689561407225_1689561156062_image_2.jpeg",
    "path": "cases/64acf0aed9a15943959dc10d/
externallmg_1689561407225_1689561156062_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64b4a967d8e04f08a37b1771",
    "name": "externallmg_1689561407370_1689561181618_image_0.jpeg",
    "path": "cases/64acf0aed9a15943959dc10d/
externallmg_1689561407370_1689561181618_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64b4a967d8e04f08a37b1772",
    "name": "externallmg_1689561407391_1689561181618_image_1.jpeg",
    "path": "cases/64acf0aed9a15943959dc10d/
externallmg_1689561407391_1689561181618_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64b4a967d8e04f08a37b1773",
    "name": "externallmg_1689561407410_1689561181618_image_2.jpeg",
    "path": "cases/64acf0aed9a15943959dc10d/
externallmg_1689561407410_1689561181618_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
"status": false,
  "_id": "64b4a967d8e04f08a37b1774",
  "name": "externallmg_1689561407430_1689561181618_image_3.jpeg",
  "path": "cases/64acf0aed9a15943959dc10d/
externallmg_1689561407430_1689561181618_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64b4a967d8e04f08a37b1775",
  "name": "externallmg_1689561408050_1689561181618_image_4.jpeg",
  "path": "cases/64acf0aed9a15943959dc10d/
externallmg_1689561408050_1689561181618_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64b4a967d8e04f08a37b1776",
  "name": "externallmg_1689561408075_1689561181618_image_5.jpeg",
  "path": "cases/64acf0aed9a15943959dc10d/
externallmg_1689561408075_1689561181618_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64b4a967d8e04f08a37b1777",
  "name": "externallmg_1689561408090_1689561181618_image_6.jpeg",
  "path": "cases/64acf0aed9a15943959dc10d/
externallmg_1689561408090_1689561181618_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64b4a967d8e04f08a37b1778",
  "name": "externallmg_1689561408115_1689561181618_image_7.jpeg",
  "path": "cases/64acf0aed9a15943959dc10d/
externallmg_1689561408115_1689561181618_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
```



```
    "_id": "64b4a967d8e04f08a37b1779",
    "name": "externalImg_1689561408135_1689561181618_image_8.jpeg",
    "path": "cases/64acf0aed9a15943959dc10d/
externalImg_1689561408135_1689561181618_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64b4a967d8e04f08a37b177a",
    "name": "externalImg_1689561408150_1689561181618_image_9.jpeg",
    "path": "cases/64acf0aed9a15943959dc10d/
externalImg_1689561408150_1689561181618_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64b4a967d8e04f08a37b177b",
    "name": "externalImg_1689561408180_1689561181618_image_10.jpeg",
    "path": "cases/64acf0aed9a15943959dc10d/
externalImg_1689561408180_1689561181618_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64b4a967d8e04f08a37b177c",
    "name": "externalImg_1689561408215_1689561181618_image_11.jpeg",
    "path": "cases/64acf0aed9a15943959dc10d/
externalImg_1689561408215_1689561181618_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64b4a967d8e04f08a37b177d",
    "name": "externalImg_1689561408240_1689561181618_image_12.jpeg",
    "path": "cases/64acf0aed9a15943959dc10d/
externalImg_1689561408240_1689561181618_image_12.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-07-11T06:03:26.102Z",
"updatedAt": "2023-07-17T02:43:14.485Z",
```

"\_\_v": 0,  
"invoiceId": "64acf0aed9a15943959dc119",  
"fullAddress": " Flat No. 202, 2nd Floor, Meghana Shivam CHSL, Plot No. 12, Sector 4,  
Village - karanjade, Navi MUMbai, State - Maharashtra, India",  
"updatedBy": "60f9343b45132d6a6bdd96e8",  
"addressForMap": "",  
"caseReferredBy": "",  
"contactPersonName": "Chandrashekhar Lalsingh Kashyap",  
"email": "",  
"isExternal": "false",  
"isUrgent": "false",  
"ownershipShare": "",  
"purchaseValueAsPerDocument": "",  
"relationWithOwner": "self",  
"siteVisitContactNo": "7506404281",  
"briefDescOfProperty": "",  
"carpetTotal": "0",  
"finalMeasurementType": "",  
"otherCarpetTotal": "0"

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
-------------	---------------	--------------	--------------

---

Composition :

---

Other

Composition :

---