

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b951"
    },
    "type": "CREDITOFFICER",
    "_id": "635f732fe363ef22db2f1c80",
    "firstName": "Ravindra Sir",
    "lastName": "sir",
    "mobileNo": "",
    "email": "me1@me.com",
    "workMobileNo": "7738642220"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6600000",
    "discussWithPerson": "Ravindra Sir",
    "expectedFees": 3300,
    "quotedAmount": "2950"
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
```

```
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b951",
  "branchCode": "000167",
  "type": "BRANCH",
  "name": "RACPC Belapur ",
  "email": "sbi.14677@sbi.co.in",
  "mobileNo": "022-27524090",
  "alternateMobileNo": "",
  "address": "Estate Department Corporate Centre, 4th Floor, CIDCO Tower No. 4,
Railway Station Building, C.B.D. Belapur, Navi Mumbai - 400 614, State - Maharashtra,
Country - India.",
  "ledgerName": "STATE BANK OF INDIA - CBD Estate Department",
  "fax": "022 2757 7002",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7189d2ffdf65bcd65882b",
    "role": "PICKUPPERSON",
    "firstName": "Ravindra",
    "email": "ravindrakasare186@gmail.com",
```

```
"lastName": "Kasare",
"mobileNo": "9167204055",
"shortName": "RBK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60b7189d2ffdf65bcd65882b\
\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "60f9343b45132d6a6bdd96e8",
"role": "SITEENGINEER",
"firstName": "Rajesh",
"email": "rajeshb.ghadi@gmail.com",
"lastName": "Ghadi",
"mobileNo": "8652092666",
"designation": "",
"shortName": "RHG",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"maker": {
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
```

```
},
"checker": "",
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "CAT-I-A-1930",
        "label": "Chartered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "60af7d4d2ffdf65bcd658643",
    "PANNo": "AESPC7493M",
    "role": "VALUER",
    "firstName": "Vidhi",
    "fatherName": "Manoj",
    "email": "vids_singh@yahoo.com",
    "lastName": "Chalikwar",
    "mobileNo": "9820549087",
    "designation": "Valuer",
    "registrationNo": [
      {
        "title": {
          "value": "Chartered_Valuer",
          "label": "Chartered Valuer"
        },
        "_id": "60eeb39af3dd69653a58168d",
        "number": "CAT-I-A-1930"
      }
    ],
    "shortName": "VC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af7d4d2ffdf65bcd658643\\
profilePhoto_1622113613002_Vidhi C.jpeg"
  }
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.102305668331226",
  "longitude": "73.00484269362327"
},
"geo": {
```

```
"type": "Point",
"coordinates": [
  73.00484269362327,
  19.102305668331226
]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-07-18T09:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-07-18T09:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-07-18T09:00:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft."
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
```

```
"key": "country",
"value": "Country - India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Koparkhairane",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
```

```
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "41",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Kaypee Heritage Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "07",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
```

```
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
```



```
"status": false,
"name": "Block No",
"key": "blockNo",
"value": "",
"label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "106",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
```

```
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 709",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills",
    "label": "Powder coated Aluminum sliding windows with M. S. Grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
}
```

```
"finishing": {
  "value": "Cement_Plastering_+_POP_Finish",
  "label": "Cement Plastering + POP Finish"
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "NMMC",
    "label": "Navi Mumbai Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Sector 6 Koparkhairane Road",
    "west": "D Mart Galli",
    "south": "Tanwar Villa CHSL",
    "east": "Plot No. 40"
  },
  "asPerDocumentAgreement": {
    "north": "Plot No. 42",
    "west": "Internal Road",
    "south": "Internal Road",
    "east": "Plot No. 40"
  },
  "extraDetailOfProperty": "Details is not available"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
```

```
"value": "Residential_Purpose",
"label": "Residential Purpose"
},
"propertyOccupiedByList": {
"value": "Owner_Occupied",
"label": "Owner Occupied"
},
"monthlyRent": "25,000",
"assessmentNo": "Details is not available",
"taxPaidHolderName": "Details is not available",
"taxAmount": "Details is not available",
"electricityServiceConnectionNo": "Details is not available",
"meterCardHolderName": "Details is not available",
"undividedAreaOfLandAsPerSaleDeed": "Details is not available",
"floorSpaceIndex": "As per NMMC norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
"marketabilityList": {
"value": "Good",
"label": "Good"
}
},
"anyFavouringForExtraPotentialValue": "Located in developed area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
"roof": {
"value": "rcc_Slab",
"label": "R. C. C. Slab"
}
},
"partitions": {
"value": "6\"_Thk._Brick_Masonry",
"label": "6\" Thk. Brick Masonery"
}
},
"waterTank": {
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
}
},
"pavementLaid": {
"value": "Yes",
"label": "Yes"
}
},
"carParking": "Open Car Parking",
"constructionWorkStatus": {
"value": "Completed",
```

```
"label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "1999",
  "fullDate": "1/1/1999"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
```

```
"label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "36",
"ageOfBuilding": "24",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "3",
```

```
"flatFloorNo": "1",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "685.20",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/64b655a849e7304e4a7cf4a9/
routeMap_1689838882272_Image.png",
    "routeLat": "19.101917",
    "routeLng": "73.004889",
    "stationName": "Kopar Khairane",
    "routeDistance": "1.4 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "zro6ln",
      "name": "zro6ln",
      "image": "cases/64b655a849e7304e4a7cf4a9/
routeMap_1689838770863_Image.png"
    }
  ]
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
```

```
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```



```
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0.00",
  "selectedBuildUpValue": "685.20",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "64b8af9638df6b2b30c5249d",
      "name": "externallmg_r_1689825173046_00308____20230719Wed_120508PM____
xrrdrrxz2223murism_____hnbm_lmjn____org.jpg",
      "path": "cases/64b655a849e7304e4a7cf4a9/externallmg_r_1689825173046_0030
8____20230719Wed_120508PM____xrrdrrxz2223murism_____hnbm_lmjn____org.jpg"
    }
  ]
}
```

```
,
  "orientation": "landscape"
}
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "64b8af9638df6b2b30c52493",
    "name": "Living Room",
    "path": "cases/64b655a849e7304e4a7cf4a9/externallmg_r_1689825172993_0029
7___20230719Wed_114817AM___xrrdrrxz2223murism_____hnbm_lmjn___org.jpg"
  },
  {
    "status": false,
    "_id": "64b8af9638df6b2b30c52495",
    "name": "Living Room",
    "path": "cases/64b655a849e7304e4a7cf4a9/externallmg_r_1689825173009_0030
0___20230719Wed_114824AM___xrrdrrxz2223murism_____hnbm_lmjn___org.jpg"
  },
  {
    "status": false,
    "_id": "64b8af9638df6b2b30c52499",
    "name": "Living Room",
    "path": "cases/64b655a849e7304e4a7cf4a9/externallmg_r_1689825173027_0030
4___20230719Wed_114901AM___xrrdrrxz2223murism_____hnbm_lmjn___org.jpg"
  },
  {
    "status": false,
    "_id": "64b8af9638df6b2b30c52497",
    "name": "Living Room",
    "path": "cases/64b655a849e7304e4a7cf4a9/externallmg_r_1689825173017_0030
2___20230719Wed_114847AM___xrrdrrxz2223murism_____hnbm_lmjn___org.jpg"
  },
  {
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64b8af9638df6b2b30c52497",
    "name": "Living Room",
    "path": "cases/64b655a849e7304e4a7cf4a9/externallmg_r_1689825173017_0030
2___20230719Wed_114847AM___xrrdrrxz2223murism_____hnbm_lmjn___org.jpg"
  },
  {
    "orientation": "portrait"
  },
  {

```

```
    "status": false,
    "_id": "64b8af9638df6b2b30c5249b",
    "name": "Living Room",
    "path": "cases/64b655a849e7304e4a7cf4a9/externallmg_r_1689825173036_0030
6___20230719Wed_120314PM___xrrddrrxz2223murism_____hnbm_lmjn___org.jpg
",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64b8af9638df6b2b30c52492",
    "name": "Living Room",
    "path": "cases/64b655a849e7304e4a7cf4a9/externallmg_r_1689825172984_0029
6___20230719Wed_114017AM___xrrddrrxz2223murism_____hnbm_lmjn___org.jpg
",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64b8af9638df6b2b30c5249d",
    "name": "Living Room",
    "path": "cases/64b655a849e7304e4a7cf4a9/externallmg_r_1689825173046_0030
8___20230719Wed_120508PM___xrrddrrxz2223murism_____hnbm_lmjn___org.jpg
",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "64b8af9638df6b2b30c5249e",
    "name": "Living Room",
    "path": "cases/64b655a849e7304e4a7cf4a9/externallmg_r_1689825173053_0030
9___20230719Wed_120510PM___xrrddrrxz2223murism_____hnbm_lmjn___org.jpg
",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "64b8af9638df6b2b30c5249f",
    "name": "Living Room",
    "path": "cases/64b655a849e7304e4a7cf4a9/externallmg_r_1689825173058_0031
0___20230719Wed_120517PM___xrrddrrxz2223murism_____hnbm_lmjn___org.jpg
",
    "orientation": "portrait"
  }
]
},
```

```
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
```

```
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "571.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"_id": "64b655a849e7304e4a7cf4a9",
"ownerName": "Mr. Arvind Pralhad Gangane",
"ownerPhoneNo": "9594366694",
"appAddress": "flat no. 106.1 st floor kaypee Heritage vo. op hsg soc Ltd plot no 41
sector no 07 koparkhairne ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    }
  },

```

```
"inputs": {
  "documentDate": "17/11/2018",
  "from": {
    "value": "The_Assignor",
    "label": "The Assignor"
  },
  "The_Assignor": "Mr. Umesh Shetty ",
  "to": {
    "value": "The_Assignee",
    "label": "The Assignee"
  },
  "The_Assignee": "Mr. Arvind Pralhad Gangane"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1689838131384_gangane.pdf",
"path": "cases/64b655a849e7304e4a7cf4a9/
document_1689838131384_gangane.pdf",
"id": "121611",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Thu Jul 20 2023 12:58:51 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "30/09/1999",
    "nameOfApprovingAuthority": {
      "value": "Navi_Mumbai_Municipal_Corporation.",
      "label": "Navi Mumbai Municipal Corporation."
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "NMMC / NRV / OC / 3426"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/64b655a849e7304e4a7cf4a9/
document_1689838247156_1052107.pdf",
  "id": "463391",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Thu Jul 20 2023 13:00:47 GMT+0530 (India Standard Time)"
}
```



```
}
],
"caseNumber": "002644",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "152589",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Jul 18 2023 14:34:40 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Arvind Pralhad Gangane",
    "phone": "9594366694",
    "email": "",
    "ownershipShare": "",
    "id": "558797"
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "650294",
    "name": "Living Room",
    "length": "10.25",
    "length1": "10",
    "length2": "3",
    "width": "18.92",
    "width1": "18",
    "width2": "11",
    "totalArea": "193.90",
    "images": [],
    "extraAreas": [],
    "finalArea": "193.90"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  },
]
```

```
"id": "1",
"name": "Kitchen",
"length": "10.75",
"length1": "10",
"length2": "9",
"width": "6.83",
"width1": "6",
"width2": "10",
"totalArea": "73.46",
"images": [],
"extraAreas": [],
"finalArea": "73.46"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "10.08",
  "length1": "10",
  "length2": "1",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "30.25",
  "images": [],
  "extraAreas": [],
  "finalArea": "30.25"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "11.08",
  "length1": "11",
  "length2": "1",
  "width": "9.50",
  "width1": "9",
  "width2": "6",
  "totalArea": "105.29",
  "images": [],
```

```
"extraAreas": [],
"finalArea": "105.29"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bedroom",
  "length": "9.50",
  "length1": "9",
  "length2": "6",
  "width": "11.92",
  "width1": "11",
  "width2": "11",
  "totalArea": "113.21",
  "images": [],
  "extraAreas": [],
  "finalArea": "113.21"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "7.00",
  "length1": "7",
  "length2": "00",
  "width": "4.00",
  "width1": "4",
  "width2": "00",
  "totalArea": "28.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "28.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
```

```
"length": "3.25",
"length1": "3",
"length2": "3",
"width": "6.42",
"width1": "6",
"width2": "5",
"totalArea": "20.85",
"images": [],
"extraAreas": [],
"finalArea": "20.85"
}
],
"otherComposition": [
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "value": "Terrace",
    "label": "Terrace"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length1": "7",
  "length2": "00",
  "length": "7.00",
  "width1": "12",
  "width2": "00",
  "width": "12.00",
  "totalArea": "84.00",
  "percentageBeforeTotal": "84.00",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "84"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
```

```
    "value": "Terrace",
    "label": "Terrace"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length1": "3",
  "length2": "1",
  "length": "3.08",
  "width1": "10",
  "width2": "00",
  "width": "10.00",
  "totalArea": "30.83",
  "percentageBeforeTotal": "30.83",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "30.83"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "value": "Terrace",
    "label": "Terrace"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length1": "6",
  "length2": "1",
  "length": "6.08",
  "width1": "10",
  "width2": "00",
  "width": "10.00",
  "totalArea": "60.83",
  "percentageBeforeTotal": "60.83",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
```

```
"finalArea": "60.83"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "763539",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "571",
  "squareMeterArea": "53.05",
  "docFinalBuiltUp": "685.2",
  "docFinalBuiltUpSquareMeter": "63.66",
  "docBuiltupPercentage": "20",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [],
"externalImages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b8af9638df6b2b30c52490",
  "name": "externalImg_r_1689825172976_00295___20230719Wed_114016AM___x
rrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "path": "cases/64b655a849e7304e4a7cf4a9/externalImg_r_1689825172976_00295
___20230719Wed_114016AM___xrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b8af9638df6b2b30c52491",
  "name": "externalImg_r_1689825173000_00298___20230719Wed_114819AM___x
rrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "path": "cases/64b655a849e7304e4a7cf4a9/externalImg_r_1689825173000_00298
```

```
____20230719Wed_114819AM____xrddrrxz2223murism____hnbm_lmjn____org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b8af9638df6b2b30c52492",
  "name": "externallmg_r_1689825172984_00296____20230719Wed_114017AM____x
rrddrrxz2223murism____hnbm_lmjn____org.jpg",
  "path": "cases/64b655a849e7304e4a7cf4a9/externallmg_r_1689825172984_00296
____20230719Wed_114017AM____xrddrrxz2223murism____hnbm_lmjn____org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b8af9638df6b2b30c52493",
  "name": "externallmg_r_1689825172993_00297____20230719Wed_114817AM____x
rrddrrxz2223murism____hnbm_lmjn____org.jpg",
  "path": "cases/64b655a849e7304e4a7cf4a9/externallmg_r_1689825172993_00297
____20230719Wed_114817AM____xrddrrxz2223murism____hnbm_lmjn____org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b8af9638df6b2b30c52494",
  "name": "externallmg_r_1689825173005_00299____20230719Wed_114823AM____x
rrddrrxz2223murism____hnbm_lmjn____org.jpg",
  "path": "cases/64b655a849e7304e4a7cf4a9/externallmg_r_1689825173005_00299
____20230719Wed_114823AM____xrddrrxz2223murism____hnbm_lmjn____org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b8af9638df6b2b30c52495",
  "name": "externallmg_r_1689825173009_00300____20230719Wed_114824AM____x
rrddrrxz2223murism____hnbm_lmjn____org.jpg",
  "path": "cases/64b655a849e7304e4a7cf4a9/externallmg_r_1689825173009_00300
____20230719Wed_114824AM____xrddrrxz2223murism____hnbm_lmjn____org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
  "_id": "64b8af9638df6b2b30c52496",
  "name": "externalimg_r_1689825173013_00301___20230719Wed_114837AM___x
rrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "path": "cases/64b655a849e7304e4a7cf4a9/externalimg_r_1689825173013_00301
___20230719Wed_114837AM___xrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b8af9638df6b2b30c52497",
  "name": "externalimg_r_1689825173017_00302___20230719Wed_114847AM___x
rrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "path": "cases/64b655a849e7304e4a7cf4a9/externalimg_r_1689825173017_00302
___20230719Wed_114847AM___xrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b8af9638df6b2b30c52498",
  "name": "externalimg_r_1689825173022_00303___20230719Wed_114849AM___x
rrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "path": "cases/64b655a849e7304e4a7cf4a9/externalimg_r_1689825173022_00303
___20230719Wed_114849AM___xrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b8af9638df6b2b30c52499",
  "name": "externalimg_r_1689825173027_00304___20230719Wed_114901AM___x
rrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "path": "cases/64b655a849e7304e4a7cf4a9/externalimg_r_1689825173027_00304
___20230719Wed_114901AM___xrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b8af9638df6b2b30c5249a",
  "name": "externalimg_r_1689825173032_00305___20230719Wed_114903AM___x
rrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "path": "cases/64b655a849e7304e4a7cf4a9/externalimg_r_1689825173032_00305
___20230719Wed_114903AM___xrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
}
```



```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b8af9638df6b2b30c5249b",
  "name": "externallmg_r_1689825173036_00306___20230719Wed_120314PM___x
rrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "path": "cases/64b655a849e7304e4a7cf4a9/externallmg_r_1689825173036_00306
___20230719Wed_120314PM___xrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b8af9638df6b2b30c5249c",
  "name": "externallmg_r_1689825173040_00307___20230719Wed_120459PM___x
rrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "path": "cases/64b655a849e7304e4a7cf4a9/externallmg_r_1689825173040_00307
___20230719Wed_120459PM___xrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b8af9638df6b2b30c5249d",
  "name": "externallmg_r_1689825173046_00308___20230719Wed_120508PM___x
rrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "path": "cases/64b655a849e7304e4a7cf4a9/externallmg_r_1689825173046_00308
___20230719Wed_120508PM___xrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b8af9638df6b2b30c5249e",
  "name": "externallmg_r_1689825173053_00309___20230719Wed_120510PM___x
rrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "path": "cases/64b655a849e7304e4a7cf4a9/externallmg_r_1689825173053_00309
___20230719Wed_120510PM___xrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b8af9638df6b2b30c5249f",
  "name": "externallmg_r_1689825173058_00310___20230719Wed_120517PM___x
```

```
rrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "path": "cases/64b655a849e7304e4a7cf4a9/externallmg_r_1689825173058_00310
____20230719Wed_120517PM___xrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"createdAt": "2023-07-18T09:04:40.161Z",
"updatedAt": "2023-07-20T07:43:48.022Z",
"__v": 0,
"fullAddress": "Residential Flat No. 106, 1st Floor, Kaypee Heritage Co-Op. Hsg. Soc.
Ltd., Plot No. 41, Sector 07, Village - Koparkhairane, Taluka - Thane, District - Thane,
Navi Mumbai, PIN - 400 709, State - Maharashtra, Country - India",
"updatedBy": "62fe044a48a26047e6552796",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Arvind Prahlad Gangane ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9594366694",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Passage + 2 Toilet",
"carpetTotal": "564.96",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "175.66",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "175.66",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "814.68",
"finalCarpetArea": "740.62",
"finalSalableArea": "896.15",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 565.00\nTerrace Area in Sq. Ft. =
176.00\n\n",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 571.00"
```

Name	Length	Width	Total
Composition :			
Living Room	10'3"	18'11"	193.90
Kitchen	10'9"	6'10"	73.46
Passage	10'1"	3'00"	30.25
Bedroom	11'1"	9'6"	105.29
Bedroom	9'6"	11'11"	113.21
Toilet	7'00"	4'00"	28.00
Toilet	3'3"	6'5"	20.85
Other Composition :			
Terrace	7'00"	12'00"	84.00
Terrace	3'1"	10'00"	30.83
Terrace	6'1"	10'00"	60.83