

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b80a"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230c78",
    "firstName": "Arjun R. Narayankar",
    "email": "0_default_sbi.17889@sbi.co.in_and_ajun.n@sbi.co.in",
    "mobileNo": "0_DEFAULT_022-23707515",
    "workMobileNo": "0_DEFAULT_91-9930242491"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2000000",
    "discussWithPerson": "KAUSHUIK DATTA",
    "expectedFees": 1000,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072.",
    "city": "Mumbai"
  }
}
```

```
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b80a",
  "branchCode": "000088",
  "type": "BRANCH",
  "name": "RACPC - Chinchpokli ",
  "email": "sbi.17889@sbi.co.in",
  "mobileNo": "022-23707514",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, Mumbai South Voltas
House, 'A', 1st Floor, Dr. Ambedkar Road, Chinchpokli (East), Mumbai - 400 033, State
- Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - CHINCHPOKALI",
  "fax": "022-23707512 / 13",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62727444afd7d55eddee092c",
    "role": "PICKUPPERSON",
    "firstName": "Shantilal",
    "email": "shantilal@vastukala.org",
    "lastName": "Patel",
    "mobileNo": "9969039853",
```

```
"shortName": "SHP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62ea09ea4e679b264caf07d7",
"role": "SITEENGINEER",
"firstName": "Suraj",
"email": "suraj@vastukala.org",
"lastName": "Zore",
"mobileNo": "8652448654",
"designation": "",
"shortName": "SZ",
"workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
"profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shyma_Photo.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60eebe33f3dd69653a5837ae",
"role": "MAKER",
"firstName": "Shamal",
"email": "shamal@vastukala.org",
"lastName": "Bodke",
"mobileNo": "9821740317",
"designation": "",
"shortName": "SB",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
```

```
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyam_Photo.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "CAT-I-A-1930",
        "label": "Chartered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "60af7d4d2ffdf65bcd658643",
    "PANNo": "AESPC7493M",
    "role": "VALUER",
    "firstName": "Vidhi",
    "fatherName": "Manoj",
    "email": "vids_singh@yahoo.com",
    "lastName": "Chalikwar",
    "mobileNo": "9820549087",
    "designation": "Valuer",
    "registrationNo": [
      {
        "title": {
          "value": "Chartered_Valuer",
          "label": "Chartered Valuer"
        },
        "_id": "60eeb39af3dd69653a58168d",
        "number": "CAT-I-A-1930"
      }
    ],
    "shortName": "VC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af7d4d2ffdf65bcd658643\\
```

```
\profilePhoto_1622113613002_Vidhi C.jpeg"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.288128112915643",
  "longitude": "72.94786939274215"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.94786939274215,
    19.288128112915643
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-07-21",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft."
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
```

```
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Bhayenderpada",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "10",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "3, Shamrock",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Thane (West)",
  "label": false
},
"tahasilNo": {
```

```
"status": false,
"name": "Tahasil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Emerald Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Ghodbunder Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
```

```
"label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Vihang Hills",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Godrej Emerald",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "91/1/1A, 91/2A, 109/30/1/B(P), 109/30/4A, 109/33, 109/34, 102/2B,
102/2C, 102/3B(P), 103/4(P), 103/5/B/2, 103/3A(P), 102/1",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
```



```
"status": false,
"name": "CTS No.",
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1006",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
```

```
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 615",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
```

```
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Thane_Municipal_Corporation",
    "label": "Thane Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Pine Building",
    "west": "Club House",
    "south": "TMC Play Ground / Internal Road",
    "east": "JVM Sky Court Building "
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "extraDetailOfProperty": ""
}
```

```
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "83300",
  "landRate": "16400",
  "igrImage": "cases/64b6b61cf76ce54e5d43a21c/igr_1690019181176_Image.png",
  "squareMeterGuideLineRate": "87465.00",
  "squareFeetGuideLineRate": "8126.00"
},
"igrFinalRate": {
  "rate": "83300",
  "squareMeterGuideLineRate": "87465.00",
  "squareFeetGuideLineRate": "8126.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "22,500",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per TMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
```

```
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Along with One Covered Car Parking Space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2022",
    "fullDate": "1/1/2022"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "R.C.C._Framed_Structure",
```

```
"label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
}
```

```
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "1",
"totalLifeBuilding": "60",
"estimatedAge": "59",
"noOfBasement": "3",
"noOfPodium": "1",
"noOfAmenityFloors": "",
"noOfFloors": "27",
"flatFloorNo": "10",
"noOfLifts": "3",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "630.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "routeMapImg": "cases/64b6b61cf76ce54e5d43a21c/
routeMap_1690019383706_Image.png",
  "routeLat": "19.282339",
```

```
"routeLng": "72.951634",
"stationName": "Thane",
"routeDistance": "13.08 Km"
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": true,
  "finallatLng": true
},
"locationMapImg": [
  {
    "id": "dj4h9d",
    "name": "dj4h9d",
    "image": "cases/64b6b61cf76ce54e5d43a21c/
routeMap_1690019275882_Image.png"
  }
],
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
```



```
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "9030000.00",
"bookValue": "0",
"finalValue": "9030000.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Sat Jul 22 2023 15:57:54 GMT+0530 (India Standard Time)",
  "number": "2301738",
  "dayCount": "10",
  "monthCount": "363",
  "generatedBy": "60eeaeddf3dd69653a581316"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
```

```
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "5119380.00",
  "selectedBuildUpValue": "630.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "64bab9d2a87c525d5c04527d",
      "name": "externallmg_1689958861052_1689958638042_image_3.jpeg",
      "path": "cases/64b6b61cf76ce54e5d43a21c/
externallmg_1689958861052_1689958638042_image_3.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "64bab9d2a87c525d5c04527a",
      "name": "externallmg_1689958860962_1689958638042_image_0.jpeg",
      "path": "cases/64b6b61cf76ce54e5d43a21c/
externallmg_1689958860962_1689958638042_image_0.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "64bab9d2a87c525d5c04527c",
      "name": "externallmg_1689958861024_1689958638042_image_2.jpeg",
      "path": "cases/64b6b61cf76ce54e5d43a21c/
externallmg_1689958861024_1689958638042_image_2.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "64bab9d2a87c525d5c04528b",
      "name": "externallmg_1689958861238_1689958638042_image_17.jpeg",
      "path": "cases/64b6b61cf76ce54e5d43a21c/
externallmg_1689958861238_1689958638042_image_17.jpeg",
      "orientation": "portrait"
    }
  ]
}
```

```
    },
    {
      "status": false,
      "_id": "64bab9d2a87c525d5c04528a",
      "name": "externallmg_1689958861225_1689958638042_image_16.jpeg",
      "path": "cases/64b6b61cf76ce54e5d43a21c/
externallmg_1689958861225_1689958638042_image_16.jpeg",
      "orientation": "portrait"
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "64bab9d2a87c525d5c04527e",
      "name": "Living Room",
      "path": "cases/64b6b61cf76ce54e5d43a21c/
externallmg_1689958861083_1689958638042_image_4.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "64bab9d2a87c525d5c045284",
      "name": "Living Room",
      "path": "cases/64b6b61cf76ce54e5d43a21c/
externallmg_1689958861144_1689958638042_image_10.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "64bab9d2a87c525d5c045283",
      "name": "Living Room",
      "path": "cases/64b6b61cf76ce54e5d43a21c/
externallmg_1689958861136_1689958638042_image_9.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "64bab9d2a87c525d5c045285",
      "name": "Living Room",
      "path": "cases/64b6b61cf76ce54e5d43a21c/
externallmg_1689958861158_1689958638042_image_11.jpeg",
      "orientation": "portrait"
    }
  ]
}
```

```
    "status": false,
    "_id": "64bab9d2a87c525d5c045289",
    "name": "Living Room",
    "path": "cases/64b6b61cf76ce54e5d43a21c/
externallmg_1689958861212_1689958638042_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "64bab9d2a87c525d5c045288",
    "name": "Living Room",
    "path": "cases/64b6b61cf76ce54e5d43a21c/
externallmg_1689958861201_1689958638042_image_14.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
```



```
"finalValuationArea": "525.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86A/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"_id": "64b6b61cf76ce54e5d43a21c",
"ownerName": "Mr. Dadaso J. Jadhav & Mrs. Pranita D. Jadhav",
"ownerPhoneNo": "9702206551",
"appAddress": "Flat no 1006\n10th floor\nbuilding no 3\nEmerald chs Ltd\nngodbunder
Road Thane ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "11/07/2023",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Dr. Mrs. Priya I. Rohra",
      "to": {
        "value": "Transferee",
        "label": "Transferee"
      },
      "Transferee": "Mr. Dadaso J. Jadhav & Mrs. Pranita D. Jadhav"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "992518",
    "path": "cases/64b6b61cf76ce54e5d43a21c/
document_1689749414634_D_j_jadhav__1.pdf",
    "fileName": "document_1689749414634_D_j_jadhav__1.pdf"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    },
    "inputs": {
      "documentDate": "02/02/2018",
```

```
"nameOfApprovingAuthority": {
  "value": "Thane_Municipal_Corporation",
  "label": "Thane Municipal Corporation"
},
"number": {
  "value": "No",
  "label": "No"
},
"No": "V. P. No. S06 / 0084 / 10 / TMC / TDD / 2502 / 18"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1690015589102_2_Commencement_Certificates__NA_Order_for_plotted_development.pdf",
"path": "cases/64b6b61cf76ce54e5d43a21c/document_1690015589102_2_Commencement_Certificates__NA_Order_for_plotted_development.pdf",
"id": "593572",
"uploadedBy": "60eebe33f3dd69653a5837ae",
"createdAt": "Sat Jul 22 2023 14:16:29 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "06/07/2022",
    "nameOfApprovingAuthority": {
      "value": "Thane_Municipal_Corporation",
      "label": "Thane Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "V. P. No. S06 / 0084 / 10 / TMC / TDD / OCC / 1078 / 22"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1690015777948_1_Occupancy_Certificate__Completion_Certificate__Architects_certificate_of_completion_for_plotted_development.pdf",
"path": "cases/64b6b61cf76ce54e5d43a21c/document_1690015777948_1_Occupancy_Certificate__Completion_Certificate__Architects_certificate_of_completion_for_plotted_development.pdf",
"id": "676941",
"uploadedBy": "60eebe33f3dd69653a5837ae",
```

```
"createdAt": "Sat Jul 22 2023 14:19:38 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "08/09/2021",
    "number": {
      "value": "Registration_No",
      "label": "Registration No"
    },
    "Registration_No": "P51700000120"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1690015835695_P51700000120.pdf",
  "path": "cases/64b6b61cf76ce54e5d43a21c/
document_1690015835695_P51700000120.pdf",
  "id": "160676",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Sat Jul 22 2023 14:20:35 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "002653",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "409088",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Jul 18 2023 21:26:12 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Dadaso J. Jadhav & Mrs. Pranita D. Jadhav",
    "phone": "9702206551",
    "ownershipShare": "",
    "email": "",
    "id": "480405"
  }
],
"siteInspection": [],
"composition": [
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "973179",
  "name": "Living Room",
  "length": "10.75",
  "length1": "10",
  "length2": "9",
  "width": "13.75",
  "width1": "13",
  "width2": "9",
  "totalArea": "147.81",
  "images": [],
  "extraAreas": [],
  "finalArea": "147.81"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "7.17",
  "length1": "7",
  "length2": "2",
  "width": "8.17",
  "width1": "8",
  "width2": "2",
  "totalArea": "58.53",
  "images": [],
  "extraAreas": [],
  "finalArea": "58.53"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "3.25",
  "length1": "3",
  "length2": "3",
```

```
"width": "11.00",
"width1": "11",
"width2": "0",
"totalArea": "35.75",
"images": [],
"extraAreas": [],
"finalArea": "35.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Toilet",
  "length": "3.83",
  "length1": "3",
  "length2": "10",
  "width": "6.83",
  "width1": "6",
  "width2": "10",
  "totalArea": "26.19",
  "images": [],
  "extraAreas": [],
  "finalArea": "26.19"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "3.75",
  "length1": "3",
  "length2": "9",
  "width": "6.75",
  "width1": "6",
  "width2": "9",
  "totalArea": "25.31",
  "images": [],
  "extraAreas": [],
  "finalArea": "25.31"
},
{
  "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "8.17",
  "length1": "8",
  "length2": "2",
  "width": "7.42",
  "width1": "7",
  "width2": "5",
  "totalArea": "60.57",
  "images": [],
  "extraAreas": [],
  "finalArea": "60.57"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "10.17",
  "length1": "10",
  "length2": "2",
  "width": "11.08",
  "width1": "11",
  "width2": "1",
  "totalArea": "112.68",
  "images": [],
  "extraAreas": [],
  "finalArea": "112.68"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "value": "Cupboard",
      "label": "Cupboard"
    }
  },
  "measurementType": {
```

```
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "0",
"length1": "1",
"length2": "10",
"length": "1.83",
"width1": "6",
"width2": "11",
"width": "6.92",
"totalArea": "12.68",
"percentageBeforeTotal": "19.45",
"images": [],
"extraAreas": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "_id": "64bb9600a87c525d5c05431d",
    "name": "Cupboard 2",
    "extraAreaType": "Add",
    "length": "3.25",
    "length1": "3",
    "length2": "3",
    "width": "2.08",
    "width1": "2",
    "width2": "1",
    "totalArea": "6.77"
  }
],
"percentage": "100",
"finalArea": "19.45"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "value": "Dry_balcony",
    "label": "Dry Balcony"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  }
}
```

```
    },
    "id": "1",
    "length1": "6",
    "length2": "1",
    "length": "6.08",
    "width1": "2",
    "width2": "1",
    "width": "2.08",
    "totalArea": "12.67",
    "percentageBeforeTotal": "12.67",
    "images": [],
    "extraAreas": [],
    "percentage": "100",
    "finalArea": "12.67"
  }
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "471620",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "525",
    "squareMeterArea": "48.77",
    "docFinalBuiltUp": "630",
    "docFinalBuiltUpSquareMeter": "58.524",
    "docBultupPercentage": "20",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "64bba3c9a87c525d5c0565ea",
    "id": "1",
    "property": "Residential Flat",
```



```
"area": "519.36",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "21",
"source": "https://www.99acres.com/",
"expectedPrice": "9500000",
"expectedRate": "18291.74",
"builtUpExpectedRate": "15243.17",
"image": "cases/64b6b61cf76ce54e5d43a21c/
indicator_1690018761504_Image.png"
},
{
  "printlnReport": true,
  "_id": "64bba3f9a87c525d5c056618",
  "id": "2",
  "property": "Residential Flat",
  "area": "502",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "1st to 28",
  "source": "https://www.99acres.com/",
  "expectedPrice": "8900000",
  "expectedRate": "17729.08",
  "builtUpExpectedRate": "14774.24",
  "image": "cases/64b6b61cf76ce54e5d43a21c/
indicator_1690018809087_Image.png"
},
{
  "printlnReport": true,
  "_id": "64bba43ca87c525d5c056642",
  "id": "3",
  "property": "Residential Flat",
  "area": "525",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "4 to 27",
  "source": "magic_bricks",
  "expectedPrice": "9000000",
  "expectedRate": "17142.86",
  "builtUpExpectedRate": "14285.71",
```

```
    "image": "cases/64b6b61cf76ce54e5d43a21c/
indicator_1690018876315_Image.png"
  },
  {
    "printlnReport": true,
    "_id": "64bba46ba87c525d5c056655",
    "id": "4",
    "property": "Residential Flat",
    "area": "525",
    "builtUpPercentage": "20",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "floor": "8 to 26",
    "source": "magic_bricks",
    "expectedPrice": "9500000",
    "expectedRate": "18095.24",
    "builtUpExpectedRate": "15079.37",
    "image": "cases/64b6b61cf76ce54e5d43a21c/
indicator_1690018923796_Image.png"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64bab9d2a87c525d5c04527a",
    "name": "externalImg_1689958860962_1689958638042_image_0.jpeg",
    "path": "cases/64b6b61cf76ce54e5d43a21c/
externalImg_1689958860962_1689958638042_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64bab9d2a87c525d5c04527b",
    "name": "externalImg_1689958860993_1689958638042_image_1.jpeg",
    "path": "cases/64b6b61cf76ce54e5d43a21c/
externalImg_1689958860993_1689958638042_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64bab9d2a87c525d5c04527c",
    "name": "externalImg_1689958861024_1689958638042_image_2.jpeg",
```

```
    "path": "cases/64b6b61cf76ce54e5d43a21c/
externallmg_1689958861024_1689958638042_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64bab9d2a87c525d5c04527d",
    "name": "externallmg_1689958861052_1689958638042_image_3.jpeg",
    "path": "cases/64b6b61cf76ce54e5d43a21c/
externallmg_1689958861052_1689958638042_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64bab9d2a87c525d5c04527e",
    "name": "externallmg_1689958861083_1689958638042_image_4.jpeg",
    "path": "cases/64b6b61cf76ce54e5d43a21c/
externallmg_1689958861083_1689958638042_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64bab9d2a87c525d5c04527f",
    "name": "externallmg_1689958861097_1689958638042_image_5.jpeg",
    "path": "cases/64b6b61cf76ce54e5d43a21c/
externallmg_1689958861097_1689958638042_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64bab9d2a87c525d5c045280",
    "name": "externallmg_1689958861109_1689958638042_image_6.jpeg",
    "path": "cases/64b6b61cf76ce54e5d43a21c/
externallmg_1689958861109_1689958638042_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64bab9d2a87c525d5c045281",
    "name": "externallmg_1689958861120_1689958638042_image_7.jpeg",
    "path": "cases/64b6b61cf76ce54e5d43a21c/
externallmg_1689958861120_1689958638042_image_7.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64bab9d2a87c525d5c045282",
    "name": "externallmg_1689958861129_1689958638042_image_8.jpeg",
    "path": "cases/64b6b61cf76ce54e5d43a21c/
externallmg_1689958861129_1689958638042_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64bab9d2a87c525d5c045283",
    "name": "externallmg_1689958861136_1689958638042_image_9.jpeg",
    "path": "cases/64b6b61cf76ce54e5d43a21c/
externallmg_1689958861136_1689958638042_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64bab9d2a87c525d5c045284",
    "name": "externallmg_1689958861144_1689958638042_image_10.jpeg",
    "path": "cases/64b6b61cf76ce54e5d43a21c/
externallmg_1689958861144_1689958638042_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64bab9d2a87c525d5c045285",
    "name": "externallmg_1689958861158_1689958638042_image_11.jpeg",
    "path": "cases/64b6b61cf76ce54e5d43a21c/
externallmg_1689958861158_1689958638042_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64bab9d2a87c525d5c045286",
    "name": "externallmg_1689958861177_1689958638042_image_12.jpeg",
    "path": "cases/64b6b61cf76ce54e5d43a21c/
externallmg_1689958861177_1689958638042_image_12.jpeg",
    "orientation": "portrait"
  }
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64bab9d2a87c525d5c045287",
      "name": "externallmg_1689958861191_1689958638042_image_13.jpeg",
      "path": "cases/64b6b61cf76ce54e5d43a21c/
externallmg_1689958861191_1689958638042_image_13.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64bab9d2a87c525d5c045288",
      "name": "externallmg_1689958861201_1689958638042_image_14.jpeg",
      "path": "cases/64b6b61cf76ce54e5d43a21c/
externallmg_1689958861201_1689958638042_image_14.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64bab9d2a87c525d5c045289",
      "name": "externallmg_1689958861212_1689958638042_image_15.jpeg",
      "path": "cases/64b6b61cf76ce54e5d43a21c/
externallmg_1689958861212_1689958638042_image_15.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64bab9d2a87c525d5c04528a",
      "name": "externallmg_1689958861225_1689958638042_image_16.jpeg",
      "path": "cases/64b6b61cf76ce54e5d43a21c/
externallmg_1689958861225_1689958638042_image_16.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "64bab9d2a87c525d5c04528b",
      "name": "externallmg_1689958861238_1689958638042_image_17.jpeg",
      "path": "cases/64b6b61cf76ce54e5d43a21c/
externallmg_1689958861238_1689958638042_image_17.jpeg",
      "orientation": "portrait"
    },
  },
}
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64bab9d2a87c525d5c04528c",
  "name": "externalImg_1689958806504_1689958583558_image_0.png",
  "path": "cases/64b6b61cf76ce54e5d43a21c/
externalImg_1689958806504_1689958583558_image_0.png",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64bab9d2a87c525d5c04528d",
  "name": "externalImg_1689958806597_1689958589858_image_0.jpeg",
  "path": "cases/64b6b61cf76ce54e5d43a21c/
externalImg_1689958806597_1689958589858_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "64bab9d2a87c525d5c04528e",
  "name": "externalImg_1689958806802_1689958589858_image_1.jpeg",
  "path": "cases/64b6b61cf76ce54e5d43a21c/
externalImg_1689958806802_1689958589858_image_1.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"createdAt": "2023-07-18T15:56:12.621Z",
"updatedAt": "2023-07-22T10:30:57.051Z",
"__v": 0,
"invoiceId": "64b6b61cf76ce54e5d43a223",
"updatedBy": "60eeaeddf3dd69653a581316",
"fullAddress": "Residential Flat No. 1006, 10th Floor, Building No 3, Shamrock,
Emerald Co-op. Hsg. Soc. Ltd., Godrej Emerald, Vihang Hills, Ghodbunder Road,
Village - Bhayenderpada, Taluka - Thane, District - Thane, Thane (West), PIN - 400
615, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Bapinder Singh",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
```

"relationWithOwner": "Broker",
 "siteVisitContactNo": "9172319081",
 "siteVisitDate": "2023-07-21",
 "briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Passage + 2 Toilet",
 "carpetTotal": "466.84",
 "finalMeasurementType": "Sq. Ft.",
 "otherCarpetTotal": "31.67",
 "otherCompositionBuiltUpTotal": "0.00",
 "otherCompositionCarpetTotal": "32.12",
 "otherCompositionSaleableTotal": "0.00",
 "builtupPercentage": "10",
 "finalBuiltupArea": "548.86",
 "finalCarpetArea": "498.96",
 "finalSalableArea": "603.74",
 "salablePercentage": "10",
 "toBeAdded": "",
 "extendOfSiteRemark": "\nCarpet Area in Sq. Ft. = 476.00\nExclusive Area in Sq. Ft. = 49.00\n(Area as per Agreement for sale)\n\nAll the above areas are within +/- 10% of the Agreement for Sale Area. The above calculations and detail measurements taken by us prove that the Agreement for Sale area is not exorbitantly inflated. Hence, valuation is based on the Agreement for Sale area.\n",
 "siteMeasurementRemark": "",
 "finalAreaType": "Carpet Area",
 "finalAsPerArea": "Agreement for sale",
 "finalBuiltUpPercentage": "20",
 "finalCarpetConvertToBuiltUpPer": "20",
 "finalSaleablePercentage": "0",
 "finalValuationAreaString": "Carpet Area in Sq. Ft. = 525.00",
 "buildingServicesRate": "2500",
 "flatRate": "17200",
 "landOtherRate": "14700"

Name	Length	Width	Total
Composition :			
Living Room	10'9"	13'9"	147.81
Kitchen	7'2"	8'2"	58.53
Passage	3'3"	11'0"	35.75
Toilet	3'10"	6'10"	26.19
Toilet	3'9"	6'9"	25.31
Bedroom	8'2"	7'5"	60.57

Bedroom	10'2"	11'1"	112.68
<hr/>			
Other Composition :			
<hr/>			
Cupboard	1'10"	6'11"	12.68
<hr/>			
Dry Balcony	6'1"	2'1"	12.67
<hr/>			